



Maintenance Items

N530BD

Make & Model (Serial) BOMBARDIER CL 604 (5352)	Operator Jet Linx Aviation	Reported Date 30-May-2026	Hours 8695.10	Landings 4002
--	--------------------------------------	-------------------------------------	-------------------------	-------------------------

- Major Components

Component	Model (Serial)	Hours	Cycles
Engine 1	CF34-3B (872215)	8695.10	4003.00
Engine 2	CF34-3B (872216)	8695.10	4003.00
APU 0	GTCP36-100(E) (P-223C)	10307.00	0.00

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining					
00 Airframe INSPECTION #1207	(BILLING ONLY) PREFLIGHT FOR THE MONTH	02-DEC-2020										
	Notes (AVG MAN HRS: 12) (APX COST: 679.8)											
00 Airframe INSPECTION #538	MISC. PARTS	27-APR-2022										
	Notes (AVG MAN HRS: 0.25) (APX COST: 310.52)											
00 9999.1 Airframe PART #1623	DEFIBRILLATOR SPARE BATTERY	31-MAY-2025										
	<table border="0" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%; text-align: right;">Part Number</td> <td style="width: 20%; text-align: left;">Serial Number</td> <td style="width: 60%;"></td> </tr> <tr> <td>M5070A</td> <td>346240098</td> <td></td> </tr> </table>	Part Number	Serial Number		M5070A	346240098		H: 8649.70	L: 3986			
Part Number	Serial Number											
M5070A	346240098											
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)											
00 JLA-Aircraft Records (-JLCD) Airframe INSPECTION #1083	(NON-GROUNDING, LOG ENTRY/MTR NOT REQUIRED TO COMPLETE THIS TASK) COLLECT/FILE RTS DOCUMENTATION FOR ALL MAINTENANCE PERFORMED IN THE LAST 30 DAYS. REVIEW COMPLIANCE HISTORY IN THE MAINTENANCE TRACKING SYSTEM TO CONFIRM ALL MAINTENANCE THAT WAS PERFORMED DURING THAT TIME.	14-MAY-2026	D: 30			13-JUN-2026	M: 0 D: 12					
		H: 8686.90	L: 3999									
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: VERIFIED LOG ENTRIES AGAINST COMPLIANCE HISTORY.)											



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
00 JLA-BPO - 000001.1 Airframe INSPECTION #3037	SERVICING - (BILLING PURPOSES ONLY)	25-FEB-2026					
	Notes (AVG MAN HRS: 1.5) (APX COST: 104.38)						
00 JLA-BPO - 000001.3 Airframe INSPECTION #2550	COST ADJUSTMENTS (BILLING PURPOSES ONLY)	19-AUG-2024 H: 8508.70 L: 3897					
	Notes (APX COST: 0.1) (UPDATE NOTE: BILLING PURPOSES ONLY)						
00 JLA-BPO - 000001.4 Airframe INSPECTION #135	CONSUMABLES FEE (BILLING PURPOSES ONLY)	25-FEB-2026					
	Notes (AVG MAN HRS: 3) (APX COST: 35.34)						
00 JLA-BPO 000001 - EVEN Airframe INSPECTION #1148	PRE/POST FLIGHT INSPECTION (BILLING PURPOSES ONLY)	25-FEB-2026					
	Notes (AVG MAN HRS: 6) (APX COST: 40)						
00 JLA-BPO 000001 - ODD Airframe INSPECTION #3617	PRE/POST FLIGHT INSPECTION (BILLING PURPOSES ONLY)	21-MAY-2026 H: 8686.90 L: 3999					
	Notes (AVG MAN HRS: 3) (APX COST: 0)						
00 JLA-BPO 000001.1 - EVEN Airframe INSPECTION #527	SERVICING (BILLING PURPOSES ONLY)	18-DEC-2025 H: 8670.40 L: 3995					
	Notes (AVG MAN HRS: 12) (APX COST: 453.5)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
00 JLA-BPO 000001.1 - ODD Airframe INSPECTION #1618	SERVICING (BILLING PURPOSES ONLY)	21-MAY-2026 H: 8686.90 L: 3999					
	Notes (AVG MAN HRS: 3) (APX COST: 30)						
00 JLA-BPO 000001.2 - ODD Airframe INSPECTION #1903	COORDINATE SCHEDULED/UNSCHEDULED/REQUIRED MAINTENANCE ITEMS (BILLING PURPOSES ONLY)	19-SEP-2025 H: 8650.80 L: 3987					
	Notes (AVG MAN HRS: 0.75) (APX COST: 11.25)						
00 JLA-BPO 000001.3 - EVEN Airframe INSPECTION #1420	CONSUMABLES FEE (BILLING PURPOSES ONLY)	18-DEC-2025 H: 8670.40 L: 3995					
	Notes (AVG MAN HRS: 3) (APX COST: 0)						
00 JLA-BPO 000001.3 - ODD Airframe INSPECTION #677	CONSUMABLES FEE (BILLING PURPOSES ONLY)	21-MAY-2026 H: 8686.90 L: 3999					
	Notes (AVG MAN HRS: 0) (APX COST: 229.66)						
00 JLA-BPO 000001.4 Airframe INSPECTION #1150	ENGINE & APU HOURS REPORTING (NON - GROUNDING)	21-MAY-2026 H: 8686.90 L: 3999					
	Notes (AVG MAN HRS: 0.5)						
00 JLA-BPO-000001.2 - EVEN Airframe INSPECTION #178	TECHNICAL REPRESENTATION ASSESSMENT AND AUTHORIZATION FOR SCHEDULED/UNSCHEDULED/REQUIRED MAINTENANCE ITEMS (BILLING PURPOSES ONLY)	25-FEB-2026					
	Notes (AVG MAN HRS: 19.5) (APX COST: 169.64)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
00 JLA-BPO-00001.2 - ODD Airframe INSPECTION #1520	TECHNICAL REPRESENTATION ASSESSMENT AND AUTHORIZATION FOR SCHEDULED/UNSCHEDULED/REQUIRED MAINTENANCE ITEMS (BILLING PURPOSES ONLY)	21-MAY-2026 H: 8686.90 L: 3999					
	Notes (AVG MAN HRS: 7.75) (APX COST: 1,359.6)						
00 JLA-Monthly0021-(- JLCD) Airframe INSPECTION #1768	MONTHLY MAINTENANCE ITEMS CHECK	26-MAY-2026 H: 8686.90 L: 3999	D: 30	D: 7		25-JUN-2026	M: 0 D: 24
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: COMPLIED WITH MONTHLY CHECKLIST)						
00 RTS Checklist Airframe INSPECTION #3500	RTS PACKAGE						
	Notes 0/14 STEPS ACCOMPLISHED.						
05 0014 APU INSPECTION #149	APU - 400 HOUR CHECK	05-JUL-2024 H: 10002.00	H: 400.00	H: 40.00		H: 10442.00	H: 135.00
	Notes (TOL. ADJUSTMENT: 40 HRS) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)						
05 0016 APU INSPECTION #41	APU - 600 HOUR CHECK	21-OCT-2024 H: 10142.00	H: 600.00	H: 40.00		H: 10742.00	H: 435.00
	Notes (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
05 0018 APU INSPECTION #94	APU - 800 HOUR CHECK	03-JAN-2023 H: 9642.00	H: 800.00	H: 40.00		H: 10442.00	H: 135.00



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 0020 APU INSPECTION #180	APU - 1200 HOUR CHECK	03-JAN-2023 H: 9642.00	H: 1200.00	H: 40.00		H: 10842.00	H: 535.00
05 0021 APU INSPECTION #140	APU - 2100 HOUR INSPECTION	03-JAN-2023 H: 9642.00	H: 2250.00	H: 40.00		H: 11892.00	H: 1585.00
05 0026 APU INSPECTION #166	APU - 2400 HOUR CHECK	03-JAN-2023 H: 9642.00	H: 2400.00	H: 40.00		H: 12042.00	H: 1735.00
05 50-41-210-801 Airframe INSPECTION #582	INSPECTION AFTER THE AIRCRAFT IS PARKED IN STRONG WINDS OR WINDGUSTS						
05 51-01-210-801 Airframe INSPECTION #3712	GENERAL VISUAL INSPECTION FOR HARD/OVERWEIGHT LANDING DAMAGE	29-APR-2010 H: 3805.90 L: 1609					
05 51-02-210-801 Airframe INSPECTION #1033	GENERAL VISUAL INSPECTION FOR HARD LANDING DAMAGE						
05 51-03-210-801 Airframe INSPECTION #3639	GENERAL VISUAL INSPECTION FOR EXTREME TURBULENCE/MANEUVER DAMAGE						
05 51-04-210-801 Airframe INSPECTION #2960	GENERAL VISUAL INSPECTION FOR LIGHTNING STRIKE DAMAGE						
05 51-05-210-801 Airframe INSPECTION #274	GENERAL VISUAL INSPECTION OF THE FLAPS AND THE LANDING GEAR FOR OVERSPEED DAMAGE						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 51-06-210-801 Airframe INSPECTION #2143	GENERAL VISUAL INSPECTION FOR TIRE BURST DAMAGE						
05 51-06-210-802 Airframe INSPECTION #845	GENERAL VISUAL INSPECTION AFTER A TIRE DEFLATES						
05 51-07-210-801 Airframe INSPECTION #1418	GENERAL VISUAL INSPECTION OF AIRCRAFT FOR WING LEADING-EDGE OVERHEAT DAMAGE						
05 51-08-210-801 Airframe INSPECTION #1502	GENERAL VISUAL INSPECTION OF AIR DRIVEN GENERATOR (ADG) AFTER IN-FLIGHT DEPLOYMENT					24-MAR-2017 H: 5979.40 L: 2577	
05 51-09-220-801 Airframe INSPECTION #690	DETAILED INSPECTION OF CABIN OVERPRESSURIZATION DAMAGE						
05 51-11-210-801 Airframe INSPECTION #2132	GENERAL VISUAL INSPECTION OF THE ENGINE DRIVEN PUMP (EDP) AFTER DRY OPERATION DUE TO HYDRAULIC FLUID LOSS						
05 51-12-281-801 Airframe INSPECTION #388	INSPECTION OF HYDRAULIC FLUID AFTER SYSTEM OVERHEAT						
05 51-13-220-801 Airframe INSPECTION #1297	DETAILED DIMENSIONAL INSPECTION OF AIRCRAFT FOR SYMMETRY AND ALIGNMENT						
05 51-14-210-801 Airframe INSPECTION #3581	GENERAL VISUAL INSPECTION OF THE PITOT-STATIC VISUAL DRAINS AFTER ADVERSE WEATHER OPERATIONS						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 51-15-210-801 Airframe INSPECTION #229	GENERAL VISUAL INSPECTION FOR HIGH ENERGY STOP/REJECT TAKEOFF (RTO) DAMAGE	17-MAY-2022 H: 7519.50 L: 3350					
	Notes (UPDATE NOTE: COMPLIED WITH INSPECTION 05-51-15-210-801, GENERAL VISUAL INSPECTION FOR HIGH ENERGY STOP/REJECT TAKEOFF (RTO) DAMAGE, IAW CL604 AMM REVISION 95 TASK 05-51-15-210-801. NO DEFECTS NOTED. ALL MAIN WHEEL FUSIBLE PLUGS ARE INTACT.)						
05 51-16-210-801 Airframe INSPECTION #3411	GENERAL VISUAL INSPECTION OF HYDRAULIC HARRISSON "H" FITTINGS						
05 51-17-210-801 Airframe INSPECTION #179	GENERAL VISUAL INSPECTION OF HYDRAULIC-PUMP SHOCK-MOUNT-CONTAMINATION-CHECK						
05 51-18-210-802 Airframe INSPECTION #2335	GENERAL VISUAL INSPECTION OF THE ELECTRICAL MOTOR DRIVEN PUMP (EMPD) AFTER DRY OPERATION DUE TO HYDRAULIC FLUID LOSS						
05 51-19-210-802 Airframe INSPECTION #306	DETAILED INSPECTION AFTER LAVATORY SPILL OR LEAK						
05 51-20-210-801 Airframe INSPECTION #2980	VISUAL INSPECTION AFTER A BIRD STRIKE						
05 51-21-210-801 Airframe INSPECTION #2535	INSPECTION AFTER RAPID CONTROL REVERSAL						
05 51-22-210-801 Airframe INSPECTION #839	INSPECTION OF AIRCRAFT AFTER CONTAMINATION WITH ORGANIC SALT BASED RUNWAY DE-ICING PRODUCTS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 52-00-210-801 Airframe INSPECTION #2612	UNSCHEDULED ENGINE CHECKS						
05 H6400 Airframe INSPECTION #3365	6400 HOUR CHECK	16-JUN-2018 H: 6372.80 L: 2715	H: 6400.00	H: 40.00		H: 12795.00	H: 4099.90
	Notes (MANUAL ADJUSTMENT: 22.2 HRS)						
05 M006 Airframe INSPECTION #2648	6 MONTH CHECK	26-MAY-2026 H: 8686.90 L: 3999	M: 6	M: 1		26-NOV-2026	M: 5 D: 25
	Notes (AVG MAN HRS: 16) (TOL. ADJUSTMENT: -17D) (UPDATE NOTE: COMPLIED WITH 6 MONTH CHECK TASKS IAW CL604 MPD REV 35 SECTION 2.4)						
05 M192 Airframe INSPECTION #3693	192 MONTH CHECK	13-APR-2013 H: 4782.30 L: 2063	M: 192	M: 1		13-APR-2029	M: 34 D: 12
05 PKG 12 Month Airframe INSPECTION #3714	12 MONTHLY TASKS	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 11 D: 25
	Notes (AVG MAN HRS: 48) (APX COST: 3,288.94) (TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: SDL MX CAPABLE)						
05 PKG 1200 Hour Airframe INSPECTION #16	1200 HOURLY TASKS	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
	Notes (AVG MAN HRS: 10.5) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 PKG 1600 Hour Airframe INSPECTION #1024	1600 HOURLY TASKS	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
	Notes (AVG MAN HRS: 14.7) (APX COST: 248.05) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)						
05 PKG 24 Month Airframe INSPECTION #2311	24 MONTHLY TASKS	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		29-MAY-2027	M: 11 D: 28
	Notes (AVG MAN HRS: 3.5) (TOL. ADJUSTMENT: -1D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
05 PKG 2400 Hour Airframe INSPECTION #1622	2400 HOURLY TASKS	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (UPDATE NOTE: WORK PERFORMED BY DUNCAN AVIATION UNDER WO FFMB)						
05 PKG 3200 Hour Airframe INSPECTION #3283	3200 HOURLY TASKS	16-JUN-2018 H: 6372.80 L: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (MANUAL ADJUSTMENT: -3.2 HRS)						
05 PKG 36 Month Airframe INSPECTION #1964	36 MONTHLY TASKS	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
	Notes (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
05 PKG 400 Hour Airframe INSPECTION #2044	400 HOURLY TASKS	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00	H: 40.00		H: 8875.40	H: 180.30
	Notes (AVG MAN HRS: 1.5) (TOL. ADJUSTMENT: 19.6 HRS) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
05 PKG 48 Month Airframe INSPECTION #1949	48 MONTHLY TASKS	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (TOL. ADJUSTMENT: -47D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
05 PKG 4800 Hour Airframe INSPECTION #1102	4800 HOURLY TASKS	13-APR-2013 H: 4782.30 L: 2063	H: 4800.00	H: 40.00		H: 9595.00	H: 899.90
	Notes (MANUAL ADJUSTMENT: 12.7 HRS)						
05 PKG 600 Hour Airframe INSPECTION #211	600 HOURLY TASKS	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
05 PKG 800 Hour Airframe INSPECTION #2990	800 HOURLY TASKS	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
05 PKG 96 Month Airframe INSPECTION #3510	96 MONTHLY TASKS	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 26.4) (TOL. ADJUSTMENT: -79D)						
08 0005 Airframe INSPECTION #1663	36 MONTH AIRCRAFT WEIGH	05-JUL-2024 H: 8455.80 L: 3862	M: 36			31-JUL-2027	M: 13 D: 30
	Notes (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
10 00-00 Airframe INSPECTION #3736	Airframe Storage Requirements	26-MAY-2026 H: 8686.90 L: 3999	D: 7			02-JUN-2026	M: 0 D: 1
21 Airframe PART #1099	AFT - LEFT SENSOR, DUCT TEMPERATURE (COCKPIT) Part Number 627962-2 Serial Number 116C9569					15-OCT-1997	
21 Airframe PART #2625	AFT - RIGHT SENSOR, DUCT TEMPERATURE (COCKPIT) Part Number 627962-2 Serial Number 126C9763					15-OCT-1997	
21 Airframe PART #2388	AFT VALVE, CHECK (PRESSURIZATION) Part Number 2770080-102 Serial Number 1426					15-OCT-1997	
21 Airframe PART #3477	AIR HEATER (ENTRY AREA UNDERFLOOR) Part Number Unknown Serial Number Unknown					15-OCT-1997	
21 Airframe PART #2916	CABIN CONTROL, TEMPERATURE Part Number 625514-2 Serial Number 106C0960					18-MAR-1998 H: 12.00 L: 6	
21 Airframe PART #2026	CABIN FAN, COOLING, MCE Part Number Unknown Serial Number Unknown					15-OCT-1997	
21 Airframe PART #2203	CABIN PRESSURE CONTROLLER Part Number 2117804-5 Serial Number 15-450					03-JAN-2024 H: 8219.50 L: 3728	

Notes

(APX COST: 0) (UPDATE NOTE: FOUND THE VOLTAGE COMING FROM THE CPC TO BE 0.2 VOLTS BELOW THE LIMITS OF 13V+/- 4V LISTED IN THE TROUBLESHOOTING PUB, INDICATING A MALFUNCTIONING CPC. REMOVED CPC (PN 2117804-5, SN 15-450) AND REPLACED THE CPC WITH CUSTOMER SUPPLIED, REPAIRED CPC (PN 2117804-5, SN 108-374, REPAIRED BY HONEYWELL INTERNATIONAL, REPAIR STATION# HZ3R571L, WORK ORDER 800721281/347110263, FORM TRACKING# 20230012791852Y15/347114667, REPAIR DATE 05/MAY/2023). OPS CHECK GOOD, STATIC LEAK TEST IS GOOD, WORK DONE IAW CL604 AMM 21-31-13. WORK COMPLETED BY JET EAST AVIATION CRS J21R713Y UNDER WORK ORDER AOG-79833, SEE MAINTENANCE LOG ENTRY DATED 03 JAN 2024 FOR DETAILS.)



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 Airframe PART #1800	CABIN SELECTOR, TEMPERATURE Part Number: 627964-1 Serial Number: Unknown	15-OCT-1997					
21 Airframe PART #3220	CABIN SELECTOR, TEMPERATURE MODE Part Number: 625638-1 Serial Number: Unknown	15-OCT-1997					
21 Airframe PART #2258	CABIN SENSOR, FAN Part Number: 625692-2-1 Serial Number: Unknown	15-OCT-1997					
21 Airframe PART #1809	COCKPIT CONTROL, TEMPERATURE Part Number: 625514-2 Serial Number: 076C0941	15-OCT-1997					
21 Airframe PART #3181	COCKPIT SELECTOR, TEMPERATURE Part Number: 627964-1 Serial Number: Unknown	15-OCT-1997					
21 Airframe PART #3606	COCKPIT SELECTOR, TEMPERATURE MODE Part Number: 625638-1 Serial Number: Unknown	15-OCT-1997					
21 Airframe PART #3252	CONTROL CABLE, FOOT WARMER/DEMIST Part Number: 601A95121-1 Serial Number: Unknown	15-OCT-1997					
21 Airframe PART #1992	CONTROLLER ASSY, CABIN PRESSURE Part Number: 604-51246-47 Serial Number: REL914065 5	27-MAY-2022 H: 7537.20 L: 3358					

Notes

(UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS# PAZR068H UNDER WO 356414)



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 Airframe PART #235	DUCT ASSY, AIR CONDITIONING Part Number: 601-95014-1 Serial Number: Unknown	15-OCT-1997					
Notes (ZONE: STA 621 TO 677)							
21 Airframe PART #3067	EJECTOR, JET PUMP Part Number: 131428-1 Serial Number: 76A0332	15-OCT-1997					
21 Airframe PART #2915	FAN, FOOT WARMER/DEMIST Part Number: 601R96380-3 Serial Number: C97177422	15-OCT-1997					
21 Airframe PART #222	FWD - LEFT SENSOR, DUCT TEMPERATURE (COCKPIT) Part Number: 627962-2 Serial Number: 106C9481	15-OCT-1997					
21 Airframe PART #3428	FWD - RIGHT SENSOR, DUCT TEMPERATURE (COCKPIT) Part Number: 627962-2 Serial Number: 056C9018	15-OCT-1997					
21 Airframe PART #370	FWD VALVE, CHECK (PRESSURIZATION) Part Number: 2770080-102 Serial Number: 1423	15-OCT-1997					
21 Airframe PART #1000	HEATER, FOOT WARMER/DEMIST Part Number: 601R96381-1 Serial Number: 221	15-OCT-1997					
21 Airframe PART #1058	LEFT COMPRESSOR OVERTEMPERATURE SWITCH Part Number: 641119-2 Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 Airframe PART #3625	LEFT CONTROL UNIT, ENVIRONMENTAL (ECU) Part Number: 2201600-6 Serial Number: 106-921	15-OCT-1997					
21 Airframe PART #2514	LEFT CONTROL, TEMP AND ELT UNIT (LOW LIMIT) Part Number: 625520-2 Serial Number: 047C0966	15-OCT-1997					
21 Airframe PART #1322	LEFT COOLING TURBINE Part Number: 586110-9 Serial Number: Unknown						
21 Airframe PART #3149	LEFT MIDGET THERMO SWITCH Part Number: 67321-27-240 Serial Number: Unknown	15-OCT-1997					
21 Airframe PART #1959	LEFT MOTOR, TORQUE (PNEUMATIC SHUTOFF(ACM)) Part Number: 124904-1-1 Serial Number: Unknown	15-OCT-1997					
21 Airframe PART #1217	LEFT SENSOR, DUCT TEMPERATURE (LOW LIMIT) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
21 Airframe PART #3306	LEFT SENSOR, DUCT TEMPERATURE (TEMP CONTROL) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
21 Airframe PART #1887	LEFT VALVE, CHECK, PRESS BKLHD Part Number: 3202062-1-1 Serial Number: 1089	15-OCT-1997					
	Notes (ZONE: AFT FUSE)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 Airframe PART #744	LEFT VALVE, LIMITER, TEMP, A/C DUCT Part Number: 129580-6 Serial Number: 8443	28-SEP-2010 H: 3976.30 L: 1697					
21 Airframe PART #665	LEFT VALVE, PRESSURE REGULATING (ACU) Part Number: 3213876-2 Serial Number: 1724	15-JUL-2023 H: 8083.20 L: 3653					
	<p>Notes</p> <p>(APX COST: 0) (UPDATE NOTE: TROUBLESHOT BY SWAPPING LH AND RH PRSOV REF. CL604 AMM 21-54-34. CLEANED PRSOV FILTERS REF. CL604 AMM 21-54-34. OPS AND LEAK CHECK SATISFACTORY. NO DIFFERENCE IN CABIN OR COCKPIT CONDITIONING PRESSURE. LH PN (OFF/ON): 3213876-2, SN (OFF): 1726, SN (ON): 1724. RH PN (OFF/ON): 3213876-2, SN (OFF): 1724, SN (ON): 1726. COMPLETED BY DIRECTMX AVIATION UNDER WORK ORDER SDL230411, SEE MAINTENANCE LOG ENTRY DATED 07-15-2023 FOR DETAILS.)</p>						
21 Airframe PART #2571	LEFT VALVE, SERVO, PRESSURE REGULATING (ACU) Part Number: 3214066-1 Serial Number: 1880	15-OCT-1997					
21 Airframe PART #442	LEFT VALVE, SHUT-OFF, A/C DUCT (TEMP. CONTROL, A.C.M) Part Number: 979558-8 Serial Number: Unknown	15-OCT-1997					
21 Airframe PART #657	NO. 2 MOTOR, TORQUE (LOW LIMIT) Part Number: 124904-1-1 Serial Number: 8811	11-AUG-2023 H: 8088.50 L: 3658					
	<p>Notes</p> <p>(APX COST: 0) (UPDATE NOTE: REMOVED LOW LIMIT ELECTROMAGNETIC CONTROL VALVE, P/N 124904-1-1 S/N UNKNOWN, AND INSTALLED NEW VALVE, P/N 124904-1-1 S/N 8811, IAW CL604 AMM REVISION 100 TASK 21-61-27. PERFORMED OPERATIONAL CHECK OF TEMPERATURE CONTROL SYSTEM IAW CL604 AMM REVISION 100 TASK 21-61-00-710-801. NO DEFECTS NOTED.)</p>						
21 Airframe PART #1303	NO. 2 VALVE, MODULATING, LOW LIMIT Part Number: 979580-4 Serial Number: 2134	11-AUG-2023 H: 8088.50 L: 3658					
	<p>Notes</p> <p>(APX COST: 0) (UPDATE NOTE: REMOVED LOW LIMIT VALVE, P/N 979580-4 S/N UNKNOWN, AND INSTALLED OVERHAULED LOW LIMIT VALVE, P/N 979580-4 S/N 2134, IAW CL604 AMM REVISION 100 TASK 21-61-29. LOW LIMIT SHUTOFF VALVE OVERHAULED BY TRIUMPH ACCESSORY SERVICES CRS OB2R051L, SEE FAA FORM 8130-3 TRACKING NUMBER 24S0000692 UNDER WORK ORDER 5800723233 DATED 29-JUN-2023 FOR DETAILS. PERFORMED OPERATIONAL CHECK OF TEMPERATURE CONTROL SYSTEM IAW CL604 AMM REVISION 100 TASK 21-61-00-710-801. NO DEFECTS NOTED)</p>						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 Airframe PART #130	NO.1 DUAL HEAT EXCHANGER Part Number Unknown Serial Number Unknown	15-OCT-1997					
21 Airframe PART #2968	NO.1 DUCT ASSY, AIR CONDITIONING (FLIGHT COMPARTMENT) Part Number 601-95006-1 Serial Number Unknown	15-OCT-1997					
21 Airframe PART #3127	NO.1 IRU TRAY FAN Part Number 026949 Serial Number 197423271	11-JUL-2023 H: 8075.40 L: 3647					
Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)							
21 Airframe PART #607	NO.1 MODULE, CABIN PRESSURE ACQUISITION Part Number 10275B04C03 Serial Number B610	15-OCT-1997					
21 Airframe PART #3187	NO.1 SENSOR, FAN (COCKPIT) Part Number Unknown Serial Number Unknown	15-OCT-1997					
21 Airframe PART #3338	NO.1 TEMPERATURE CONTROL MODULATING VALVE Part Number 979580-4 Serial Number Unknown						
21 Airframe PART #1718	NO.2 DUAL HEAT EXCHANGER Part Number Unknown Serial Number Unknown	15-OCT-1997					
21 Airframe PART #3402	NO.2 DUCT ASSY, AIR CONDITIONING (FLIGHT COMPARTMENT) Part Number 601-95007-1 Serial Number Unknown	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 Airframe PART #234	NO.2 MODULE, CABIN PRESSURE ACQUISITION Part Number Unknown Serial Number Unknown	15-OCT-1997					
21 Airframe PART #1533	NO.2 SENSOR, FAN (COCKPIT) Part Number 625692-2 Serial Number 066C0989	15-OCT-1997					
21 Airframe PART #1823	NO.2 TEMPERATURE CONTROL MODULATING VALVE Part Number 979580-4 Serial Number Unknown						
21 Airframe PART #1162	NO.3 DUCT ASSY, AIR CONDITIONING (FLIGHT COMPARTMENT) Part Number 601-95016-1 Serial Number Unknown	15-OCT-1997					
21 Airframe PART #942	REGULATOR, AIR PRESSURE, VACUUM Part Number 131402-2 Serial Number 0693A Notes (ZONE: BAGGAGE BAY)	15-OCT-1997					
21 Airframe PART #349	RIGHT COMPRESSOR OVERTEMPERATURE SWITCH Part Number 641119-2 Serial Number Unknown	15-OCT-1997					
21 Airframe PART #1628	RIGHT CONTROL UNIT, ENVIRONMENTAL (ECU) Part Number 2201600-6 Serial Number 106-929	15-OCT-1997					
21 Airframe PART #204	RIGHT CONTROL, TEMP AND ELT UNIT (LOW LIMIT) Part Number 625520-2 Serial Number 037C0964	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 Airframe PART #2819	RIGHT COOLING TURBINE Part Number: 586110-9 Serial Number: Unknown						
21 Airframe PART #502	RIGHT FAN, ASSY DISPLAY COOLING (LOWER FLOOR COCKPIT) Part Number: 604-96001-1 Serial Number: C96345376					15-OCT-1997	
21 Airframe PART #2397	RIGHT MIDGET THERMO SWITCH Part Number: 67321-27-240 Serial Number: Unknown					15-OCT-1997	
21 Airframe PART #3659	RIGHT MOTOR, TORQUE (PNEUMATIC SHUTOFF(ACM)) Part Number: 124904-1-1 Serial Number: 8805					11-AUG-2023 H: 8088.50 L: 3658	
	<p>Notes</p> <p>(APX COST: 0) (UPDATE NOTE: REMOVED ELECTROMAGNETIC TEMPERATURE CONTROL VALVE, P/N 124904-1-1 S/N UNKNOWN, AND INSTALLED NEW VALVE, P/N 124904-1-1 S/N 8805, IAW CL604 AMM REVISION 100 TASK 21-61-25. PERFORMED OPERATIONAL CHECK OF TEMPERATURE CONTROL SYSTEM IAW CL604 AMM REVISION 100 TASK 21-61-00-710-801. NO DEFECTS NOTED.)</p>						
21 Airframe PART #626	RIGHT SENSOR, DUCT TEMPERATURE (LOW LIMIT) Part Number: Unknown Serial Number: Unknown					15-OCT-1997	
21 Airframe PART #1383	RIGHT SENSOR, DUCT TEMPERATURE (TEMP CONTROL) Part Number: Unknown Serial Number: Unknown					15-OCT-1997	
21 Airframe PART #1536	RIGHT VALVE, CHECK, PRESS BKLHD Part Number: 3202062-1-1 Serial Number: 1134					15-OCT-1997	
	<p>Notes</p> <p>(ZONE: AFT FUSE)</p>						
21 Airframe PART #3589	RIGHT VALVE, LIMITER, TEMP, A/C DUCT Part Number: 129580-6 Serial Number: 4217					15-OCT-1997	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 Airframe PART #1853	RIGHT VALVE, PRESSURE REGULATING (ACU) Part Number: 3213876-2 Serial Number: 1726	15-JUL-2023 H: 8083.20 L: 3653					
Notes (APX COST: 0) (UPDATE NOTE: TROUBLESHOT BY SWAPPING LH AND RH PRSOV REF. CL604 AMM 21-54-34. CLEANED PRSOV FILTERS REF. CL604 AMM 21-54-34. OPS AND LEAK CHECK SATISFACTORY. NO DIFFERENCE IN CABIN OR COCKPIT CONDITIONING PRESSURE. LH PN (OFF/ON): 3213876-2, SN (OFF): 1726, SN (ON): 1724. RH PN (OFF/ON): 3213876-2, SN (OFF): 1724, SN (ON): 1726. COMPLETED BY DIRECTMX AVIATION UNDER WORK ORDER SDL230411, SEE MAINTENANCE LOG ENTRY DATED 07-15-2023 FOR DETAILS.)							
21 Airframe PART #872	RIGHT VALVE, SERVO, PRESSURE REGULATING (ACU) Part Number: 3214066-1 Serial Number: 1888	15-OCT-1997					
21 Airframe PART #1447	RIGHT VALVE, SHUT-OFF, A/C DUCT (TEMP. CONTROL, A.C.M) Part Number: 979558-8 Serial Number: Unknown	15-OCT-1997					
21 Airframe PART #1124	SELECTOR, CABIN PRESSURE Part Number: 2117598-7 Serial Number: 125-B0020	15-DEC-2023 H: 8207.00 L: 3719					
Notes (ZONE: OVERHEAD PANEL) (APX COST: 0) (UPDATE NOTE: REMOVED CABIN PRESSURE SELECTOR P/N 2117598-7 S/N 106B0048 AND INSTALLED REPAIRED SELECTOR P/N 2117598-7 S/N 125-B0020, TIGHTENED PNEUMATIC HOSES IAW BOMBARDIER CL 604 AMM 21-31-10. OPERATIONAL CHECK PASSED. UNIT REPAIRED BY HONEYWELL INTERNATIONAL INC. FORM TRACKING 20200007951740Y15339004126 WORK ORDER BBR37090/5800611053338983670 CRS# HZ3R571L DATED 11/MAR/2020)							
21 Airframe PART #2336	SWITCH, TEMPERATURE Part Number: 601R96384-4 Serial Number: 272	15-OCT-1997					
21 Airframe PART #962	VALVE, CHECK (CONDITIONED AIR DUCT) Part Number: 3202076-1-1 Serial Number: Unknown	15-OCT-1997					
21 Airframe PART #3678	VALVE, CHECK (FLT DECK CONDITIONED AIR) Part Number: 123790-1-1 Serial Number: 771	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 Airframe PART #514	VALVE, EMERGENCY (AFT FUSE EMERGENCY RAM AIR) Part Number: 398724-1-1 Serial Number: 1065268	15-OCT-1997					
21 Airframe PART #1656	VALVE, PRIMARY OUTFLOW Part Number: 103632-2 Serial Number: 118-314	08-FEB-2023 H: 7925.20 L: 3563					
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)						
21 Airframe PART #3649	VALVE, REGULATING, CABIN PRESSURE SELECTOR PANEL Part Number: 131400-2 Serial Number: 10-1590	07-AUG-2021 H: 7009.20 L: 3077					
21 Airframe PART #2298	VALVE, SECONDARY OUTFLOW Part Number: 103664-1 Serial Number: 102-359	08-FEB-2023 H: 7925.20 L: 3563					
	Notes (APX COST: 0) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)						
21 Airframe PART #842	WARDROBE FAN, IFE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
21 20-00-201 Airframe INSPECTION PKG 800 Hour #970	OPERATIONAL TEST OF THE PRESSURE-BULKHEAD CHECK VALVES	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
	Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
21 20-00-202 Airframe INSPECTION PKG1200Hour #1931	OPERATIONAL TEST OF THE LOW SPEED DETECTOR FOR THE AVIONICS EXHAUST FAN	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
21 24-34-301 Airframe INSPECTION PKG1600Hour #802	OPERATIONAL TEST OF THE DATA CONCENTRATOR UNIT (DCU) FAN.	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
	Notes (ZONE: 221) (ACCESS: 221CLF) (AVG MAN HRS: 2) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)						
21 30-00-201 Airframe INSPECTION PKG1600Hour #3429	RESTORATION (CLEANING) OF THE OUTFLOW VALVE POPPET AREA	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
	Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)						
21 30-00-202 Airframe INSPECTION PKG1600Hour #1216	DISCARD OF THE PRIMARY OUTFLOW VALVE AIR FILTER	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
	Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)						
21 30-00-203 Airframe INSPECTION PKG 600 Hour #2629	OPERATIONAL TEST OF THE PRESSURIZATION CONTROL SYSTEM (MANUAL MODE)	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 2.5) (TOL. ADJUSTMENT: -250.7 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
21 30-00-205 Airframe INSPECTION PKG2400Hour #901	OPERATIONAL TEST OF THE EMER DEPRESS SWITCH/LIGHT	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 1)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining				
21 31-00-101** Airframe INSPECTION #867	FUNCTIONAL TEST OF THE OUTFLOW VALVES	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00			H: 9525.20	H: 830.10				
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY.										
21 50-00-201 Airframe INSPECTION PKG2400Hour #3091	OPERATIONAL TEST OF THE RAM-AIR SHUTOFF VALVE	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50				
	Notes (AVG MAN HRS: 1)										
21 51-00-301 Airframe INSPECTION PKG 800 Hour #1658	CLEANING OF THE WATER SEPARATOR.	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40	H: 180.30				
	Notes (ZONE: 311312) (ACCESS: 311BB) (AVG MAN HRS: 7.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)										
22 Airframe PART #2063	(MDC) MAINTENANCE DIAGNOSTIC, COMPUTER (IAPS)										
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>622-9818-405</td> <td>1VV6H</td> </tr> </table>	Part Number	Serial Number	622-9818-405	1VV6H	31-MAY-2025 H: 8649.70 L: 3986					
Part Number	Serial Number										
622-9818-405	1VV6H										
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)										
22 Airframe PART #2444	ACTUATOR, SERVO AILERON										
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>622-4404-001</td> <td>900</td> </tr> </table>	Part Number	Serial Number	622-4404-001	900	15-OCT-1997					
Part Number	Serial Number										
622-4404-001	900										
	Notes (ZONE: MLG BAY)										



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
22 Airframe PART #3409	ACTUATOR, SERVO ELEVATOR Part Number: 622-5027-101 Serial Number: 21M3H	20-AUG-2007 H: 3113.60 L: 1258					
	Notes (RII ITEM)						
22 Airframe PART #2435	CARD, CAGE (IAPS) Part Number: 822-0781-001 Serial Number: 817	15-OCT-1997					
22 Airframe PART #2013	COMPUTER, AUTOPOWER Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: AVIONIC BAY)						
22 Airframe PART #2534	COUPLER, DUAL VOR ANTENNA (VERTICAL STAB) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
22 Airframe PART #2215	LEFT ACTUATOR LINEAR, YAW DAMPER, SVL-4000 Part Number: 622-9968-002 Serial Number: 1018	16-OCT-2021 H: 7109.30 L: 3137					
	Notes (UPDATE NOTE: ACTUATOR WAS REPLACED BY STEVENS AEROSPACE AND DEFENSE SYSTEMS CRS VIBR368K ON WO 8343)						
22 Airframe PART #2924	LEFT INDICATOR, AUTOPOWER Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
22 Airframe PART #337	MOUNT, SERVO, AILERON Part Number: 822-0259-001 Serial Number: 868	15-OCT-1997					
	Notes (ZONE: MLG BAY)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
22 Airframe PART #150	MOUNT, SERVO, ELEVATOR, SMT-87B Part Number: 822-0260-001 Serial Number: 2NV4Y	25-MAR-2008					
22 Airframe PART #2791	NO.1 OCM-4100,OPTIONS CONTROL MODULE Part Number: Unknown Serial Number: Unknown Notes (ZONE: AVIONIC BAY)	15-OCT-1997					
22 Airframe PART #1592	NO.1A FCC-4006, FLIGHT CONTROL COMPUTER (IAPS) Part Number: 822-0809-710 Serial Number: 1287 Notes (RII ITEM)	29-JUN-2018					
22 Airframe PART #2770	NO.1A IOC-4100, INPUT/OUTPUT CONCENTRATOR (IAPS) Part Number: 622-9814-715 Serial Number: 12BHW	25-JAN-2007					
22 Airframe PART #747	NO.1A POWER SUPPLY (IAPS) Part Number: 622-9945-020 Serial Number: Unknown	15-OCT-1997					
22 Airframe PART #719	NO.1A PROTECTOR, LIGHTNING/HIRF, LHP4000 (IAPS) Part Number: 822-0287-702 Serial Number: 2402 Notes (ZONE: FS333 BL0 WL60)	23-MAR-2008					
22 Airframe PART #1435	NO.1A SERVO SWITCHING, SSM-4000 (IAPS) Part Number: 822-0782-001 Serial Number: 274	25-FEB-2008					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
22 Airframe PART #289	NO.1B CONTROLLER, ENVIR (IAPS) Part Number 822-0288-001 Serial Number 1492	15-OCT-1997					
22 Airframe PART #2416	NO.1B FCC-4006, FLIGHT CONTROL COMPUTER (IAPS) Part Number 822-0809-710 Serial Number 2267 Notes (RII ITEM)	03-JUN-2009 H: 3637.50 L: 1526					
22 Airframe PART #3432	NO.1B FLIGHT MANAGEMENT COMPUTER (FMC) (IAPS) Part Number 822-0868-071 Serial Number 20D6 Notes (APX COST: 0) (UPDATE NOTE: DOWNLOADED MDC DATA IAW CL-604 AMM 45-45-00-978-801. SWAPPED #1 FMC AND #3 FMC CARDS IAW CL-604 AMM 22-12-16-400-801. COMPLIED WITH OPS TEST OF THE #1 FMC AND #3 FMC IAW CL-604 AMM 34-61-00-710-801, OPS TEST GOOD. FMC #1 P/N 822-0868-071 S/N 194WP. #3 FMC P/N 822-0868-071 S/N 20D6. COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)	21-OCT-2024 H: 8557.60 L: 3931					
22 Airframe PART #1111	NO.1B IOC-4100, INPUT/OUTPUT CONCENTRATOR (IAPS) Part Number 622-9814-715 Serial Number 1G83M	25-JAN-2007 H: 2895.70 L: 1155					
22 Airframe PART #2365	NO.1B POWER SUPPLY (IAPS) Part Number 622-9945-020 Serial Number Unknown	15-OCT-1997					
22 Airframe PART #1754	NO.1B UNIT, CONFIGURATION STRAPPING (IAPS) Part Number Unknown Serial Number Unknown	15-OCT-1997					
22 Airframe PART #2361	NO.2 OCM-4100,OPTIONS CONTROL MODULE Part Number Unknown Serial Number Unknown Notes (ZONE: AVIONIC BAY)	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
22 Airframe PART #2429	NO.2A FCC-4006, FLIGHT CONTROL COMPUTER (IAPS) Part Number: 822-0809-710 Serial Number: NLYT	29-JUN-2018 H: 6374.00 L: 2717					
	Notes (RII ITEM)						
22 Airframe PART #106	NO.2A IOC-4100, INPUT/OUTPUT CONCENTRATOR (IAPS) Part Number: 622-9814-715 Serial Number: G5LK	25-JAN-2007 H: 2895.70 L: 1155					
22 Airframe PART #536	NO.2A POWER SUPPLY (IAPS) Part Number: 622-9945-020 Serial Number: Unknown	15-OCT-1997					
22 Airframe PART #1764	NO.2A PROTECTOR, LIGHTNING (IAPS) Part Number: 822-0332-702 Serial Number: 10MRB	23-MAR-2008 H: 3294.10 L: 1352					
22 Airframe PART #1017	NO.2A SERVO SWITCHING, SSM-4000 (IAPS) Part Number: 822-0782-001 Serial Number: 1NK2G	25-FEB-2008 H: 3271.40 L: 1340					
22 Airframe PART #3312	NO.2B CONTROLLER, ENVIR (IAPS) Part Number: 822-0288-001 Serial Number: 1493	15-OCT-1997					
22 Airframe PART #445	NO.2B FCC-4006, FLIGHT CONTROL COMPUTER (IAPS) Part Number: 822-0809-710 Serial Number: 25RVP	06-JUL-2012 H: 4568.40 L: 1968					
	Notes (RII ITEM)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
22 Airframe PART #64	NO.2B FLIGHT MANAGEMENT COMPUTER (FMC) (IAPS) Part Number: 822-0868-071 Serial Number: 1NRLJ	31-MAY-2025 H: 8649.70 L: 3986					
Notes (APX COST: 0) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
22 Airframe PART #2213	NO.2B IOC-4100, INPUT/OUTPUT CONCENTRATOR (IAPS) Part Number: 622-9814-715 Serial Number: G5LL	25-JAN-2007 H: 2895.70 L: 1155					
22 Airframe PART #1236	NO.2B POWER SUPPLY (IAPS) Part Number: 622-9945-020 Serial Number: Unknown	15-OCT-1997					
22 Airframe PART #1705	NO.2B UNIT, CONFIGURATION STRAPPING (IAPS) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
22 Airframe PART #3166	NO.3B FLIGHT MANAGEMENT COMPUTER (FMC) (IAPS) Part Number: 822-0868-071 Serial Number: 934	31-MAY-2025 H: 8649.70 L: 3986					
Notes (APX COST: 0) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
22 Airframe PART #3122	PANEL, ATS, CONTROL Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
22 Airframe PART #977	PANEL, FLIGHT CONTROL , FCP4003 (COCKPIT GLARESHIELD) Part Number: 822-0182-101 Serial Number: 1RTWB	10-JUL-2021 H: 6958.00 L: 3045					
Notes (RII ITEM) (UPDATE NOTE: REMOVED FLIGHT CONTROL PANEL P/N 822-0182-001 S/N 103, AND INSTALLED OVERHAULED UNIT, P/N 822-0182-001 S/N 1RTWB, IAW CL604 AMM REV. 92 TASK 22-11-01-400-801. OPERATIONAL CHECK SATISFACTORY. FLIGHT CONTROL PANEL OVERHAULED BY ROCKWELL COLLINS CRS ED7Y210Y, SEE WORK ORDER 3381303/001000/POOL AND FORM TRACKING NUMBER 106034408 DATED 06-30-2021 FOR DETAILS.)							



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
22 Airframe PART #832	POWER ASSY (AUTO THROTTLE COCKPIT UNDERFLOOR) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
22 Airframe PART #246	RIGHT ACTUATOR LINEAR, YAW DAMPER, SVL-4000 Part Number: 622-9968-102 Serial Number: 3R30W	29-JUN-2018 H: 6374.00 L: 2717					
22 Airframe PART #3585	RIGHT INDICATOR, AUTOPOWER Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
22 Airframe PART #1548	RIGHT TRANSMITTER, CONTROL SURFACE POSITION (AILERON) Part Number: 600-59191-5 Serial Number: Unknown	15-OCT-1997					
22 11-00-201 Airframe INSPECTION PKG1600Hour #3531	OPERATIONAL TEST OF THE SVL-4000 RUDDER ACTUATOR BRAKE Notes (AVG MAN HRS: 1.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
22 11-00-202 Airframe INSPECTION PKG 48 Month #552	LUBRICATION OF THE ELEVATOR SERVO Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
22 12-00-201 Airframe INSPECTION PKG 96 Month #1165	DETAILED INSPECTION OF THE LIGHTNING/HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE FLIGHT COMPARTMENT Notes (AVG MAN HRS: 30)	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
22 12-00-202 Airframe INSPECTION PKG 48 Month #353	DETAILED INSPECTION OF THE LIGHTNING/HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE FUSELAGE/STABILIZER - INTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
22 12-00-203 Airframe INSPECTION PKG 96 Month #154	DETAILED INSPECTION OF THE LIGHTNING/HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION OF THE VERTICAL STABILIZER - INTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 6)						
22 12-00-204 Airframe INSPECTION PKG 48 Month #201	DETAILED INSPECTION OF THE LIGHTNING/HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE AFT EQUIPMENT COMPARTMENT	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
22 12-00-205 Airframe INSPECTION PKG 96 Month #400	DETAILED INSPECTION OF THE LIGHTNING/HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE FUSELAGE BETWEEN FS409.00 AND FS621.00, BELOW WL73.5 - INTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 5)						
22 12-00-206 Airframe INSPECTION PKG 96 Month #1350	DETAILED INSPECTION OF THE LIGHTNING/HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION ON THE AVIONICS RACKS	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 22)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
22 12-00-207 Airframe INSPECTION PKG 96 Month #3316	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE LIGHTNING/HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION ON THE #2 VHF ANTENNA	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2)						
22 12-00-208 Airframe INSPECTION PKG 48 Month #3376	DETAILED INSPECTION OF THE LIGHTNING/HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE AVIONICS COMPARTMENTS	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
22 12-00-209 Airframe INSPECTION PKG 96 Month #2556	DETAILED INSPECTION OF THE LIGHTNING/HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION ON THE UPPER FS621 BULKHEAD	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3.5)						
22 12-00-210 Airframe INSPECTION PKG 96 Month #1302	DETAILED INSPECTION OF THE LIGHTNING/HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION ON THE WING DISCONNECTS - EXTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 4.5)						
22 12-00-211 Airframe INSPECTION PKG 96 Month #381	DETAILED INSPECTION OF THE LIGHTNING/HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION ON THE WING DISCONNECTS - INTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
22 12-00-212 Airframe INSPECTION PKG 48 Month #924	DETAILED INSPECTION OF THE LIGHTNING/HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE MAIN WHEEL WELLS	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (ZONE: 164) (ACCESS: 163AZ, 164AZ, 191AB, 191BB, 192BB) (AVG MAN HRS: 2.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
22 12-00-213 Airframe INSPECTION PKG 48 Month #3178	DETAILED INSPECTION OF THE LIGHTNING/HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE NOSE WHEEL WELL AND LANDING GEAR ASSEMBLY	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
22 12-16-301 Airframe INSPECTION PKG 48 Month #2657	NO.1B DISCARD OF THE FLIGHT MANAGEMENT COMPUTER BATTERY.	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (ZONE: 220) (ACCESS: 221CLF) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: PRE ROCKWELL COLLINS SB 25 REQUIREMENT 24 M OR 48 M NOTE: NOTE: REFER TO ROCKWELL COLLINS SERVICE INFORMATION LETTER (SIL) 06-1 (FMC-XX00 SIL 06-1) REV-05 OR LATEST REVISION. POST ROCKWELL COLLINS SB 25 AND PRE SB 27 REQUIREMENT IS 48 MOS)						
22 12-16-301 Airframe INSPECTION PKG 48 Month #174	NO.2B DISCARD OF THE FLIGHT MANAGEMENT COMPUTER BATTERY.	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (ZONE: 220) (ACCESS: 221CLF) (TOL. ADJUSTMENT: -47D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: PRE ROCKWELL COLLINS SB 25 REQUIREMENT 24 M OR 48 M NOTE: NOTE: REFER TO ROCKWELL COLLINS SERVICE INFORMATION LETTER (SIL) 06-1 (FMC-XX00 SIL 06-1) REV-05 OR LATEST REVISION. POST ROCKWELL COLLINS SB 25 AND PRE SB 27 REQUIREMENT IS 48 MOS)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
22 12-16-301 Airframe INSPECTION PKG 48 Month #2602	NO.3B DISCARD OF THE FLIGHT MANAGEMENT COMPUTER BATTERY.	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(ZONE: 220) (ACCESS: 221CLF) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: PRE ROCKWELL COLLINS SB 25 REQUIREMENT 24 M OR 48 M NOTE: NOTE: REFER TO ROCKWELL COLLINS SERVICE INFORMATION LETTER (SIL) 06-1 (FMC-XX00 SIL 06-1) REV-05 OR LATEST REVISION. POST ROCKWELL COLLINS SB 25 AND PRE SB 27 REQUIREMENT IS 48 MOS .)</p>						
22 12-25-301 Airframe INSPECTION PKG 48 Month #1942	DISCARD OF THE MAINTENANCE DIAGNOSTIC COMPUTER BATTERY.	31-MAY-2025 H: 8649.70 L: 3986	M: 48			31-MAY-2029	M: 35 D: 30
	<p>Notes</p> <p>(ZONE: 220) (ACCESS: 221CLF) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: NOTE: ROCKWELL COLLINS SERVICE INFORMATION LETTER FMC-XX00-06-1 STATES "FOR AIRCRAFT WITH A YEARLY UTILIZATION SIGNIFICANTLY LOWER THAN 400 HOURS, IT IS RECOMMENDED TO REPLACE THE BATTERY AT THE LOWER INTERVAL".)</p>						
22 1233-001 Airframe PART #513	AVIONICS BAY (CSU-4100) UNIT	Part Number 822-1364-002	Serial Number 1Y1LI	28-JUL-2005 H: 2522.30 L: 983			
22 1233-002 Airframe PART #1243	AVIONICS BAY (CSU-4100) UNIT	Part Number 822-1364-002	Serial Number 1Y1LR	28-JUL-2005 H: 2522.30 L: 983			
22 22-00-101** Airframe INSPECTION #3667	OPERATIONAL TEST OF THE YAW DAMPER LINEAR ACTUATORS (SVL-4000 RELAYS).	12-APR-2013 H: 4782.30 L: 2063	H: 4800.00			H: 9582.30	H: 887.20
	<p>Notes</p> <p>(AVG MAN HRS: 4) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 Airframe PART #2733	AFT EQUIPMENT BAY UNIT INTERPHONE Part Number: 600-59146-3 Serial Number: 8711	03-APR-2024 H: 8338.60 L: 3799					
Notes (APX COST: 0) (UPDATE NOTE: COMPLIED WITH BY RAPID AOG LLC JEAN CARLOS SUCHINI A&P 3794398 ON WO 23322 DATED APRIL 03, 2024.)							
23 Airframe PART #2537	AIRCELL ATG-5000 UNIT Part Number: 15864-001 Serial Number: 1586412475	05-MAY-2014 H: 5192.00 L: 2249					
23 Airframe PART #1876	AIRSHOW DATA COMMUNICATION UNIT Part Number: 920040 Serial Number: 154	18-OCT-2016 H: 5872.70 L: 2537					
23 Airframe PART #3172	ALTITUDE INDICATOR, CABIN Part Number: 604-59022-3 Serial Number: 158	15-OCT-1997					
23 Airframe PART #1192	AVIONIC BAY DECODER, SELCAL Part Number: 1200008-001 Serial Number: 198	15-OCT-1997					
23 Airframe PART #3289	AVIONIC BAY UNIT INTERPHONE Part Number: 600-59146-3 Serial Number: 1882	15-OCT-1997					
23 Airframe PART #57	BEACON, ACCOUSTIC, UNDERWATER LOCATOR (CVR) Part Number: DK120 Serial Number: DU15305	27-JAN-2015 H: 5388.20 L: 2339					
23 Airframe PART #34	CABIN ALTITUDE INDICATOR Part Number: Unknown Serial Number: Unknown						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 Airframe PART #3021	COCKPIT MICROPHONE, VOICE RECORDER Part Number: 93A055-40 Serial Number: 50220	15-OCT-1997					
23 Airframe PART #1352	COCKPIT UNIT, PANEL, CVR CONTROL Part Number: 93A151-20 Serial Number: 76167	15-OCT-1997					
23 Airframe PART #3674	COMMUNICATION MANAGEMENT UNIT (CMU-4000) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
23 Airframe PART #3520	COPILOT AUDIO CONTROL PANEL Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
23 Airframe PART #2683	DME MOUNT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
23 Airframe PART #3090	GALLEY AUDIO CONTROL PANEL (TOWER ASSY) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
23 Airframe PART #167	HEADPHONE Part Number: AIRMEN 750 Serial Number: Unknown	23-FEB-2003 H: 1595.00 L: 581					
23 Airframe PART #3217	LEFT AIS-ACP3V, AUDIO CONTROL UNIT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 Airframe PART #1627	LEFT NO.1 RECEIVER/TRANSMITTER - HF-9031A Part Number: 822-0101-002 Serial Number: 1580	10-NOV-2022 H: 7833.70 L: 3514					
Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK PERFORMED BY DIRECT MX AVIATION ZACK BRAWNER A&P 3725527 UNDER WO 20220391)							
23 Airframe PART #1923	LEFT RADIO TUNE UNIT (RTU4000) Part Number: 622-9852-224 Serial Number: 1BVDR	07-NOV-2022 H: 7820.30 L: 3509					
Notes (APX COST: 0) (UPDATE NOTE: REMOVED LEFT RADIO TUNE UNIT, P/N 622-9852-224 S/N 2355, AND INSTALLED OVERHAULED UNIT, P/N 622-9852-224 S/N 1BVDR, IAW CL604 AMM REVISION 97 TASK 23-81-01-400-801. OPERATIONAL CHECK SATISFACTORY. RADIO TUN UNIT OVERHAULED BY ENSAMBLADORES ELECTRONICOS DE MEXICO S. DE R.L. DE C.V ROCKWELL COLLINS CRS ED7Y210Y, SEE WORK ORDER RE POOL ON FAA FORM 8130-3 TRACKING NUMBER 106198304 DATED 17-OCT-2022 FOR DETAILS.)							
23 Airframe PART #2249	MODULE, CONFIGURATION IDE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
Notes (ZONE: AVIONIC BAY)							
23 Airframe PART #1041	NO.1 ANTENNA, VHF (FWD UPPER) Part Number: S65-8280-10 Serial Number: 4177	15-OCT-1997					
23 Airframe PART #254	NO.1 AUDIO CONTROL (DUAL VHF) PANEL Part Number: 856-0073-020 Serial Number: 1114	15-OCT-1997					
23 Airframe PART #1486	NO.1 COUPLER, HF ANTENNA Part Number: 622-8114-002 Serial Number: 8149	02-MAY-2022 H: 7496.00 L: 3339					
Notes (UPDATE NOTE: REMOVED #1 HF COUPLER, P/N 622-8114-002 S/N 1732, AND INSTALLED REPAIRED COUPLER, P/N 622-8114-002 S/N 8149, IAW CL604 AMM REVISION 95 TASK 23-12-03-400-801. OPERATIONAL CHECK SATISFACTORY. HF COUPLER REPAIRED BY ROCKWELL COLLINS SOUTHEAST ASIA PTE LTD CRS R5CY955J, SEE WORK ORDER 3445060/001000/POOL ON 8130 FORM TRACKING NUMBER 106117182 DATED 07-MAR-2022 FOR DETAILS)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 Airframe PART #1916	NO.1 TRANSCEIVER, VHF COMM ASSEMBLY (VHF-4000) Part Number: 822-1115-021 Serial Number: 5555	13-APR-2013 H: 4782.30 L: 2063					
	Notes (ZONE: AVIONIC BAY)						
23 Airframe PART #1368	NO.2 ANTENNA, VHF (FWD LOWER) Part Number: S65-8280-10 Serial Number: 4117	15-OCT-1997					
23 Airframe PART #2402	NO.2 AUDIO CONTROL (DUAL VHF) PANEL Part Number: 856-0073-020 Serial Number: 1116	15-OCT-1997					
23 Airframe PART #2216	NO.2 COUPLER, HF ANTENNA Part Number: 685-0350-002 Serial Number: 4638	28-SEP-2010 H: 3976.30 L: 1697					
23 Airframe PART #878	NO.2 TRANSCEIVER, VHF COMM ASSEMBLY (VHF-4000) Part Number: 822-1115-021 Serial Number: 3153	13-APR-2013 H: 4782.30 L: 2063					
	Notes (ZONE: AVIONIC BAY)						
23 Airframe PART #99	NO.3 ANTENNA, VHF (AFT UPPER) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
23 Airframe PART #2740	NO.3 TRANSCEIVER, VHF COMM ASSEMBLY (VHF-4000) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: AVIONIC BAY)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 Airframe PART #98	NOSE WHEEL WELL UNIT INTERPHONE Part Number: 600-59146-3 Serial Number: 2002	15-OCT-1997					
23 Airframe PART #629	PILOT AUDIO CONTROL PANEL Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
23 Airframe PART #81	RECORDER, COCKPIT VOICE (CVR) (120 MIN) Part Number: S100-0080-01 Serial Number: 01593	15-OCT-1997					
23 Airframe PART #2496	RIGHT AIS-ACP3V, AUDIO CONTROL UNIT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
23 Airframe PART #2472	RIGHT ELECTRONIC AUDIO CONTROL UNIT Part Number: 856-0073-010 Serial Number: 405 Notes (ZONE: AVIONIC BAY - FS235)	15-OCT-1997					
23 Airframe PART #2046	RIGHT NO.2 RECEIVER/TRANSMITTER - HF-9031A Part Number: 822-0101-002 Serial Number: 7374 Notes (APX COST: 0) (UPDATE NOTE: REMOVED HF #2 TRANSCEIVER, P/N 822-0101-002 S/N 2164, AND INSTALLED MODIFIED TRANSCEIVER, P/N 822-0101-002 S/N 7374, IAW CL604 AMM REVISION 94 TASK 23-12-01-400-801. SERVICED #1 AND #2 HF COUPLERS IAW CL604 AMM REVISION 94 TASK 23-12-03-720-801. OPERATIONAL CHECK OF HF SYSTEM SATISFACTORY. TRANSCEIVER MODIFIED BY ROCKWELL COLLINS, INC CRS NZ2R049L, SEE WORK ORDER 5800642717 AND FORM TRACKING NUMBER 105988147 DATED 19-MAR-2021 FOR DETAILS.)	28-JAN-2022 H: 7361.20 L: 3269					
23 Airframe PART #1920	RIGHT RADIO TUNE UNIT (RTU4000) Part Number: 622-9852-224 Serial Number: 24J1F Notes (APX COST: 0) (UPDATE NOTE: REMOVED RIGHT RADIO TUNING UNIT, P/N 622-9852-224 S/N 2356, AND INSTALLED A REPAIRED RADIO TUNING UNIT, P/N 622-9852-224 S/N 24J1F, IAW CL 604 AMM REVISION 94 TASK 23-81-01-400-801. OPERATIONAL CHECK SATISFACTORY. RADIO TUNING UNIT REPAIRED BY ROCKWELL COLLINS CRS ED7Y210Y, SEE WORK ORDER 5800672138 AND FORM TRACKING NUMBER 106092545 DATED 15-DEC-2021 FOR DETAILS.)	28-DEC-2021 H: 7285.70 L: 3229					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 Airframe PART #956	RIPS TYPE II, NICAD Part Number Unknown Serial Number Unknown	15-OCT-1997					
23 Airframe PART #426	SKYLIGHT DDA Part Number 08090021-6 Serial Number 776	27-DEC-2018 H: 6424.10 L: 2747					
23 Airframe PART #3208	SWITCH, INERTIA (CVR) Part Number 3L0-453-2 Serial Number 6904 Notes (ZONE: CENTER PEDESTAL)	15-OCT-1997					
23 Airframe PART - Expiration #2752	UNDERWATER LOCATING DEVICE (ULD) BATTERY (CVR) Part Number DK120 Serial Number NT64257 Notes (AVG MAN HRS: 1.5) (APX COST: 0) (UPDATE NOTE: WORK ACCOMPLISHED BY DIRECT MX CRS # FMSR378E DATED 10/29/2025 SEE WORK ORDER # CRS250482.) (NOTE: NOTE 14: DISCARD AT THE MANUFACTURER'S EXPIRATION DATE.)	29-OCT-2025 H: 8656.00 L: 3990				01-JUL-2031	M: 61 D: 0
23 00-ICA-9003 Airframe INSPECTION #3591	HIGH FREQUENCY EDDY CURRENT FORWARD FUSELAGE FEED THROUGH INSTALLATION PER DUNCAN AVIATION ICA DOC. NO. 110808030 SECTION 9.0 SPECIAL INSPECTION REQUIREMENTS Notes (MANUAL ADJUSTMENT: 2063 LDG)		L: 8900			L: 10963	L: 6961
23 00-ICA-9005 Airframe INSPECTION #1373	INSPECT (DETAILED) AIRCELL IRIDIUM ST 3100 ANTENNA CONNECTOR FEED-THRU HOLE - PER GULFSTREAM DOC NO. CBD4468A003		L: 11310			L: 11310	L: 7308
23 00-ICA-9006 Airframe INSPECTION #3058	INSPECT AIRCELL IRIDIUM ST 3100 ANTENNA ATTACHMENT HOLES - PER GULFSTREAM ICA DOC NO. CBD4468A003 Notes (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)	21-OCT-2024 H: 8557.60 L: 3931	L: 3980			L: 7911	L: 3909



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 60-00-201 Airframe INSPECTION PKG 96 Month #355	FUNCTIONAL TEST OF THE STATIC DISCHARGERS	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 4)						
23 60-00-202 Airframe INSPECTION PKG 48 Month #2395	FUNCTIONAL TEST (BONDING CHECK) OF THE STATIC DISCHARGER BASE	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
23 60-00-203 Airframe INSPECTION PKG 48 Month #813	FUNCTIONAL TEST (BONDING CHECK) OF THE NOSE-RADOME LIGHTNING STRIPS	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
23 71-00-202 Airframe INSPECTION PKG1200Hour #2818	OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER (CVR) SYSTEM	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.) (NOTE: NOTE 3: TASK AND INTERVAL MAY BE PART OF THE OPERATOR'S NATIONAL REGULATORY REQUIREMENTS. WHEN A TASK HAS 2 INTERVALS, ONE BEING "NOTE 3", THE MOST RESTRICTIVE INTERVAL APPLIES. WHEN A NATIONAL REGULATORY REQUIREMENT DOES NOT EXIST, THE MRB REPORT INTERVAL SHALL BE FOLLOWED.)						
23 71-00-203 Airframe INSPECTION #1261	OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATING DEVICE (ULD)	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 11 D: 30
	Notes (MANUAL ADJUSTMENT: 0D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: NOTE 3: TASK AND INTERVAL MAY BE PART OF THE OPERATOR'S NATIONAL REGULATIONS. WHENEVER A TASK HAS TWO INTERVALS, ONE BEING NOTE 3", THE GREATER INTERVAL IS RECOMMENDED. WHEN A NATIONAL REGULATION DOES NOT EXIST, THE MRB REPORT INTERVAL SHALL BE FOLLOWED.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
23 71-00-204 Airframe INSPECTION #360	ICA - VISUAL INSPECTION OF AIRCELL HIGH SPEED INTERNET SYSTEM WITH WIRELESS LAN	11-JUL-2023 H: 8075.40 L: 3647	M: 60			11-JUL-2028	M: 25 D: 10
Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)							
24 Airframe PART #1902	1T1XA TRANSFORMER Part Number: 720847A Serial Number: Unknown					15-OCT-1997	
24 Airframe PART #981	1T2XA TRANSFORMER Part Number: 720847A Serial Number: Unknown					15-OCT-1997	
24 Airframe PART #2544	1T3XA TRANSFORMER, INSTRUMENT CURRENT (JB1) (LOWER)(A/C SYS NO.1) Part Number: 601R59155-1 Serial Number: Unknown					15-OCT-1997	
24 Airframe PART #3711	2T1XA TRANSFORMER Part Number: 720847A Serial Number: Unknown					15-OCT-1997	
24 Airframe PART #1305	2T2XA TRANSFORMER Part Number: 720847A Serial Number: Unknown					15-OCT-1997	
24 Airframe PART #741	2T3XA TRANSFORMER, INSTRUMENT CURRENT (JB1) (MIDDLE)(A/C SYS NO.2) Part Number: 601R59155-1 Serial Number: Unknown					15-OCT-1997	
24 Airframe PART #1715	ADG ACTUATOR, EJECTION JACK Part Number: 728431B Serial Number: 0724					15-OCT-1997	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 Airframe PART - Life Limited #1734	ADG ACTUATOR, ELECTRICAL UPLOCK (SQUIB) Part Number: 055046B Serial Number: 931	21-OCT-2024 H: 8557.60 L: 3931	M: 60		M: 0	30-JUN-2028	M: 24 D: 29
Notes (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605. DOM 06/2023) (NOTE: ACTUATOR, ELECTRICAL UPLOCK (SQUIB))							
24 Airframe PART #1596	ADG ADAPTOR, GENERATOR Part Number: 720845D Serial Number: Unknown					15-OCT-1997	
24 Airframe PART #2856	ADG AIR DRIVEN GENERATOR UPLOCK ASSY Part Number: 721863C Serial Number: 0674					15-OCT-1997	
24 Airframe PART #1654	ADG BAY GENERATOR, AIR DRIVEN Part Number: Unknown Serial Number: Unknown					15-OCT-1997	
24 Airframe PART #2339	ADG GENERATOR, CONTROL UNIT Part Number: 756654A Serial Number: 0452					15-OCT-1997	
24 Airframe PART #1579	AFT FUSE - LEFT ENGINE PYLON HARNESS Part Number: 1697M51G03 Serial Number: Unknown					15-OCT-1997	
24 Airframe PART #3284	AFT FUSE - RIGHT ENGINE PYLON HARNESS Part Number: 1697M51G03 Serial Number: Unknown					15-OCT-1997	
24 Airframe PART #3157	AIR DRIVEN TURBINE ASSEMBLY Part Number: 756652A Serial Number: 0575	05-AUG-2005 H: 2523.60 L: 984					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 Airframe PART #2781	APU ADAPTOR, GENERATOR Part Number 722882E Serial Number 0359/1428	31-JUL-1999 H: 392.00 L: 148					
24 Airframe PART #3579	APU BATTERY Part Number 024453-000 Serial Number 093520	26-MAY-2026 H: 8686.90 L: 3999					
	Notes (APX COST: 0) (UPDATE NOTE: REMOVED APU BATTERY FOR CAP CHECK PN 024453-000, SN 090520028CC7A AND INSTALLED INSPECTED BATTERY PN 60059151-11, SN 090520028CC7A. IAW BOMBARDIER CL 604 AMM 24-32-04. OPERATIONAL CHECK GOOD. NO DEFECTS NOTED AT THIS TIME. REFERENCE 8130 DATED 08/DEC/2025, WORK ORDER NUMBER 001674-N530BD. SCRNM CERTIFICATE NUMBER 4SMR148C.)						
24 Airframe PART #3648	APU CHARGER, BATTERY Part Number 100-1084-02 Serial Number 1188006	29-JAN-2020 H: 6545.90 L: 2818					
	Notes (APX COST: 0) (UPDATE NOTE: REMOVED APU BATTERY CHARGER, P/N 237BC101-2 S/N 578, IAW CL-604 AMM TASK 24-32-07-000-802. INSTALLED INSPECTED APU BATTERY CHARGER, P/N 100-1084-02 S/N 1188006, IAW CL-604 AMM TASK 24-32-07-400-802. OPERATIONAL TEST SATISFACTORY. INSTALLED BATTERY CHARGER INSPECTED BY SECURAPLANE TECHNOLOGIES CERTIFICATE NO. SR0R383N W/O RMA-091049 FORM TRACKING NO. BBW17981/5800605779. THIS ACTION CLEARS MEL 24-32-4. AIRCRAFT RETURNED TO NORMAL CONFIGURATION.)						
24 Airframe PART #188	APU CONTROL UNIT, GENERATOR Part Number 720846D Serial Number 1784	15-OCT-1997					
24 Airframe PART #182	APU GENERATOR CONTACTOR Part Number P600-A803-E015 Serial Number 5157	21-OCT-2009 H: 3725.60 L: 1574					
24 Airframe PART #909	APU GENERATOR/ADAPTOR OIL COOLER ASSEMBLY (OIL/FUEL COOLED) Part Number 723210 Serial Number Unknown	15-OCT-1997					
24 Airframe PART #996	CONTROL ASSY, ADG RELEASE Part Number 601R90830-23 Serial Number Unknown	15-OCT-1997					
	Notes (ZONE: FWD FUSE - RIGHT)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 Airframe PART #3471	CONTROLLER, ADG AUTO DEPLOYMENT Part Number: 82046-4 Serial Number: Unknown Notes (ZONE: CENTER PEDESTAL)	15-OCT-1997					
24 Airframe PART #939	ESS TRU 1, FAN Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
24 Airframe PART #1366	EXTERNAL POWER MONITOR Part Number: 600-59142-3 Serial Number: Unknown	15-OCT-1997					
24 Airframe PART #28	GALLEY CB PANEL ASSY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
24 Airframe PART #477	GENERATOR, APU Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
24 Airframe PART #3214	HAND AIR DRIVEN GENERATOR PUMP Part Number: 731879C Serial Number: 0533	18-MAR-1998 H: 12.00 L: 6					
24 Airframe PART #3107	JB14 RELAY Part Number: TDH-1729-2500 Serial Number: Unknown	15-OCT-1997					
24 Airframe PART #3042	JB15 RELAY Part Number: TDH-1729-2500 Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 Airframe PART #2559	JUNCTION BOX ASSY, JB8 Part Number: 822-0845-001 Serial Number: Unknown	15-OCT-1997					
24 Airframe PART #2900	JUNCTION BOX ASSY, JB9 Part Number: 822-0845-001 Serial Number: Unknown	15-OCT-1997					
24 Airframe PART #2517	LEFT ENGINE CONTROL UNIT, GENERATOR Part Number: 720846D Serial Number: 5623	16-JAN-2020 H: 6542.90 L: 2815					
	Notes (UPDATE NOTE: REMOVED LEFT GENERATOR CONTROL UNIT, P/N 720846D S/N 1796, AND INSTALLED INSPECTED GENERATOR CONTROL UNIT, P/N 720846D S/N 5623, IAW CL-604 AMM REVISION 86 TASK 24-21-04-400-801. OPERATIONAL CHECK SATISFACTORY. GENERATOR CONTROL UNITS SWAPPED FOR TROUBLESHOOTING PURPOSES.)						
24 Airframe PART #398	LEFT ENGINE COOLER, IDG OIL Part Number: 63E79-1 Serial Number: Unknown	15-OCT-1997					
24 Airframe PART #2773	LEFT ENGINE GENERATOR, INTEGR DRIVE Part Number: 731579C Serial Number: 0656/1645	12-MAR-2020 H: 6560.10 L: 2832					
	Notes (APX COST: 0) (UPDATE NOTE: PERFORMED OPERATIONAL CHECK. OPERATIONAL CHECK SATISFACTORY. SWAPPED IDG'S FOR TROUBLESHOOTING PURPOSES. REMOVED IDG FROM #1 ENGINE P/N 731579-C S/N 0967 IAW CHALLENGER 604 24-11-01-000-801, AND INSTALLED P/N 731579-C S/N 1645 IAW CHALLENGER 604 AMM 24-11-01-400-801. REMOVED IDG FROM NUMBER 2 ENGINE P/N 731579-C S/N 1645 AND INSTALLED P/N 731579-C S/N 0967. WORK DONE IAW CHALLENGER 604 AMM TASK 24-11-01-400-801. OPERATION CHECK IS GOOD AT THIS TIME. WORK COMPLETED BY WESTSTAR AVIATION. SEE WORK ORDER 345832 FOR DETAILS.)						
24 Airframe PART #2828	LEFT JUNCTION BOX ASSY, JB10 Part Number: 604-51423-1 Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: AVIONIC BAY)						
24 Airframe PART #2316	MAIN BATTERY CHARGER Part Number: 237BC101-2 Serial Number: 582	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 Airframe PART #959	MAIN BATTERY, MODEL 1756-3 Part Number: 024637-000 Serial Number: 0905200150 F76	26-MAY-2026					
Notes (APX COST: 0) (UPDATE NOTE: REMOVED MAIN BATTERY FOR CAP CHECK PN 601R59041-3, SN 0905200222B1B AND INSTALLED INSPECTED BATTERY PN 601R59041-3, SN 0905200222B1B, IAW BOMBARDIER CL 604 AMM 24-32-01. OPERATIONAL CHECK GOOD. NO DEFECTS NOTED AT THIS TIME. REFERENCE 8130 DATED 08/DEC/2025, WORK ORDER NUMBER 001674-N530BD. SCRNR CERTIFICATE NUMBER 4SMR148C.) (NOTE: ALT PN: 024637-000)							
24 Airframe PART #2863	NO.1 CONSTANT SPEED UNIT Part Number: 731633 Serial Number: Unknown	15-OCT-1997					
24 Airframe PART #619	NO.1 CONVERTER, 100 AMP (TRU) Part Number: MS179676-2 Serial Number: 0447	15-OCT-1997					
24 Airframe PART #3379	NO.2 CONSTANT SPEED UNIT Part Number: 731633 Serial Number: Unknown	15-OCT-1997					
24 Airframe PART #577	NO.2 CONVERTER, 100 AMP (TRU) Part Number: MS179676-2 Serial Number: 0448	15-OCT-1997					
24 Airframe PART #452	NO.3 CONVERTER, 100 AMP (TRU) Part Number: MS17976-2 Serial Number: Unknown	15-OCT-1997					
24 Airframe PART #2627	NO.4 CONVERTER, 100 AMP (TRU) Part Number: MS17976-2 Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 Airframe PART #1852	PUMP, RESTOW ADG SYSTEM Part Number Unknown Serial Number Unknown	15-OCT-1997					
	Notes (ZONE: AVIONIC BAY - RIGHT)						
24 Airframe PART #795	RIGHT ENGINE CONTROL UNIT, GENERATOR Part Number 720846D Serial Number 1796	16-JAN-2020 H: 6542.90 L: 2815					
	Notes (UPDATE NOTE: REMOVED RIGHTGENERATOR CONTROL UNIT, P/N 720846D S/N 5623, AND INSTALLED INSPECTED GENERATOR CONTROL UNIT, P/N 720846D S/N 1796, IAW CL-604 AMM REVISION 86 TASK 24-21-04-400-801. OPERATIONAL CHECK SATISFACTORY. GENERATOR CONTROL UNITS SWAPPED FOR TROUBLESHOOTING PURPOSES.)						
24 Airframe PART #3055	RIGHT ENGINE COOLER, IDG OIL Part Number 63E79-1 Serial Number Unknown	15-OCT-1997					
24 Airframe PART #3323	RIGHT ENGINE GENERATOR, INTEGR DRIVE Part Number 731579C Serial Number 1524/7041	06-APR-2022 H: 7470.80 L: 3326					
	Notes (APX COST: 0)						
24 Airframe PART #706	RIGHT JUNCTION BOX ASSY, JB11 Part Number 604-51423-3 Serial Number Unknown	15-OCT-1997					
	Notes (ZONE: AVIONIC BAY)						
24 Airframe PART #1098	SENSOR, POWER EQUIPEMENT, JB18 Part Number 600-59181-3 Serial Number Unknown	15-OCT-1997					
24 Airframe PART #628	T1XB TRANSFORMER Part Number 720847A Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 Airframe PART #587	T2XB TRANSFORMER, INSTRUMENT CURRENT (JB1) (UPPER)(APU/EXT PWR) Part Number: 601R59155-1 Serial Number: Unknown	15-OCT-1997					
24 Airframe PART #3259	TRANSFORMER, JB1 Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
24 Airframe PART #2427	TRANSFORMER, JB18 Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
24 00-00-301 Airframe INSPECTION PKG 12 Month #1134	OPERATIONAL TEST (CYCLING) OF THE THERMAL CIRCUIT BREAKERS Notes (ZONE: 221222311) (ACCESS: 311BB,221EZ,222EZ) (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 11 D: 25
24 0026-701 Airframe PART #609	NO.1 MOUNTING TRAY Part Number: 622-8124-001 Serial Number: 3155	03-AUG-2010 H: 3929.20 L: 1671					
24 01-00-101 * Airframe PART - Life Limited #3216	DISCARD OF THE EXTENSION AND RETRACTION RELAY (K1CE) Part Number: B0804077-D4L-C Serial Number: N/A	18-MAR-2026 H: 8670.40 L: 3995	H: 3000.00		M: 0 H: 0.00	H: 11670.40	H: 2975.30
	Notes (SOURCE: CH 604 TLMC) (NOTE: PHASE-IN: FOR AIRCRAFT WITH 3001 HOURS TO 3999 HOURS, AS OF THE DATE OF FEB 25/2025, THIS TASK MUST BE ACCOMPLISHED WITHIN 1200 HOURS OR 36 MONTHS, WHICHEVER COMES FIRST. FOR AIRCRAFT WITH 4000 HOURS TO 7999 HOURS, AS OF THE DATE OF FEB 25/2025, THIS TASK MUST BE ACCOMPLISHED WITHIN 800 HOURS OR 24 MONTHS, WHICHEVER COMES FIRST. FOR AIRCRAFT WITH MORE THAN 7999 HOURS, AS OF THE DATE OF FEB 25/2025, THIS TASK MUST BE ACCOMPLISHED WITHIN 400 HOURS OR 12 MONTHS, WHICHEVER COMES FIRST.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 01-00-101 * Airframe PART - Life Limited #1613	DISCARD OF THE EXTENSION AND RETRACTION RELAY (K2CE) Part Number: K-D4L-050 Serial Number: N/A	18-MAR-2026 H: 8670.40 L: 3995	H: 3000.00		M: 0 H: 0.00	H: 11670.40	H: 2975.30
Notes (SOURCE: CH 604 TLMC) (NOTE: PHASE-IN: FOR AIRCRAFT WITH 3001 HOURS TO 3999 HOURS, AS OF THE DATE OF FEB 25/2025, THIS TASK MUST BE ACCOMPLISHED WITHIN 1200 HOURS OR 36 MONTHS, WHICHEVER COMES FIRST. FOR AIRCRAFT WITH 4000 HOURS TO 7999 HOURS, AS OF THE DATE OF FEB 25/2025, THIS TASK MUST BE ACCOMPLISHED WITHIN 800 HOURS OR 24 MONTHS, WHICHEVER COMES FIRST. FOR AIRCRAFT WITH MORE THAN 7999 HOURS, AS OF THE DATE OF FEB 25/2025, THIS TASK MUST BE ACCOMPLISHED WITHIN 400 HOURS OR 12 MONTHS, WHICHEVER COMES FIRST.)							
24 01-00-101 * Airframe PART - Life Limited #1713	DISCARD OF THE EXTENSION AND RETRACTION RELAY (K3CE) Part Number: B0804077-D4L-C Serial Number: N/A	18-MAR-2026 H: 8670.40 L: 3995	H: 3000.00		M: 0 H: 0.00	H: 11670.40	H: 2975.30
Notes (SOURCE: CH 604 TLMC) (NOTE: PHASE-IN: FOR AIRCRAFT WITH 3001 HOURS TO 3999 HOURS, AS OF THE DATE OF FEB 25/2025, THIS TASK MUST BE ACCOMPLISHED WITHIN 1200 HOURS OR 36 MONTHS, WHICHEVER COMES FIRST. FOR AIRCRAFT WITH 4000 HOURS TO 7999 HOURS, AS OF THE DATE OF FEB 25/2025, THIS TASK MUST BE ACCOMPLISHED WITHIN 800 HOURS OR 24 MONTHS, WHICHEVER COMES FIRST. FOR AIRCRAFT WITH MORE THAN 7999 HOURS, AS OF THE DATE OF FEB 25/2025, THIS TASK MUST BE ACCOMPLISHED WITHIN 400 HOURS OR 12 MONTHS, WHICHEVER COMES FIRST.)							
24 01-00-101 * Airframe PART - Life Limited #1678	DISCARD OF THE EXTENSION AND RETRACTION RELAY (K4CE) Part Number: K-D4L-050 Serial Number: N/A	18-MAR-2026 H: 8670.40 L: 3995	H: 3000.00		M: 0 H: 0.00 L: 0	H: 11670.40	H: 2975.30
Notes (SOURCE: CH 604 TLMC) (NOTE: PHASE-IN: FOR AIRCRAFT WITH 3001 HOURS TO 3999 HOURS, AS OF THE DATE OF FEB 25/2025, THIS TASK MUST BE ACCOMPLISHED WITHIN 1200 HOURS OR 36 MONTHS, WHICHEVER COMES FIRST. FOR AIRCRAFT WITH 4000 HOURS TO 7999 HOURS, AS OF THE DATE OF FEB 25/2025, THIS TASK MUST BE ACCOMPLISHED WITHIN 800 HOURS OR 24 MONTHS, WHICHEVER COMES FIRST. FOR AIRCRAFT WITH MORE THAN 7999 HOURS, AS OF THE DATE OF FEB 25/2025, THIS TASK MUST BE ACCOMPLISHED WITHIN 400 HOURS OR 12 MONTHS, WHICHEVER COMES FIRST.)							
24 20-00-201 Airframe INSPECTION PKG2400Hour #162	LEFT ENGINE DISCARD OF THE IDG CHARGE (OIL-IN) FILTER ELEMENT	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
Notes (AVG MAN HRS: 6)							



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 20-00-201 Airframe INSPECTION PKG2400Hour #2642	RIGHT ENGINE DISCARD OF THE IDG CHARGE (OIL-IN) FILTER ELEMENT	06-APR-2022 H: 7470.80 L: 3326	H: 2400.00	H: 40.00		H: 9870.80	H: 1175.70
	Notes (AVG MAN HRS: 6)						
24 20-00-202 Airframe INSPECTION PKG2400Hour #3126	LEFT ENGINE DISCARD OF THE IDG SCAVENGE (OIL-OUT) FILTER ELEMENT	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 6)						
24 20-00-202 Airframe INSPECTION PKG2400Hour #2464	RIGHT ENGINE DISCARD OF THE IDG SCAVENGE (OIL-OUT) FILTER ELEMENT	06-APR-2022 H: 7470.80 L: 3326	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 6)						
24 20-00-203 APU INSPECTION 050026 #83	DISCARD OF THE APU GENERATOR/ADAPTOR FILTER ELEMENT	03-JAN-2023 H: 9642.00	H: 2400.00	H: 40.00		H: 12042.00	H: 1735.00
24 20-00-205 APU INSPECTION 050016 #79	DETAILED INSPECTION OF THE AUXILIARY POWER UNIT (APU) GENERATOR/ ADAPTOR DRY CAVITY	21-OCT-2024 H: 10142.00	H: 600.00	H: 40.00		H: 10742.00	H: 435.00
	Notes (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
24 20-00-207 Airframe INSPECTION #2521	FUNCTIONAL TEST OF THE AIR DRIVEN GENERATOR (ADG) HEATER (A/C 5574, 5595 TO 5665)						
	Notes (AVG MAN HRS: 3.5)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 21-00-101* Airframe INSPECTION #1318	FUNCTIONAL TEST OF THE GENERATOR CONTROL UNIT (GCU) OVERVOLTAGE PROTECTION CIRCUITS	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00			H: 9525.20	H: 830.10
	<p>Notes</p> <p>(UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFI</p>						
24 23-00-101* Airframe INSPECTION #841	OPERATIONAL TEST OF THE AIR DRIVEN GENERATOR (ADG)	31-MAY-2025 H: 8649.70 L: 3986	M: 24 H: 1600.00			31-MAY-2027 H: 10249.70	M: 11 D: 30 H: 1554.60
	<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT.</p>						
24 23-25-101* Airframe INSPECTION #2399	ADG DISCARD OF THE ACTUATOR, ELECTRICAL UPLOCK (SQUIB) - 42 MONTHS FROM INSTALLATION	21-OCT-2024 H: 8557.60 L: 3931	M: 42			30-APR-2028	M: 22 D: 29
	<p>Notes</p> <p>(UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. PHASE-IN: FOR AIRCRAFT WITH ADG PART NO. 756652 INSTALLED, ON WHICH THIS TASK WAS NOT PERFORMED, THE SQUIB MUST BE DISCARDED NO LATER THAN OCT 31/2017. NOTE 2: NOT TO EXCEED VENDOR RECOMMENDATION. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TA</p>						
24 30-00-201 Airframe INSPECTION PKG 600 Hour #1616	OPERATIONAL TEST OF THE TRANSFORMER RECTIFIER UNIT (TRU) FAN	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	<p>Notes</p> <p>(AVG MAN HRS: 2) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
24 30-00-202 Airframe INSPECTION 05M006 #1780	MAIN FUNCTIONAL TEST (CAPACITY CHECK) OF THE MAIN BATTERY	26-MAY-2026 H: 8686.90 L: 3999	M: 6			30-NOV-2026	M: 5 D: 29
	<p>Notes</p> <p>(AVG MAN HRS: 1.5) (UPDATE NOTE: REMOVED MAIN BATTERY FOR CAP CHECK PN 601R59041-3, SN 0905200222B1B AND INSTALLED INSPECTED BATTERY PN 601R59041-3, SN 0905200222B1B, IAW BOMBARDIER CL 604 AMM 24-32-01. OPERATIONAL CHECK GOOD. NO DEFECTS NOTED AT THIS TIME. REFERENCE 8130 DATED 08/DEC/2025, WORK ORDER NUMBER 001674-N530BD. SCRNM CERTIFICATE NUMBER 4SMR148C.)</p>						
24 30-00-203 Airframe INSPECTION 05M006 #1171	APU FUNCTIONAL TEST (CAPACITY CHECK) OF THE APU BATTERY	26-MAY-2026 H: 8686.90 L: 3999	M: 6			30-NOV-2026	M: 5 D: 29
	<p>Notes</p> <p>(AVG MAN HRS: 1.5) (UPDATE NOTE: REMOVED APU BATTERY FOR CAP CHECK PN 024453-000, SN 090520028CC7A AND INSTALLED INSPECTED BATTERY PN 60059151-11, SN 090520028CC7A. IAW BOMBARDIER CL 604 AMM 24-32-04. OPERATIONAL CHECK GOOD. NO DEFECTS NOTED AT THIS TIME. REFERENCE 8130 DATED 08/DEC/2025, WORK ORDER NUMBER 001674-N530BD. SCRNM CERTIFICATE NUMBER 4SMR148C.)</p>						
24 30-00-204 Airframe INSPECTION PKG1200Hour #2817	OPERATIONAL TEST OF THE DC ESSENTIAL BUS	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
	<p>Notes</p> <p>(AVG MAN HRS: 2) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)</p>						
24 30-00-205 Airframe INSPECTION PKG1600Hour #3703	OPERATIONAL TEST OF THE LEFT AND RIGHT BATTERY BUSES	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
	<p>Notes</p> <p>(AVG MAN HRS: 1) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)</p>						
24 30-00-206 Airframe INSPECTION PKG1200Hour #2460	OPERATIONAL TEST OF THE DC EMERGENCY BUS	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
	<p>Notes</p> <p>(AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 Airframe PART #3317	AED - PHILIPS DEFIBRILLATOR Part Number: PM-AED FRx Defibrillator with soft case Serial Number: B25C-01992	19-SEP-2025 H: 8650.80 L: 3987					
	Notes (UPDATE NOTE: INSTALLED NEW DEFIBRILLATOR P/N PM-AED FRX DEFIBRILLATOR WITH SOFT CASE S/N B25C-01992 IAW BOMBARDIER CL 604 AMM 24-32-01)						
25 Airframe PART - Expiration #3048	BATTERY, ELT Part Number: 452-0133 Serial Number: 1013347-027	31-MAY-2025 H: 8649.70 L: 3986				01-NOV-2029	M: 41 D: 0
	Notes (AVG MAN HRS: 1.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: NOTE 14: DISCARD AT THE MANUFACTURER'S EXPIRATION DATE.)						
25 Airframe PART #3039	BLADE, ANTENNA, 406, ELT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: AFT FUSE - RIGHT UPPER)						
25 Airframe PART #3319	COFFEE MAKER Part Number: 500-0615-06 Serial Number: 06-02-38431	02-JUL-2021 H: 6939.60 L: 3034					
	Notes (UPDATE NOTE: REPAIRED BY ZODIAC EXECUTIVE AIRCRAFT INSERTS CRS Z2KR493B UNDER FORM TRACKING NUMBER IAM003544 DATED 19 SEP 2016.)						
25 Airframe PART #2199	COPILOT LAP BELT Part Number: 1101020-31 Serial Number: Unknown	15-OCT-1997					
25 Airframe PART #1391	COPILOT LIFE VEST Part Number: P01074-101C Serial Number: 2107110041	22-JAN-2025 H: 8628.90 L: 3975					
	Notes (APX COST: 132.48) (UPDATE NOTE: REMOVED COPILOT LIFE VEST, P/N P01074-101C S/N 20011360020 AND REPLACED WITH NEW LIFE VEST, P/N P0174-101C S/N 2107110041, IAW GULFSTREAM ICA REPORT CBD 4468A002 CHAPTER 25-60-00. INSPECTION OF LIFE VEST DUE 01/2026 DOM JUL/2021)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 Airframe PART #354	COPILOT SEAT Part Number: 600-40022-8 Serial Number: 9600109	19-SEP-2025 H: 8650.80 L: 3987					
Notes (UPDATE NOTE: REMOVED CO-PILOT SEAT P/N 600-40022-8 S/N 9600109 AND REINSTALLED REPAIRED CO-PILOT SEAT P/N 600-40022-8 S/N 9600109 IAW BOMBARDIER CL 604 AMM 25-11-01. SEAT REPAIRED BY ARIZONA AIRCRAFT INTERIOR DESIGN, INC CRS# LG3R656L UNDER WO# 19202.)							
25 Airframe PART #1574	COPILOT SEAT INERTIA REEL Part Number: 0108143-13 Serial Number: Unknown	15-OCT-1997					
25 Airframe PART #1677	EMERGENCY LOCATOR TRANSMITTER (ELT) Part Number: 453-5060 Serial Number: 07599	06-JUL-2012 H: 4568.40 L: 1968					
25 Airframe PART #2470	FIRST AID KIT Part Number: RE1013-107 Serial Number: FA5AT102	31-MAY-2025 H: 8649.70 L: 3986					
Notes (ZONE: .) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
25 Airframe PART #3304	GALLEY MICROWAVE, OVEN Part Number: 400-1409-01-L Serial Number: 09-08-46036	03-APR-2021 H: 6882.90 L: 3004					
Notes (APX COST: 6,090) (UPDATE NOTE: REMOVED MICROWAVE, P/N 400-1409-01-L S/N 05-11-38026, AND INSTALLED REPAIRED MICROWAVE, P/N 400-1409-01-L S/N 09-08-46036, IAW GULFSTREAM INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, FORWARD RH GALLEY, REPORT NO. CBB2801A002 REVISION A DRAWING NO. CCS1067. OPERATIONAL CHECK SATISFACTORY. THIS CLEARS AMDL 22494. MICROWAVE OVEN REPAIRED BY POLE AIR AVIATION CRS QCH4T 1G3, SEE WORK ORDER 1716271 AND FORM TRACKING NUMBER 79851 DATED 03-11-2021 FOR DETAILS.)							
25 Airframe INSPECTION #3733	HeartSine Model 350P, 360P & 450P Defibrillator Verbal Prompts Test. Reference HeartSine/Stryker Field Action Number PR3224192-FA305	14-MAY-2026 H: 8686.90 L: 3999					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 Airframe PART #546	HYDRO-LOCK ACTUATOR Part Number SL02300-40 Serial Number 8876DA	18-OCT-2021 H: 7112.50 L: 3138					
	Notes (APX COST: 463.65)						
25 Airframe PART #318	JUMPSEAT LIFE VEST Part Number P01074-101C Serial Number 2107110058	22-JAN-2025 H: 8628.90 L: 3975					
	Notes (APX COST: 132.48) (UPDATE NOTE: REMOVED JUMP SEAT LIFE VEST, P/N P01074-101C S/N 20011360109 AND REPLACED WITH NEW LIFE VEST, P/N P0174-101C S/N 2107110058, IAW GULFSTREAM ICA REPORT CBD 4468A002 CHAPTER 25-60-00. INSPECTION OF LIFE VEST DUE 01/2026 DOM JUL/2021)						
25 Airframe PART #2200	NO.01 AIRCELL REMOTE DIVERSITY ANTENNA Part Number P12344 Serial Number N/A	21-SEP-2021 H: 7063.80 L: 3109					
	Notes (AVG MAN HRS: 0.25) (APX COST: 271)						
25 Airframe PART #2103	NO.02 AIRCEL REMOTE DIVERSITY ANTENNA Part Number P12344 Serial Number N/A	21-SEP-2021 H: 7063.80 L: 3109					
	Notes (APX COST: 271)						
25 Airframe PART #1659	NO.1 LIFE VEST Part Number P01074-201W Serial Number 2407193007	22-JAN-2025 H: 8628.90 L: 3975					
	Notes (APX COST: 60.94) (UPDATE NOTE: REMOVED NO.1 LIFE VEST, P/N P01074-201 S/N 19121020137 AND REPLACED WITH NEW LIFE VEST, P/N P0174-201W S/N 24071930007, IAW GULFSTREAM ICA REPORT CBD 4468A002 CHAPTER 25-60-00. INSPECTION OF LIFE VEST DUE 07/2034 DOM JUL/2024)						
25 Airframe PART #957	NO.1 ORDINANCE SIGN Part Number 1643-1-18 Serial Number 204490183	01-OCT-2010 H: 3976.30 L: 1697					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 Airframe PART #1794	NO.10 LIFE VEST Part Number: P01074-201 Serial Number: 2211026131 8	05-JUL-2024 H: 8455.80 L: 3862					
Notes (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)							
25 Airframe PART #702	NO.2 LIFE VEST Part Number: P01074-101 Serial Number: 2201075033 1	25-APR-2022 H: 7477.20 L: 3329					
Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)							
25 Airframe PART #501	NO.2 ORDINANCE SIGN Part Number: 1643-1-18 Serial Number: 204490185	01-OCT-2010 H: 3976.30 L: 1697					
25 Airframe PART #1320	NO.3 LIFE VEST Part Number: P01074-101W Serial Number: 2201075032 8	25-APR-2022 H: 7477.20 L: 3329					
Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)							
25 Airframe PART #3352	NO.4 LIFE VEST Part Number: P01074-101W Serial Number: 2201075017 3	25-APR-2022 H: 7477.20 L: 3329					
Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)							
25 Airframe PART #2420	NO.5 LIFE VEST Part Number: P01074-101 Serial Number: 2201075011 1	25-APR-2022 H: 7477.20 L: 3329					
Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 Airframe PART #392	NO.6 LIFE VEST						
	Part Number	Serial Number					
	P01074-101W	2201075002					
		7					
	Notes						
	(APX COST: 147.45) (UPDATE NOTE: COMPLIED WITH INSPECTION 25-60-00-007, NO.6 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION, BY INSTALLATION OF NEW LIFE VEST. REMOVED NO. 6 LIFE VEST, P/N P01074-101W S/N 17101310046 AND INSTALLED NEW LIFE VEST, P/N P01074-101W S/N 22010750027 IAW GULFSTREAM INSTRUCTIONS FOR CONTINUED AIRWORTHINESS REPORT NO. CBD4468A002 CHAPTER 25-60-00. DOM 26-JAN-2022, NEXT INSPECTION DUE 31-JAN-2027.)						
25 Airframe PART #40	NO.7 LIFE VEST						
	Part Number	Serial Number					
	P01074-101W	2201075003					
		5					
	Notes						
	(UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)						
25 Airframe PART #2438	NO.8 LIFE VEST						
	Part Number	Serial Number					
	P01074-201	2211026063					
		8					
	Notes						
	(UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)						
25 Airframe PART #1783	NO.9 LIFE VEST						
	Part Number	Serial Number					
	P01074-201	2211026159					
		4					
	Notes						
	(UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)						
25 Airframe PART #3298	ORDINANCE SIGN						
	Part Number	Serial Number					
	1643-1-19	0406067					
	Notes						
25 Airframe PART #1140	PILOT LAP BELT						
	Part Number	Serial Number					
	1101020-29	Unknown					
	Notes						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 Airframe PART #1741	PILOT LIFE VEST Part Number: P01074-101C Serial Number: 2107110042	22-JAN-2025 H: 8628.90 L: 3975					
	Notes (APX COST: 132.48) (UPDATE NOTE: REMOVED PILOT SEAT LIFE VEST, P/N P01074-101C S/N 20011360203 AND REPLACED WITH NEW LIFE VEST, P/N P0174-101C S/N 2107110042, IAW GULFSTREAM ICA REPORT CBD 4468A002 CHAPTER 25-60-00. INSPECTION OF LIFE VEST DUE 01/2026 DOM JUL/2021)						
25 Airframe PART #2589	PILOT SEAT Part Number: 600-40022-7 Serial Number: 9700125	19-SEP-2025 H: 8650.80 L: 3987					
	Notes (UPDATE NOTE: REMOVED PILOT SEAT P/N 600-4022-7 S/N 9700125 AND REINSTALLED REPAIRED PILOT SEAT P/N 600-40022-7 S/N 9600125 IAW BOMBARDIER CL 604 AMM 25-11-01. SEAT REPAIRED BY ARIZONA AIRCRAFT INTERIOR DESIGN, INC CRS# LG3R656L UNDER WO# 19202.)						
25 Airframe PART #869	PILOT SEAT INERTIA REEL Part Number: 0108143-13 Serial Number: Unknown	15-OCT-1997					
25 Airframe PART #721	TOILET Part Number: 4620-57 Serial Number: 105	02-JUL-2021 H: 6939.60 L: 3034					
	Notes (UPDATE NOTE: OVERHAULED BY AVIATION FABRICATORS CRS GVRR304K UNDER FORM TRACKING NUMBER M09449 DATED 21 JUN 2021)						
25 00-ICA-004 Airframe INSPECTION #3360	HIGH SPEED INTERNET SYSTEM - FORWARD DME ANTENNA INSTALLATION - HIGH FREQUENCY EDDY CURRENT (HFEC) INSPECTION		L: 21759			L: 23822	L: 19820
	Notes (MANUAL ADJUSTMENT: 2063 LDG)						
25 00-ICA-9001 Airframe INSPECTION #1821	INSPECT RIGHT HAND GALLEY - 12 MONTH PER GULFSTREAM AEROSPACE ICA DOCUMENT CBB2801A002	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 00-ICA-9001A Airframe INSPECTION #2385	RIGHT HAND GALLEY WATER FILTER - 12 MONTH PER GULFSTREAM AEROSPACE ICA DOCUMENT CBB2801A002	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
	Notes (AVG MAN HRS: 1.5) (APX COST: 210.45) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 00-ICA-9002 Airframe INSPECTION #1193	INSPECTION RIGHT HAND GALLEY 24 MONTH PER GULFSTREAM DOC. NO. CBB2801A002	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 2		31-MAY-2027	M: 11 D: 30
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 00-ICA-9003 Airframe INSPECTION #2277	INSPECT (GENERAL VISUAL) CABIN INTERIOR - 12 MONTH/400 HOUR PER GULFSTREAM DOC. NO. CBD4468A002	21-MAY-2026 H: 8686.90 L: 3999	M: 12 H: 400.00	M: 1 H: 30.00		21-MAY-2027 H: 9086.90	M: 11 D: 20 H: 391.80
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 00-ICA-9004 Airframe INSPECTION #2734	INSPECTION CABIN INTERIOR 48MONTH/1600 HOUR - ICA - PER GULFSTREAM DOC. NO. CBD4468A002	21-OCT-2024 H: 8557.60 L: 3931	M: 48 H: 1600.00	M: 2 H: 30.00		21-OCT-2028 H: 10157.60	M: 28 D: 20 H: 1462.50
	Notes (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
25 00-ICA-9005 Airframe INSPECTION #1625	INSPECTION CABIN INTERIOR 400 HOUR - ICA - PER GULFSTREAM DOC. NO. CBD4468A002	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00	H: 40.00		H: 8855.80	H: 160.70
	Notes (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)						
25 00-ICA-9006 Airframe INSPECTION #997	INSPECTION CABIN INTERIOR 800 HOUR - ICA - PER GULFSTREAM DOC. NO. CBD4468A002	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 00-ICA-9007 Airframe INSPECTION #2938	INSPECTION CABIN INTERIOR 1600 HOUR PER GULFSTREAM ICA DOC. CBD4468A002	21-OCT-2024 H: 8557.60 L: 3931	H: 1600.00	H: 40.00		H: 10157.60	H: 1462.50
	Notes (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
25 00-ICA-9008 Airframe INSPECTION #3226	INSPECTION CABIN INTERIOR - 12 MONTH PER GULFSTREAM DOC. NO. CBD4468A002	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 00-KCA-9174 Airframe INSPECTION #2810	NO.2 LIFE RAFT - RECERTIFICATION	10-APR-2024 H: 8348.50 L: 3805	M: 36			29-MAR-2027	M: 9 D: 28
	Notes (AVG MAN HRS: 3) (UPDATE NOTE: INSTALLED OVERHAULED NO. 2 LIFE RAFT P/N RAF1210-305T1 S/N 1054KO ON AIRCRAFT AFTER OVERHAUL. LIFE RAFT OVERHAULED BY SAFETECH FORM TRACKING NUMBER WSM2400108 WORK ORDER WSM2400108 RO-6340-N530BD CRS# WV1R599K DATED 29-MAR-2024)						
25 11-00-201 Airframe INSPECTION PKG 36 Month #1858	OPERATIONAL TEST OF THE INERTIAL REEL CONTROL AND INERTIA REEL	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
	Notes (AVG MAN HRS: 0.5) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 11-00-202 Airframe INSPECTION PKG 36 Month #1427	GENERAL VISUAL INSPECTION OF THE PILOT'S/COPILOT'S SEAT RESTRAINTS	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
	Notes (AVG MAN HRS: 0.5) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 1897-701A Airframe INSPECTION #2468	NO.1 RECERTIFY LIFE RAFT	28-AUG-2024 H: 8524.50 L: 3908	M: 36			31-JUL-2027	M: 13 D: 30
	<p>Notes</p> <p>(UPDATE NOTE: INSTALLED OVERHAULED #1 LIFE RAFT P/N: RAF1210-311T1, S/N: 1121062491H, SAFETECH USA INC. TRACKING #WSM2411359, WORK ORDER #WSM241135924294, CRS #WV1R599K, DATED 29-JUL-2024. HYDRO DATE: 07/2024, NEXT HYDRO DUE: 07/2029. ELT S/N: 24321, ELT BEACON ID: 09082. ELT BATTERY EXP: 03/2029. HEX ID: ADCC408DE8001BD. NEXT LIFE RAFT SERVICE DATE 07/2027.)</p>						
25 21-00-601 Airframe INSPECTION PKG 48 Month #2136	DETAILED INSPECTION OF THE PASSENGER SEATS (INCLUDING DIVANS) FOR ATTACHMENT AND LOCKING	31-MAY-2025 H: 8649.70 L: 3986	M: 48		M: 1	13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
25 21-00-602 Airframe INSPECTION #1769	DETAILED INSPECTION PASSENGER SEATS RESTRAINTS	31-MAY-2025 H: 8649.70 L: 3986	M: 24		M: 1	31-MAY-2027	M: 11 D: 30
	<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
25 29-00-601 Airframe INSPECTION #1588	INSPECT INTERIOR DRAWERS, DOORS, AND CABINETS	21-MAY-2026 H: 8686.90 L: 3999	M: 12		M: 1	21-MAY-2027	M: 11 D: 20
	<p>Notes</p> <p>(TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
25 30-00-001 Airframe INSPECTION #2259	GALLEY - VISUALLY INSPECT GENERAL CONDITION AND SECURITY.	21-MAY-2026 H: 8686.90 L: 3999	M: 12		M: 1	21-MAY-2027	M: 11 D: 20
	<p>Notes</p> <p>(TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-00-007 Airframe INSPECTION #1531	COPILOT CREW LIFE VEST COPILOT - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	22-JAN-2025 H: 8628.90 L: 3975	M: 60			31-AUG-2026	M: 2 D: 30
<p>Notes</p> <p>(UPDATE NOTE: REMOVED COPILOT LIFE VEST, P/N P01074-101C S/N 20011360020 AND REPLACED WITH NEW LIFE VEST, P/N P0174-101C S/N 2107110041, IAW GULFSTREAM ICA REPORT CBD 4468A002 CHAPTER 25-60-00. INSPECTION OF LIFE VEST DUE 01/2026 DOM JUL/2021)</p>							
25 60-00-007 Airframe INSPECTION #429	JUMPSEAT CREW LIFE VEST JUMPSEAT - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	22-JAN-2025 H: 8628.90 L: 3975	M: 60			31-AUG-2026	M: 2 D: 30
<p>Notes</p> <p>(UPDATE NOTE: REMOVED JUMP SEAT LIFE VEST, P/N P01074-101C S/N 20011360109 AND REPLACED WITH NEW LIFE VEST, P/N P0174-101C S/N 2107110058, IAW GULFSTREAM ICA REPORT CBD 4468A002 CHAPTER 25-60-00. INSPECTION OF LIFE VEST DUE 01/2026 DOM JUL/2021)</p>							
25 60-00-007 Airframe INSPECTION #371	NO.1 PASSENGER LIFE VEST NO. 1 - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	22-JAN-2025 H: 8628.90 L: 3975	M: 60	M: 1		07-JUL-2029	M: 37 D: 6
<p>Notes</p> <p>(UPDATE NOTE: REMOVED NO.1 LIFE VEST, P/N P01074-201 S/N 19121020137 AND REPLACED WITH NEW LIFE VEST, P/N P0174-201W S/N 24071930007, IAW GULFSTREAM ICA REPORT CBD 4468A002 CHAPTER 25-60-00. INSPECTION OF LIFE VEST DUE 07/2034 DOM JUL/2024)</p>							
25 60-00-007 Airframe INSPECTION #2829	NO.10 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	05-JUL-2024 H: 8455.80 L: 3862	M: 60			30-NOV-2027	M: 17 D: 29
<p>Notes</p> <p>(UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)</p>							
25 60-00-007 Airframe INSPECTION #209	NO.2 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	25-APR-2022 H: 7477.20 L: 3329	M: 60			31-JAN-2027	M: 7 D: 30
<p>Notes</p> <p>(UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)</p>							
25 60-00-007 Airframe INSPECTION #3143	NO.3 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	25-APR-2022 H: 7477.20 L: 3329	M: 60			31-JAN-2027	M: 7 D: 30
<p>Notes</p> <p>(UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)</p>							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-00-007 Airframe INSPECTION #2841	NO.4 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	25-APR-2022 H: 7477.20 L: 3329	M: 60			31-JAN-2027	M: 7 D: 30
Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)							
25 60-00-007 Airframe INSPECTION #1512	NO.5 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	25-APR-2022 H: 7477.20 L: 3329	M: 60			31-JAN-2027	M: 7 D: 30
Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)							
25 60-00-007 Airframe INSPECTION #615	NO.6 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	12-JUL-2022 H: 7626.60 L: 3406	M: 60			31-JAN-2027	M: 7 D: 30
Notes (UPDATE NOTE: COMPLIED WITH INSPECTION 25-60-00-007, NO.6 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION, BY INSTALLATION OF NEW LIFE VEST. REMOVED NO. 6 LIFE VEST, P/N P01074-101W S/N 17101310046 AND INSTALLED NEW LIFE VEST, P/N P01074-101W S/N 22010750027 IAW GULFSTREAM INSTRUCTIONS FOR CONTINUED AIRWORTHINESS REPORT NO. CBD4468A002 CHAPTER 25-60-00. DOM 26-JAN-2022, NEXT INSPECTION DUE 31-JAN-2027.)							
25 60-00-007 Airframe INSPECTION #2191	NO.7 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	25-APR-2022 H: 7477.20 L: 3329	M: 60			31-JAN-2027	M: 7 D: 30
Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)							
25 60-00-007 Airframe INSPECTION #1359	NO.8 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	05-JUL-2024 H: 8455.80 L: 3862	M: 60			30-NOV-2027	M: 17 D: 29
Notes (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)							
25 60-00-007 Airframe INSPECTION #3052	NO.9 PASSENGER LIFE VEST - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	05-JUL-2024 H: 8455.80 L: 3862	M: 60	M: 1		01-NOV-2027	M: 17 D: 0
Notes (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)							



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 60-00-007 Airframe INSPECTION #441	PILOT CREW LIFE VEST PILOT - RETURN TO AUTHORIZED SERVICE CENTER FOR MAINTENANCE INSPECTION	22-JAN-2025 H: 8628.90 L: 3975	M: 60			31-AUG-2026	M: 2 D: 30
	Notes (UPDATE NOTE: REMOVED PILOT SEAT LIFE VEST, P/N P01074-101C S/N 20011360203 AND REPLACED WITH NEW LIFE VEST, P/N P0174-101C S/N 2107110042, IAW GULFSTREAM ICA REPORT CBD 4468A002 CHAPTER 25-60-00. INSPECTION OF LIFE VEST DUE 01/2026 DOM JUL/2021)						
25 60-00-201 Airframe INSPECTION #331	OPERATIONAL TEST OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 60-00-203 Airframe INSPECTION #2920	DETAILED INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 60-00-601 Airframe INSPECTION PKG 12 Month #1314	LIFE VEST CHECK FOR EXPIRATION DATE	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 11 D: 25
	Notes (TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 60-00-603 Airframe INSPECTION #262	INSPECT DETAILED OF LIFE RAFTS EXPIRATION DATE	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 60-00-605 Airframe INSPECTION #3509	DETAILED INSPECTION OF THE DITCHING LINES (IF APPLICABLE)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 62-00.2 Airframe INSPECTION #415	EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA GENERAL VISUAL INSPECTION. REF. BOMBARDIER DOC. NO. BAS63017002-SM-1	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
<p>Notes</p> <p>(AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>							
25 62-BCC-9001 Airframe INSPECTION #499	DETAILED VISUAL INSPECTION AIRCRAFT SKIN AROUND ANTENNA CUTOUTS AND DOUBLER ATTACH RIVETS	15-OCT-1997	H: 15000.00 L: 7800			H: 15000.00 L: 7800	H: 6304.90 L: 3798
25 62.00.1 Airframe INSPECTION #2093	EMERGENCY LOCATOR TRANSMITTER (ELT) GENERAL VISUAL INSPECTION. REF. BOMBARDIER DOC. NO. BAS63017002-SM-1	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>							
25 6201-001C Airframe INSPECTION #2417	ELT INSPECT	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
<p>Notes</p> <p>(AVG MAN HRS: 0.5) (APX COST: 987.69) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>							
25 6205-701 Airframe PART #1872	PORTABLE ELT	Part Number 500-27Y	Serial Number 2393				
25 6205-702 Airframe PART #2720	PORTABLE ELT BATTERY	Part Number A0696Y	Serial Number 117564	28-MAR-2018 H: 6319.00 L: 2697			
<p>Notes</p> <p>(NOTE: EXP: 3/2023)</p>							



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 9320 Airframe INSPECTION #737	FIRST AID KIT INSPECTION	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 9990 Airframe INSPECTION #2084	DEFIBRILLATOR VISUAL INSPECTION	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
	Notes (ZONE: --) (AVG MAN HRS: 2) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
25 9991 Airframe PART - Life Limited #3396	DEFIBRILLATOR SMART PADS						
	Part Number	Serial Number					
	989803139261	241022-0952	19-SEP-2025 H: 8650.80 L: 3987	M: 24	M: 0	19-SEP-2027	M: 15 D: 18
	Notes (UPDATE NOTE: REMOVED OLD DEFIBRILLATOR PADS P/N 989803139261 S/N 230517-0957 AND INSTALLED NEW DEFIBRILLATOR PADS P/N 989803139261 S/N 241022-0952 EXPIRES 22/APR/2027 IAW BOMBARDIER CL 604 AMM 24-32-01.)						
25 9991 Airframe INSPECTION #720	DEFIBRILLATOR SMART PADS REPLACEMENT	19-SEP-2025 H: 8650.80 L: 3987				22-APR-2027	M: 10 D: 21
	Notes (UPDATE NOTE: REMOVED OLD DEFIBRILLATOR PADS P/N 989803139261 S/N 230517-0957 AND INSTALLED NEW DEFIBRILLATOR PADS P/N 989803139261 S/N 241022-0952 EXPIRES 22/APR/2027 IAW BOMBARDIER CL 604 AMM 24-32-01.) (NOTE: EXPIRE DATE ON PADS)						
25 9992 Airframe INSPECTION #3326	DEFIBRILLATOR BATTERY REPLACEMENT	12-OCT-2023 H: 8130.00 L: 3683				31-MAY-2029	M: 35 D: 30
	Notes (APX COST: 164.09) (UPDATE NOTE: REMOVED DEFIB BATTER P/N B03202505 LOT 86809P AND INSTALLED NEW DEFIB BATTERY P/N 989803139301 LOT 04802P EXPIRES 2029-05-31) (NOTE: EXPIRE DATE ON BATTERY)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 9999 Airframe INSPECTION #1610	DEFIBRILLATOR SPARE BATTERY LIFE LIMIT	31-MAY-2025 H: 8649.70 L: 3986				01-NOV-2030	M: 53 D: 0
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: EXPIRE DATE ON BATTERY)						
25 FAR 91.207 Airframe INSPECTION FAA #1777	EMERGENCY LOCATOR TRANSMITTER (ELT) INSPECTION AND TEST PER FAR 91.207 (D)	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: FAA)						
25 JLA-FLYAWAY Kit Contents Airframe INSPECTION #952	FLY-A-WAY KIT INVENTORY (DOCUMENT CONTENTS IN THE FLY-A-WAY KIT UNDER COMPLIANCE NOTES)	28-APR-2023 H: 8029.90 L: 3621					
	Notes (UPDATE NOTE: UPDATED FLY AWAY KIT. EXTERIOR LIGHTING 2WL-1524NAV LIGHT BULB WINGTIP 11683NAV LIGHT BULB TAIL 14526WING TAXI LIGHT BULB 24596WING/ NOSE LANDING LIGHT BULB 21619EXTERIOR EMERGENCY LIGHT BULB 2MS15570-81EXTERIOR EMERGENCY LIGHT BULB 1A7079B24WING INSPECTION LIGHT BULB INTERIOR LIGHTING 10MS3338-6839PUSHBUTTON SWITCH BULB 2MS25237-387MASTER WARNING/CAUTION BULB STATIC DISCHARGERS 1B0818024-001STATIC DISCHARGER ANGLED 1B0818023-001STATIC DISCHARGER 1B0818021-001STATIC DISCHARGER 1B0818022-001STATIC DISCHARGER						
	TOOLING 1#1 SCREWDRIVER 1#2 SCREWDRIVER 11/4" WRENCH 1						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 JLA-Onboarding Check-SAFO21002 Airframe INSPECTION #101	PERFORM FLAMMABILITY TESTING RECORDS CHECK TO ENSURE NO CERTIFICATIONS FROM BIG WINGS INTERIOR, INC. PER SAFO 21002	09-APR-2021 H: 6886.60 L: 3007					
	Notes (UPDATE NOTE: COMPLIED WITH SAFO21002 BY INSPECTION OF AIRCRAFT RECORDS. NO INTERIOR CERTIFICATIONS FROM BIG WING INTERIORS, INC. NO FURTHER ACTION NECESSARY.)						
25 JLA-Wifi SSID Check Airframe INSPECTION #3257	CHANGE WIFI SSID TO CURRENT TAIL NUMBER (NON-GROUNDING)	13-OCT-2023 H: 8130.00 L: 3683					
	Notes (UPDATE NOTE: CHANGED WIFI SSID TO CURRENT TAIL NUMBER)						
25 T.M5352-0256 Life Line Airframe INSPECTION #1947	INSPECT EMERGENCY EXIT LIFE LINE FOR CONDITION & SECURITY. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	11-JUL-2023 H: 8075.40 L: 3647	H: 1600.00			H: 9675.40	H: 980.30
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
25 T.M5352-0256 Vanity 1 Airframe INSPECTION #2902	VANITY FLOOR ATTACHMENT, CONTROL PANELS, CONNECTORS, WIRING CONDITION & SECURITY. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	11-JUL-2023 H: 8075.40 L: 3647	H: 1600.00			H: 9675.40	H: 980.30
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
25 T.M5352-0256 Vanity 2 Airframe INSPECTION #2742	INSPECT VANITY DOORS, DRAWERS & LATCHES FOR WEAR & OPERATION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
25 T.M5352-0256 Vanity 3 Airframe INSPECTION #2342	VANITY TRASH CONTAINER INSPECT FOR ACCESS, & DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING AND LATCHING. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00			H: 8855.80	H: 160.70
<p>Notes</p> <p>(AVG MAN HRS: 0.5) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)</p>							
25 T.M5352-0256 Vanity 4 Airframe INSPECTION #2913	INSPECT VANITY WATER LINES ABOVE THE FLOOR CONDITION	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00			H: 8855.80	H: 160.70
<p>Notes</p> <p>(AVG MAN HRS: 0.5) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)</p>							
26 Airframe PART #1	AFT PORTABLE FIRE EXTINGUISHER					15-OCT-1997	
	Part Number	Serial Number					
	Unknown	Unknown					
26 Airframe PART - Life Limited #745	APU CARTRIDGE, FIREX					21-MAY-2026	M: 120
	Part Number	Serial Number				H: 8686.90 L: 3999	M: 4
	897776-01	46350					31-JAN-2036 M: 115 D: 30
<p>Notes</p> <p>(AVG MAN HRS: 2) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>							
26 Airframe PART #464	APU EXTINGUISHER, FIRE APU CONTAINER					26-JUL-2019	
	Part Number	Serial Number				H: 6476.10 L: 2770	
	897889-2	15896EL					
<p>Notes</p> <p>(ZONE: AFT FUSE)</p>							
26 Airframe PART #2481	APU SENSOR, TEMPERATURE, FIRE DETECTION SYSTEM					15-OCT-1997	
	Part Number	Serial Number					
	377-02836	9634-035					
<p>Notes</p> <p>(ZONE: A1WG)</p>							



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 Airframe PART #2315	APU, SENSING ELEMENT Part Number: 244-21086 Serial Number: Unknown	15-OCT-1997					
26 Airframe PART #2617	CABIN PORTABLE FIRE EXTINGUISHER Part Number: 30H673 Serial Number: I-48489258	29-JAN-2025			H: 8628.90 L: 3975		
Notes (APX COST: 1,367.12) (UPDATE NOTE: REMOVED CABIN FIRE EXTINGUISHER P/N 30H673 S/N F-68184866 AND INSTALLED NEW PORTABLE FIRE EXTINGUISHER P/N 30H673 S/N I-48489258 IAW BOMBARDIER CL 604 AMM 26-26-01. DOM 20/DEC/2024)							
26 Airframe PART #2017	COCKPIT PORTABLE FIRE EXTINGUISHER Part Number: 898052 Serial Number: B71139484	20-MAR-2024			H: 8325.70 L: 3788		
Notes (APX COST: 0) (UPDATE NOTE: REMOVED COCKPIT PORTABLE FIRE EXTINGUISHER P/N 898052 S/N X-987629. INSTALLED OVERHAULED COCKPIT PORTABLE FIRE EXTINGUISHER P/N 898052 S/N B71139484 IAW BOMBARDIER CL 604 AMM 26-26-01. BOTTLES MFG. DATE 2016 AND LAST HYDRO 02-2024. FIRE EXTINGUISHER WAS OVERHAULED BY SAFETECH FORM TRACKING NUMBER WSM2402633 WORK ORDER WSM2402633 RO-17592 CRS# SMRE451X DATED 19-FEB-2024)							
26 Airframe PART #2691	LAVATORY LAVATORY FIRE EXTINGUISHER Part Number: BA22557-1 Serial Number: 55538	12-APR-2013			H: 4782.30 L: 2063		
26 Airframe PART #2530	LEFT ENGINE COMBUSTION-ZONE, SENSING ELEMENT Part Number: 244-10457 Serial Number: Unknown	15-OCT-1997					
26 Airframe PART #1528	LEFT ENGINE SENSOR, TEMPERATURE, FIRE DETECTION SYSTEM Part Number: 377-02836 Serial Number: 9651-006	15-OCT-1997					
26 Airframe PART #3118	LEFT EXHAUST-NOZZLE ASSEMBLY, SENSING ELEMENT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 Airframe PART #800	LEFT EXTINGUISHER, FIRE CONTAINER Part Number: 601-65910-13 Serial Number: AGI2345	24-FEB-2023 H: 7944.00 L: 3577					
	Notes (ZONE: ENGINE) (AVG MAN HRS: 1.5) (APX COST: 9,371.54) (UPDATE NOTE: REMOVED AFT L/H FIRE CONTAINER P/N 899074-1 S/N 18263EL. INSTALLED NEW AFT L/H FIRE CONTAINER P/N 601-65910-13 S/N AGI2345. DATE OF MANUFACTURE 08/2022 HYDROSTATIC TEST DATE 08/2022. SEE 8130 BOMBARDIER INC CRS B0573123/12-58 UNDER W/O 5035379539 DATE 21/SEP/2022. INSTALLED ORIGINAL FIREX CARTRIDGE ON TO NEW BOTTLE INTO ORIGINAL POSITION L/H NO 1 P/N 897776-01 S/N 41913 L/H NO 2 P/N 897776-01 S/N 41906. ALL WORK PERFORMED IAW BOMBARDIER CHALLENGER 604 AMM 26-21-04 AND 26-21-07.)						
26 Airframe PART #2391	LEFT HOSE ASSY, FIRE EXTINGUISHER Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: ENGINE)						
26 Airframe PART #2443	LEFT MAIN LANDING GEAR (MLG), SENSING ELEMENT Part Number: 244-03615 Serial Number: Unknown	15-OCT-1997					
26 Airframe PART #768	LEFT MAIN LANDING GEAR WHEEL BIN TEMP. SENSOR CONTROL UNIT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
26 Airframe PART - Life Limited #30	LEFT NO.1 CARTRIDGE, FIREX Part Number: 897776-01 Serial Number: 41913	02-JUL-2021 H: 6939.60 L: 3034	M: 120		M: 0 H: 0.00 L: 0	31-JAN-2031	M: 55 D: 30
	Notes (ZONE: ENGINE) (AVG MAN HRS: 2.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
26 Airframe PART - Life Limited #2256	LEFT NO.2 CARTRIDGE, FIREX Part Number: 897776-01 Serial Number: 41906	02-JUL-2021 H: 6939.60 L: 3034	M: 120		M: 0 H: 0.00 L: 0	31-JAN-2031	M: 55 D: 30
	Notes (ZONE: ENGINE) (AVG MAN HRS: 2.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining				
26 Airframe PART #3404	LEFT SENSOR, TEMPERATURE, FIRE DETECTION SYSTEM (EXHAUST NOZZLE ASSEMBLY AND PYLON FIRE DETECTION)	15-OCT-1997									
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>377-02836</td> <td>9709-035</td> </tr> </table>	Part Number	Serial Number	377-02836	9709-035						
Part Number	Serial Number										
377-02836	9709-035										
	Notes (ZONE: EXHAUST)										
26 Airframe PART #1173	LEFT ZONE A PYLON, SENSING ELEMENT	15-OCT-1997									
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>244-03057</td> <td>Unknown</td> </tr> </table>	Part Number	Serial Number	244-03057	Unknown						
Part Number	Serial Number										
244-03057	Unknown										
	Notes (ZONE: ENGINE - PYLON)										
26 Airframe PART #3374	MLG OVERHEAT SENSOR, TEMPERATURE, FIRE DETECTION SYSTEM	15-OCT-1997									
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>377-02836</td> <td>9713</td> </tr> </table>	Part Number	Serial Number	377-02836	9713						
Part Number	Serial Number										
377-02836	9713										
	Notes										
26 Airframe PART #991	NO.1 EXHAUST NOZZLE ASSY OVERHEAT DETECTION ELEMENT	17-JUL-2020									
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> <td>H: 6606.00</td> <td>L: 2858</td> </tr> <tr> <td>744-12047</td> <td>201806</td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number	H: 6606.00	L: 2858	744-12047	201806				
Part Number	Serial Number	H: 6606.00	L: 2858								
744-12047	201806										
	Notes (APX COST: 0) (UPDATE NOTE: REMOVED LEFT EXHAUST FAIRING FIRE DETECTION LOOP, P/N 244-12047 S/N UNK, AND INSTALLED NEW FIRE DETECTION LOOP, P/N 744-12047 S/N 201806, IAW BOMBARDIER CL-604 AMM 26-11-04-400-801. PERFORMED OPERATIONAL TEST OF THE ENGINE FIRE/ OVERHEAT DETECTION SYSTEM IAW BOMBARDIER CL-604 AMM 26-11-00. SYSTEM OPS CHECKS GOOD. NO DISCREPANCIES NOTED AT THIS TIME.)										
26 Airframe PART #454	NO.1 ZONE B PYLON, SENSING ELEMENT (LEFT ENGINE)	15-OCT-1997									
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>244-05215</td> <td>Unknown</td> </tr> </table>	Part Number	Serial Number	244-05215	Unknown						
Part Number	Serial Number										
244-05215	Unknown										
	Notes (ZONE: 1A3WC)										
26 Airframe PART #735	NO.2 EXHAUST NOZZLE ASSY OVERHEAT DETECTION ELEMENT	23-MAR-2017									
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> <td>H: 5979.10</td> <td>L: 2576</td> </tr> <tr> <td>744-12047</td> <td>170808</td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number	H: 5979.10	L: 2576	744-12047	170808				
Part Number	Serial Number	H: 5979.10	L: 2576								
744-12047	170808										
	Notes										



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 Airframe PART #1651	NO.2 ZONE B PYLON, SENSING ELEMENT (LEFT ENGINE) Part Number: 244-05215 Serial Number: Unknown	15-OCT-1997					
Notes (ZONE: 2A3WC)							
26 Airframe PART #1378	RIGHT ENGINE COMBUSTION-ZONE, SENSING ELEMENT Part Number: 244-10457 Serial Number: Unknown	15-OCT-1997					
26 Airframe PART #3540	RIGHT ENGINE SENSOR, TEMPERATURE, FIRE DETECTION SYSTEM Part Number: 377-02836 Serial Number: 9651-007	15-OCT-1997					
26 Airframe PART #1899	RIGHT EXHAUST-NOZZLE ASSEMBLY, SENSING ELEMENT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
26 Airframe PART #498	RIGHT EXTINGUISHER, FIRE CONTAINER Part Number: 601-65910-13 Serial Number: AGI2357	24-FEB-2023 H: 7944.00 L: 3577					
Notes (ZONE: ENGINE) (AVG MAN HRS: 1.5) (APX COST: 9,371.54) (UPDATE NOTE: REMOVED FWD R/H FIRE CONTAINER P/N 899074-1 S/N 18260EL.INSTALLED NEW FWD R/H FIRE CONTAINER P/N 601-65910-13 S/N AGI2357. DATE OF MANUFACTURE 09/2022 HYDROSTATIC TEST DATE 09/2022. SEE 8130 BOMBARDIER INC CRS B0573121/12-58 W/O 5035646325 DATE 18/NOV/2022.INSTALLED ORIGINAL FIREX CARTRIDGE ON TO NEW BOTTLE INTO ORIGINAL POSITION R/H NO 1 P/N 897776-01 S/N 41904 R/H NO 2 P/N 897776-01 S/N 41866. ALL WORK PERFORMED IAW BOMBARDIER CHALLENGER 604 AMM 26-21-04 AND 26-21-07.)							
26 Airframe PART #2393	RIGHT HOSE ASSY, FIRE EXTINGUISHER Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
Notes (ZONE: ENGINE)							
26 Airframe PART #1838	RIGHT MAIN LANDING GEAR (MLG), SENSING ELEMENT Part Number: 244-03615 Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 Airframe PART #483	RIGHT MAIN LANDING GEAR WHEEL BIN TEMP. SENSOR CONTROL UNIT Part Number Unknown Serial Number Unknown	15-OCT-1997					
26 Airframe PART - Life Limited #3266	RIGHT NO.1 CARTRIDGE, FIREX Part Number 897776-01 Serial Number 41904	02-JUL-2021 H: 6939.60 L: 3034	M: 120		M: 0 H: 0.00 L: 0	31-JAN-2031	M: 55 D: 30
Notes (ZONE: ENGINE) (AVG MAN HRS: 2.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
26 Airframe PART - Life Limited #2507	RIGHT NO.2 CARTRIDGE, FIREX Part Number 897776-01 Serial Number 41866	02-JUL-2021 H: 6939.60 L: 3034	M: 120		M: 0 H: 0.00 L: 0	31-JAN-2031	M: 55 D: 30
Notes (ZONE: ENGINE) (AVG MAN HRS: 2.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
26 Airframe PART #833	RIGHT SENSOR, TEMPERATURE, FIRE DETECTION SYSTEM (EXHAUST NOZZLE ASSEMBLY AND PYLON FIRE DETECTION) Part Number 377-02836 Serial Number 9709-036	15-OCT-1997					
Notes (ZONE: EXHAUST)							
26 Airframe PART #1831	RIGHT ZONE A PYLON, SENSING ELEMENT Part Number 244-03057 Serial Number Unknown	15-OCT-1997					
Notes (ZONE: ENGINE - PYLON)							
26 13-04-201 Airframe INSPECTION PKG1200Hour #1449	VISUAL CHECK OF THE MAIN LANDING GEAR (MLG) SENSING	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 13-04-202 Airframe INSPECTION PKG3200Hour #1519	FUNCTIONAL TEST OF THE MAIN LANDING GEAR (MLG) SENSING ELEMENT	16-JUN-2018 H: 6372.80 L: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 2)						
26 20-00-204 Airframe INSPECTION PKG2400Hour #2715	FUNCTIONAL TEST OF THE ENGINE FIRE SHUTOFF - RELAY CIRCUITRY	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 4.5)						
26 20-00-205 Airframe INSPECTION PKG 24 Month #830	COCKPIT FUNCTIONAL TEST (WEIGHT CHECK) OF THE PORTABLE FIRE - EXTINGUISHER CONTAINER	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		31-MAY-2027	M: 11 D: 30
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
26 20-00-207 Airframe INSPECTION #3654	LEFT DETAILED INSPECTION OF THE ENGINE FIRE-EXTINGUISHER CONTAINER	24-FEB-2023 H: 7944.00 L: 3577	M: 60	M: 1		24-FEB-2028	M: 20 D: 23
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: REMOVED AFT L/H FIRE CONTAINER P/N 899074-1 S/N 18263EL. INSTALLED NEW AFT L/H FIRE CONTAINER P/N 601-65910-13 S/N AGI2345. DATE OF MANUFACTURE 08/2022 HYDROSTATIC TEST DATE 08/2022. SEE 8130 BOMBARDIER INC CRS B0573123/12-58 UNDER W/O 5035379539 DATE 21/SEP/2022. INSTALLED ORIGINAL FIREX CARTRIDGE ON TO NEW BOTTLE INTO ORIGINAL POSITION L/H NO 1 P/N 897776-01 S/N 41913 L/H NO 2 P/N 897776-01 S/N 41906. ALL WORK PERFORMED IAW BOMBARDIER CHALLENGER 604 AMM 26-21-04 AND 26-21-07.)						
26 20-00-207 Airframe INSPECTION #2394	RIGHT DETAILED INSPECTION OF THE ENGINE FIRE-EXTINGUISHER CONTAINER	24-FEB-2023 H: 7944.00 L: 3577	M: 60	M: 1		24-FEB-2028	M: 20 D: 23
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: REMOVED FWD R/H FIRE CONTAINER P/N 899074-1 S/N 18260EL. INSTALLED NEW FWD R/H FIRE CONTAINER P/N 601-65910-13 S/N AGI2357. DATE OF MANUFACTURE 09/2022 HYDROSTATIC TEST DATE 09/2022. SEE 8130 BOMBARDIER INC CRS B0573121/12-58 W/O 5035646325 DATE 18/NOV/2022. INSTALLED ORIGINAL FIREX CARTRIDGE ON TO NEW BOTTLE INTO ORIGINAL POSITION R/H NO 1 P/N 897776-01 S/N 41904 R/H NO 2 P/N 897776-01 S/N 41866. ALL WORK PERFORMED IAW BOMBARDIER CHALLENGER 604 AMM 26-21-04 AND 26-21-07.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 20-00-207.1 Airframe INSPECTION #2851	LEFT FIRE EXTINGUISHING CONTAINER - (HYDROSTATIC) FUNCTIONAL CHECK	24-FEB-2023 H: 7944.00 L: 3577					
	<p>Notes</p> <p>(UPDATE NOTE: REMOVED AFT L/H FIRE CONTAINER P/N 899074-1 S/N 18263EL. INSTALLED NEW AFT L/H FIRE CONTAINER P/N 601-65910-13 S/N AGI2345. DATE OF MANUFACTURE 08/2022 HYDROSTATIC TEST DATE 08/2022. SEE 8130 BOMBARDIER INC CRS B0573123/12-58 UNDER W/O 5035379539 DATE 21/SEP/2022. INSTALLED ORIGINAL FIREX CARTRIDGE ON TO NEW BOTTLE INTO ORIGINAL POSITION L/H NO 1 P/N 897776-01 S/N 41913 L/H NO 2 P/N 897776-01 S/N 41906. ALL WORK PERFORMED IAW BOMBARDIER CHALLENGER 604 AMM 26-21-04 AND 26-21-07.)</p>						
26 20-00-207.2 Airframe INSPECTION #2717	RIGHT FIRE EXTINGUISHING CONTAINER - (HYDROSTATIC) FUNCTIONAL CHECK	24-FEB-2023 H: 7944.00 L: 3577					
	<p>Notes</p> <p>(UPDATE NOTE: REMOVED FWD R/H FIRE CONTAINER P/N 899074-1 S/N 18260EL. INSTALLED NEW FWD R/H FIRE CONTAINER P/N 601-65910-13 S/N AGI2357. DATE OF MANUFACTURE 09/2022 HYDROSTATIC TEST DATE 09/2022. SEE 8130 BOMBARDIER INC CRS B0573121/12-58 W/O 5035646325 DATE 18/NOV/2022. INSTALLED ORIGINAL FIREX CARTRIDGE ON TO NEW BOTTLE INTO ORIGINAL POSITION R/H NO 1 P/N 897776-01 S/N 41904 R/H NO 2 P/N 897776-01 S/N 41866. ALL WORK PERFORMED IAW BOMBARDIER CHALLENGER 604 AMM 26-21-04 AND 26-21-07.)</p>						
26 20-00-208 Airframe INSPECTION #71	CABIN DETAILED INSPECTION & HYDROSTATIC TEST OF THE PORTABLE FIRE-EXTINGUISHER CONTAINER	29-JAN-2025 H: 8628.90 L: 3975	M: 144			31-DEC-2036	M: 126 D: 30
	<p>Notes</p> <p>(UPDATE NOTE: COMPLIED WITH INSPECTION TASK 26-20-00-208 CABIN DETAILED INSPECTION & HYDROSTATIC TEST OF THE PORTABLE FIRE-EXTINGUISHER CONTAINER BY INSTALLATION OF NEW BOTTLE. REMOVED CABIN FIRE EXTINGUISHER P/N 30H673 S/N F-68184866 AND INSTALLED NEW PORTABLE FIRE EXTINGUISHER P/N 30H673 S/N I-48489258 IAW BOMBARDIER CL 604 AMM 26-26-01. DOM 20/DEC/2024)</p>						
26 20-00-208 Airframe INSPECTION PKG 96 Month #1946	COCKPIT DETAILED INSPECTION OF THE PORTABLE FIRE-EXTINGUISHER CONTAINER	20-MAR-2024 H: 8325.70 L: 3788	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 0.5)</p>						
26 20-00-208.1 Airframe INSPECTION #955	COCKPIT DETAILED INSPECTION & HYDROSTATIC TEST OF THE PORTABLE FIRE-EXTINGUISHER CONTAINER	20-MAR-2024 H: 8325.70 L: 3788	M: 144			29-FEB-2036	M: 116 D: 28
	<p>Notes</p> <p>(UPDATE NOTE: COMPLIED WITH INSPECTION TASK 26-20-00-208.1 BY INSTALLATION OF OVERHAULED FIRE BOTTLE. BOTTLE HYDRO TEST COMPLIED WITH ON 02-2024. REMOVED COCKPIT PORTABLE FIRE EXTINGUISHER P/N 898052 S/N X-987629. INSTALLED OVERHAULED COCKPIT PORTABLE FIRE EXTINGUISHER P/N 898052 S/N B71139484 IAW BOMBARDIER CL 604 AMM 26-26-01. BOTTLES MFG. DATE 2016 AND LAST HYDRO 02-2024. FIRE EXTINGUISHER WAS OVERHAULED BY SAFETECH FORM TRACKING NUMBER WSM2402633 WORK ORDER WSM2402633 RO-17592 CRS# SMRE451X DATED 19-FEB-2024)</p>						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 20-00-209 Airframe INSPECTION #367	APU DETAILED INSPECTION OF THE AUXILIARY POWER UNIT (APU) FIRE-EXTINGUISHER CONTAINER	05-JUL-2024 H: 8455.80 L: 3862	M: 60	M: 1		26-JUL-2029	M: 37 D: 25
	Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: 21D) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)						
26 20-00-209.1 Airframe INSPECTION #589	APU FIRE EXTINGUISHING CONTAINER - (HYDROSTATIC) FUNCTIONAL CHECK	26-JUL-2019					
26 21-00-201 Airframe INSPECTION PKG4800Hour #558	FUNCTIONAL TEST OF THE BOTTLE 1 AND BOTTLE 2 ARMED PUSH TO DISCH SWITCH/LIGHTS	12-APR-2013 H: 4782.30 L: 2063	H: 4800.00	H: 40.00		H: 9595.00	H: 899.90
	Notes (AVG MAN HRS: 3.5)						
26 21-04-201 Airframe INSPECTION PKG 24 Month #2784	LEFT DETAILED INSPECTION OF THE ENGINE FIRE-EXTINGUISHER - BOTTLE PRESSURE GAUGE	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		31-MAY-2027	M: 11 D: 30
	Notes (ZONE: ENGINE) (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
26 21-04-201 Airframe INSPECTION PKG 24 Month #2471	RIGHT DETAILED INSPECTION OF THE ENGINE FIRE-EXTINGUISHER - BOTTLE PRESSURE GAUGE	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		31-MAY-2027	M: 11 D: 30
	Notes (ZONE: ENGINE) (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
26 21-16-201 Airframe INSPECTION PKG 48 Month #1723	DETAILED INSPECTION OF THE FIRE-EXTINGUISHING - SYSTEM LINES	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 8.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
26 22-00-201 Airframe INSPECTION PKG4800Hour #2179	FUNCTIONAL TEST OF THE AUXILIARY POWER UNIT (APU) FIRE - EXTINGUISHING SYSTEM	12-APR-2013 H: 4782.30 L: 2063	H: 4800.00	H: 40.00		H: 9595.00	H: 899.90
	Notes (AVG MAN HRS: 2)						
26 22-04-201 Airframe INSPECTION PKG 24 Month #1289	APU DETAILED INSPECTION OF THE AUXILIARY POWER UNIT (APU) FIRE-EXTINGUISHER-BOTTLE PRESSURE GAUGE	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		31-MAY-2027	M: 11 D: 30
	Notes (ZONE: AFT FUSE) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
26 2303 Airframe INSPECTION #763	COCKPIT WEIGHT CHECK COCKPIT (HALON) FIRE EXTINGUISHER PORTABLE	01-FEB-2026 H: 8670.40 L: 3995	M: 12			01-FEB-2027	M: 8 D: 0
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: COMPLIED WITH INSPECTION 262303 COCKPIT WEIGHT CHECK COCKPIT (HALON) BOTTLE WEIGHT 3.16 OZ 29-JAN-2025.)						
26 2505-701B Airframe INSPECTION #1341	CABIN WEIGHT CHECK FIRE EXTINGUISHER PORTABLE BOTTLE 26-25-00-9002 - FIRE EXT HALON TYPE	01-FEB-2026 H: 8670.40 L: 3995	M: 12			28-FEB-2027	M: 8 D: 27
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: COMPLIED WITH 262505-701B, WEIGHT CHECK OF CABIN FIRE EXTINGUISHER, IAW PLACARDED INSTRUCTIONS. WEIGHT FOUND WITHIN LIMITS. WEIGHT 5 LBS. 5 OZ. REMOVED CABIN FIRE EXTINGUISHER P/N 30H673 S/N F-68184866 AND INSTALLED NEW PORTABLE FIRE EXTINGUISHER P/N 30H673 S/N I-48489258 IAW BOMBARDIER CL 604 AMM 26-26-01. DOM 20/DEC/2024)						
26 2505-702C Airframe INSPECTION #2670	COCKPIT DETAILED INTERNAL INSPECTION FIRE EXTINGUISHER PORTABLE BOTTLE 26-25-00-9003	20-MAR-2024 H: 8325.70 L: 3788	M: 72			01-FEB-2030	M: 44 D: 0
	Notes (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 262505-702C DETAILED INTERNAL INSPECTION ON 02-2024. REMOVED COCKPIT PORTABLE FIRE EXTINGUISHER P/N 898052 S/N X-987629. INSTALLED OVERHAULED COCKPIT PORTABLE FIRE EXTINGUISHER P/N 898052 S/N B71139484 IAW BOMBARDIER CL 604 AMM 26-26-01. BOTTLES MFG. DATE 2016 AND LAST HYDRO 02-2024. FIRE EXTINGUISHER WAS OVERHAULED BY SAFETECH FORM TRACKING NUMBER WSM2402633 WORK ORDER WSM2402633 RO-17592 CRS# SMRE451X DATED 19-FEB-2024)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining				
26 2505-702E Airframe INSPECTION #1714	CABIN DETAILED INTERNAL INSPECTION FIRE EXTINGUISHER PORTABLE BOTTLE 26-25-00-9003	29-JAN-2025 H: 8628.90 L: 3975	M: 72			31-JAN-2031	M: 55 D: 30				
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH 262505-702E, CABIN DETAILED INTERN INSPECTION OF CABIN FIRE EXTINGUISHER BY INSTALLATION OF NEW FIRE BOTTLE. REMOVED CABIN FIRE EXTINGUISHER P/N 30H673 S/N F-68184866 AND INSTALLED NEW PORTABLE FIRE EXTINGUISHER P/N 30H673 S/N I-48489258 IAW BOMBARDIER CL 604 AMM 26-26-01. DOM 20/DEC/2024)										
26 C208 Airframe INSPECTION PKG 12 Month #2562	CHECK AFT LAVATORY FIRE EXTINGUISHER CONDITION / SECURITY MOUNTING. WEIGHT / PRESSURE CHECK	26-MAY-2026 H: 8686.90 L: 3999	M: 12			26-MAY-2027	M: 11 D: 25				
	Notes (AVG MAN HRS: 0.5)										
26 JLA-FIREEXTMTLY26-(-JLCD) Airframe INSPECTION #241	CABIN & COCKPIT FIRE EXTINGUISHER VISUAL INSPECTION	26-MAY-2026 H: 8686.90 L: 3999	D: 30			30-JUN-2026	M: 0 D: 29				
	Notes (ZONE: --) (AVG MAN HRS: 0.5) (UPDATE NOTE: COMPLIED WITH COCKPIT AND CABIN FIRE EXTINGUISHER VISUAL CHECKS.)										
27 Airframe PART #1614	ACTUATOR, TRIM, ROLL AND YAW (AILERON TRIM ACTUATOR)					15-OCT-1997					
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>600-91100-3</td> <td>0469</td> </tr> </table>	Part Number	Serial Number	600-91100-3	0469						
Part Number	Serial Number										
600-91100-3	0469										
27 Airframe PART #2821	ACTUATOR, TRIM, ROLL AND YAW (RUDDER TRIM ACTUATOR)					15-OCT-1997					
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>600-91100-3</td> <td>1282</td> </tr> </table>	Part Number	Serial Number	600-91100-3	1282						
Part Number	Serial Number										
600-91100-3	1282										
27 Airframe PART #3109	AFT - LOWER ROD ASSY, CONTROL					15-OCT-1997					
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>Unknown</td> <td>Unknown</td> </tr> </table>	Part Number	Serial Number	Unknown	Unknown						
Part Number	Serial Number										
Unknown	Unknown										
27 Airframe PART #308	AFT - UPPER ROD ASSY, CONTROL					15-OCT-1997					
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>Unknown</td> <td>Unknown</td> </tr> </table>	Part Number	Serial Number	Unknown	Unknown						
Part Number	Serial Number										
Unknown	Unknown										



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #978	AFT LIMITER, LOAD (RUDDER) Part Number: 37340 Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #284	CENTER BUNGEE, LOAD LIMITER Part Number: 37350 Serial Number: Unknown Notes (ZONE: RUDDER)	15-OCT-1997					
27 Airframe PART #1558	CENTER LIMITER, LOAD (RUDDER) Part Number: 600-91302-53 Serial Number: 299	15-OCT-1997					
27 Airframe PART #3629	COCKPIT PANEL, FLAP CONTROL, MPE2CE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #2014	COCKPIT POWER SUPPLY, 28VDC TO 5VDC Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #345	COMPUTER, STALL PROTECTION Part Number: 600-59152-35 Serial Number: M3145 Notes (ZONE: AVIONIC BAY) (APX COST: 0) (UPDATE NOTE: WORK PERFORMED BY KEYSTONE AVIATION UNDER W/O NC-1221022, SEE MAINTENANCE LOG ENTRY DATED 16-JUN-2022 FOR DETAILS.)	16-JUN-2022 H: 7572.50 L: 3379					
27 Airframe PART #3527	CONTROL ASSY, FLIGHT SPOILER Part Number: Unknown Serial Number: Unknown Notes (ZONE: CENTER PEDESTAL)	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #1611	CONTROL COLUMN INSTL Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #225	CONTROL UNIT, FLAP Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #1046	COPILOT - LEFT TRANSDUCER, RUDDER (CFMS) Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #594	COPILOT - RIGHT TRANSDUCER, RUDDER (CFMS) Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #612	COPILOT ACTUATOR, STICK PUSHER Part Number 600-59156-15 Serial Number 1659	15-OCT-1997					
27 Airframe PART #2190	COPILOT CAPSTAN, STICK PUSHER Part Number 600-59156-7 Serial Number 1691	15-OCT-1997					
27 Airframe PART #2156	COPILOT INDICATOR, SPS TEST Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #2232	COPILOT SHAKER, STICK, STALL PROTECTION Part Number 600-59155-1 Serial Number 6673	15-OCT-1997					
27 Airframe PART #896	COPILOT STALL PROTECTION CONTROL PANEL Part Number 604-51413-4 Serial Number Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #2797	COPILOT TRANSDUCER UNIT, ELEVATOR Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #3691	COPILOT WHEEL, COLUMN, CONTROL Part Number 601R90101-2 Serial Number 0496	15-OCT-1997					
27 Airframe PART #2755	DISCONNECT, HANDLE, PITCH Part Number 7-44853-17 Serial Number Unknown	15-OCT-1997					
27 Airframe PART #647	FLAP CONTROL UNIT Part Number 600-93000-121 Serial Number D776	10-JUL-2006 H: 2685.50 L: 1052					
27 Airframe PART #2453	FWD - LEFT TRANSDUCER ASSY, AOA (SENSOR ASSY) Part Number 600-59154-3 Serial Number 05154	22-DEC-2004 H: 2413.00 L: 936					
27 Airframe PART #2445	FWD - RIGHT TRANSDUCER ASSY, AOA (SENSOR ASSY) Part Number 600-59154-3 Serial Number 05155	22-DEC-2004 H: 2413.00 L: 936					
27 Airframe PART #1655	HANDLE, ROLL, DISCONNECT Part Number 7-44853-19 Serial Number Unknown	15-OCT-1997					
27 Airframe PART #1719	LEFT ACCELEROMETER, UNDERFLOOR (LATERAL STALL WARNING) Part Number 600-59199-9 Serial Number 1135	15-OCT-1997					
27 Airframe PART #2403	LEFT ACTUATOR, INBD OUTER FLAP Part Number 600-93000-115 Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #2820	LEFT ACTUATOR, INBD, INNER FLAP Part Number: 600-93000-95 Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #3077	LEFT ACTUATOR, OUTBD INNER FLAP Part Number: 600-93000-93 Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #1120	LEFT ACTUATOR, OUTBD OUTER FLAP Part Number: 600-93000-113 Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #1554	LEFT AILERON ASSY Part Number: 600-13000-1003 Serial Number: 9766788	15-OCT-1997					
27 Airframe PART #3092	LEFT AILERON, I/O, DUMMY ROD UNIT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART - Life Limited #38	LEFT BAR, TORSION, ANTI-FLOAT, (AILERON) Part Number: 600-10057-5 Serial Number: P29424	15-OCT-1997	H: 10000.00		H: 0.00 L: 0	H: 10000.00	H: 1304.90
<p>Notes</p> <p>(AVG MAN HRS: 10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>							
27 Airframe PART #2906	LEFT BRAKE, DETECTOR UNIT (FLAP) Part Number: 600-93000-123 Serial Number: 1608A	12-OCT-2017					H: 6181.40 L: 2646
27 Airframe PART #489	LEFT CONTROL, PUSH/PULL SPOILER (FLIGHT SPOILER) Part Number: 600-91303-11 Serial Number: 363	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #2777	LEFT CRVDT (AILERON) Part Number Unknown Serial Number Unknown Notes (ZONE: LBL17)	15-OCT-1997					
27 Airframe PART #1197	LEFT DAMPER, FLUTTER (AILERON) Part Number 600-75142-9 Serial Number HA0100	21-OCT-2015 H: 5601.80 L: 2432					
27 Airframe PART #3445	LEFT FLAP ASSY OUTBD Part Number 600-14500-805 Serial Number 9723309	15-OCT-1997					
27 Airframe PART #3255	LEFT FLAP POSITION TRANSMITTER ASSY Part Number 600-93030-9 Serial Number 1004890 Notes (ZONE: WS76.5L)	15-OCT-1997					
27 Airframe PART #2329	LEFT INBOARD ACTUATOR,ASSY FLAP VANE Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #3450	LEFT INBOARD AILERON (PCU) PRESSURE SWITCH Part Number 3941008-101 Serial Number 3893 Notes (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)	02-JUL-2021 H: 6939.60 L: 3034					
27 Airframe PART #2018	LEFT INBOARD DAMPER, FLUTTER (ELEVATOR) Part Number 600-75142-9 Serial Number HAI2366	12-APR-2013 H: 4782.30 L: 2063					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART - Life Limited #3420	LEFT INBOARD FLAP VANE ACTUATOR SYSTEM, BEAM ASSEMBLY Part Number: 600-14250-15 Serial Number: Unknown	15-OCT-1997	L: 9600		M: 0 H: 0.00 L: 0	L: 9600	L: 5598
Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
27 Airframe PART #138	LEFT INBOARD PCU, ELEVATOR Part Number: 600-75102-23 Serial Number: 1650	15-OCT-1997					
27 Airframe PART #3004	LEFT INBOARD PCU, FLIGHT SPOILER Part Number: 600-75103-15 Serial Number: 1645	15-OCT-1997					
27 Airframe PART #1410	LEFT INPUT/OUTPUT UNIT, AILERON Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #266	LEFT LIMITER, LOAD (FLIGHT SPOILER) Part Number: 600-91302-47 Serial Number: 356	15-OCT-1997					
27 Airframe PART #2974	LEFT NO.1 SHAFT, FLEXIBLE DRIVE (FLAP) Part Number: 600-93000-61 Serial Number: 2279	22-APR-2005			H: 2522.30 L: 983		
27 Airframe PART #2305	LEFT NO.2 SHAFT, FLEXIBLE DRIVE (FLAP) Part Number: 600-93000-63 Serial Number: 037-1228	15-OCT-1997					
27 Airframe PART #2523	LEFT NO.3 SHAFT, FLEXIBLE DRIVE (FLAP) Part Number: 600-93000-65 Serial Number: 1316	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #3094	LEFT NO.4 SHAFT, FLEXIBLE DRIVE (FLAP) Part Number: 600-93000-67 Serial Number: 037-1260	15-OCT-1997					
27 Airframe PART #1042	LEFT NO.5 SHAFT, FLEXIBLE DRIVE (FLAP) Part Number: 600-93000-69 Serial Number: 1443	15-OCT-1997					
27 Airframe PART #673	LEFT OUTBOARD ACTUATOR,ASSY FLAP VANE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #3040	LEFT OUTBOARD AILERON (PCU) PRESSURE SWITCH Part Number: Unknown Serial Number: Unknown						
27 Airframe PART #2	LEFT OUTBOARD DAMPER, FLUTTER (ELEVATOR) Part Number: 1018100-7 Serial Number: HAI4857	11-JUL-2023 H: 8075.40 L: 3647					
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
27 Airframe PART - Life Limited #1022	LEFT OUTBOARD FLAP VANE ACTUATOR SYSTEM, BEAM ASSEMBLY Part Number: 600-14250-15 Serial Number: Unknown	15-OCT-1997	L: 9600		M: 0 H: 0.00 L: 0	L: 9600	L: 5598
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
27 Airframe PART #2070	LEFT OUTBOARD PCU, ELEVATOR Part Number: 600-75102-23 Serial Number: 1636	15-OCT-1997					
27 Airframe PART #1643	LEFT OUTBOARD PCU, FLIGHT SPOILER Part Number: 600-75103-15 Serial Number: 1647	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #1367	LEFT PCU, AILERON Part Number 600-75100-17 Serial Number 1513D	06-AUG-2012 H: 4594.60 L: 1980					
27 Airframe PART #2840	LEFT PCU, GROUND SPOILER Part Number 2770535-106 Serial Number Unknown	15-OCT-1997					
27 Airframe PART #561	LEFT PITCH FEEL SIMULATOR DISCONNECT Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #1620	LEFT REGULATOR, TENSION Part Number 600-91301-11 Serial Number 9700145 Notes (ZONE: AILERON)	15-OCT-1997					
27 Airframe PART #2518	LEFT RVDT, SINGLE CHANNEL Part Number Unknown Serial Number Unknown Notes (ZONE: LBL26)	15-OCT-1997					
27 Airframe PART #545	LEFT SENSOR, AOA Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #1924	LEFT SIMULATOR, PITCH FEEL Part Number 600-92300-61 Serial Number 10430 Notes (AVG MAN HRS: 2) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)	23-AUG-2006 H: 2749.80 L: 1084					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #2847	LEFT TRANSMITTER, CONTROL SURFACE POSITION (AILERON) Part Number: 600-59132-1 Serial Number: 54039	15-OCT-1997					
27 Airframe PART #2251	LEFT TRANSMITTER, CONTROL SURFACE POSITION (ELEVATOR) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #2114	LEFT TRANSMITTER, CONTROL SURFACE POSITION (SPOILER) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART - Life Limited #1597	LOWER - LEFT HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) PIN Part Number: 600-92383-7 Serial Number: 23-5352-C	23-MAR-2017 H: 5979.10 L: 2576	L: 7800		H: 5979.10 L: 2576	L: 7800	L: 3798
Notes (ZONE: FS855 BLO WL231 LBL5) (SOURCE: 05-10-10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
27 Airframe PART - Life Limited #2591	LOWER - LEFT SUPPORT, TRUNNION, HSTA ACTUATOR Part Number: 601R92386-1 Serial Number: 12-5352-D	23-MAR-2017 H: 5979.10 L: 2576	L: 20000		H: 5979.10 L: 2576	L: 20000	L: 15998
Notes (ZONE: WL231) (AVG MAN HRS: 31) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
27 Airframe PART - Life Limited #3367	LOWER - RIGHT HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) PIN Part Number: 600-92383-7 Serial Number: 22-5352-G	23-MAR-2017 H: 5979.10 L: 2576	L: 7800		M: 0 H: 5979.10 L: 2576	L: 7800	L: 3798
Notes (ZONE: FS855 BLO WL231 RBL5) (SOURCE: 05-10-10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART - Life Limited #2169	LOWER - RIGHT SUPPORT, TRUNNION, HSTA ACTUATOR Part Number: 601R92386-1 Serial Number: 22-5352-H	23-MAR-2017 H: 5979.10 L: 2576	L: 20000		H: 5979.10 L: 2576	L: 20000	L: 15998
	Notes (ZONE: WL231) (AVG MAN HRS: 31) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
27 Airframe PART #342	LOWER BUNGEE, LOAD LIMITER Part Number: 37380 Serial Number: Unknown					15-OCT-1997	
	Notes (ZONE: RUDDER)						
27 Airframe PART #3302	LOWER CONVERTER SIGNAL, AOA Part Number: Unknown Serial Number: Unknown					15-OCT-1997	
	Notes (ZONE: LEFT FWD FUSE)						
27 Airframe PART #3169	LOWER PCU, RUDDER Part Number: 600-75101-29 Serial Number: 7284					15-OCT-1997	
27 Airframe PART #3548	LOWER ROD ASSY, CONTROL Part Number: Unknown Serial Number: Unknown					15-OCT-1997	
27 Airframe PART #86	MANIFOLD, GROUND SPOILER Part Number: 600-75124-7 Serial Number: 429					15-OCT-1997	
27 Airframe PART #2152	MIDDLE - LEFT ACTUATOR, ASSY FLAP VANE Part Number: Unknown Serial Number: Unknown					15-OCT-1997	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART - Life Limited #1304	MIDDLE - LEFT FLAP VANE ACTUATOR SYSTEM, BEAM ASSEMBLY Part Number: 600-14250-15 Serial Number: Unknown	15-OCT-1997	L: 9600		M: 0 H: 0.00 L: 0	L: 9600	L: 5598
Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
27 Airframe PART #3227	MIDDLE - RIGHT ACTUATOR, ASSY FLAP VANE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART - Life Limited #230	MIDDLE - RIGHT FLAP VANE ACTUATOR SYSTEM, BEAM ASSEMBLY Part Number: 600-14250-15 Serial Number: Unknown	15-OCT-1997	L: 9600		M: 0 H: 0.00 L: 0	L: 9600	L: 5598
Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
27 Airframe PART #3236	MIDDLE PCU, RUDDER Part Number: 600-75101-29 Serial Number: 7283	15-OCT-1997					
27 Airframe PART #2869	MIDDLE ROD ASSY, CONTROL Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #1229	MOTOR CONTROL UNIT, HORIZONTAL STABILIZER Part Number: 604-92306-11 Serial Number: 831	27-DEC-2024			H: 8606.70 L: 3964		
27 Airframe PART #787	NO.1 FLAP (POWER DRIVE UNIT (PDU)), MOTOR Part Number: 516456-2 Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #3324	NO.1 LIMITER, LOAD (ELEVATOR) Part Number: 37360 Serial Number: Unknown	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #474	NO.1 TRANSDUCER, FORCE Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #1857	NO.2 FLAP (POWER DRIVE UNIT (PDU)), MOTOR Part Number 516456-2 Serial Number Unknown	15-OCT-1997					
27 Airframe PART #1179	NO.2 LIMITER, LOAD (ELEVATOR) Part Number 37360 Serial Number Unknown	15-OCT-1997					
27 Airframe PART #2836	NO.2 TRANSDUCER, FORCE Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #2165	NO.4 FLAP CONTROL POSITION LEVER Part Number 601R93003-1 Serial Number 208	15-OCT-1997					
27 Airframe PART #563	PDU (POWER DRIVE UNIT), FLAP Part Number 600-93000-71 Serial Number 0595	15-OCT-1997					
27 Airframe PART #2293	PEDESTAL POWER SUPPLY Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #2047	PILOT - LEFT TRANSDUCER, RUDDER (CFMS) Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #1430	PILOT - RIGHT TRANSDUCER, RUDDER (CFMS) Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #1376	PILOT INDICATOR, SPS TEST Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #3456	PILOT SHAKER, STICK, STALL PROTECTION Part Number 600-59155-1 Serial Number 6674	15-OCT-1997					
27 Airframe PART #1026	PILOT STALL PROTECTION CONTROL PANEL Part Number 604-51413-3 Serial Number Unknown	15-OCT-1997					
27 Airframe PART #1265	PILOT TRANSDUCER UNIT, ELEVATOR Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #1031	PILOT WHEEL, COLUMN, CONTROL Part Number 601R90101-1 Serial Number 0587	15-OCT-1997					
27 Airframe PART #203	POTENTIOMETER ASSY-PDU FLAP Part Number C35703-002 Serial Number 0065C	20-OCT-2017 H: 6184.60 L: 2648					
27 Airframe PART #1260	RIGHT ACCELEROMETER, UNDERFLOOR (LATERAL STALL WARNING) Part Number 600-59199-9 Serial Number DT8434U	16-JUN-2022 H: 7572.50 L: 3379					
Notes (APX COST: 0) (UPDATE NOTE: WORK PERFORMED BY KEYSTONE AVIATION UNDER W/O NC-1221022, SEE MAINTENANCE LOG ENTRY DATED 16-JUN-2022 FOR DETAILS.)							
27 Airframe PART #3347	RIGHT ACTUATOR, INBD OUTER FLAP Part Number 600-93000-116 Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #533	RIGHT ACTUATOR, INBD, INNER FLAP Part Number: 600-93000-95 Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #2581	RIGHT ACTUATOR, OUTBD INNER FLAP Part Number: 600-93000-93 Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #2678	RIGHT ACTUATOR, OUTBD OUTER FLAP Part Number: 600-93000-114 Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #3525	RIGHT AILERON ASSY Part Number: 600-13000-1004 Serial Number: 9723343	15-OCT-1997					
27 Airframe PART #752	RIGHT AILERON, I/O, DUMMY ROD UNIT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART - Life Limited #1834	RIGHT BAR, TORSION, ANTI-FLOAT, (AILERON) Part Number: 600-10057-6 Serial Number: P29423	15-OCT-1997	H: 10000.00		H: 0.00 L: 0	H: 10000.00	H: 1304.90
	<p>Notes</p> <p>(AVG MAN HRS: 10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
27 Airframe PART #668	RIGHT BRAKE, DETECTOR UNIT (FLAP) Part Number: 600-93000-123 Serial Number: 1654A	23-FEB-2011					H: 4101.60 L: 1766
27 Airframe PART #3108	RIGHT CONTROL, PUSH/PULL SPOILER (FLIGHT SPOILER) Part Number: 600-91303-13 Serial Number: 369	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #419	RIGHT CRVDT (AILERON) Part Number Unknown Serial Number Unknown	15-OCT-1997					
	Notes (ZONE: RBL17)						
27 Airframe PART #358	RIGHT DAMPER, FLUTTER (AILERON) Part Number 1018100-7 Serial Number HAI4868	11-JUL-2023 H: 8075.40 L: 3647					
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
27 Airframe PART #1740	RIGHT FLAP ASSY OUTBD Part Number 600-14500-806 Serial Number 9723275	15-OCT-1997					
27 Airframe PART #1496	RIGHT FLAP POSITION TRANSMITTER ASSY Part Number 600-93030-11 Serial Number 5365840	26-JUL-2005 H: 2522.30 L: 983					
	Notes (ZONE: WS76.5R)						
27 Airframe PART #2646	RIGHT INBOARD ACTUATOR,ASSY FLAP VANE Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #255	RIGHT INBOARD AILERON (PCU) PRESSURE SWITCH Part Number Unknown Serial Number Unknown						
27 Airframe PART #1672	RIGHT INBOARD DAMPER, FLUTTER (ELEVATOR) Part Number 1018100-7 Serial Number HAI6684	02-JUL-2021 H: 6939.60 L: 3034					
	Notes (UPDATE NOTE: REPAIRED BY DUNCAN AVIATION CRS JGVR194F ON FFMB.A.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART - Life Limited #356	RIGHT INBOARD FLAP VANE ACTUATOR SYSTEM, BEAM ASSEMBLY Part Number: 600-14250-15 Serial Number: Unknown	15-OCT-1997	L: 9600		M: 0 H: 0.00 L: 0	L: 9600	L: 5598
Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
27 Airframe PART #2347	RIGHT INBOARD PCU, ELEVATOR Part Number: 600-75102-23 Serial Number: 1652	15-OCT-1997					
27 Airframe PART #3032	RIGHT INBOARD PCU, FLIGHT SPOILER Part Number: 600-75103-15 Serial Number: 1640	15-OCT-1997					
27 Airframe PART #2533	RIGHT INPUT/OUTPUT UNIT, AILERON Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #1737	RIGHT LIMITER, LOAD (FLIGHT SPOILER) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #3295	RIGHT NO.1 SHAFT, FLEXIBLE DRIVE (FLAP) Part Number: 600-93000-61 Serial Number: 2282	22-APR-2005			H: 2522.30 L: 983		
27 Airframe PART #3424	RIGHT NO.2 SHAFT, FLEXIBLE DRIVE (FLAP) Part Number: 600-93000-63 Serial Number: 037-1229	15-OCT-1997					
27 Airframe PART #3130	RIGHT NO.3 SHAFT, FLEXIBLE DRIVE (FLAP) Part Number: 600-93000-65 Serial Number: 037-1313	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #242	RIGHT NO.4 SHAFT, FLEXIBLE DRIVE (FLAP) Part Number: 600-93000-67 Serial Number: 94697	15-OCT-1997					
27 Airframe PART #432	RIGHT NO.5 SHAFT, FLEXIBLE DRIVE (FLAP) Part Number: 600-93000-69 Serial Number: 1440	15-OCT-1997					
27 Airframe PART #2706	RIGHT OUTBOARD ACTUATOR,ASSY FLAP VANE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #1327	RIGHT OUTBOARD AILERON (PCU) PRESSURE SWITCH Part Number: Unknown Serial Number: Unknown						
27 Airframe PART #3449	RIGHT OUTBOARD DAMPER, FLUTTER (ELEVATOR) Part Number: 600-75142-9 Serial Number: HAI2374	12-APR-2013 H: 4782.30 L: 2063					
27 Airframe PART - Life Limited #748	RIGHT OUTBOARD FLAP VANE ACTUATOR SYSTEM, BEAM ASSEMBLY Part Number: 600-14250-15 Serial Number: Unknown	15-OCT-1997	L: 9600		M: 0 H: 0.00 L: 0	L: 9600	L: 5598
<p>Notes</p> <p>(AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>							
27 Airframe PART #3709	RIGHT OUTBOARD PCU, ELEVATOR Part Number: 600-75102-23 Serial Number: 1658	15-OCT-1997					
27 Airframe PART #282	RIGHT OUTBOARD PCU, FLIGHT SPOILER Part Number: 600-75103-15 Serial Number: 1644	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #611	RIGHT PCU, AILERON Part Number 600-75100-17 Serial Number 1665D	19-MAY-2015 H: 5498.10 L: 2377					
27 Airframe PART #553	RIGHT PCU, GROUND SPOILER Part Number 2770535-106 Serial Number Unknown	15-OCT-1997					
27 Airframe PART #478	RIGHT PITCH FEEL SIMULATOR DISCONNECT Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 Airframe PART #2381	RIGHT PUSHER ASSY, CABLE AND STICK Part Number Unknown Serial Number Unknown Notes (ZONE: FS269)	15-OCT-1997					
27 Airframe PART #1710	RIGHT REGULATOR, TENSION Part Number 600-91301-12 Serial Number 9200102 Notes (ZONE: AILERON)	15-OCT-1997					
27 Airframe PART #120	RIGHT RVDT, SINGLE CHANNEL Part Number Unknown Serial Number Unknown Notes (ZONE: RBL26)	15-OCT-1997					
27 Airframe PART #660	RIGHT SENSOR, AOA Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #3479	RIGHT SIMULATOR, PITCH FEEL Part Number: 600-92300-61 Serial Number: 10038	23-AUG-2006 H: 2749.80 L: 1084					
Notes (AVG MAN HRS: 2) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
27 Airframe PART #2029	RIGHT TRANSMITTER, CONTROL SURFACE POSITION (AILERON) Part Number: 600-59132-1 Serial Number: 54044	15-OCT-1997					
27 Airframe PART #1727	RIGHT TRANSMITTER, CONTROL SURFACE POSITION (ELEVATOR) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #3444	RIGHT TRANSMITTER, CONTROL SURFACE POSITION (SPOILER) Part Number: 600-59132-903 Serial Number: 49076	20-APR-2018 H: 6346.70 L: 2706					
27 Airframe PART #1006	ROLL/YAW TRIM PANEL Part Number: Unknown Serial Number: Unknown						
27 Airframe PART #2570	RUDDER ASSY, COMPLETE Part Number: 600-22000-1009 Serial Number: 5320	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: REMOVED SERVICEABLE FROM N611AB SN 5324. TSN: 9396.1 CSN 4784)							
27 Airframe PART #1439	RUDDER RVDT, SINGLE CHANNEL Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #777	SECONDARY GEARBOX HOUSING (HSTA) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #1798	SPOILER CONTROL LEVER Part Number: 600-90606-7 Serial Number: 458	15-OCT-1997					
27 Airframe PART #2988	STAB/MACH TRIM CONTROL PANEL ASSEMBLY Part Number: 604-51706-1 Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #567	SWITCH, ACCELERATION Part Number: Unknown Serial Number: Unknown Notes (ZONE: NOSE AVIONIC EQUIPMENT)	15-OCT-1997					
27 Airframe PART #1201	TRANSMITTER TRANSDUCER, ELEVATOR POSITION TANDEM Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
27 Airframe PART #1112	TRANSMITTER, CONTROL SURFACE POSITION (RUDDER) Part Number: 600-59191-5 Serial Number: 60492	15-OCT-1997					
27 Airframe PART #1717	UNIT, HORIZONTAL STAB TRIM CONTROL (HSTC) Part Number: 601R92301-15 Serial Number: 5727 Notes (APX COST: 0)	27-DEC-2024 H: 8606.70 L: 3964					
27 Airframe PART - Life Limited #620	UPPER - LEFT HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) PIN Part Number: 600-92384-7 Serial Number: 11-5352-A Notes (ZONE: FS855 BLO WL231 LBL3) (SOURCE: 05-10-10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)	23-MAR-2017 H: 5979.10 L: 2576	L: 7800		M: 0 H: 5979.10 L: 2576	L: 7800	L: 3798



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART - Life Limited #852	UPPER - LEFT SUPPORT, TRUNNION, HSTA ACTUATOR	23-MAR-2017	L: 20000		H: 5979.10 L: 2576	L: 20000	L: 15998
	Part Number: 601R92386-1 Serial Number: 11-5352-B						
	Notes (ZONE: WL231) (AVG MAN HRS: 31) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
27 Airframe PART - Life Limited #3003	UPPER - RIGHT HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) PIN	23-MAR-2017	L: 7800		M: 0 H: 5979.10 L: 2576	L: 7800	L: 3798
	Part Number: 600-92384-7 Serial Number: 21-5352-E						
	Notes (ZONE: FS855 BLO WL231 RBL3) (SOURCE: 05-10-10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
27 Airframe PART - Life Limited #3076	UPPER - RIGHT SUPPORT, TRUNNION, HSTA ACTUATOR	23-MAR-2017	L: 20000		H: 5979.10 L: 2576	L: 20000	L: 15998
	Part Number: 601R92386-1 Serial Number: 21-5352-F						
	Notes (ZONE: WL231) (AVG MAN HRS: 31) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
27 Airframe PART #3182	UPPER BUNGEE, LOAD LIMITER			15-OCT-1997			
	Part Number: 600-91302-53 Serial Number: 296						
	Notes (ZONE: RUDDER)						
27 Airframe PART #3680	UPPER CONVERTER SIGNAL, AOA			15-OCT-1997			
	Part Number: Unknown Serial Number: Unknown						
	Notes (ZONE: LEFT FWD FUSE)						
27 Airframe PART #923	UPPER PCU, RUDDER			15-OCT-1997			
	Part Number: 600-75101-29 Serial Number: 7282						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 Airframe PART #2294	UPPER ROD ASSY, CONTROL Part Number Unknown Serial Number Unknown	15-OCT-1997					
27 00-00-201 Airframe INSPECTION PKG 48 Month #1994	DETAILED INSPECTION OF THE AILERON, RUDDER, ELEVATOR AND SPOILER CONTROL CABLES IN THE LOWER FORWARD FUSELAGE Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
27 00-00-202 Airframe INSPECTION PKG 48 Month #276	DETAILED INSPECTION OF THE AILERON, RUDDER, ELEVATOR AND SPOILER CONTROL CABLES IN THE MAIN AVIONICS COMPARTMENT Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
27 00-00-203 Airframe INSPECTION PKG 48 Month #2634	DETAILED INSPECTION OF THE AILERON AND SPOILER CONTROL CABLES IN THE MAIN LANDING GEAR (MLG) WHEEL WELL Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
27 00-00-204 Airframe INSPECTION PKG 96 Month #1394	DETAILED INSPECTION OF THE AILERON, RUDDER, ELEVATOR AND SPOILER CONTROL CABLES IN THE MID-LOWER FUSELAGE Notes (AVG MAN HRS: 22)	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
27 00-00-205 Airframe INSPECTION PKG 96 Month #1295	DETAILED INSPECTION OF THE RUDDER AND ELEVATOR CONTROL CABLES IN THE LOWER MID-FUSELAGE COMPARTMENT Notes (AVG MAN HRS: 9)	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 00-00-206 Airframe INSPECTION PKG 24 Month #3615	DETAILED INSPECTION OF THE RUDDER AND ELEVATOR CONTROL CABLES IN THE AFT EQUIPMENT COMPARTMENT	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		31-MAY-2027	M: 11 D: 30
	Notes (AVG MAN HRS: 4.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
27 00-00-207 Airframe INSPECTION PKG 96 Month #3705	DETAILED INSPECTION OF THE ELEVATOR CONTROL CABLES IN THE VERTICAL STABILIZER	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 8)						
27 00-00-208 Airframe INSPECTION PKG 48 Month #2947	DETAILED INSPECTION OF THE RUDDER AND ELEVATOR CONTROL CABLES IN THE FUSELAGE/STABILIZER SECTION	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
27 00-00-209 Airframe INSPECTION PKG 48 Month #3507	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE OUTBOARD WING BOX	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
27 00-00-210 Airframe INSPECTION PKG 36 Month #1114	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE INBOARD TRAILING EDGE	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
	Notes (AVG MAN HRS: 2) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 00-00-211 Airframe INSPECTION PKG 36 Month #2554	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE OUTBOARD TRAILING EDGE	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
	Notes (AVG MAN HRS: 9.5) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
27 00-00-212 Airframe INSPECTION PKG 48 Month #2936	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE CONTROL COLUMN	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
27 10-00-204 Airframe INSPECTION PKG 800 Hour #1029	OPERATIONAL TEST OF THE AILERON ANTIFLOAT MECHANISM	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
27 10-00-207 Airframe INSPECTION PKG4800Hour #1779	LEFT FUNCTIONAL TEST OF THE AILERON FLUTTER DAMPERS	12-APR-2013 H: 4782.30 L: 2063	H: 4800.00	H: 40.00		H: 9595.00	H: 899.90
	Notes (AVG MAN HRS: 10)						
27 10-00-207 Airframe INSPECTION PKG4800Hour #1941	RIGHT FUNCTIONAL TEST OF THE AILERON FLUTTER DAMPERS	11-JUL-2023 H: 8075.40 L: 3647	H: 4800.00	H: 40.00		H: 9595.00	H: 899.90
	Notes (AVG MAN HRS: 10)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 13-04-101* Airframe INSPECTION #224	OPERATIONAL TEST OF THE ROLL DISCONNECT SYSTEM	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
	<p>Notes</p> <p>(AVG MAN HRS: 1.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE O</p>						
27 14-01-101** Airframe INSPECTION #2595	FUNCTIONAL TEST OF THE AILERON POWER CONTROL UNITS (PCUS)	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
	<p>Notes</p> <p>(AVG MAN HRS: 4) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)</p>						
27 15-07-101** Airframe INSPECTION #1180	LEFT DETAILED INSPECTION OF THE AILERON FLUTTER DAMPER	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
	<p>Notes</p> <p>(AVG MAN HRS: 6) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS D</p>						
27 15-07-101** Airframe INSPECTION #1909	RIGHT DETAILED INSPECTION OF THE AILERON FLUTTER DAMPER	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
	<p>Notes</p> <p>(AVG MAN HRS: 6) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS D</p>						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 20-00-201 Airframe INSPECTION PKG4800Hour #1035	GENERAL VISUAL INSPECTION OF THE SINGLE RUDDER CONTROL PATH	12-APR-2013 H: 4782.30 L: 2063	H: 4800.00	H: 40.00		H: 9595.00	H: 899.90
	Notes (AVG MAN HRS: 8)						
27 20-00-204 Airframe INSPECTION PKG4800Hour #404	FUNCTIONAL TEST OF THE LOAD LIMITER (IN VERTICAL STABILIZER) TRAVELS	12-APR-2013 H: 4782.30 L: 2063	H: 4800.00	H: 40.00		H: 9595.00	H: 899.90
	Notes (AVG MAN HRS: 3)						
27 21-00-101** Airframe INSPECTION #2714	FUNCTIONAL TEST OF THE RUDDER BACKLASH	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
	Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)						
27 21-25-201 Airframe INSPECTION PKG1600Hour #2796	GENERAL VISUAL INSPECTION OF THE RUDDER BALANCE SPRING	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
	Notes (AVG MAN HRS: 3.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)						
27 23-00-101** Airframe INSPECTION #405	OPERATIONAL TEST OF THE PCU LOAD LIMITERS	16-JUN-2018 H: 6372.80 L: 2715	H: 3200.00			H: 9572.80	H: 877.70
	Notes (AVG MAN HRS: 2.5) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 30-00-202 Airframe INSPECTION PKG1200Hour #3646	GENERAL VISUAL INSPECTION OF THE ELEVATOR POWER-CONTROL-UNIT (PCU) CENTERING -SPRING	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
	<p>Notes</p> <p>(AVG MAN HRS: 2.5) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)</p>						
27 30-00-209 Airframe INSPECTION PKG3200Hour #1896	OPERATIONAL TEST OF THE ELEVATOR JAM-TOLERANT MECHANISM	16-JUN-2018 H: 8372.80 L: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	<p>Notes</p> <p>(AVG MAN HRS: 2)</p>						
27 30-00-210 Airframe INSPECTION PKG3200Hour #1615	OPERATIONAL TEST OF THE LOAD LIMITER (VERTICAL STABILIZER)	16-JUN-2018 H: 6372.80 L: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	<p>Notes</p> <p>(AVG MAN HRS: 2)</p>						
27 31-13-102 Airframe INSPECTION #3592	RIGHT FUNCTIONAL TEST OF THE PITCH FEEL SIMULATOR	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00			H: 9525.20	H: 830.10
	<p>Notes</p> <p>(AVG MAN HRS: 2) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL.)</p>						
27 31-13-102** Airframe INSPECTION #1480	LEFT FUNCTIONAL TEST OF THE PITCH FEEL SIMULATOR	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00			H: 9525.20	H: 830.10
	<p>Notes</p> <p>(AVG MAN HRS: 2) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 32-00-101* Airframe INSPECTION #1344	OPERATIONAL TEST OF THE ELEVATOR DISCONNECT SYSTEM	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
	<p>Notes</p> <p>(AVG MAN HRS: 1) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR</p>						
27 33-01-101* Airframe INSPECTION #871	FUNCTIONAL TEST OF THE ELEVATOR BACKLASH	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
	<p>Notes</p> <p>(AVG MAN HRS: 3) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)</p>						
27 33-01-201 Airframe INSPECTION PKG4800Hour #2766	GENERAL VISUAL INSPECTION OF THE ELEVATOR BALANCE SPRINGS	12-APR-2013 H: 4782.30 L: 2063	H: 4800.00	H: 40.00		H: 9595.00	H: 899.90
	<p>Notes</p> <p>(AVG MAN HRS: 6)</p>						
27 34-04-101* Airframe INSPECTION #2690	LEFT INBOARD FUNCTIONAL TEST OF THE ELEVATOR FLUTTER DAMPERS	12-APR-2013 H: 4782.30 L: 2063	H: 4800.00			H: 9582.30	H: 887.20
	<p>Notes</p> <p>(NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 34-04-101* Airframe INSPECTION #662	LEFT OUTBOARD FUNCTIONAL TEST OF THE ELEVATOR FLUTTER DAMPERS	11-JUL-2023 H: 8075.40 L: 3647	H: 4800.00			H: 12875.40	H: 4180.30
	<p>Notes</p> <p>(UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS</p>						
27 34-04-101* Airframe INSPECTION #3417	RIGHT INBOARD FUNCTIONAL TEST OF THE ELEVATOR FLUTTER DAMPERS	02-JUL-2021 H: 6939.60 L: 3034	H: 4800.00			H: 11739.60	H: 3044.50
	<p>Notes</p> <p>(AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS</p>						
27 34-04-101* Airframe INSPECTION #3473	RIGHT OUTBOARD FUNCTIONAL TEST OF THE ELEVATOR FLUTTER DAMPERS	12-APR-2013 H: 4782.30 L: 2063	H: 4800.00			H: 9582.30	H: 887.20
	<p>Notes</p> <p>(AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS</p>						
27 34-04-102** Airframe INSPECTION #1766	LEFT INBOARD DETAILED INSPECTION OF THE ELEVATOR FLUTTER DAMPERS	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
	<p>Notes</p> <p>(AVG MAN HRS: 2.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 34-04-102** Airframe INSPECTION #3113	LEFT OUTBOARD DETAILED INSPECTION OF THE ELEVATOR FLUTTER DAMPERS	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
<p>Notes</p> <p>(AVG MAN HRS: 2.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY.</p> <p>NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS</p>							
27 34-04-102** Airframe INSPECTION #1187	RIGHT INBOARD DETAILED INSPECTION OF THE ELEVATOR FLUTTER DAMPERS	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
<p>Notes</p> <p>(AVG MAN HRS: 2.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY.</p> <p>NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS</p>							
27 34-04-102** Airframe INSPECTION #434	RIGHT OUTBOARD DETAILED INSPECTION OF THE ELEVATOR FLUTTER DAMPERS	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00			H: 8875.40	H: 180.30
<p>Notes</p> <p>(AVG MAN HRS: 2.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY.</p> <p>NOTE 16: THE INTENT OF THIS MRBR TASK IS ALSO COVERED UNDER A CMR OR A LIFE LIMIT. REFER TO TLMC SECTION 5-10-11 OR 5-10-40. AN OPERATOR WILL HAVE COMPLIED WITH THE CMR OR LIFE LIMIT AND MRBR REQUIREMENT BY COMPLETING THE TASK WITH THE MOST RESTRICTIVE INTERVAL. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS</p>							
27 35-00-201 Airframe INSPECTION PKG 800 Hour #1649	OPERATIONAL TEST FOR THE SINGLE CHANNEL OF THE STALL PROTECTION COMPUTER	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
<p>Notes</p> <p>(AVG MAN HRS: 1.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)</p>							



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 35-00-202 Airframe INSPECTION PKG 800 Hour #2309	OPERATIONAL TEST FOR THE DUAL CHANNEL OF THE STALL PROTECTION COMPUTER	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
	<p>Notes</p> <p>(AVG MAN HRS: 1.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)</p>						
27 35-01-103* Airframe INSPECTION #3345	FUNCTIONAL TEST OF THE STALL PROTECTION SYSTEM (SPS) FLAP INPUT (AIRCRAFT 5301 TO 5560 PRE SB 604-27-005)	15-APR-2005 H: 2522.30 L: 983					
	<p>Notes</p> <p>(AVG MAN HRS: 2) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 10 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)</p>						
27 35-01-104* Airframe INSPECTION #451	FUNCTIONAL TEST OF THE PHASE ADVANCE AND SIDESLIP COMPENSATION (AIRCRAFT 5301 TO 5560 PRE SB 604-27-005)	15-APR-2005 H: 2522.30 L: 983					
	<p>Notes</p> <p>(NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE O</p>						
27 35-01-105** Airframe INSPECTION #1321	FUNCTIONAL TEST FOR THE FLAP AND SIDESLIP COMPENSATION MONITOR OF THE STALL PROTECTION SYSTEM (AIRCRAFT 5561 AND SUBS AND 5301 TO 5560 POST SB 604-27-005)	12-APR-2013 H: 4782.30 L: 2063	H: 4800.00			H: 9582.30	H: 887.20
	<p>Notes</p> <p>(NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHO</p>						
27 35-04-101* Airframe INSPECTION #1776	FWD - LEFT FUNCTIONAL TEST OF THE ANGLE OF ATTACK (AOA) TRANSDUCER LINEARITY	05-JUL-2024 H: 8455.80 L: 3862	H: 300.00			H: 8755.80	H: 60.70
	<p>Notes</p> <p>(AVG MAN HRS: 5.5) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 35-04-101* Airframe INSPECTION #4	FWD - RIGHT FUNCTIONAL TEST OF THE ANGLE OF ATTACK (AOA) TRANSDUCER LINEARITY	05-JUL-2024 H: 8455.80 L: 3862	H: 300.00			H: 8755.80	H: 60.70
	Notes (AVG MAN HRS: 5.5) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
27 35-04-102* Airframe INSPECTION #557	FWD - LEFT RESTORATION OF THE ANGLE OF ATTACK (AOA) TRANSDUCER	22-DEC-2004 H: 2413.00					
	Notes (AVG MAN HRS: 2) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
27 35-04-102* Airframe INSPECTION #929	FWD - RIGHT RESTORATION OF THE ANGLE OF ATTACK (AOA) TRANSDUCER	22-DEC-2004 H: 2413.00					
	Notes (AVG MAN HRS: 2) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
27 35-10-101** Airframe INSPECTION #1518	COPILOT FUNCTIONAL TEST FOR THE STALL PROTECTION SYSTEM (SPS) STICK PUSHER CAPSTAN SHAFT, PART NO. 600-59156-7 (VENDOR PART NO. 501-1258-01)	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00			H: 9525.20	H: 830.10
	Notes (AVG MAN HRS: 1.4) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)						
27 40-00-202 Airframe INSPECTION PKG 48 Month #2126	DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TRIM-ACTUATOR ASSEMBLY	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 7) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGV194F DATED MAY 31, 2025)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 40-00-204 Airframe INSPECTION PKG 48 Month #233	LUBRICATION OF THE HORIZONTAL STABILIZER PITCH-TRIM-ACTUATOR	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
27 40-00-205 Airframe INSPECTION PKG 800 Hour #1828	OPERATIONAL TEST OF THE PITCH TRIM SWITCH	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
	<p>Notes</p> <p>(AVG MAN HRS: 1) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)</p>						
27 40-00-206 Airframe INSPECTION PKG 800 Hour #1483	OPERATIONAL TEST OF THE HORIZONTAL STABILIZER TRIM SYSTEM	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
	<p>Notes</p> <p>(AVG MAN HRS: 1) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)</p>						
27 41-00-101** Airframe INSPECTION #3388	OPERATIONAL TEST (BITE) OF THE HORIZONTAL-STABILIZER TRIM-CONTROL SYSTEM (HSTCS)	05-JUL-2024 H: 8455.80 L: 3862	H: 640.00			H: 9095.80	H: 400.70
	<p>Notes</p> <p>(AVG MAN HRS: 1.5) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY.)</p>						
27 42-01-109* Airframe INSPECTION #1203	RESTORATION (OVERHAUL) OF THE HORIZONTAL STABILIZER TRIM ACTUATOR, PART NO. 604-92305-7 AND SUBS (VENDOR PART NO. 8454-3 AND SUBS)	23-MAR-2017 H: 5979.10 L: 2576	H: 9600.00 L: 8420			H: 15105.10 L: 10711	H: 6410.00 L: 6709
	<p>Notes</p> <p>(ZONE: 326) (ACCESS: 326BT, 326CL, 326CR) (AVG MAN HRS: 31) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE: REMOVE HSTA FROM AIRCRAFT AND SEND TO VENDOR NOTE: WHEN THIS TASK IS PERFORMED, CREDIT CAN BE TAKEN FOR TASK 27-42-01-110**, TASK 27-42-01-111* AND MRB 27-40-00-202 AND THEIR TIME RESET TO ZERO. REPEAT INTERVAL FOR TASK 27-42-01-110** IS 120 M. REPEAT INTERVAL FOR TASK 27-42-01-111* IS 5000 H.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 42-01-110** Airframe INSPECTION #3353	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA), PART NO. 604-92305-7 AND SUBS (VENDOR PART NO. 8454-3 AND SUBS)	23-MAR-2017 H: 5979.10 L: 2576	M: 120			23-MAR-2027	M: 9 D: 22
	Notes (AVG MAN HRS: 31) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY.)						
27 42-01-111* Airframe INSPECTION #2779	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) SECONDARY LOAD PATH INDICATOR, PART NO. 604-92305-7 AND SUBS (VENDOR PART NO. 8454-3 AND SUBS).	31-MAY-2025 H: 8649.70 L: 3986	H: 5000.00			H: 13649.70	H: 4954.60
	Notes (ZONE: 326) (ACCESS: 326BT, 326CL, 326CR) (AVG MAN HRS: 31) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE: WHEN TASK 27-42-01-109*, VSB 8454-27-008, OR MRB 27-40-00-202 ARE PERFORMED, CREDIT CAN BE TAKEN FOR TASK 27-42-01-111* AND ITS TIME RESET TO ZERO. REPEAT INTERVAL FOR TASK 27-42-01-111* IS 5000 H.)						
27 4201-001A Airframe INSPECTION #1273	PERFORM HORIZONTAL STABILIZER TRIM ACTUATOR MAJOR OVERHAUL AND VISUAL CHECK (AWL 55-10-00-104)	23-MAR-2017 H: 5979.10 L: 2576	L: 7800			L: 10091	L: 6089
27 4201-0101 Airframe PART - Life Limited #1637	HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) Part Number Serial Number 604-92305-7 2183	23-MAR-2017 H: 5979.10 L: 2576	H: 19200.00 L: 20000		H: 474.00 L: 285	H: 24705.10 L: 22291	H: 16010.00 L: 18289
	Notes (ZONE: FS855 BL0 WL231) (AVG MAN HRS: 31) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
27 50-00-104 * Airframe INSPECTION #3597	FUNCTIONAL TEST OF THE FLAP EXTENSION AND RETRACTION (FLAP HALF-SPEED TEST).	26-FEB-2026 H: 8670.40 L: 3995	H: 400.00			H: 9070.40	H: 375.30
	Notes (SOURCE: CH 604 TLMC)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 50-00-201 Airframe INSPECTION PKG1200Hour #2242	FUNCTIONAL TEST OF THE ASYMMETRY/OVERSPEED DETECTOR AND BRAKE UNIT	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
	Notes (AVG MAN HRS: 10) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
27 50-00-202 Airframe INSPECTION PKG2400Hour #3170	LEFT NO.1 DETAILED INSPECTION OF THE FLEXIBLE DRIVE SHAFT ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 44)						
27 50-00-202 Airframe INSPECTION PKG2400Hour #1817	LEFT NO.2 DETAILED INSPECTION OF THE FLEXIBLE DRIVE SHAFT ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 44)						
27 50-00-202 Airframe INSPECTION PKG2400Hour #1308	LEFT NO.3 DETAILED INSPECTION OF THE FLEXIBLE DRIVE SHAFT ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 44)						
27 50-00-202 Airframe INSPECTION PKG2400Hour #2731	LEFT NO.4 DETAILED INSPECTION OF THE FLEXIBLE DRIVE SHAFT ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 44)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 50-00-202 Airframe INSPECTION PKG2400Hour #1521	LEFT NO.5 DETAILED INSPECTION OF THE FLEXIBLE DRIVE SHAFT ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 44)						
27 50-00-202 Airframe INSPECTION PKG2400Hour #2456	RIGHT NO.1 DETAILED INSPECTION OF THE FLEXIBLE DRIVE SHAFT ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 44)						
27 50-00-202 Airframe INSPECTION PKG2400Hour #566	RIGHT NO.2 DETAILED INSPECTION OF THE FLEXIBLE DRIVE SHAFT ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 44)						
27 50-00-202 Airframe INSPECTION PKG2400Hour #2744	RIGHT NO.3 DETAILED INSPECTION OF THE FLEXIBLE DRIVE SHAFT ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 44)						
27 50-00-202 Airframe INSPECTION PKG2400Hour #1694	RIGHT NO.4 DETAILED INSPECTION OF THE FLEXIBLE DRIVE SHAFT ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 44)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 50-00-202 Airframe INSPECTION PKG2400Hour #3018	RIGHT NO.5 DETAILED INSPECTION OF THE FLEXIBLE DRIVE SHAFT ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 44)						
27 50-00-203 Airframe INSPECTION PKG 12 Month #850	LUBRICATION OF THE BALL NUT OF THE FLAP ACTUATORS	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 11 D: 25
	Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
27 50-00-205 Airframe INSPECTION PKG 12 Month #3125	LUBRICATION OF THE FLAP VANE ACTUATOR RODS	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 11 D: 25
	Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
27 50-00-206 Airframe INSPECTION PKG 12 Month #1291	LUBRICATION OF THE BENT-UP TRAILING EDGE (BUTE) DOOR HINGE	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 11 D: 25
	Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
27 50-00-207 Airframe INSPECTION PKG 800 Hour #258	VISUAL CHECK OF THE INBOARD AND OUTBOARD FLAP ACTUATORS	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
	Notes (AVG MAN HRS: 21.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 50-00-208 Airframe INSPECTION PKG2400Hour #1270	FUNCTIONAL TEST OF THE INBOARD AND OUTBOARD FLAP ACTUATORS	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 3)						
27 51-04-101* Airframe INSPECTION #3726	FUNCTIONAL TEST OF THE FLAP CONTROL UNIT (ALL DRIVERS-ON CIRCUIT)	12-APR-2013 H: 4782.30 L: 2063	H: 4800.00			H: 9582.30	H: 887.20
	Notes (AVG MAN HRS: 5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)						
27 53-00-101** Airframe INSPECTION #2413	LEFT RESTORATION OF THE INBD (OUTER) FLAP ACTUATOR		L: 9600			L: 9600	L: 5598
	Notes (AVG MAN HRS: 8) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 50 LANDINGS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)						
27 53-00-101** Airframe INSPECTION #1560	LEFT RESTORATION OF THE OUTBOARD (OUTER) FLAP ACTUATOR		L: 9600			L: 9600	L: 5598
	Notes (AVG MAN HRS: 8) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 50 LANDINGS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
27 53-00-101** Airframe INSPECTION #2721	RIGHT RESTORATION OF THE INBD (OUTER) FLAP ACTUATOR		L: 9600			L: 9600	L: 5598
	<p>Notes</p> <p>(AVG MAN HRS: 8) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 50 LANDINGS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)</p>						
27 53-00-101** Airframe INSPECTION #3513	RIGHT RESTORATION OF THE OUTBOARD (OUTER) FLAP ACTUATOR		L: 9600			L: 9600	L: 5598
	<p>Notes</p> <p>(AVG MAN HRS: 8) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 50 LANDINGS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)</p>						
27 60-00-201 Airframe INSPECTION PKG 400 Hour #2754	LUBRICATION OF THE FLIGHT SPOILER FLEXSHAFT AND CONTROL CABLE ENDS	05-JUL-2024	H: 400.00 H: 8455.80 L: 3862	H: 40.00		H: 8875.40	H: 180.30
	<p>Notes</p> <p>(AVG MAN HRS: 1.5) (TOL. ADJUSTMENT: 19.6 HRS) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)</p>						
28 Airframe PART #653	2-WAY APU FUEL VALVE					15-OCT-1997	
	Part Number	Serial Number					
	AV16E1295-2	Unknown					
28 Airframe PART #2855	ADAPTOR, REFUELING					15-OCT-1997	
	Part Number	Serial Number					
	2770082-101	0725					
28 Airframe PART #3422	AFT SENSOR, FUEL LEVEL					15-OCT-1997	
	Part Number	Serial Number					
	601R62304-5	896					
	<p>Notes</p> <p>(ZONE: AUXILIARY TANK)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 Airframe PART #2124	AFT TANK ASSY (AUXILIARY FUEL) Part Number Unknown Serial Number Unknown	15-OCT-1997					
28 Airframe PART #3399	AFT TANK ASSY (LOWER CENTER FUSELAGE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
28 Airframe PART #3322	AFT VALVE ASSY, SHUTOFF, FUEL Part Number AV16B2177-3 Serial Number Unknown Notes (ZONE: TAIL TANK)	16-JUN-2018 H: 6372.80 L: 2715					
28 Airframe PART #2341	AFT VALVE ASSY, SHUTOFF, FUEL (TAIL TANK XFER SOV) Part Number Unknown Serial Number Unknown	15-OCT-1997					
28 Airframe PART #1891	APU CARTRIDGE, FUEL BOOST PUMP Part Number 226114-5 Serial Number 399 Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820. ALT P/N 601R62181-11)	08-FEB-2023 H: 7925.20 L: 3563					
28 Airframe PART #2806	APU PUMP ELECTRIC BOOST CANISTER Part Number Unknown Serial Number Unknown						
28 Airframe PART #667	APU SWITCH, PRESSURE (FUEL PUMP) Part Number 600-59180-3 Serial Number 1232	15-OCT-1997					
28 Airframe PART #1788	CASE ASSY Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 Airframe PART #2079	CENTER VALVE, REFUEL/DEFUEL, SHUT-OFF Part Number: 2880025-101 Serial Number: 0828 Notes (ZONE: AUXILIARY TANK)	15-OCT-1997					
28 Airframe PART #1525	CENTER VALVE, RELIEF, VENT Part Number: 2880022-102 Serial Number: 0881 Notes (ZONE: AUXILIARY TANK)	15-OCT-1997					
28 Airframe PART #2473	COCKPIT PANEL, REFUEL/DEFUEL Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #2698	COMPUTER, FUEL, QUANTITY, GAUGING Part Number: 736-847-4 Serial Number: 0241	16-JUN-2005 H: 2522.30 L: 983					
28 Airframe PART #1892	FORWARD AUXILIARY FUEL TANK LEVEL SENSOR Part Number: Unknown Serial Number: Unknown						
28 Airframe PART #973	FUEL FLOW CHECK VALVE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #1753	FWD AUXILIARY TANK-LINE FLOAT VALVE Part Number: Unknown Serial Number: Unknown						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 Airframe PART #965	FWD SENSOR, FUEL LEVEL Part Number: 601R62304-5 Serial Number: 757 Notes (ZONE: AUXILIARY TANK)	15-OCT-1997					
28 Airframe PART #3102	FWD TANK Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #2101	FWD TANK ASSY (AUXILIARY FUEL) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #1208	FWD VALVE ASSY, SHUTOFF, FUEL Part Number: AV16B2177-3 Serial Number: Unknown Notes (ZONE: TAIL TANK)	16-JUN-2018 H: 6372.80 L: 2715					
28 Airframe PART #93	FWD VALVE ASSY, SHUTOFF, FUEL (TAIL TANK XFER SOV) Part Number: 601-62900-7 Serial Number: AA101148	21-FEB-2007 H: 2928.20 L: 1171					
28 Airframe PART #3228	LEFT EJECTOR, FUEL SYSTEM (PRIMARY) Part Number: 2780602-105 Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #3180	LEFT EJECTOR, FUEL SYSTEM (SCAVANGE) Part Number: 2780472-103 Serial Number: 0687	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 Airframe PART #1283	LEFT ENGINE CARTRIDGE, FUEL BOOST PUMP Part Number: 226114-5 Serial Number: 732	08-FEB-2023 H: 7925.20 L: 3563					
Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820. ALT P/N 601R62181-11)							
28 Airframe PART #3129	LEFT INBOARD VALVE, DRAIN, FUEL (FUEL PANEL) Part Number: 2770086-103 Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #375	LEFT NO.1 PROBE, FUEL, CENTER TANK Part Number: 768-965-1 Serial Number: 152	15-OCT-1997					
28 Airframe PART #418	LEFT NO.2 PROBE, FUEL, CENTER TANK Part Number: 768-966-1 Serial Number: 163	15-OCT-1997					
28 Airframe PART #2428	LEFT NO.2 PROBE, FUEL, MAIN WING TANK Part Number: 768-960-1 Serial Number: 197	15-OCT-1997					
28 Airframe PART #820	LEFT NO.3 PROBE, FUEL, MAIN WING TANK Part Number: 768-961-1 Serial Number: 203	15-OCT-1997					
28 Airframe PART #2759	LEFT NO.4 PROBE, FUEL, MAIN WING TANK Part Number: 768-962-2 Serial Number: 210	15-OCT-1997					
28 Airframe PART #3100	LEFT NO.5 PROBE, FUEL, MAIN WING TANK Part Number: 768-963-1 Serial Number: 201	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 Airframe PART #1716	LEFT NO.6 PROBE, FUEL, MAIN WING TANK Part Number: 768-964-1 Serial Number: 196	15-OCT-1997					
28 Airframe PART #3119	LEFT OUTBOARD VALVE, DRAIN, FUEL (FUEL PANEL) Part Number: 2770086-103 Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #828	LEFT PROBE, FUEL, MAIN WING TANK Part Number: 768-959-1 Serial Number: 222	15-OCT-1997					
28 Airframe PART #1011	LEFT PUMP ASSY, TRANSFER Part Number: 229672 Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #1927	LEFT PUMP, EJECTOR, TRANSFER Part Number: 2780473-105 Serial Number: 0961	15-OCT-1997					
28 Airframe PART #2436	LEFT SENSOR, FUEL LEVEL (HIGH LEVEL) Part Number: 601R62304-5 Serial Number: 6271	05-AUG-2011 H: 4291.30 L: 1846					
28 Airframe PART #1584	LEFT SWITCH, DIFFERENTIAL PRESS (SCAVENGE EJECTOR) Part Number: D15S3 Serial Number: 1159	15-OCT-1997					
28 Airframe PART #165	LEFT SWITCH, PRESSURE (MAIN EJECTOR) Part Number: 601R62291-1 Serial Number: V25751	15-OCT-1997					
28 Airframe PART #1138	LEFT SWITCH, PRESSURE, ELECT BOOST PUMP Part Number: 601R62291-3 Serial Number: V18505	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 Airframe PART #606	LEFT TAIL TANK FUEL PRESSURE SWITCH Part Number: 604-62149-1 Serial Number: V21458	15-OCT-1997					
28 Airframe PART #3204	LEFT TAIL TANK TRANSFER PRESSURE SWITCH Part Number: Unknown Serial Number: Unknown Notes (ZONE: TAIL TANK)	15-OCT-1997					
28 Airframe PART #805	LEFT VALVE ASSY, SHUTOFF FUEL (ENGINE FIREWALL) Part Number: 601-62900-7 Serial Number: AA463346	08-FEB-2023 H: 7925.20 L: 3563					
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)						
28 Airframe PART #1250	LEFT VALVE, CHECK Part Number: 601R62296-5 Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #1317	LEFT VALVE, CHECK, FUEL (MOTIVE FLOW) Part Number: 869A8TB Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #515	LEFT VALVE, FUEL TRANSFER SHUTOFF Part Number: 2810007-101 Serial Number: 852	15-OCT-1997					
28 Airframe PART #2178	LEFT VALVE, REFUEL/DEFUEL, SHUT-OFF Part Number: 2880025-101 Serial Number: 0824 Notes (ZONE: MAIN TANK)	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 Airframe PART #1428	LEFT VALVE, RELIEF, VENT Part Number 2880022-101 Serial Number 0758	15-OCT-1997					
28 Airframe PART #2117	LEFT VALVE, SHUTOFF, MOTORIZED Part Number Unknown Serial Number Unknown	15-OCT-1997					
28 Airframe PART #2162	LOWER SENSOR, LEVEL, FUEL SYSTEM Part Number 601R62304-3 Serial Number 0234 Notes (ZONE: TAIL TANK - MANIFOLD)	15-OCT-1997					
28 Airframe PART #2904	NO.1 CANNISTER, FUEL BOOST PUMP Part Number 226115-2 Serial Number Unknown Notes (ZONE: AUXILIARY TANK)	15-OCT-1997					
28 Airframe PART #3152	NO.1 CENTER AND MAIN FUEL TANKS LEVEL SENSOR Part Number 722-610 Serial Number 6729	31-MAR-2012 H: 4512.00 L: 1932					
28 Airframe PART #3249	NO.2 CANNISTER, FUEL BOOST PUMP Part Number 226115-2 Serial Number 754 Notes (ZONE: WING - RIGHT (APU)) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)	08-FEB-2023 H: 7925.20 L: 3563					
28 Airframe PART #2888	NO.3 CANNISTER, FUEL BOOST PUMP Part Number Unknown Serial Number Unknown Notes (ZONE: WING - RIGHT)	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 Airframe PART #1595	PANEL, REFUEL/DEFUEL (INSIDE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
Notes (NOTE: (CUSTOMER OPTION FOR A/C 5331 TO 5990) (REF CMM:28-25-17))							
28 Airframe PART #2805	PUMP. EJECTOR, REFUEL TANK (FORWARD AUXILIARY TANK) Part Number Unknown Serial Number Unknown	15-OCT-1997					
28 Airframe PART #1662	RIGHT EJECTOR, FUEL SYSTEM (PRIMARY) Part Number 2780602-105 Serial Number Unknown	15-OCT-1997					
28 Airframe PART #1163	RIGHT EJECTOR, FUEL SYSTEM (SCAVANGE) Part Number 2780472-103 Serial Number 0702	15-OCT-1997					
28 Airframe PART #3271	RIGHT ENGINE CARTRIDGE, FUEL BOOST PUMP Part Number 226114-5 Serial Number 1295	08-FEB-2023 H: 7925.20 L: 3563					
Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820. ALT P/N 601R62181-11)							
28 Airframe PART #758	RIGHT NO.2 PROBE, FUEL, MAIN WING TANK Part Number 768-960-1 Serial Number 202	15-OCT-1997					
28 Airframe PART #2064	RIGHT NO.3 PROBE, FUEL, CENTER TANK Part Number 768-967-1 Serial Number Unknown	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 Airframe PART #584	RIGHT NO.3 PROBE, FUEL, MAIN WING TANK Part Number: 768-961-1 Serial Number: 212	15-OCT-1997					
28 Airframe PART #755	RIGHT NO.4 PROBE, FUEL, MAIN WING TANK Part Number: 768-962-2 Serial Number: 213	15-OCT-1997					
28 Airframe PART #2344	RIGHT NO.5 PROBE, FUEL, MAIN WING TANK Part Number: 768-963-1 Serial Number: 205	15-OCT-1997					
28 Airframe PART #3013	RIGHT NO.6 PROBE, FUEL, MAIN WING TANK Part Number: 768-964-1 Serial Number: 198	15-OCT-1997					
28 Airframe PART #2218	RIGHT PROBE, FUEL, MAIN WING TANK Part Number: 768-959-1 Serial Number: 228	15-OCT-1997					
28 Airframe PART #1972	RIGHT PUMP ASSY, TRANSFER Part Number: 229672 Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #2127	RIGHT PUMP, EJECTOR, TRANSFER Part Number: 2780473-105 Serial Number: 0965	15-OCT-1997					
28 Airframe PART #3605	RIGHT SENSOR, FUEL LEVEL (HIGH LEVEL) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #2387	RIGHT SWITCH, DIFFERENTIAL PRESS (SCAVENGE EJECTOR) Part Number: D15S3 Serial Number: 1160	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 Airframe PART #1223	RIGHT SWITCH, PRESSURE (MAIN EJECTOR) Part Number: 601R62291-1 Serial Number: V25758	15-OCT-1997					
28 Airframe PART #1565	RIGHT SWITCH, PRESSURE, ELECT BOOST PUMP Part Number: 601R62291-3 Serial Number: V26125	15-OCT-1997					
28 Airframe PART #951	RIGHT TAIL TANK FUEL PRESSURE SWITCH Part Number: 604-62149-1 Serial Number: V21443	15-OCT-1997					
28 Airframe PART #1125	RIGHT TAIL TANK TRANSFER PRESSURE SWITCH Part Number: Unknown Serial Number: Unknown Notes (ZONE: TAIL TANK)	15-OCT-1997					
28 Airframe PART #913	RIGHT VALVE ASSY, SHUTOFF FUEL (ENGINE FIREWALL) Part Number: 601-62900-8 Serial Number: AA50289	16-DEC-2016 H: 5906.90 L: 2555					
28 Airframe PART #365	RIGHT VALVE, CHECK Part Number: 601R62296-5 Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #598	RIGHT VALVE, CHECK, FUEL (MOTIVE FLOW) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #2982	RIGHT VALVE, DRAIN, FUEL (FUEL PANEL) Part Number: 2770086-103 Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 Airframe PART #391	RIGHT VALVE, FUEL TRANSFER SHUTOFF Part Number: 2810007-101 Serial Number: 854	15-OCT-1997					
28 Airframe PART #296	RIGHT VALVE, REFUEL/DEFUEL, SHUT-OFF Part Number: 2880025-101 Serial Number: 0826 Notes (ZONE: MAIN TANK)	15-OCT-1997					
28 Airframe PART #3504	RIGHT VALVE, RELIEF, VENT Part Number: 2880022-101 Serial Number: 0761	15-OCT-1997					
28 Airframe PART #639	RIGHT VALVE, SHUTOFF, MOTORIZED Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #1012	SENSOR, FUEL LEVEL (HIGH LEVEL) Part Number: 722-610 Serial Number: 7565 Notes (ZONE: TAIL TANK)	16-JAN-2014 H: 5036.00 L: 2179					
28 Airframe PART #1285	SENSOR, FUEL TEMPERATURE Part Number: 601R62452-1 Serial Number: 0147 Notes (ZONE: WING - LEFT)	15-OCT-1997					
28 Airframe PART #2175	SWITCH, PRESSURE (ROTOR - BURST PROTECTION PRESS) Part Number: 12543-3 Serial Number: Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 Airframe PART #3721	TAIL TANK PROBE, FUEL Part Number: 768-969-1 Serial Number: Unknown	15-OCT-1997					
28 Airframe PART #301	UPPER SENSOR, LEVEL, FUEL SYSTEM Part Number: 601R62304-3 Serial Number: 0240 Notes (ZONE: TAIL TANK)	15-OCT-1997					
28 Airframe PART #772	VALVE, 2-WAY, FUEL SYSTEM (NEGATIVE-G SHUTOFF) Part Number: AV16E1295-2 Serial Number: AA364437 Notes (ZONE: APU)	08-AUG-2019 H: 6476.10 L: 2770					
28 Airframe PART #214	VALVE, CHECK, REFUEL/DEFUEL Part Number: 2780481-102 Serial Number: 1683	15-OCT-1997					
28 Airframe PART #1016	VALVE, RELIEF Part Number: Unknown Serial Number: Unknown Notes (ZONE: TAIL TANK)	15-OCT-1997					
28 Airframe PART #916	VALVE, SHUT-OFF (APU FUEL FEED) Part Number: AV16B2178-2 Serial Number: RP85432	15-OCT-1997					
28 Airframe PART #1938	VALVE, SHUT-OFF, FUEL (TAIL TANK DUMP) Part Number: AV16B2178-2 Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 Airframe PART #2072	VALVE, SHUTOFF, MOTORIZED (GRAVITY XFLOW SOV / AUX TANK) Part Number: AV16B2082-3 Serial Number: Unknown	15-OCT-1997					
28 10-00-201 Airframe INSPECTION PKG 600 Hour #2854	GENERAL VISUAL INSPECTION OF THE FUEL ACCESS PANELS Notes (AVG MAN HRS: 1.5) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
28 10-00-202 Airframe INSPECTION PKG 600 Hour #2355	GENERAL VISUAL INSPECTION OF THE FUEL DRAIN VALVES Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
28 10-00-203 Airframe INSPECTION PKG 600 Hour #678	GENERAL VISUAL INSPECTION OF THE WATER DRAIN VALVES Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
28 10-00-204 Airframe INSPECTION PKG 600 Hour #2210	GENERAL VISUAL INSPECTION OF THE FUEL TANK EXTERIOR Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
28 10-00-205 Airframe INSPECTION PKG 600 Hour #649	GENERAL VISUAL INSPECTION OF THE SADDLE TANK DRAIN Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 10-00-206 Airframe INSPECTION PKG 600 Hour #676	GENERAL VISUAL INSPECTION OF THE GRAVITY FILLER CAP	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
28 10-00-207 Airframe INSPECTION PKG 96 Month #1770	FUNCTIONAL TEST OF THE VENT LINE SHROUDS	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3.5)						
28 10-00-208 Airframe INSPECTION PKG 96 Month #1417	FUNCTIONAL TEST OF THE MOTIVE-FLOW LINE SHROUDS	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 5)						
28 10-00-209 Airframe INSPECTION PKG 96 Month #2455	FUNCTIONAL TEST OF THE FUEL-FEED LINE SHROUDS	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 35)						
28 10-00-210 Airframe INSPECTION PKG 96 Month #807	FUNCTIONAL TEST OF THE FORWARD AND AFT AUXILIARY TANKS – INTERSPACE AND FUEL TRANSFER LINE SHROUDS	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 10.5)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 10-00-213 Airframe INSPECTION PKG 600 Hour #1443	VISUAL CHECK OF THE VENT AND DISTRIBUTION SHROUD DRAINS FOR BLOCKAGE AND LEAKAGE	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	<p>Notes</p> <p>(AVG MAN HRS: 1) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)</p>						
28 15-00-201 Airframe INSPECTION PKG1600Hour #2376	FUNCTIONAL TEST OF THE ROTOR-BURST PROTECTION PRESSURE-SWITCH	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
	<p>Notes</p> <p>(AVG MAN HRS: 1.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)</p>						
28 15-00-202 Airframe INSPECTION PKG1600Hour #3340	OPERATIONAL TEST OF THE TAIL-TANK TRANSFER SHUTOFF-VALVE	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
	<p>Notes</p> <p>(AVG MAN HRS: 2.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)</p>						
28 15-00-203 Airframe INSPECTION PKG1600Hour #2954	OPERATIONAL TEST OF THE TAIL-TANK SECONDARY TRANSFER-PUMP	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
	<p>Notes</p> <p>(AVG MAN HRS: 3) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)</p>						
28 15-43-101** Airframe INSPECTION #2498	FUNCTIONAL TEST OF THE TAIL TANK RESTRICTOR		H: 15000.00			H: 15000.00	H: 6304.90
	<p>Notes</p> <p>(AVG MAN HRS: 8) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 50 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 20-00-201 APU INSPECTION 050018 #7	DISCARD OF THE FUEL-FEED LINE FILTER OF THE AUXILIARY POWER UNIT (APU)	03-JAN-2023 H: 9642.00	H: 800.00	H: 40.00		H: 10442.00	H: 135.00
28 20-00-202 Airframe INSPECTION PKG 96 Month #411	OPERATIONAL TEST OF THE COLLECTOR-TANK CHECK VALVE	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2.5)						
28 21-13-201 Airframe INSPECTION PKG 600 Hour #932	LEFT OPERATIONAL TEST OF THE ENGINE-FIREWALL FUEL SHUTOFF-VALVE	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 1.5) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
28 21-13-201 Airframe INSPECTION PKG 600 Hour #1463	RIGHT OPERATIONAL TEST OF THE ENGINE-FIREWALL FUEL SHUTOFF-VALVE	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 1.5) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
28 21-13-202 Engine 1 INSPECTION PKG1200Hour #592	OPERATIONAL TEST OF THE ENGINE-FIREWALL FUEL SHUTOFF-VALVE FOR LEAKS	08-FEB-2023 H: 7925.20 C: 3564	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
	Notes (AVG MAN HRS: 10) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)						
28 21-13-202 Engine 2 INSPECTION PKG1200Hour #98	OPERATIONAL TEST OF THE ENGINE-FIREWALL FUEL SHUTOFF-VALVE FOR LEAKS	08-FEB-2023 H: 7925.20 C: 3564	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
	Notes (AVG MAN HRS: 10) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
28 24-00-101* Airframe INSPECTION #333	OPERATIONAL TEST OF THE AUXILIARY POWER UNIT (APU) FUEL FEED SHUTOFF-VALVE AND NEGATIVE-G SHUTOFF-VALVE FOR INTERNAL LEAKS.	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00			H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 5.5) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)						
28 31-00-201 Airframe INSPECTION PKG1200Hour #2887	OPERATIONAL TEST OF THE DUMP VALVE	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
29 Airframe PART #3253	ACCUMULATOR, NO.3 HYDRAULIC SYSTEM Part Number 2770571-105 Serial Number 1760A	22-JUL-2010 H: 3912.80 L: 1666					
	Notes (AVG MAN HRS: 4.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
29 Airframe PART #163	INBOARD GAUGE, AIR PRESSURE INDICATING (BRAKE ACCUMULATOR) Part Number G4227 Serial Number Unknown	15-OCT-1997					
29 Airframe PART #1369	LEFT ACCUMULATOR, NO.1 HYDRAULIC SYSTEM Part Number 2770571-103 Serial Number 1735A	15-OCT-1997					
	Notes (ZONE: AFT BAY) (AVG MAN HRS: 5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE: THIS TASK IS ONLY APPLICABLE TO ACCUMULATORS IDENTIFIED WITH "TNAE" AFTER THE SERIAL NUMBER.)						
29 Airframe PART #3574	LEFT ELECTRICAL ACTUATOR Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 Airframe PART #1810	LEFT FILTER, CASE DRAIN ASSY (SYSTEM NO.3A PUMP) Part Number AC7031-8Y181 Serial Number Unknown	15-OCT-1997					
29 Airframe PART #3464	LEFT PUMP, HYDRAULIC (ENGINE DRIVEN PUMP) Part Number 601R75113-5 Serial Number MX677321	28-MAR-2018			H: 6319.00 L: 2697		
29 Airframe PART #1778	LEFT VALVE, SHUT OFF (FIREWALL) Part Number 601R75151-7 Serial Number 21328	14-JUL-2004			H: 2246.20 L: 857		
29 Airframe PART #940	NO. 2 CASE DRAIN FILTER HYDRAULIC SYSTEM Part Number Unknown Serial Number Unknown						
29 Airframe PART #219	NO.1 (UPPER) GAUGE, AIR PRESSURE INDICATING (HYDRAULIC SYSTEM ACCUMULATOR) Part Number G4227 Serial Number Unknown	15-OCT-1997					
29 Airframe PART #1154	NO.1 BALL ASSY, ATTENUATOR (HYDRAULIC SYSTEM) Part Number 601R75155-1 Serial Number MX582126	15-OCT-1997					
29 Airframe PART #644	NO.1 CASE DRAIN FILTER Part Number 600-75114-3 Serial Number 1692	15-OCT-1997					
29 Airframe PART #1404	NO.1 CASE DRAIN VALVE Part Number 601R75119-1 Serial Number Unknown	15-OCT-1997					
29 Airframe PART #145	NO.1 FILTER, HYDRAULIC MANIFOLD (HYDRAULIC SYSTEM) Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 Airframe PART #950	NO.1 MANIFOLD, HYDRAULIC RETURN (HYDRAULIC SYSTEM) Part Number 600-75117-1 Serial Number 2239	15-OCT-1997					
29 Airframe PART #613	NO.1 PRESSURE - HYDRAULIC SYSTEM MANIFOLD Part Number ADA686-30 Serial Number Unknown	15-OCT-1997					
29 Airframe PART #1555	NO.1 PUMP, ELECTRIC MOTOR DRIVEN (HYDRAULIC SYSTEM) Part Number 601R75154-7 Serial Number MX584000	15-OCT-1997					
29 Airframe PART #949	NO.1 RESERVOIR ASSY, HYDRAULIC SYSTEM Part Number 600-75112-21 Serial Number 051	15-OCT-1997					
29 Airframe PART #56	NO.1 TRANSDUCER, PRESSURE (HYDRAULIC SYSTEM) Part Number 600-59174-17 Serial Number 5799-1-263	15-OCT-1997					
29 Airframe PART #3603	NO.1 TRANSDUCER, TEMPERATURE (HYDRAULIC SYSTEM) Part Number 601R75127-1 Serial Number V0416	15-OCT-1997					
29 Airframe PART #1884	NO.1 VALVE, PRESSURE RELIEF (HYDRAULIC SYSTEM) Part Number 601R75158-1 Serial Number 815	15-OCT-1997					
29 Airframe PART #784	NO.1A FILTER, CASE DRAIN ASSY (HYDRAULIC SYSTEM) Part Number 600-75114-3 Serial Number 1663	15-OCT-1997					
29 Airframe PART #3280	NO.1A SWITCH, HYDRAULIC, PRESSURE (HYDRAULIC SYSTEM) Part Number 1206P0169 Serial Number Unknown	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 Airframe PART #670	NO.1B FILTER, CASE DRAIN ASSY (HYDRAULIC SYSTEM) Part Number: 600-75114-3 Serial Number: Unknown	15-OCT-1997					
29 Airframe PART #2430	NO.1B SWITCH, HYDRAULIC, PRESSURE (HYDRAULIC SYSTEM) Part Number: 1206P0169 Serial Number: Unknown	15-OCT-1997					
29 Airframe PART #2263	NO.2 (LOWER) GAUGE, AIR PRESSURE INDICATING (HYDRAULIC SYSTEM ACCUMULATOR) Part Number: G4227 Serial Number: Unknown	15-OCT-1997					
29 Airframe PART #2711	NO.2 BALL ASSY, ATTENUATOR (HYDRAULIC SYSTEM) Part Number: 601R75155-1 Serial Number: MX582125	15-OCT-1997					
29 Airframe PART #171	NO.2 CASE DRAIN FILTER Part Number: 600-75114-3 Serial Number: 1671	15-OCT-1997					
29 Airframe PART #2882	NO.2 CASE DRAIN VALVE Part Number: 601R75119-1 Serial Number: Unknown	15-OCT-1997					
29 Airframe PART #449	NO.2 FILTER, HYDRAULIC MANIFOLD (HYDRAULIC SYSTEM) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
29 Airframe PART #2265	NO.2 MANIFOLD, HYDRAULIC RETURN (HYDRAULIC SYSTEM) Part Number: 600-75117-1 Serial Number: 2198	15-OCT-1997					
29 Airframe PART #1398	NO.2 PRESSURE - HYDRAULIC SYSTEM MANIFOLD Part Number: ADA686-30 Serial Number: Unknown	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 Airframe PART #208	NO.2 PUMP, ELECTRIC MOTOR DRIVEN (HYDRAULIC SYSTEM) Part Number: 601R75154-7 Serial Number: MX581660	15-OCT-1997					
29 Airframe PART #2699	NO.2 RESERVOIR,FUSELAGE,REAR (HYDRAULIC SYSTEM) Part Number: 601R75120-3 Serial Number: 148	15-OCT-1997					
29 Airframe PART #422	NO.2 TRANSDUCER, PRESSURE (HYDRAULIC SYSTEM) Part Number: 600-59174-17 Serial Number: 5799-1-166	15-OCT-1997					
29 Airframe PART #3026	NO.2 TRANSDUCER, TEMPERATURE (HYDRAULIC SYSTEM) Part Number: 601R75127-1 Serial Number: U0339	15-OCT-1997					
29 Airframe PART #2585	NO.2 VALVE, PRESSURE RELIEF (HYDRAULIC SYSTEM) Part Number: 601R75158-1 Serial Number: 830	15-OCT-1997					
29 Airframe PART #195	NO.2A FILTER, CASE DRAIN ASSY (HYDRAULIC SYSTEM) Part Number: AC-7031F-8 Serial Number: NA	09-FEB-2017 H: 5969.40 L: 2571					
29 Airframe PART #2547	NO.2A SWITCH, HYDRAULIC, PRESSURE (HYDRAULIC SYSTEM) Part Number: 600-59134-1 Serial Number: 6353	23-JUL-2010 H: 3912.80 L: 1666					
29 Airframe PART #1617	NO.2B FILTER, CASE DRAIN ASSY (HYDRAULIC SYSTEM) Part Number: 600-75114-3 Serial Number: Unknown	15-OCT-1997					
29 Airframe PART #3005	NO.2B SWITCH, HYDRAULIC, PRESSURE (HYDRAULIC SYSTEM) Part Number: 1206P0169 Serial Number: Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 Airframe PART #848	NO.3 FILTER, HYDRAULIC MANIFOLD (HYDRAULIC SYSTEM) Part Number: ADA686-30 Serial Number: Unknown	15-OCT-1997					
29 Airframe PART #1462	NO.3 GAUGE, AIR PRESSURE INDICATING (HYDRAULIC SYSTEM ACCUMULATOR) Part Number: G4227 Serial Number: Unknown	15-OCT-1997					
29 Airframe PART #269	NO.3 MANIFOLD, HYDRAULIC RETURN (HYDRAULIC SYSTEM) Part Number: 600-75117-1 Serial Number: 2012	15-OCT-1997					
29 Airframe PART #631	NO.3 MANIFOLD, PRESSURE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
29 Airframe PART #1389	NO.3 RESERVOIR QUANTITY INDICATOR Part Number: 9416-4 Serial Number: 2699	14-FEB-2023 H: 7929.00 L: 3567					
<p>Notes</p> <p>(APX COST: 0) (UPDATE NOTE: REMOVED #3 HYDRAULIC INDICATOR P/N: 9416-4, S/N: 397. INSTALLED NEW INDICATOR P/N: 9416-4, S/N: 2699. SYSTEM OPS CHECKS GOOD. IAW CL604 AMM 29-32-01.)</p>							
29 Airframe PART #3161	NO.3 RESERVOIR, BOOTSTRAP, HYDRAULIC SYSTEM Part Number: 7303-1 Serial Number: 407A	02-MAY-2005 H: 2522.30 L: 983					
29 Airframe PART #1503	NO.3 TRANSDUCER, PRESSURE (HYDRAULIC SYSTEM) Part Number: 600-59174-17 Serial Number: 5799-1-274	15-OCT-1997					
29 Airframe PART #2238	NO.3 TRANSDUCER, TEMPERATURE (HYDRAULIC SYSTEM) Part Number: 601R75127-1 Serial Number: V0313	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 Airframe PART #732	NO.3 VALVE, PRESSURE RELIEF (HYDRAULIC SYSTEM) Part Number Unknown Serial Number Unknown	15-OCT-1997					
29 Airframe PART #3440	NO.3 VALVE, PRESSURE RELIEF (HYDRAULIC SYSTEM) (RESERVOIR) Part Number Unknown Serial Number Unknown	15-OCT-1997					
29 Airframe PART #742	NO.3A BALL ASSY, ATTENUATOR (HYDRAULIC SYSTEM) Part Number 601R75155-1 Serial Number MX571730	15-OCT-1997					
29 Airframe PART #2110	NO.3A PUMP, ELECTRIC MOTOR DRIVEN (HYDRAULIC SYSTEM) Part Number 601R75154-7 Serial Number MX680741	21-AUG-2023 H: 8098.80 L: 3663					
	<p>Notes</p> <p>(APX COST: 0) (UPDATE NOTE: REMOVED AND REPLACED 3A HYDRAULIC PUMP ASSY WITH OVERHAULED UNIT REF CHALLENGER 604 AMM 29-13-01. OPS CHECK AND LEAK CHECK PASSED. P/N OFF/ON: 601R75154-7 S/N ON: MX680741 S/N OFF MX582698. PUMP ELECTRIC MOTOR OVERHAULED BY "NIACC-AVITECH TECHNOLOGIES CRS DC3R444L UNDER WO#5800729134 FORM TRACKING NUMBER 482619 8130 DATED 08/08/23. WORK ACCOMPLISHED BY DIRECT MX AVIATION KSDL UNDER WORK ORDER SDL230480 SEE MAINTENANCE LOG ENTRY DATED 08-21-2023 FOR DETAILS.)</p>						
29 Airframe PART #2849	NO.3A SWITCH, HYDRAULIC, PRESSURE (HYDRAULIC SYSTEM) Part Number 600-59134-1 Serial Number 9056	08-AUG-2024 H: 8505.70 L: 3893					
	<p>Notes</p> <p>(APX COST: 0) (UPDATE NOTE: REMOVED #3 LOWER PRESSURE SWITCH P/N 1206P0169 S/N 2394 AND INSTALLED NEW PRESSURE SWITCH P/N 1206P0169 S/N 9056 IAW BOMBARDIER CL 604 AMM 29-34-01. OPERATIONAL TEST PASSED NO OTHER DEFECTS NOTED AT THIS TIME. THIS CLEARS AMDL 41552.)</p>						
29 Airframe PART #1386	NO.3B BALL ASSY, ATTENUATOR (HYDRAULIC SYSTEM) Part Number 601R75155-1 Serial Number MX560586	15-OCT-1997					
29 Airframe PART #2383	NO.3B PUMP, ELECTRIC MOTOR DRIVEN (HYDRAULIC SYSTEM) Part Number 601R75154-7 Serial Number MX583989	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 Airframe PART #2499	NO.3B SWITCH, HYDRAULIC, PRESSURE (HYDRAULIC SYSTEM) Part Number: 1206P0169 Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: MLG BAY)						
29 Airframe PART #1374	OUTBOARD GAUGE, AIR PRESSURE INDICATING (BRAKE ACCUMULATOR) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
29 Airframe PART #1381	RIGHT ACCUMULATOR, NO.2 HYDRAULIC SYSTEM Part Number: 2770571-103 Serial Number: 1737A	15-OCT-1997					
	Notes (ZONE: AFT BAY) (AVG MAN HRS: 5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE: THIS TASK IS ONLY APPLICABLE TO ACCUMULATORS IDENTIFIED WITH "TNAE" AFTER THE SERIAL NUMBER.)						
29 Airframe PART #2565	RIGHT ELECTRICAL ACTUATOR Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
29 Airframe PART #1550	RIGHT FILTER, CASE DRAIN ASSY (SYSTEM NO.3B PUMP) Part Number: AC7031-8Y181 Serial Number: Unknown	15-OCT-1997					
29 Airframe PART #35	RIGHT PUMP, HYDRAULIC (ENGINE DRIVEN PUMP) Part Number: 601R75113-3 Serial Number: MX582156A	15-OCT-1997					
29 Airframe PART #2780	RIGHT VALVE, SHUT OFF (FIREWALL) Part Number: 601R75151-3 Serial Number: 20613	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
29 10-00-201 Airframe INSPECTION PKG 600 Hour #2811	VISUAL CHECK OF THE FILTER DIFFERENTIAL-PRESSURE INDICATOR	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
<p>Notes</p> <p>(AVG MAN HRS: 5.5) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)</p>							
29 11-00-301 Airframe INSPECTION PKG 24 Month #2672	FUNCTIONAL TEST (ACIDITY INSPECTION) OF THE HYDRAULIC FLUID (SYSTEM NO. 1 AND NO. 2).	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		31-MAY-2027	M: 11 D: 30
<p>Notes</p> <p>(ZONE: 311312) (ACCESS: 311BB) (AVG MAN HRS: 2) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>							
29 11-52-201 Airframe INSPECTION PKG 600 Hour #220	LEFT OPERATIONAL TEST OF THE HYDRAULIC FIREWALL SHUTOFF-VALVE	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
<p>Notes</p> <p>(AVG MAN HRS: 2) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)</p>							
29 11-52-201 Airframe INSPECTION PKG 600 Hour #789	RIGHT OPERATIONAL TEST OF THE HYDRAULIC FIREWALL SHUTOFF-VALVE	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
<p>Notes</p> <p>(AVG MAN HRS: 2) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)</p>							
29 12-00-301 Airframe INSPECTION PKG 24 Month #2326	FUNCTIONAL TEST (ACIDITY INSPECTION) OF THE HYDRAULIC FLUID (SYSTEM NO. 3).	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		31-MAY-2027	M: 11 D: 30
<p>Notes</p> <p>(ZONE: 163164) (ACCESS: 192AR) (AVG MAN HRS: 1.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>							
30 Airframe PART #1859	AFT CONTROLLER, ANTI-ICE (FUSELAGE)					15-OCT-1997	
	Part Number	Serial Number					
	624382-2	047C0471					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 Airframe PART #3128	HEATER BLANKET, 120W (WATER TANK) Part Number: Unknown Serial Number: Unknown Notes (ZONE: BAGGAGE BAY)	15-OCT-1997					
30 Airframe PART #2285	LEFT ANTI-ICE CHECK VALVE Part Number: 3202232-1 Serial Number: Unknown	15-OCT-1997					
30 Airframe PART #1142	LEFT CONTROLLER, AIR DATA SENSOR Part Number: 604-59007-1 Serial Number: 120 Notes (ZONE: AVIONIC BAY)	15-OCT-1997					
30 Airframe PART #2800	LEFT COUPLING Part Number: 601-80026-5 Serial Number: Unknown	15-OCT-1997					
30 Airframe PART #1680	LEFT COUPLING ASSY (WING ANTI-ICE) Part Number: 601-80033-1 Serial Number: J86256	15-OCT-1997					
30 Airframe PART #223	LEFT COWL ANTI-ICE PRESSURE SWITCH Part Number: 12681 Serial Number: 1571	15-OCT-1997					
30 Airframe PART #1504	LEFT DETECTOR, ICE (FWD FUSELAGE) Part Number: 871BN3-8 Serial Number: 3895	15-OCT-1997					
30 Airframe PART #1319	LEFT DUCT ASSY (I/R FLEX SHAFT) Part Number: 228-56041-101 Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 Airframe PART #247	LEFT DUCT ASSY (WING CENTER) Part Number Unknown Serial Number Unknown	15-OCT-1997					
30 Airframe PART #1747	LEFT DUCT ASSY, (MID FUSELAGE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
30 Airframe PART #1086	LEFT INBOARD SENSOR, TEMPERATURE, WING (L/E) Part Number 624384-2 Serial Number Unknown	15-OCT-1997					
30 Airframe PART #572	LEFT NO.1 DUCT ASSY, (WING) Part Number Unknown Serial Number Unknown	15-OCT-1997					
30 Airframe PART #855	LEFT NO.2 DUCT ASSY, (WING) Part Number Unknown Serial Number Unknown	15-OCT-1997					
30 Airframe PART #425	LEFT NO.3 DUCT ASSY, (WING) Part Number Unknown Serial Number Unknown	15-OCT-1997					
30 Airframe PART #3671	LEFT NO.4 DUCT ASSY, (WING) Part Number Unknown Serial Number Unknown	15-OCT-1997					
30 Airframe PART #3413	LEFT NO.5 DUCT ASSY, (WING) Part Number Unknown Serial Number Unknown	15-OCT-1997					
30 Airframe PART #3577	LEFT OUTBOARD SENSOR, TEMPERATURE, WING (L/E) Part Number 624384-2 Serial Number Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 Airframe PART #3212	LEFT OVER PRESSURE RELIEF VALVE Part Number: 228-56480-109 Serial Number: Unknown	15-OCT-1997					
30 Airframe PART #2354	LEFT SWITCH, PRESSURE (14TH STAGE DUCT) Part Number: 642000-211 Serial Number: 4598	28-SEP-2010 H: 3976.30 L: 1697					
30 Airframe PART #1361	LEFT TEMPERATURE CONTROL UNIT ASSEMBLY (WINDSHIELD & SIDE WINDOW) Part Number: 600-59100-9 Serial Number: 918	02-MAR-2022 H: 7455.90 L: 3316					
	<p>Notes</p> <p>(UPDATE NOTE: REMOVED LEFT TEMPERATURE CONTROLLER ASSEMBLY, P/N 600-59100-9 S/N 921A, AND INSTALLED SERVICEABLE UNIT FROM RIGHT SIDE, P/N 600-59100-9 S/N 918. REMOVED RIGHT TEMPERATURE CONTROLLER ASSEMBLY, P/N 600-59100-9 S/N 918, AND INSTALLED SERVICEABLE UNIT FROM LEFT SIDE, P/N 600-59100-9 S/N 921A, IAW CL604 AMM REVISION 94 TASK 30-41-01-400-801. OPERATIONAL TEST SATISFACTORY.)</p>						
30 Airframe PART #698	LEFT TEMPERATURE SIDE WINDOW CONTROL Part Number: Unknown Serial Number: Unknown						
30 Airframe PART #3082	LEFT TEMPERATURE WINDSHIELD CONTROL Part Number: Unknown Serial Number: Unknown						
30 Airframe PART #205	LEFT VALVE, COWL, ANTI-ICE (I/R FLEX SHAFT) Part Number: 300013000-003 Serial Number: 0117	08-OCT-2012 H: 4677.30 L: 2009					
30 Airframe PART #2292	LEFT WING ANTI-ICE CONTROL AND INDICATING SYSTEM - THERMAL SWITCH Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
30 Airframe PART #3010	RIGHT ANTI-ICE CHECK VALVE Part Number: 3202232-1 Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 Airframe PART #362	RIGHT CONTROLLER, AIR DATA SENSOR Part Number 604-59007-1 Serial Number 108 Notes (ZONE: AVIONIC BAY)	15-OCT-1997					
30 Airframe PART #1989	RIGHT COUPLING Part Number 601-80026-5 Serial Number Unknown	15-OCT-1997					
30 Airframe PART #874	RIGHT COUPLING ASSY (WING ANTI-ICE) Part Number 601-80033-2 Serial Number J78919	15-OCT-1997					
30 Airframe PART #3485	RIGHT COWL ANTI-ICE PRESSURE SWITCH Part Number 12681 Serial Number 1558	15-OCT-1997					
30 Airframe PART #2956	RIGHT DETECTOR, ICE (FWD FUSELAGE) Part Number 871BN3-8 Serial Number 3894	15-OCT-1997					
30 Airframe PART #110	RIGHT DUCT ASSY (I/R FLEX SHAFT) Part Number 228-56041-101 Serial Number Unknown	15-OCT-1997					
30 Airframe PART #2306	RIGHT DUCT ASSY (WING CENTER) Part Number Unknown Serial Number Unknown	15-OCT-1997					
30 Airframe PART #3207	RIGHT DUCT ASSY, (MID FUSELAGE) Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 Airframe PART #2995	RIGHT INBOARD SENSOR, TEMPERATURE, WING (L/E) Part Number: 624384-2 Serial Number: Unknown	15-OCT-1997					
30 Airframe PART #3673	RIGHT NO.1 DUCT ASSY, (WING) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
30 Airframe PART #2074	RIGHT NO.2 DUCT ASSY, (WING) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
30 Airframe PART #166	RIGHT NO.3 DUCT ASSY, (WING) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
30 Airframe PART #1275	RIGHT NO.4 DUCT ASSY, (WING) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
30 Airframe PART #379	RIGHT NO.5 DUCT ASSY, (WING) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
30 Airframe PART #500	RIGHT OUTBOARD SENSOR, TEMPERATURE, WING (L/E) Part Number: 624384-2 Serial Number: Unknown	15-OCT-1997					
30 Airframe PART #1978	RIGHT OVER PRESSURE RELIEF VALVE Part Number: 228-56480-801 Serial Number: 2043	25-MAR-2004 H: 2086.40 L: 789					
30 Airframe PART #3412	RIGHT SWITCH, PRESSURE (14TH STAGE DUCT) Part Number: 642000-2 Serial Number: 1217	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 Airframe PART #2876	RIGHT TEMPERATURE CONTROL UNIT ASSEMBLY (WINDSHIELD & SIDE WINDOW) Part Number: 600-59100-9 Serial Number: 591A	07-MAR-2022 H: 7466.40 L: 3321					
	Notes (APX COST: 3,000) (UPDATE NOTE: REMOVED RIGHT DUAL CHANNEL TEMPERATURE CONTROLLER, P/N 600-59100-9 S/N 921A, WITH SIDE WINDOW TEMPERATURE CONTROLLER, P/N 600-59100-13 S/N 1793A, AND WINDSHIELD TEMPERATURE CONTROLLER, P/N 600-59100-11 S/N 684A, AND INSTALLED INSPECTED DUAL CHANNEL TEMPERATURE CONTROL ASSEMBLY, P/N 600-59100-9 S/N 591A, WITH SIDE WINDOW TEMPERATURE CONTROLLER, P/N 600-59100-13 S/N 1103A, AND WINDSHIELD TEMPERATURE CONTROLLER, P/N 600-59100-11 S/N 1095A. WORK ACCOMPLISHED IAW CL604 AMM REVISION 94 TASK 30-41-01-400-801. OPERATIONAL CHECK SATISFACTORY. CONTROLLER INSPECTED BY AVIATION MANAGEMENT GROUP, INC., CRS VUXR007X, SEE WORK ORDER 10046049 FORM TRACKING NUMBER 23008 DATED						
30 Airframe PART #137	RIGHT TEMPERATURE SIDE WINDOW CONTROL Part Number: 600-59100-13 Serial Number: 1103A	07-MAR-2022 H: 7466.40 L: 3321					
	Notes (UPDATE NOTE: REMOVED RIGHT DUAL CHANNEL TEMPERATURE CONTROLLER, P/N 600-59100-9 S/N 921A, WITH SIDE WINDOW TEMPERATURE CONTROLLER, P/N 600-59100-13 S/N 1793A, AND WINDSHIELD TEMPERATURE CONTROLLER, P/N 600-59100-11 S/N 684A, AND INSTALLED INSPECTED DUAL CHANNEL TEMPERATURE CONTROL ASSEMBLY, P/N 600-59100-9 S/N 591A, WITH SIDE WINDOW TEMPERATURE CONTROLLER, P/N 600-59100-13 S/N 1103A, AND WINDSHIELD TEMPERATURE CONTROLLER, P/N 600-59100-11 S/N 1095A. WORK ACCOMPLISHED IAW CL604 AMM REVISION 94 TASK 30-41-01-400-801. OPERATIONAL CHECK SATISFACTORY. CONTROLLER INSPECTED BY AVIATION MANAGEMENT GROUP, INC., CRS VUXR007X, SEE WORK ORDER 10046049 FORM TRACKING NUMBER 23008 DATED 20-APR-2021 FOR DE						
30 Airframe PART #348	RIGHT TEMPERATURE WINDSHIELD CONTROL Part Number: 600-59100-11 Serial Number: 1095A	07-MAR-2022 H: 7466.40 L: 3321					
	Notes (UPDATE NOTE: REMOVED RIGHT DUAL CHANNEL TEMPERATURE CONTROLLER, P/N 600-59100-9 S/N 921A, WITH SIDE WINDOW TEMPERATURE CONTROLLER, P/N 600-59100-13 S/N 1793A, AND WINDSHIELD TEMPERATURE CONTROLLER, P/N 600-59100-11 S/N 684A, AND INSTALLED INSPECTED DUAL CHANNEL TEMPERATURE CONTROL ASSEMBLY, P/N 600-59100-9 S/N 591A, WITH SIDE WINDOW TEMPERATURE CONTROLLER, P/N 600-59100-13 S/N 1103A, AND WINDSHIELD TEMPERATURE CONTROLLER, P/N 600-59100-11 S/N 1095A. WORK ACCOMPLISHED IAW CL604 AMM REVISION 94 TASK 30-41-01-400-801. OPERATIONAL CHECK SATISFACTORY. CONTROLLER INSPECTED BY AVIATION MANAGEMENT GROUP, INC., CRS VUXR007X, SEE WORK ORDER 10046049 FORM TRACKING NUMBER 23008 DATED 20-APR-2021 FOR DE						
30 Airframe PART #1247	RIGHT VALVE, COWL, ANTI-ICE (I/R FLEX SHAFT) Part Number: 601-97097-9 Serial Number: 2184	08-OCT-2012 H: 4677.30 L: 2009					
30 Airframe PART #129	RIGHT WING ANTI-ICE CONTROL AND INDICATING SYSTEM - THERMAL SWITCH Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 10-00-201 Airframe INSPECTION PKG2400Hour #910	FUNCTIONAL TEST OF THE SENSOR DETECTION CIRCUIT	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 1)						
30 11-00-101** Airframe INSPECTION #1446	DETAILED INSPECTION OF THE WING ANTI-ICE DUCT PICCOLO-TUBE	12-APR-2013 H: 4782.30 L: 2063	H: 6400.00			H: 11182.30	H: 2487.20
	Notes (AVG MAN HRS: 80) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. CONSIDERATION SHOULD BE GIVEN TO ACCOMPLISHING THIS TASK IN CONJUNCTION WITH TASK 57-10-00-208 WHICH REQUIRES THE REMOVAL OF THE WING LEADING EDGE.						
30 12-00-102** Airframe INSPECTION #2135	FUNCTIONAL TEST OF THE LOW TEMPERATURE GROUND WING ANTI-ICE (LTGWAIS) OVERHEAT CIRCUIT						
	Notes (AVG MAN HRS: 4) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY.)						
30 22-00-101* Airframe INSPECTION #712	OPERATIONAL TEST OF THE COWL ANTI-ICE FAILURE INDICATION						
	Notes (AVG MAN HRS: 1) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
30 40-00-201 Airframe INSPECTION PKG 600 Hour #2095	LEFT FUNCTIONAL TEST OF THE WINDSHIELD RAIN REPELLENT LAYER	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.) (NOTE: THIS TASK APPLIES TO SULLY GLASS FACEPLY WINDSHIELDS, PART NO. 270-462-00-XX AND SIERRACIN GLASS FACEPLY WINDSHIELDS, PART NO. 158700-57 AND SUBS)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
30 40-00-201 Airframe INSPECTION PKG 600 Hour #983	RIGHT FUNCTIONAL TEST OF THE WINDSHIELD RAIN REPELLENT LAYER	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9157.60	H: 462.50
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.) (NOTE: THIS TASK APPLIES TO SULLY GLASS FACEPLY WINDSHIELDS, PART NO. 270-462-00-XX AND SIERRACIN GLASS FACEPLY WINDSHIELDS, PART NO. 158700-57 AND SUBS)						
30 40-00-301 Airframe INSPECTION PKG 12 Month #1593	DETAILED INSPECTION OF THE WINDSHIELD/SIDE WINDOW AERODYNAMIC SEAL.	26-MAY-2026 H: 8686.90 L: 3999	M: 12 H: 600.00	M: 1 H: 40.00		26-MAY-2027 H: 9286.90	M: 11 D: 25 H: 591.80
	Notes (ZONE: 220) (AVG MAN HRS: 1) (APX COST: 353.88) (TOL. ADJUSTMENT: -34D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
30 81-00-201 Airframe INSPECTION PKG1200Hour #3292	OPERATIONAL TEST OF THE ICE DETECTION SYSTEM	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
31 Airframe PART #62	AFT RECORDER, FLIGHT DATA (FDR)					15-OCT-1997	
	Part Number S800-2000-00	Serial Number Unknown					
	Notes (ZONE: FS770)						
31 Airframe PART #3373	BEACON, ACCOUSTIC, UNDERWATER LOCATOR (FDR)					15-OCT-1997	
	Part Number DK120	Serial Number Unknown					
31 Airframe PART #1997	CIRCUIT BREAKER PANEL PLASTIC					15-OCT-1997	
	Part Number Unknown	Serial Number Unknown					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 Airframe PART #161	COCKPIT LAMP, UNIT, DRIVER, LDU-4000 (SIDE CONSOLE) Part Number: 622-9822-001 Serial Number: Unknown	15-OCT-1997					
31 Airframe PART #3066	ELECTRONIC CONTROL FORCE MEASURING UNIT (ECU) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
31 Airframe PART #2040	GPS DIGITAL CLOCK Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
31 Airframe PART #2189	LEFT ACCELEROMETER, TRIAXIAL Part Number: 3001-01-111 Serial Number: 0117-DT9792F	11-JUL-2023 H: 8075.40 L: 3647					
	Notes (ZONE: MLG BAY) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
31 Airframe PART #2281	LEFT CLOCK, DIGITAL Part Number: M877-5 Serial Number: 26142	19-DEC-2023 H: 8207.00 L: 3719					
	Notes (APX COST: 0) (UPDATE NOTE: REMOVED PILOTS DAVTRON DIGITAL CLOCK P/N M877-5 S/N 14441. INSTALLED NEW DIGITAL CLOCK P/N M877-5 S/N 26142. SYSTEM OPERATIONAL CHECK GOOD IAW CL 604 AMM 31-21-01.)						
31 Airframe PART #352	LEFT DCU-4002, DATA CONCENTRATOR UNIT (DCU 1) Part Number: 822-0179-014 Serial Number: 280	06-APR-2022 H: 7470.80 L: 3326					
31 Airframe PART #2871	LEFT NO.1 LIGHT DIMMER POWER SUPPLY UNIT Part Number: LH10B Serial Number: 870	15-OCT-1997					
31 Airframe PART #2378	LEFT NO.2 LIGHT DIMMER POWER SUPPLY UNIT Part Number: LH10B Serial Number: 906	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 Airframe PART #2451	NO.1 EFD-4077, ELECTRONIC FLIGHT DISPLAY (PFD) Part Number: 622-9978-314 Serial Number: 1MFXT	11-AUG-2023 H: 8088.50 L: 3658					
	Notes (ZONE: PFD - PILOT) (APX COST: 0) (UPDATE NOTE: REMOVED #1 PILOT PRIMARY FLIGHT DISPLAY (PFD) P/N 622-9978-314 S/N 1918 AND INSTALLED REPAIRED PRIMARY FLIGHT DISPLAY P/N 622-9978-314 S/N 1MFXT IAW BOMBARDIER CL 604 AMM 31-61-01. OPERATIONAL CHECK PASSED. FLIGHT DISPLAY UNIT REPAIRED BY ROCKWELL COLLINS FORM TRACKING NUMBER 106258318 WORK ORDER 5800717804 CRS ED7Y210Y DATED 21/JUL/2023.)						
31 Airframe PART #2858	NO.1 MOUNT, FLIGHT DISPLAY Part Number: 822-0826-001 Serial Number: Unknown	15-OCT-1997					
31 Airframe PART #2134	NO.2 EFD-4077, ELECTRONIC FLIGHT DISPLAY (MFD) Part Number: 622-9978-314 Serial Number: 1920	28-JUL-2005 H: 2522.30 L: 983					
	Notes (ZONE: MFD - PILOT)						
31 Airframe PART #2658	NO.2 MOUNT, FLIGHT DISPLAY Part Number: 822-0826-001 Serial Number: Unknown	15-OCT-1997					
31 Airframe PART #2702	NO.3 EFD-4077, ELECTRONIC FLIGHT DISPLAY (EICAS) Part Number: 622-9978-314 Serial Number: 1096	27-SEP-2017 H: 6177.60 L: 2644					
	Notes (ZONE: EICAS - PILOT)						
31 Airframe PART #1411	NO.3 MOUNT, FLIGHT DISPLAY Part Number: 822-0826-001 Serial Number: Unknown	15-OCT-1997					
31 Airframe PART #1070	NO.4 EFD-4077, ELECTRONIC FLIGHT DISPLAY (EICAS)) Part Number: 622-9978-314 Serial Number: 2251B	27-SEP-2017 H: 6177.60 L: 2644					
	Notes (ZONE: EICAS - COPILOT)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 Airframe PART #3698	NO.5 EFD-4077, ELECTRONIC FLIGHT DISPLAY (MFD) Part Number: 622-9978-314 Serial Number: 1984	20-SEP-2017 H: 6177.30 L: 2643					
	Notes (ZONE: MFD - COPILOT)						
31 Airframe PART #3692	NO.6 EFD-4077, ELECTRONIC FLIGHT DISPLAY (PFD) Part Number: 622-9978-314 Serial Number: 12FH Y	02-OCT-2020 H: 6640.10 L: 2878					
	Notes (ZONE: PFD - COPILOT) (APX COST: 0) (UPDATE NOTE: REMOVED COPILOT PFD (#6) ELECTRONIC FLIGHT DISPLAY, P/N 622-9978-314 S/N 2640, AND INSTALLED REPAIRED ELECTRONIC FLIGHT DISPLAY, P/N 622-9978-314 S/N 12FH Y, IAW CL 604 AMM REV. 89 TASK 31-61-01-400-802. OPERATIONAL CHECK SATISFACTORY. INSTALLED DISPLAY UNIT REPAIRED BY ROCKWELL COLLINS CRS ED7Y210Y, SEE WORK ORDER 5800628030 FORM TRACKING NUMBER 105931292 FOR DETAILS.)						
31 Airframe PART #3270	PANEL, EICAS CONTROL (ECP4003) Part Number: 822-0180-002 Serial Number: 411	25-AUG-2022 H: 7715.60 L: 3455					
	Notes (APX COST: 0) (UPDATE NOTE: REMOVED EICAS CONTROL PANEL, P/N 822-0180-002 S/N 510, AND INSTALLED REPAIRED EICAS CONTROL PANEL, P/N 822-0180-022 S/N 411, IAW CL604 AMM REVISION 96 TASK 31-41-01-400-801. OPERATIONAL CHECK SATISFACTORY. PANEL REPAIRED BY ROCKWELL COLLINS, INC. CRS NZ2R049L, SEE FAA FORM 8130-3 TRACKING NUMBER 106135846 UNDER WORK ORDER 5800683996 DATED 25-APR-2022 FOR DETAILS.)						
31 Airframe PART #286	POWER SUPPLY - LIGHT DIMMER UNIT Part Number: LH10B Serial Number: 6529	16-JUN-2018 H: 6372.80 L: 2715					
31 Airframe PART #43	RDC-4002, REMOTE DATA CONCENTRATOR (RIGHT KIDNEY) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: FWD FUSE)						
31 Airframe PART #2180	RIGHT CLOCK, DIGITAL Part Number: 811BLB Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 Airframe PART #1995	RIGHT DCU-4002, DATA CONCENTRATOR UNIT (DCU 2) Part Number: 822-0179-014 Serial Number: 390	06-APR-2022 H: 7470.80 L: 3326					
31 Airframe PART - Expiration #2228	UNDERWATER LOCATING DEVICE (ULD) BATTERY (FDR) Part Number: DK120/90 Serial Number: AT231676	29-OCT-2025 H: 8656.00 L: 3990				31-OCT-2032	M: 76 D: 30
Notes (AVG MAN HRS: 1.5) (APX COST: 0) (UPDATE NOTE: WORK ACCOMPLISHED BY DIRECT MX CRS # FMSR378E DATED 10/29/2025 SEE WORK ORDER # CRS250482.) (NOTE: NOTE 14: DISCARD AT THE MANUFACTURER'S EXPIRATION DATE.)							
31 2101-001A Airframe INSPECTION #2334	LEFT REPLACE NO. 1 DIGITAL CLOCK BATTERIES (AA)	17-DEC-2025 H: 8670.40 L: 3995	M: 12			17-DEC-2026	M: 6 D: 16
Notes (AVG MAN HRS: 1.5) (UPDATE NOTE: COMPLIED WITH REPLACEMENT OF NO.1 DAVTRON DIGITAL CLOCK BATTERY IAW CL604 AMM CH 31-21-01. OPS CHECK GOOD.)							
31 2101-002A Airframe INSPECTION #1683	RIGHT REPLACE NO. 2 DIGITAL CLOCK BATTERIES (AA)	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
31 31-00-202 Airframe INSPECTION #3443	OPERATIONAL TEST OF THE DIGITAL FLIGHT DATA RECORDER (FDR) UNDERWATER LOCATING DEVICE (ULD)	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 11 D: 30
Notes (MANUAL ADJUSTMENT: 0D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: NOTE 3: TASK AND INTERVAL MAY BE PART OF THE OPERATOR'S NATIONAL REGULATIONS. WHENEVER A TASK HAS TWO INTERVALS, ONE BEING NOTE 3", THE GREATER INTERVAL IS RECOMMENDED. WHEN A NATIONAL REGULATION DOES NOT EXIST, THE MRB REPORT INTERVAL SHALL BE FOLLOWED.)							
31 31-00-203 Airframe INSPECTION #785	FUNCTIONAL TEST OF THE FLIGHT DATA RECORDER (FDR) DEDICATED SENSORS (A/C 5463 AND SUBS, POST SB 604-31-010)						
Notes (AVG MAN HRS: 15.5)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
31 31-00-204 Airframe INSPECTION #2732	FUNCTIONAL TEST OF THE FLIGHT DATA RECORDER (FDR) FORCE SENSORS (A/C 5551 AND SUBS, POST SB 604-31-014)						
	Notes (AVG MAN HRS: 15.5)						
31 41-00-201 Airframe INSPECTION PKG 600 Hour #3512	OPERATIONAL TEST OF THE DATA CONCENTRATOR UNIT (DCU) MASTER WARNING/MASTER CAUTION SIGNALS	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 2) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
31 41-04-201 Airframe INSPECTION PKG4800Hour #1107	OPERATIONAL TEST OF THE DATA CONCENTRATOR UNIT (DCU) OUTPUT BUS	12-APR-2013 H: 4782.30 L: 2063	H: 4800.00	H: 40.00		H: 9595.00	H: 899.90
	Notes (AVG MAN HRS: 1)						
31 41-04-202 Airframe INSPECTION PKG2400Hour #3632	FUNCTIONAL TEST OF THE DATA CONCENTRATOR UNIT (DCU) AURAL WARNING	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 5)						
31 61-01-201 Airframe INSPECTION PKG 400 Hour #3294	CLEANING/RESTORATION OF THE ELECTRONIC FLIGHT DISPLAY (EFD) INLET COOLING SCREEN	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00	H: 40.00		H: 8875.40	H: 180.30
	Notes (AVG MAN HRS: 2) (TOL. ADJUSTMENT: 19.6 HRS) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)						
32 Airframe PART #193	ACTUATOR ASSY, NLG EXTENTION/RETRACTION	14-MAR-2025 H: 8631.50 L: 3977					
	Part Number 104471003	Serial Number DCL420/98					
	Notes (UPDATE NOTE: COMPLIED WITH BY DIRECT MX AVIATION CRS FMSR378E ON WORK ORDER CRS250047 DATED 14 MARCH 2025)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #2479	ACTUATOR, HYD NLG DOOR MECH Part Number: 1081100-3 Serial Number: HAI1887	11-JUL-2023					
	Notes (ZONE: NLG BAY) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
32 Airframe PART #705	AFT VALVE, NLG STEERING SELECTOR Part Number: 150446002 Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #1444	BODY-STEERING MECHANISM NLG Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #2860	COMPENSATOR ASSY, NLG STEERING Part Number: 104480001 Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: BRAKE BAY)						
32 Airframe PART #2463	CONTROL ASSY, PARKING BRAKE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #2898	CONTROL UNIT, ANTI-SKID Part Number: 604-87000-9 Serial Number: 155	25-JAN-2007					
	Notes (ZONE: AVIONIC BAY)						
32 Airframe PART #221	CONTROL UNIT, PROXIMITY SENSOR Part Number: 8-848-07 Serial Number: 0116	04-JAN-2004					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #2204	COPILOT - LEFT CABLE ASSY, COPILOT BRAKE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #1051	COPILOT - RIGHT CABLE ASSY, COPILOT BRAKE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #3490	COPILOT POTENTIOMETER, STEERING, NOSEWHEEL (RUDDER SYSTEM) Part Number: 601-86100-13 Serial Number: 97-473	15-OCT-1997					
32 Airframe PART #2508	CUFF S/A STEERING NLG Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #1879	DOOR ASSY, AFT Part Number: Unknown Serial Number: Unknown Notes (ZONE: NLG BAY)	15-OCT-1997					
32 Airframe PART - Life Limited #2749	FITTING, NOSE LANDING GEAR ASSY (MAIN FITTING) Part Number: 20090-101 Serial Number: DCL010 Notes (AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)	13-APR-2013 H: 4782.30 L: 2063	L: 19480		L: 2063	L: 19480	L: 15478
32 Airframe PART #1850	FWD VALVE, NLG STEERING SELECTOR Part Number: 150446002 Serial Number: Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #1652	GEAR ASSY, NOSE LANDING Part Number: 20020-103 Serial Number: DCL-053/97	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: OVERHAULED BY SAFRAN LANDING SYSTEMS CANADA INC. CRS 41-89 UNDER FORM TRACKING NUMBER RO-31364 DATED 31 MAY 2021. CSN 3034)							
32 Airframe PART #3586	HAND CONTROL, STEERING, NOSEWHEEL (HAND WHEEL) Part Number: 601-86100-21 Serial Number: DCL098/86/97	15-OCT-1997					
32 Airframe PART #3601	HANDLE ASSY, LANDING, GEAR, CTRL Part Number: 601R50967-5 Serial Number: 591A	15-APR-2004 H: 2094.00 L: 796					
32 Airframe PART #2219	HARNESS, STEERING (NLG SHOCK STRUT ASSY) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #1294	INBOARD TRANSDUCER, PRESSURE (UPPER BRAKE) Part Number: 600-59174-17 Serial Number: 5799-1-269	15-OCT-1997					
32 Airframe PART #147	LEFT ACTUATOR ASSY, SIDE STAY, MLG Part Number: 19011-107 Serial Number: 00363A	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)							
32 Airframe PART #3624	LEFT ACTUATOR, DOWNLOCK ASSIST Part Number: 600-85001-87 Serial Number: DCL813-97	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART - Life Limited #972	LEFT AXLE, MAIN LANDING GEAR Part Number: 19050-3 Serial Number: 11SPP0016 4	02-JUL-2021 H: 6939.60 L: 3034	L: 19250		L: 1301	L: 20983	L: 16981
Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
32 Airframe PART #59	LEFT CAP, ROD END Part Number: Unknown Serial Number: Unknown		15-OCT-1997				
32 Airframe PART - Life Limited #759	LEFT CYLINDER, MLG SIDE STAY Part Number: 17027-9 Serial Number: 3222C	02-JUL-2021 H: 6939.60 L: 3034	L: 43890		L: 0	L: 46924	L: 42922
Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
32 Airframe PART - Life Limited #2318	LEFT CYLINDER, MLG, SHOCK STRUT Part Number: 19104-1 Serial Number: DCL201	02-JUL-2021 H: 6939.60 L: 3034	L: 19250		M: 285 H: 6939.60 L: 3034	L: 19250	L: 15248
Notes (AVG MAN HRS: 20) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
32 Airframe PART #969	LEFT DOOR ASSY, MLG Part Number: Unknown Serial Number: Unknown		15-OCT-1997				
32 Airframe PART #2073	LEFT DOOR ASSY, NLG FORWARD Part Number: Unknown Serial Number: Unknown		15-OCT-1997				



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART - Life Limited #3613	LEFT FITTING ASSY, MAIN Part Number 19062-1 Serial Number DCL-065	13-APR-2013 H: 4782.30 L: 2063	L: 19250		M: 186 H: 4782.30 L: 2063	L: 19250	L: 15248
Notes (AVG MAN HRS: 10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NHA19064-103/-105)							
32 Airframe PART #2801	LEFT HARNESS ASSY, (NOSE GEAR BAY) Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #2457	LEFT HARNESS, WOW SENSOR #1 (NLG SHOCK STRUT ASSY) Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #2771	LEFT INBOARD BRAKE ASSY Part Number 5012333 Serial Number MAR06-1593	04-APR-2023 H: 7999.50 L: 3609					
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: REF DIRECTMX AVIATION LBE/WO SDL230220 DATED 20230404, VAN NGUYEN A&P 39499. BRAKE OVERHAULED BY "MEGGITT AIRCRAFT BRAKING SYSTEMS KY CORP 120 CORPORATE DR, DANVILL KY 40422. CRS# 8DRR699C. UNDER WO#: 5800717863)							
32 Airframe PART #2304	LEFT INBOARD FUSE, VOLUMETRIC, HYDRAULIC Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #2 Main W #104	LEFT INBOARD TIRE, MLG WHEEL Part Number 027-697-0 Serial Number 4132P05029	06-DEC-2024 H: 8600.30 L: 3958					
Notes (APX COST: 0) (UPDATE NOTE: REMOVED LEFT INBOARD WHEEL ASSEMBLY P/N 5012373 S/N MAY12-3695 WITH WORN TIRE P/N 027-697-0 S/N 1216P05046 AND INSTALLED OVERHAULED WHEEL ASSEMBLY P/N 5012373 S/N MAR04-1810 WITH NEW TIRE H27X825-14/16/210 P/N 027-697-0 S/N 4132P05029 BUILD UP ASSEMBLY. SERVICED TO MAX PRESSURE WITH NITROGEN. IAW BOMBARDIER CL 604 AMM 32-41-01 REF 8130-3. #200573194 BOEING DISTRIBUTION INC. 674 MADISON ST., CROWN POINT IN 46307 MFG CERT AAC# LQ5R024N DATED 21OCT24 AND CLEARS AMDL 41573)							



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #3047	LEFT INBOARD TRANSDUCER, PRESSURE (BRAKE) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #2687	LEFT INBOARD TRANSDUCER, WHEEL SPEED Part Number: 604-87000-1 Serial Number: 330	15-OCT-1997					
32 Airframe PART #2661	LEFT INBOARD WHEEL ASSY, MLG Part Number: 5012373 Serial Number: MAR04-1810	06-DEC-2024 H: 8600.30 L: 3958					
	<p>Notes</p> <p>(AVG MAN HRS: 3) (APX COST: 4,592) (UPDATE NOTE: REMOVED LEFT INBOARD WHEEL ASSEMBLY P/N 5012373 S/N MAY12-3695 WITH WORN TIRE P/N 027-697-0 S/N 1216P05046 AND INSTALLED OVERHAULED WHEEL ASSEMBLY P/N 5012373 S/N MAR04-1810 WITH NEW TIRE H27X825-14/16/210 P/N 027-697-0 S/N 4132P05029 BUILD UP ASSEMBLY. SERVICED TO MAX PRESSURE WITH NITROGEN. IAW BOMBARDIER CL 604 AMM 32-41-01 REF 8130-3. #200573194 BOEING DISTRIBUTION INC. 674 MADISON ST., CROWN POINT IN 46307 MFG CERT AAC# LQ5R024N DATED 21OCT24 AND CLEARS AMDL 41573)</p>						
32 Airframe PART #2226	LEFT MAIN GEAR HYDRAULIC SWIVEL COUPLING ASSY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART - Life Limited #3554	LEFT MAIN LANDING GEAR (MLG) TRAILING ARM Part Number: 19084-103 Serial Number: DCL150	02-JUL-2021 H: 6939.60 L: 3034	L: 36430		H: 6939.60 L: 3034	L: 36430	L: 32428
	<p>Notes</p> <p>(AVG MAN HRS: 5) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
32 Airframe PART #570	LEFT MAIN LANDING GEAR ASSY, DRESSED Part Number: 19090-105 Serial Number: DCL057/97	02-JUL-2021 H: 6939.60 L: 3034					
	<p>Notes</p> <p>(UPDATE NOTE: OVERHAULED BY SAFRAN LANDING SYSTEMS CANADA INC. APPROVED ORGANIZATION NUMBER 41-89 UNDER FORM TRACKING NUMBER RO-31370 DATED 01 JUN 2021. CSN 3034)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #511	LEFT N/W DISC HARNESS SUB ASSY Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #3505	LEFT NO.1 MAIN LANDING GEAR (MLG) SIDE STAY ACTUATOR, LOCK SEGMENT Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #2908	LEFT NO.2 MAIN LANDING GEAR (MLG) SIDE STAY ACTUATOR, LOCK SEGMENT Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #3719	LEFT NO.3 MAIN LANDING GEAR (MLG) SIDE STAY ACTUATOR, LOCK SEGMENT Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #2848	LEFT NO.4 MAIN LANDING GEAR (MLG) SIDE STAY ACTUATOR, LOCK SEGMENT Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #1910	LEFT OUTBOARD BRAKE ASSY Part Number 5012333 Serial Number FEB09-2067	04-APR-2023 H: 7999.50 L: 3609					
	<p>Notes</p> <p>(AVG MAN HRS: 0.5) (UPDATE NOTE: REF DIRECTMX AVIATION LBE/WO SDL230220 DATED 20230404, VAN NGUYEN A&P 39499. BRAKE OVERHAULED BY "MEGGITT AIRCRAFT BRAKING SYSTEMS KY CORP 120 CORPORATE DR, DANVIL KY 40422. CRS# 8DRR699C. UNDER WO#: 5800716229)</p>						
32 Airframe PART #2681	LEFT OUTBOARD FUSE, VOLUMETRIC, HYDRAULIC Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #1 Main W #1422	LEFT OUTBOARD TIRE, MLG WHEEL Part Number: 027-697-0 Serial Number: 3313P05163	06-DEC-2024 H: 8600.30 L: 3958					
Notes (APX COST: 0) (UPDATE NOTE: REMOVED LEFT OUTBOARD WHEEL ASSEMBLY P/N 5012373 S/N JAN95-0027 WITH WORN TIRE P/N 027-697-0 S/N 3181P05167 AND INSTALLED OVERHAULED WHEEL ASSEMBLY P/N 5012373 S/N MAR01-1344 WITH NEW TIRE H27X825-14/16/210 P/N 027-697-0 S/N 3313P05163 BUILD UP ASSEMBLY. SERVICED TO MAX PRESSURE WITH NITROGEN. IAW BOMBARDIER CL 604 AMM 32-41-01 REF 8130-3. #200567951 BOEING DISTRIBUTION INC. 674 MADISON ST., CROWN POINT IN 46307 MFG CERT AAC# LQ5R024N DATED 10SEP24 AND CLEARS AMDL 41572)							
32 Airframe PART #2609	LEFT OUTBOARD TRANSDUCER, PRESSURE (BRAKE) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #3550	LEFT OUTBOARD TRANSDUCER, WHEEL SPEED Part Number: 604-87000-1 Serial Number: 329	15-OCT-1997					
32 Airframe PART #3636	LEFT OUTBOARD WHEEL ASSY, MLG Part Number: 5012373 Serial Number: MAR01-1344	06-DEC-2024 H: 8600.30 L: 3958					
Notes (APX COST: 4,592) (UPDATE NOTE: REMOVED LEFT OUTBOARD WHEEL ASSEMBLY P/N 5012373 S/N JAN95-0027 WITH WORN TIRE P/N 027-697-0 S/N 3181P05167 AND INSTALLED OVERHAULED WHEEL ASSEMBLY P/N 5012373 S/N MAR01-1344 WITH NEW TIRE H27X825-14/16/210 P/N 027-697-0 S/N 3313P05163 BUILD UP ASSEMBLY. SERVICED TO MAX PRESSURE WITH NITROGEN. IAW BOMBARDIER CL 604 AMM 32-41-01 REF 8130-3. #200567951 BOEING DISTRIBUTION INC. 674 MADISON ST., CROWN POINT IN 46307 MFG CERT AAC# LQ5R024N DATED 10SEP24 AND CLEARS AMDL 41572)							
32 Airframe PART - Life Limited #1612	LEFT PIN ASSY, MLG SIDE STAY Part Number: 6350-3 Serial Number: DCL903	02-JUL-2021 H: 6939.60 L: 3034	L: 19250		L: 3034	L: 19250	L: 15248
Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining					
32 Airframe PART - Life Limited #2815	LEFT PIN, MLG, SHOCK STRUT LOWER (TO TRAILING ARM)	02-JUL-2021	L: 19250		L: 3034	L: 19250	L: 15248					
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> <td>H: 6939.60</td> <td>L: 3034</td> </tr> <tr> <td>19146-3</td> <td>1-5352/05</td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number	H: 6939.60	L: 3034	19146-3	1-5352/05					
Part Number	Serial Number	H: 6939.60	L: 3034									
19146-3	1-5352/05											
	Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)											
32 Airframe PART - Life Limited #3386	LEFT PIN, MLG, SHOCK STRUT UPPER (MAIN FITTING)	02-JUL-2021	L: 19250		L: 3034	L: 19250	L: 15248					
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> <td>H: 6939.60</td> <td>L: 3034</td> </tr> <tr> <td>19134-3</td> <td>1-5352/05</td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number	H: 6939.60	L: 3034	19134-3	1-5352/05					
Part Number	Serial Number	H: 6939.60	L: 3034									
19134-3	1-5352/05											
	Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)											
32 Airframe PART - Life Limited #816	LEFT PIN, PINTLE, MLG	02-JUL-2021	L: 19250		M: 285 H: 6939.60 L: 3034	L: 19250	L: 15248					
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> <td>H: 6939.60</td> <td>L: 3034</td> </tr> <tr> <td>19038-3</td> <td>DCL-134</td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number	H: 6939.60	L: 3034	19038-3	DCL-134					
Part Number	Serial Number	H: 6939.60	L: 3034									
19038-3	DCL-134											
	Notes (AVG MAN HRS: 8) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)											
32 Airframe PART - Life Limited #363	LEFT PIN, PIVOT, MLG	02-JUL-2021	L: 19250		L: 3034	L: 19250	L: 15248					
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> <td>H: 6939.60</td> <td>L: 3034</td> </tr> <tr> <td>19039-1</td> <td>1-5352/05</td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number	H: 6939.60	L: 3034	19039-1	1-5352/05					
Part Number	Serial Number	H: 6939.60	L: 3034									
19039-1	1-5352/05											
	Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)											
32 Airframe PART - Life Limited #3657	LEFT PIN, PIVOT, NLG, DRAG BRACE UPPER	02-JUL-2021	L: 19480		L: 3034	L: 19480	L: 15478					
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> <td>H: 6939.60</td> <td>L: 3034</td> </tr> <tr> <td>200811601</td> <td>1-5352/05</td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number	H: 6939.60	L: 3034	200811601	1-5352/05					
Part Number	Serial Number	H: 6939.60	L: 3034									
200811601	1-5352/05											
	Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)											



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining		
32 Airframe PART - Life Limited #2300	LEFT PIN, PIVOT, NLG, TRUNNION	02-JUL-2021	L: 19480		L: 3034	L: 19480	L: 15478		
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>200811601</td> <td>1-5352/05</td> </tr> </table>	Part Number	Serial Number	200811601	1-5352/05	H: 6939.60 L: 3034			
Part Number	Serial Number								
200811601	1-5352/05								
<p>Notes</p> <p>(AVG MAN HRS: 10) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>									
32 Airframe PART - Life Limited #799	LEFT PISTON, MLG SHOCK STRUT	02-JUL-2021	L: 19250		L: 3034	L: 19250	L: 15248		
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>19115-103</td> <td>DCL205</td> </tr> </table>	Part Number	Serial Number	19115-103	DCL205	H: 6939.60 L: 3034			
Part Number	Serial Number								
19115-103	DCL205								
<p>Notes</p> <p>(AVG MAN HRS: 6) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>									
32 Airframe PART - Life Limited #2588	LEFT PISTON, MLG, SIDE STAY	02-JUL-2021	L: 43890		L: 0	L: 46924	L: 42922		
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>17014-8</td> <td>5388</td> </tr> </table>	Part Number	Serial Number	17014-8	5388	H: 6939.60 L: 3034			
Part Number	Serial Number								
17014-8	5388								
<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>									
32 Airframe PART #1500	LEFT SHOCK, ABSORBER MLG (SHOCK STRUT)	02-JUL-2021							
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>604-85001-5</td> <td>DCL121-97</td> </tr> </table>	Part Number	Serial Number	604-85001-5	DCL121-97	H: 6939.60 L: 3034			
Part Number	Serial Number								
604-85001-5	DCL121-97								
<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)</p>									
32 Airframe PART - Life Limited #539	LEFT SIDE BRACE ROD END, MLG	02-JUL-2021	L: 43890		L: 0	L: 46924	L: 42922		
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>19400-1</td> <td>4404</td> </tr> </table>	Part Number	Serial Number	19400-1	4404	H: 6939.60 L: 3034			
Part Number	Serial Number								
19400-1	4404								
<p>Notes</p> <p>(AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>									



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART LH Nose W #53	LEFT TIRE, NLG Part Number Serial Number 031-614-0 2130T0034 9	08-AUG-2024 H: 8505.70 L: 3893					
Notes (APX COST: 1) (UPDATE NOTE: REMOVED LEFT NOSE WHEEL P/N: 5010598, S/N: AUG03-5056. TIRE P/N: 031-614-0, S/N: 2336T00408. INSTALLED OVERHAULED WHEEL ASSY P/N: 5010598, S/N: APR12-7988. NEW TIRE P/N: 031-614-0, S/N: 2130T00349. SCR.N. TRACKING #011148.1 WORK ORDER #101KF022302 CRS #4SMR148C DATED 21/FEB/2023. IAW CL604 AMM 32-42-01. THIS CLEARS AMDL 41555.)							
32 Airframe PART #630	LEFT UPLOCK ASSY, MLG Part Number Serial Number 601R85001-11 DH0507-05	27-JUL-2005 H: 2522.30 L: 983					
32 Airframe PART #708	LEFT VALVE ASSY, NLG HYDRAULIC BYPASS Part Number Serial Number 600-75120-3 0832	15-OCT-1997					
32 Airframe PART #3086	LEFT WHEEL, NLG Part Number Serial Number 5010598 APR12-7988	08-AUG-2024 H: 8505.70 L: 3893					
Notes (APX COST: 2,688.58) (UPDATE NOTE: REMOVED LEFT NOSE WHEEL P/N: 5010598, S/N: AUG03-5056. TIRE P/N: 031-614-0, S/N: 2336T00408. INSTALLED OVERHAULED WHEEL ASSY P/N: 5010598, S/N: APR12-7988. NEW TIRE P/N: 031-614-0, S/N: 2130T00349. SCR.N. TRACKING #011148.1 WORK ORDER #101KF022302 CRS #4SMR148C DATED 21/FEB/2023. IAW CL604 AMM 32-42-01. THIS CLEARS AMDL 41555.)							
32 Airframe PART - Life Limited #2078	LINK ASSY, LOWER, NLG DRAG BRACE Part Number Serial Number 200814213 DCL452	02-JUL-2021 H: 6939.60 L: 3034	L: 19480		L: 3034	L: 19480	L: 15478
Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
32 Airframe PART - Life Limited #743	LINK ASSY, UPPER, NLG DRAG BRACE Part Number Serial Number 20049-1 DCL-018	02-JUL-2021 H: 6939.60 L: 3034	L: 19480		L: 3034	L: 19480	L: 15478
Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #3179	LINK S/A, LOWER TORQUE NLG Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #2830	LINK S/A, UPPER TORQUE NLG Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #2619	LOWER ACCUMULATOR, HYDRAULIC (BRAKE ACCUM SYST #2) Part Number 2770571-103 Serial Number 1736A	15-OCT-1997					
	Notes (AVG MAN HRS: 5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
32 Airframe PART #2324	LOWER NO.1 NOSEWHEEL - STEERING CONTROL POTENTIOMETER COUPLING SETSCREW Part Number Unknown Serial Number Unknown	15-OCT-1997					
	Notes (SOURCE: MPD, TLMC)						
32 Airframe PART #3200	LOWER NO.2 NOSEWHEEL - STEERING CONTROL POTENTIOMETER COUPLING SETSCREW Part Number Unknown Serial Number Unknown	15-OCT-1997					
	Notes (SOURCE: MPD, TLMC)						
32 Airframe PART #3561	LOWER VALVE, BRAKE CONTROL (#2 OUTBOARD) Part Number 604-75115-5 Serial Number 0143	15-OCT-1997					
32 Airframe PART #2332	MLG - LEFT HARNESS, DOWNLOCK SENSOR NO.1 Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #3053	MLG - LEFT HARNESS, DOWNLOCK SENSOR NO.2 Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #774	MLG - LEFT HARNESS, WOW SENSOR, NO.1 (INDB) Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #1843	MLG - LEFT HARNESS, WOW SENSOR, NO.2 (OUTBD) Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #1127	MLG - RIGHT HARNESS, DOWNLOCK SENSOR NO.1 Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #1178	MLG - RIGHT HARNESS, DOWNLOCK SENSOR NO.2 Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #187	MLG - RIGHT HARNESS, WOW SENSOR, NO.1 (INDB) Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #1919	MLG - RIGHT HARNESS, WOW SENSOR, NO.2 (OUTBD) Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #1985	MLG VALVE ,LANDING GEAR SELECTOR Part Number 400017000 Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #3034	NLG ASSY, STEERING CONTROL AND POSITION FEEDBACK Part Number: 7102-7 Serial Number: CDER289/04	28-JUL-2024 H: 8487.10 L: 3880					
Notes (UPDATE NOTE: COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F ON WO# RXHMXA DATED 7/28/2024. REPAIRED TSN 1114 CSN 614)							
32 Airframe PART #2864	NLG AXLE ASSY Part Number: 200811218 Serial Number: 16	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: AXLE OVERHAULED BY SAFRAN LANDING SYSTEMS UNDER WO#6R6023976D DATED 02/FEB/2021.WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)							
32 Airframe PART - Life Limited #340	NLG AXLE FITTING ASSY Part Number: 200811218 Serial Number: 16	02-JUL-2021 H: 6939.60 L: 3034	L: 19480		L: 8998	L: 13516	L: 9514
Notes (AVG MAN HRS: 3) (UPDATE NOTE: OVERHAULED BY SAFRAN ON DUNCAN WO FFMB) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
32 Airframe PART #67	NLG BRACE ASSY, DRAG Part Number: 20045-103 Serial Number: DCL018/96/03/05	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)							
32 Airframe PART #1131	NLG HARNESS ASSY, (N/W DISC) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #343	NLG MODULE, ELECTRONIC CONTROL Part Number: 7040-15 Serial Number: Unknown	16-JUN-2018 H: 6372.80 L: 2715					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART - Life Limited #922	NLG PIN, SLIDING TUBE TO END FITTING Part Number: 200811602 Serial Number: 11EXC0611	13-APR-2013 H: 4782.30 L: 2063	L: 19480		L: 0	L: 21543	L: 17541
Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
32 Airframe PART #1811	NLG SENSOR, NOSEWHEEL STEERING, RVT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #3154	NLG SHOCK STRUT ASSY Part Number: 20020-105 Serial Number: DCL053/97	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: OVERHAULED BY SAFRAN LANDING SYSTEMS CANADA INC. CRS 41-89 UNDER FORM TRACKING NUMBER RO-31364 DATED 31 MAY 2021 ON DUNCAN AVIATION WO FFMB)							
32 Airframe PART #3111	NO.1 HARNESS, DOWNLOCK (LEFT), SENSOR (DRAG BRACE ASSEMBLY) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #3383	NO.1 VALVE, RESTRICTOR, ONE-WAY NLG Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #1551	NO.2 HARNESS, DOWNLOCK (LEFT), SENSOR (DRAG BRACE ASSEMBLY) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #160	NO.2 VALVE CONTROL, ANTI-SKID (OUTBOARD) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #1580	NO.2 VALVE, RESTRICTOR, ONE-WAY NLG Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #3258	NO.3 BRAKE ACCUMULATOR INDICATING GAUGE Part Number G4227 Serial Number Unknown	15-OCT-1997					
32 Airframe PART #692	NO.3 VALVE CONTROL, ANTI-SKID (INBOARD) Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #1301	NOSE LANDING GEAR STEERING HYDRAULIC SERVO VALVE Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #1785	OUTBOARD TRANSDUCER, PRESSURE (LOWER BRAKE) Part Number 600-59174-17 Serial Number 5799-1-260	15-OCT-1997					
32 Airframe PART #506	PILOT - LEFT CABLE, BRAKE CONTROL Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #3690	PILOT - RIGHT CABLE, BRAKE CONTROL Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #2525	PIN, ACTUATOR NLG RETRACTION Part Number 200811773 Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART - Life Limited #2620	PIN, MAIN FITTING TO DRAG STAY Part Number: 200811721 Serial Number: MY614350	02-JUL-2021 H: 6939.60 L: 3034	L: 19480		L: 3034	L: 19480	L: 15478
Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
32 Airframe PART - Life Limited #3718	PIN, NLG, DRAG BRACE HINGE Part Number: 200814624 Serial Number: DCL487	02-JUL-2021 H: 6939.60 L: 3034	L: 19480		L: 3034	L: 19480	L: 15478
Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
32 Airframe PART #206	PISTON - RETRACTION ACTUATOR ROD NLG Part Number: 104471651 Serial Number: DCL490	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)							
32 Airframe PART #3278	RIGHT ACTUATOR ASSY, SIDE STAY, MLG Part Number: 19010-107 Serial Number: 00111	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)							
32 Airframe PART #2532	RIGHT ACTUATOR, DOWNLOCK ASSIST Part Number: 600-85001-87 Serial Number: DCL814-97	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)							
32 Airframe PART - Life Limited #3470	RIGHT AXLE, MAIN LANDING GEAR Part Number: 19050-3 Serial Number: DCL053	02-JUL-2021 H: 6939.60 L: 3034	L: 19250		L: 4575	L: 17709	L: 13707
Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #2564	RIGHT CAP, ROD END Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART - Life Limited #406	RIGHT CYLINDER, MLG SIDE STAY Part Number 17027-9 Serial Number 3225C	02-JUL-2021 H: 6939.60 L: 3034	L: 43890		L: 0	L: 46924	L: 42922
Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
32 Airframe PART - Life Limited #865	RIGHT CYLINDER, MLG, SHOCK STRUT Part Number 19104-1 Serial Number DCL191	02-JUL-2021 H: 6939.60 L: 3034	L: 19250		M: 285 H: 6939.60 L: 3034	L: 19250	L: 15248
Notes (AVG MAN HRS: 20) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
32 Airframe PART #562	RIGHT DOOR ASSY, MLG Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #1100	RIGHT DOOR ASSY, NLG FORWARD Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART - Life Limited #686	RIGHT FITTING ASSY, MAIN Part Number 19062-2 Serial Number DCL-068	13-APR-2013 H: 4782.30 L: 2063	L: 19250		M: 186 H: 4782.30 L: 2063	L: 19250	L: 15248
Notes (AVG MAN HRS: 10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NHA19064-104/-106)							
32 Airframe PART #2225	RIGHT HARNESS ASSY, (NOSE GEAR BAY) Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #2148	RIGHT HARNESS, WOW SENSOR #2 (NLG SHOCK STRUT ASSY) Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #3610	RIGHT INBOARD BRAKE ASSY Part Number 604-85123-101 Serial Number DEC06-1691	20-APR-2018			H: 6346.70 L: 2706		
32 Airframe PART #1706	RIGHT INBOARD FUSE, VOLUMETRIC, HYDRAULIC Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #3 Main W #2108	RIGHT INBOARD TIRE, MLG WHEEL Part Number 027-697-0 Serial Number 3194P0513 1	08-AUG-2024			H: 8505.70 L: 3893		
Notes (APX COST: 0) (UPDATE NOTE: REMOVED RIGHT INBOARD WHEEL P/N: 5012373, S/N: JUL97-0375. TIRE P/N: 027-697-0, S/N: 3270P05206. INSTALLED OVERHAULED WHEEL P/N: 5012373, S/N: FEB16-4347. NEW TIRE P/N: 027-697-0, S/N: 3194P05131 AIRCRAFT SPECIALTIES INC. TRACKING #178788 WORK ORDER #178788 CRS #VT2R252L DATED 26/JAN/2024. IAW CL604 AMM 32-41-01. THIS CLEARS AMDL 41553.)							
32 Airframe PART #1529	RIGHT INBOARD TRANSDUCER, PRESSURE (BRAKE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #892	RIGHT INBOARD TRANSDUCER, WHEEL SPEED Part Number 604-87000-1 Serial Number 327	15-OCT-1997					
32 Airframe PART #906	RIGHT INBOARD WHEEL ASSY, MLG Part Number 5012373 Serial Number FEB16-4347	08-AUG-2024			H: 8505.70 L: 3893		
Notes (APX COST: 5,000) (UPDATE NOTE: REMOVED RIGHT INBOARD WHEEL P/N: 5012373, S/N: JUL97-0375. TIRE P/N: 027-697-0, S/N: 3270P05206. INSTALLED OVERHAULED WHEEL P/N: 5012373, S/N: FEB16-4347. NEW TIRE P/N: 027-697-0, S/N: 3194P05131 AIRCRAFT SPECIALTIES INC. TRACKING #178788 WORK ORDER #178788 CRS #VT2R252L DATED 26/JAN/2024. IAW CL604 AMM 32-41-01. THIS CLEARS AMDL 41553.)							



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #1025	RIGHT MAIN GEAR HYDRAULIC SWIVEL COUPLING ASSY Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART - Life Limited #12	RIGHT MAIN LANDING GEAR (MLG) TRAILING ARM Part Number 19084-103 Serial Number DCL156	02-JUL-2021 H: 6939.60 L: 3034	L: 36430		H: 6939.60 L: 3034	L: 36430	L: 32428
Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
32 Airframe PART #2798	RIGHT MAIN LANDING GEAR ASSY, DRESSED Part Number 19090-106 Serial Number DCL057/97	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)							
32 Airframe PART #1526	RIGHT N/W DISC HARNESS SUB ASSY Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #3192	RIGHT NO.1 MAIN LANDING GEAR (MLG) SIDE STAY ACTUATOR, LOCK SEGMENT Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #3496	RIGHT NO.2 MAIN LANDING GEAR (MLG) SIDE STAY ACTUATOR, LOCK SEGMENT Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #1757	RIGHT NO.3 MAIN LANDING GEAR (MLG) SIDE STAY ACTUATOR, LOCK SEGMENT Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #350	RIGHT NO.4 MAIN LANDING GEAR (MLG) SIDE STAY ACTUATOR, LOCK SEGMENT Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #2262	RIGHT OUTBOARD BRAKE ASSY Part Number 604-85123-101 Serial Number JAN96-0075	12-NOV-2020					
Notes (APX COST: 0) (UPDATE NOTE: WORK COMPLETED BY WEST STAR AVIATION, CRS PAZR068H, SEE MAINTENANCE LOG ENTRY DATED 11/12/2020 W/O 348369 FOR DETAILS.)							
32 Airframe PART #2106	RIGHT OUTBOARD FUSE, VOLUMETRIC, HYDRAULIC Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #4 Main W #3116	RIGHT OUTBOARD TIRE, MLG WHEEL Part Number 027-697-0 Serial Number 3171P0513 4	08-AUG-2024			H: 8505.70 L: 3893		
Notes (APX COST: 0) (UPDATE NOTE: REMOVED RIGHT OUTBOARD WHEEL P/N: 5012373, S/N: DEC99-1074. TIRE P/N: 027-697-0, S/N: 3171P05134. INSTALLED OVERHAULED WHEEL P/N: 5012373, S/N: MAY11-3427. NEW TIRE P/N: 027-697-0, S/N: 3171P05134 AIRCRAFT SPECIALTIES INC. TRACKING #178787 WORK ORDER #178787 CRS #VT2R252L DATED 29/JAN/2024. IAW CL604 AMM 32-41-01. THIS CLEARS AMDL 41554.)							
32 Airframe PART #637	RIGHT OUTBOARD TRANSDUCER, PRESSURE (BRAKE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
32 Airframe PART #2710	RIGHT OUTBOARD TRANSDUCER, WHEEL SPEED Part Number 604-87000-1 Serial Number 478	15-OCT-1997					
32 Airframe PART #773	RIGHT OUTBOARD WHEEL ASSY, MLG Part Number 5012373 Serial Number MAY11-3427	08-AUG-2024			H: 8505.70 L: 3893		
Notes (APX COST: 5,000) (UPDATE NOTE: REMOVED RIGHT OUTBOARD WHEEL P/N: 5012373, S/N: DEC99-1074. TIRE P/N: 027-697-0, S/N: 3171P05134. INSTALLED OVERHAULED WHEEL P/N: 5012373, S/N: MAY11-3427. NEW TIRE P/N: 027-697-0, S/N: 3171P05134 AIRCRAFT SPECIALTIES INC. TRACKING #178787 WORK ORDER #178787 CRS #VT2R252L DATED 29/JAN/2024. IAW CL604 AMM 32-41-01. THIS CLEARS AMDL 41554.)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining														
32 Airframe PART - Life Limited #3264	RIGHT PIN ASSY, MLG SIDE STAY	02-JUL-2021	L: 19250		L: 3034	L: 19250	L: 15248														
	<table border="0"> <tr> <td style="text-align: right;">Part Number</td> <td style="text-align: right;">Serial Number</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: right;">6350-3</td> <td style="text-align: right;">DCL906</td> <td>H: 6939.60</td> <td>L: 3034</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number							6350-3	DCL906	H: 6939.60	L: 3034								
Part Number	Serial Number																				
6350-3	DCL906	H: 6939.60	L: 3034																		
	Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)																				
32 Airframe PART - Life Limited #652	RIGHT PIN, MLG, SHOCK STRUT LOWER (TO TRAILING ARM)	02-JUL-2021	L: 19250		L: 3034	L: 19250	L: 15248														
	<table border="0"> <tr> <td style="text-align: right;">Part Number</td> <td style="text-align: right;">Serial Number</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: right;">19146-3</td> <td style="text-align: right;">2-5352/05</td> <td>H: 6939.60</td> <td>L: 3034</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number							19146-3	2-5352/05	H: 6939.60	L: 3034								
Part Number	Serial Number																				
19146-3	2-5352/05	H: 6939.60	L: 3034																		
	Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)																				
32 Airframe PART - Life Limited #3099	RIGHT PIN, MLG, SHOCK STRUT UPPER (MAIN FITTING)	02-JUL-2021	L: 19250		L: 3034	L: 19250	L: 15248														
	<table border="0"> <tr> <td style="text-align: right;">Part Number</td> <td style="text-align: right;">Serial Number</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: right;">19134-3</td> <td style="text-align: right;">2-5352/05</td> <td>H: 6939.60</td> <td>L: 3034</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number							19134-3	2-5352/05	H: 6939.60	L: 3034								
Part Number	Serial Number																				
19134-3	2-5352/05	H: 6939.60	L: 3034																		
	Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)																				
32 Airframe PART - Life Limited #633	RIGHT PIN, PINTLE, MLG	02-JUL-2021	L: 19250		M: 285 H: 6939.60 L: 3034	L: 19250	L: 15248														
	<table border="0"> <tr> <td style="text-align: right;">Part Number</td> <td style="text-align: right;">Serial Number</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: right;">19038-3</td> <td style="text-align: right;">DCL-136</td> <td>H: 6939.60</td> <td>L: 3034</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number							19038-3	DCL-136	H: 6939.60	L: 3034								
Part Number	Serial Number																				
19038-3	DCL-136	H: 6939.60	L: 3034																		
	Notes (AVG MAN HRS: 8) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)																				
32 Airframe PART - Life Limited #3542	RIGHT PIN, PIVOT, MLG	02-JUL-2021	L: 19250		L: 3034	L: 19250	L: 15248														
	<table border="0"> <tr> <td style="text-align: right;">Part Number</td> <td style="text-align: right;">Serial Number</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: right;">19039-1</td> <td style="text-align: right;">2-5352/05</td> <td>H: 6939.60</td> <td>L: 3034</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number							19039-1	2-5352/05	H: 6939.60	L: 3034								
Part Number	Serial Number																				
19039-1	2-5352/05	H: 6939.60	L: 3034																		
	Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)																				



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining					
32 Airframe PART - Life Limited #1863	RIGHT PIN, PIVOT, NLG, DRAG BRACE UPPER	02-JUL-2021	L: 19480		L: 3034	L: 19480	L: 15478					
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> <td>H: 6939.60</td> <td>L: 3034</td> </tr> <tr> <td>200814601</td> <td>2-5352/05</td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number	H: 6939.60	L: 3034	200814601	2-5352/05					
Part Number	Serial Number	H: 6939.60	L: 3034									
200814601	2-5352/05											
	Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)											
32 Airframe PART - Life Limited #1721	RIGHT PIN, PIVOT, NLG, TRUNNION	02-JUL-2021	L: 19480		L: 3034	L: 19480	L: 15478					
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> <td>H: 6939.60</td> <td>L: 3034</td> </tr> <tr> <td>200811601</td> <td>2-5352/05</td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number	H: 6939.60	L: 3034	200811601	2-5352/05					
Part Number	Serial Number	H: 6939.60	L: 3034									
200811601	2-5352/05											
	Notes (AVG MAN HRS: 10) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)											
32 Airframe PART - Life Limited #263	RIGHT PISTON, MLG SHOCK STRUT	02-JUL-2021	L: 19250		L: 3034	L: 19250	L: 15248					
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> <td>H: 6939.60</td> <td>L: 3034</td> </tr> <tr> <td>19115-101</td> <td>DCL204</td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number	H: 6939.60	L: 3034	19115-101	DCL204					
Part Number	Serial Number	H: 6939.60	L: 3034									
19115-101	DCL204											
	Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)											
32 Airframe PART - Life Limited #3074	RIGHT PISTON, MLG, SIDE STAY	02-JUL-2021	L: 43890		L: 0	L: 46924	L: 42922					
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> <td>H: 6939.60</td> <td>L: 3034</td> </tr> <tr> <td>17014-8</td> <td>5382</td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number	H: 6939.60	L: 3034	17014-8	5382					
Part Number	Serial Number	H: 6939.60	L: 3034									
17014-8	5382											
	Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)											
32 Airframe PART #1682	RIGHT SHOCK, ABSORBER MLG (SHOCK STRUT)	02-JUL-2021										
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> <td>H: 6939.60</td> <td>L: 3034</td> </tr> <tr> <td>604-85001-5</td> <td>DCL118-97</td> <td></td> <td></td> </tr> </table>	Part Number	Serial Number	H: 6939.60	L: 3034	604-85001-5	DCL118-97					
Part Number	Serial Number	H: 6939.60	L: 3034									
604-85001-5	DCL118-97											
	Notes (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)											



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART - Life Limited #2949	RIGHT SIDE BRACE ROD END, MLG Part Number 19400-1 Serial Number 4405	02-JUL-2021 H: 6939.60 L: 3034	L: 43890		L: 0	L: 46924	L: 42922
Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
32 Airframe PART RH Nose W #3097	RIGHT TIRE, NLG Part Number 031-614-0 Serial Number 1285T0044 5	08-AUG-2024 H: 8505.70 L: 3893					
Notes (UPDATE NOTE: REMOVED RIGHT NOSE WHEEL P/N: 5010598, S/N: AUG98-1691/S-JAN00-0063. TIRE P/N: 031-614-0, S/N: 3099T00502. INSTALLED OVERHAULED WHEEL ASSY P/N: 5010598, S/N: JUL06-6261. NEW TIRE P/N: 031-614-0, S/N: 1285T00445. SCR.N. TRACKING #010563.1 WORK ORDER #22-01376 CRS #4SMR148C DATED 08/DEC/2022. IAW CL604 AMM 32-42-01. THIS CLEARS AMDL 41556.)							
32 Airframe PART #2411	RIGHT UPLOCK ASSY, MLG Part Number 601R85001-11 Serial Number DH-0506-05	23-MAR-2017 H: 5979.10 L: 2576					
32 Airframe PART #198	RIGHT VALVE ASSY, NLG DOOR BYPASS Part Number 600-75120-3 Serial Number 0829	15-OCT-1997					
32 Airframe PART #1905	RIGHT VALVE, RELIEF (EMERGENCY EXIT) Part Number Unknown Serial Number Unknown	15-OCT-1997					
Notes (ZONE: MLG BAY)							
32 Airframe PART #2843	RIGHT WHEEL, NLG Part Number 5010598 Serial Number JUL06-6261	08-AUG-2024 H: 8505.70 L: 3893					
Notes (APX COST: 2,688.58) (UPDATE NOTE: REMOVED RIGHT NOSE WHEEL P/N: 5010598, S/N: AUG98-1691/S-JAN00-0063. TIRE P/N: 031-614-0, S/N: 3099T00502. INSTALLED OVERHAULED WHEEL ASSY P/N: 5010598, S/N: JUL06-6261. NEW TIRE P/N: 031-614-0, S/N: 1285T00445. SCR.N. TRACKING #010563.1 WORK ORDER #22-01376 CRS #4SMR148C DATED 08/DEC/2022. IAW CL604 AMM 32-42-01. THIS CLEARS AMDL 41556.)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #1242	SOLENOID SELECTOR VALVE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: NLG DOOR)						
32 Airframe PART #2859	SOLENOID SELECTOR VALVE, NLG Part Number: 750006000 Serial Number: 0583	11-JUL-2007 H: 3081.60 L: 1242					
	Notes (ZONE: BRAKE BAY)						
32 Airframe PART - Life Limited #1306	TUBE, SLIDING, NLG, SHOCK STRUT Part Number: 200811707 Serial Number: MBM-0375	13-APR-2013 H: 4782.30 L: 2063	L: 19480		L: 1080	L: 20463	L: 16461
	Notes (AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
32 Airframe PART #3020	UPLOCK ASSY, NLG Part Number: 601R85002-91 Serial Number: 08SM00001	06-DEC-2024 H: 8600.30 L: 3958					
	Notes (ZONE: NLG BAY) (APX COST: 0) (UPDATE NOTE: REMOVED NOSE GEAR UPLOCK ASSY P/N 166000-103 S/N 0001 AND INSTALLED REPAIRED NOSE GEAR UPLOCK ASSY P/N 16600-103 S/N 08SM00001. PERFORMED SEVERAL GEAR SWINGS. NO DEFECTS NOTED. WORK ACCOMPLISHED IAW CL MM 32-33-04. REF FORM ONE: SAFRAN LANDING SYSTEMS CANADA INC. WO#6044356 APPROVAL NO 41-89, STATUS: REPAIRED, DATED: 10 JULY 2024 RII ACCOMPLISHED BY MICHAEL BURDESHAW)						
32 Airframe PART #3627	UPPER ACCUMULATOR, HYDRAULIC (BRAKE ACCUM SYST #3) Part Number: 2770571-103 Serial Number: 1671A	15-OCT-1997					
	Notes (AVG MAN HRS: 5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #1277	UPPER NO.1 NOSEWHEEL - STEERING CONTROL POTENTIOMETER COUPLING SETSCREW Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
Notes (SOURCE: MPD, TLMC)							
32 Airframe PART #1961	UPPER NO.2 NOSEWHEEL - STEERING CONTROL POTENTIOMETER COUPLING SETSCREW Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
Notes (SOURCE: MPD, TLMC)							
32 Airframe PART #2675	UPPER VALVE, BRAKE CONTROL (#3 INBOARD) Part Number: 604-75115-5 Serial Number: 0127	15-OCT-1997					
32 Airframe PART #627	VALVE, MLG RUNAROUND AND BYPASS Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
32 Airframe PART #1037	VALVE, PRIORITY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
Notes (ZONE: MLG BAY)							
32 Airframe PART #3240	VALVE, RELIEF, PRIORITY Part Number: 4622 Serial Number: 2559A	18-JAN-2024 H: 8242.90 L: 3740					
Notes (ZONE: NLG BAY) (APX COST: 0) (UPDATE NOTE: COMPLIED WITH MULTIPLE GEAR SWINGS, COULD NOT DUPLICATE PROBLEM. TALKING TO TECH SUPPORT THE MOST LOGICAL PROBLEM IS THE NOSE LANDING GEAR PRIORITY VALVE. REMOVED VALVE P/N 4622 S/N 589. INSTALLED NEW VALVE P/N 4622 S/N 2559A. BLEED AIR OUT OF #3 HYDRAULIC SYSTEM. MULTIPLE GEAR SWINGS, NO DEFECTS NOTED. IAW CL 604 AMM 32-30-00.)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 Airframe PART #2222	VALVE, SELECTOR Part Number 601R75145-1 Serial Number 0347	15-OCT-1997					
	Notes (ZONE: MLG BAY)						
32 Airframe PART #1505	VALVE, SHUTOFF PARKING BRAKE Part Number 604-75401-5 Serial Number 029	15-OCT-1997					
32 00-00-301 Airframe INSPECTION #456	CLEANING OF THE LANDING GEAR AND UNDERCARRIAGE AREA Notes (ZONE: 710,740) (NOTE: NOTE: IMPROVED CORROSION PROTECTION CAN BE ACHIEVED BY ACCOMPLISHING THIS TASK AT THE EARLIEST CONVENIENCE AFTER OPERATION IN AIRPORTS THAT USE POTASSIUM ACETATE-BASED OR SALT-BASED RUNWAY DE-ICING FLUID)						
32 00-01-201 Airframe INSPECTION PKG 800 Hour #2016	FUNCTIONAL TEST OF THE LANDING-GEAR EMERGENCY-EXTENSION SYSTEM Notes (AVG MAN HRS: 7.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)	11-JUL-2023 H: 800.00 H: 8075.40 L: 3647		H: 40.00		H: 8875.40	H: 180.30
32 00-01-202 Airframe INSPECTION PKG1200Hour #1081	FUNCTIONAL TEST OF THE MAIN LANDING GEAR (MLG) SHOCK STRUT ASSEMBLY Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
32 00-01-203 Airframe INSPECTION PKG1200Hour #826	FUNCTIONAL TEST OF THE NOSE LANDING GEAR (NLG) SHOCK STRUT ASSEMBLY Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 00-01-204 Airframe INSPECTION PKG 400 Hour #917	LUBRICATION OF THE MAIN LANDING GEAR (MLG)	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00	H: 40.00		H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 2) (TOL. ADJUSTMENT: 19.6 HRS) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)							
32 00-01-205 Airframe INSPECTION PKG 400 Hour #2245	LUBRICATION OF THE NOSE LANDING GEAR (NLG)	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00	H: 40.00		H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: 19.6 HRS) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)							
32 00-01-206 Airframe INSPECTION PKG 400 Hour #1900	LUBRICATION OF THE MAIN LANDING GEAR (MLG) DOORS	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00	H: 40.00		H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: 19.6 HRS) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)							
32 00-01-207 Airframe INSPECTION PKG 400 Hour #995	LUBRICATION OF THE NOSE LANDING GEAR (NLG) DOORS	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00	H: 40.00		H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: 19.6 HRS) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)							
32 00-01-208 Airframe INSPECTION PKG 48 Month #1846	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CABLE IN THE NLG WHEEL WELL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 1.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 00-01-209 Airframe INSPECTION PKG 48 Month #3007	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CABLE IN THE FORWARD AVIONICS COMPARTMENT	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
32 00-01-210 Airframe INSPECTION PKG 48 Month #2368	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CABLE IN THE MAIN AVIONICS COMPARTMENT	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
32 00-01-211 Airframe INSPECTION PKG 96 Month #2396	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CABLE IN THE MID-LOWER FUSELAGE COMPARTMENT	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 7)						
32 00-01-212 Airframe INSPECTION PKG 48 Month #3536	DETAILED INSPECTION OF THE LANDING-GEAR EMERGENCY-EXTENSION CABLE IN THE MLG WHEEL WELL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
32 00-01-213 Airframe INSPECTION PKG 600 Hour #2320	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR (MLG) ASSEMBLY	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 2) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 00-01-214 Airframe INSPECTION PKG 600 Hour #1986	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR (NLG) ASSEMBLY	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
32 00-01-215 Airframe INSPECTION PKG 96 Month #2621	DETAILED INSPECTION OF THE MAIN LANDING GEAR (MLG) ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 80)						
32 00-01-216 Airframe INSPECTION PKG 96 Month #1332	DETAILED INSPECTION OF THE NOSE LANDING GEAR (NLG) ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 50)						
32 00-01-217 Airframe INSPECTION PKG 96 Month #1600	LEFT RESTORATION (OVERHAUL) OF THE MAIN LANDING GEAR (MLG) ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 80)						
32 00-01-217 Airframe INSPECTION PKG 96 Month #2458	RIGHT RESTORATION (OVERHAUL) OF THE MAIN LANDING GEAR (MLG) ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 80)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining				
32 00-01-218 Airframe INSPECTION PKG 96 Month #190	RESTORATION (OVERHAUL) OF THE NOSE LANDING GEAR (NLG) ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12				
	Notes (AVG MAN HRS: 50) (TOL. ADJUSTMENT: -79D)										
32 10-00-201 Airframe INSPECTION #2542	LEFT SPECIAL DETAILED INSPECTION OF THE MAIN LANDING-GEAR SIDE BRACE FITTING SHAFT, PART NO. 601R10237-1 ONLY										
	Notes (AVG MAN HRS: 12)										
32 10-00-201 Airframe INSPECTION #516	RIGHT SPECIAL DETAILED INSPECTION OF THE MAIN LANDING-GEAR SIDE BRACE FITTING SHAFT, PART NO. 601R10237-1 ONLY										
	Notes (AVG MAN HRS: 12)										
32 12-00-201 Airframe INSPECTION PKG 48 Month #757	DETAILED INSPECTION OF THE HINGE AND FASTENERS OF THE MAIN LANDING-GEAR DOOR	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12				
	Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)										
32 2213-001 Airframe PART #2786	NOSE LANDING GEAR DOOR SELECTOR VALVE										
	<table border="0"> <tr> <td>Part Number</td> <td>Serial Number</td> </tr> <tr> <td>601R75146-1</td> <td>2309T</td> </tr> </table>	Part Number	Serial Number	601R75146-1	2309T	21-DEC-2024 H: 8606.70 L: 3964					
Part Number	Serial Number										
601R75146-1	2309T										
	Notes (UPDATE NOTE: COMPLIED WITH BY DIRECT MX CRS# FMSR378E ON WORK ORDER CRS240033)										
32 31-01-101 Airframe INSPECTION #3134	RESTORATION OF THE LANDING GEAR CONTROL HANDLE ASSEMBLY, PART NO. 601R50967-7 (VENDOR PART NO. 7-45502-1) WITH SUFFIX A AFTER S/N										
	Notes (AVG MAN HRS: 1) (NOTE: FOR LANDING GEAR CONTROL HANDLE ASSEMBLIES THAT HAVE BEEN IN SERVICE FOR MORE THAN 150 LANDINGS AT THE TIME OF ISSUE OF TEMPORARY REVISION 5-2-8, RESTORATION IS REQUIRED WITHIN THE NEXT 150 LANDINGS (REFER TO SERVICE BULLETIN 604-32-017))										



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining				
32 31-01-102 Airframe INSPECTION #3630	RESTORATION OF THE LANDING GEAR CONTROL HANDLE ASSEMBLY PART NO. 601R50967-7 (VENDOR PART NO. 7-45502-1) WITH SUFFIX B AFTER S/N OR PART NO. 601R50967-9 (VENDOR PART NO. 7-45502-3)										
	Notes (AVG MAN HRS: 5) (NOTE: THE ALLOWABLE EXTENSION OF 60 LANDINGS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)										
32 31-01-103 Airframe INSPECTION #1258	DETAILED INSPECTION OF THE LANDING GEAR CONTROL HANDLE ASSEMBLY, PART NO. 601R50967-7 (VENDOR PART NO. 7-45502-1) WITH SUFFIX B AFTER S/N OR PART NO. 601R50967-9 (VENDOR PART NO. 7-45502-3)	25-JAN-2007									
	Notes (AVG MAN HRS: 2) (NOTE: FOR LANDING GEAR CONTROL HANDLE ASSEMBLIES THAT HAVE BEEN IN SERVICE FOR MORE THAN 450 LANDINGS AT THE TIME OF ISSUE OF TEMPORARY REVISION 5-2-8, DETAILED INSPECTION IS REQUIRED WITHIN THE NEXT 150 LANDINGS)	H: 2895.70 L: 1155									
32 40-00-201 Airframe INSPECTION PKG 800 Hour #1661	FUNCTIONAL TEST OF THE BRAKE ACCUMULATORS	11-JUL-2023	H: 800.00	H: 40.00		H: 8875.40	H: 180.30				
	Notes (AVG MAN HRS: 1.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)	H: 8075.40 L: 3647									
32 40-00-202 Airframe INSPECTION #2 Main W #2527	LEFT INBOARD SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR WHEELS	06-DEC-2024									
	<table border="1"> <thead> <tr> <th>Part Number</th> <th>Serial Number</th> </tr> </thead> <tbody> <tr> <td>5012373</td> <td>MAR04-1810</td> </tr> </tbody> </table>	Part Number	Serial Number	5012373	MAR04-1810	H: 8600.30 L: 3958					
Part Number	Serial Number										
5012373	MAR04-1810										
	Notes (AVG MAN HRS: 8) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-202 LEFT INBOARD SPECIAL INSPECTION OF THE MAIN LANDING GEAR WHEEL BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED LEFT INBOARD WHEEL ASSEMBLY P/N 5012373 S/N MAY12-3695 WITH WORN TIRE P/N 027-697-0 S/N 1216P05046 AND INSTALLED OVERHAULED WHEEL ASSEMBLY P/N 5012373 S/N MAR04-1810 WITH NEW TIRE H27X825-14/16/210 P/N 027-697-0 S/N 4132P05029 BUILD UP ASSEMBLY. SERVICED TO MAX PRESSURE WITH NITROGEN. IAW BOMBARDIER CL 604 AMM 32-41-01 REF 8130-3. #200573194 BOEING DISTRIBUTION INC. 674 MADISON ST., CROWN POINT IN 46307 MFG CERT AAC# LQ5R024N DATED 21OCT24 AND CLEARS AMDL 41573) (NOTE: NOTE 17: THE ABS C WHEELS RECOMMEN										



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 40-00-202 Airframe INSPECTION #1 Main W #2151	LEFT OUTBOARD SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR WHEELS Part Number 5012373 Serial Number MAR01-1344	06-DEC-2024 H: 8600.30 L: 3958					
Notes (AVG MAN HRS: 8) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-202 LEFT OUTBOARD SPECIAL INSPECTION OF THE MAIN LANDING GEAR WHEEL BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED LEFT OUTBOARD WHEEL ASSEMBLY P/N 5012373 S/N JAN95-0027 WITH WORN TIRE P/N 027-697-0 S/N 3181P05167 AND INSTALLED OVERHAULED WHEEL ASSEMBLY P/N 5012373 S/N MAR01-1344 WITH NEW TIRE H27X825-14/16/210 P/N 027-697-0 S/N 3313P05163 BUILD UP ASSEMBLY. SERVICED TO MAX PRESSURE WITH NITROGEN. IAW BOMBARDIER CL 604 AMM 32-41-01 REF 8130-3. #200567951 BOEING DISTRIBUTION INC. 674 MADISON ST., CROWN POINT IN 46307 MFG CERT AAC# LQ5R024N DATED 10SEP24 AND CLEARS AMDL 41572) (NOTE: NOTE 17: THE ABSC WHEELS RECOM							
32 40-00-202 Airframe INSPECTION #3 Main W #764	RIGHT INBOARD SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR WHEELS Part Number 5012373 Serial Number FEB16-4347	08-AUG-2024 H: 8505.70 L: 3893					
Notes (AVG MAN HRS: 8) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-202 RIGHT INBOARD SPECIAL DETAILED INSPECTION OF MAIN LANDING GEAR WHEEL BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED RIGHT INBOARD WHEEL P/N: 5012373, S/N: JUL97-0375. TIRE P/N: 027-697-0, S/N: 3270P05206. INSTALLED OVERHAULED WHEEL P/N: 5012373, S/N: FEB16-4347. NEW TIRE P/N: 027-697-0, S/N: 3194P05131 AIRCRAFT SPECIALTIES INC. TRACKING #178788 WORK ORDER #178788 CRS #VT2R252L DATED 26/JAN/2024. IAW CL604 AMM 32-41-01. THIS CLEARS AMDL 41553.) (NOTE: NOTE 17: THE ABSC WHEELS RECOMMENDED INSPECTION SCHEDULE FOUND IN THIS PROGRAM NOTE IS COPIED FROM ABSC GENERAL SERVICE LETTER GS-SL-36 REVISION NO.7. (REFER TO CMM							
32 40-00-202 Airframe INSPECTION #4 Main W #2133	RIGHT OUTBOARD SPECIAL DETAILED INSPECTION OF THE MAIN LANDING GEAR WHEELS Part Number 5012373 Serial Number MAY11-3427	08-AUG-2024 H: 8505.70 L: 3893					
Notes (AVG MAN HRS: 8) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-202 RIGHT OUTBOARD SPECIAL DETAILED INSPECTION OF MAIN LANDING GEAR WHEEL BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED RIGHT OUTBOARD WHEEL P/N: 5012373, S/N: DEC99-1074. TIRE P/N: 027-697-0, S/N: 3171P05134. INSTALLED OVERHAULED WHEEL P/N: 5012373, S/N: MAY11-3427. NEW TIRE P/N: 027-697-0, S/N: 3171P05134 AIRCRAFT SPECIALTIES INC. TRACKING #178787 WORK ORDER #178787 CRS #VT2R252L DATED 29/JAN/2024. IAW CL604 AMM 32-41-01. THIS CLEARS AMDL 41554.) (NOTE: NOTE 17: THE ABSC WHEELS RECOMMENDED INSPECTION SCHEDULE FOUND IN THIS PROGRAM NOTE IS COPIED FROM ABSC GENERAL SERVICE LETTER GS-SL-36 REVISION NO.7. (REFER TO C							
32 40-00-203 Airframe INSPECTION LH Nose W #1951	LEFT SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR WHEELS Part Number 5010598 Serial Number APR12-7988	08-AUG-2024 H: 8505.70 L: 3893					
Notes (AVG MAN HRS: 7.5) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-203 LEFT SPECIAL DETAILED INSPECTION OF NOSE LANDING HEAR WHEEL BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED LEFT NOSE WHEEL P/N: 5010598, S/N: AUG03-5056. TIRE P/N: 031-614-0, S/N: 2336T00408. INSTALLED OVERHAULED WHEEL ASSY P/N: 5010598, S/N: APR12-7988. NEW TIRE P/N: 031-614-0, S/N: 2130T00349. SCR.N. TRACKING #011148.1 WORK ORDER #101KF022302 CRS #4SMR148C DATED 21/FEB/2023. IAW CL604 AMM 32-42-01. THIS CLEARS AMDL 41555.) (NOTE: NOTE 17: THE ABSC WHEELS RECOMMENDED INSPECTION SCHEDULE FOUND IN THIS PROGRAM NOTE IS COPIED FROM ABSC GENERAL SERVICE LETTER GS-SL-36 REVISION NO.7. (REFER TO CMM 32-42-28 FOR MAIN							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 40-00-203 Airframe INSPECTION RH Nose W #860	RIGHT SPECIAL DETAILED INSPECTION OF THE NOSE LANDING GEAR WHEELS Part Number: 5010598 Serial Number: JUL06-6261	08-AUG-2024 H: 8505.70 L: 3893					
Notes (AVG MAN HRS: 7.5) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-203 RIGHT SPECIAL DETAILED INSPECTION OF NOSE LANDING HEAR WHEEL BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED RIGHT NOSE WHEEL P/N: 5010598, S/N: AUG98-1691/S-JAN00-0063. TIRE P/N: 031-614-0, S/N: 3099T00502. INSTALLED OVERHAULED WHEEL ASSY P/N: 5010598, S/N: JUL06-6261. NEW TIRE P/N: 031-614-0, S/N: 1285T00445. SCR. TRACKING #010563.1 WORK ORDER #22-01376 CRS #4SMR148C DATED 08/DEC/2022. IAW CL604 AMM 32-42-01. THIS CLEARS AMDL 41556.) (NOTE: NOTE 17: THE ABCS WHEELS RECOMMENDED INSPECTION SCHEDULE FOUND IN THIS PROGRAM NOTE IS COPIED FROM ABCS GENERAL SERVICE LETTER GS-SL-36 REVISION NO.7. (REFER TO CMM 32-42							
32 40-00-204 Airframe INSPECTION PKG 800 Hour #1286	LUBRICATION OF THE MAIN LANDING GEAR (MLG) BRAKE CONTROL-VALVE ASSEMBLY	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)							
32 40-00-205 Airframe INSPECTION PKG 600 Hour #3273	DETAILED INSPECTION OF THE BRAKE WEAR PINS	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)							
32 40-00-206 Airframe INSPECTION #2 Main W #1576	LEFT INBOARD DETAILED INSPECTION OF THE MAIN LANDING GEAR WHEELS Part Number: 5012373 Serial Number: MAR04-1810	06-DEC-2024 H: 8600.30 L: 3958					
Notes (AVG MAN HRS: 8) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-206 LEFT INBOARD DETAILED INSPECTION OF THE MAIN LANDING GEAR WHEELS. REMOVED LEFT INBOARD WHEEL ASSEMBLY P/N 5012373 S/N MAY12-3695 WITH WORN TIRE P/N 027-697-0 S/N 1216P05046 AND INSTALLED OVERHAULED WHEEL ASSEMBLY P/N 5012373 S/N MAR04-1810 WITH NEW TIRE H27X825-14/16/210 P/N 027-697-0 S/N 4132P05029 BUILD UP ASSEMBLY. SERVICED TO MAX PRESSURE WITH NITROGEN. IAW BOMBARDIER CL 604 AMM 32-41-01 REF 8130 -3. #200573194 BOEING DISTRIBUTION INC. 674 MADISON ST., CROWN POINT IN 46307 MFG CERT AAC# LQ5R024N DATED 21OCT24 AND CLEARS AMDL 41573)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 40-00-206 Airframe INSPECTION #1 Main W #2280	LEFT OUTBOARD DETAILED INSPECTION OF THE MAIN LANDING GEAR WHEELS	06-DEC-2024					
	Part Number	Serial Number	H: 8600.30				
	5012373	MAR01-1344	L: 3958				
	Notes (AVG MAN HRS: 8) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-206 LEFT OUTBOARD DETAILED INSPECTION OF THE MAIN LANDING GEAR WHEELS BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED LEFT OUTBOARD WHEEL ASSEMBLY P/N 5012373 S/N JAN95-0027 WITH WORN TIRE P/N 027-697-0 S/N 3181P05167 AND INSTALLED OVERHAULED WHEEL ASSEMBLY P/N 5012373 S/N MAR01-1344 WITH NEW TIRE H27X825-14/16/210 P/N 027-697-0 S/N 3313P05163 BUILD UP ASSEMBLY. SERVICED TO MAX PRESSURE WITH NITROGEN. IAW BOMBARDIER CL 604 AMM 32-41-01 REF 8130-3. #200567951 BOEING DISTRIBUTION INC. 674 MADISON ST., CROWN POINT IN 46307 MFG CERT AAC# LQ5R024N DATED 10SEP24 AND CLEARS AMDL 41572)						
32 40-00-206 Airframe INSPECTION #3 Main W #2726	RIGHT INBOARD DETAILED INSPECTION OF THE MAIN LANDING GEAR WHEELS	08-AUG-2024					
	Part Number	Serial Number	H: 8505.70				
	5012373	FEB16-4347	L: 3893				
	Notes (AVG MAN HRS: 8) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-206 RIGHT INBOARD DETAILED INSPECTION OF MAIN LANDING GEAR WHEEL BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED RIGHT INBOARD WHEEL P/N: 5012373, S/N: JUL97-0375. TIRE P/N: 027-697-0, S/N: 3270P05206. INSTALLED OVERHAULED WHEEL P/N: 5012373, S/N: FEB16-4347. NEW TIRE P/N: 027-697-0, S/N: 3194P05131 AIRCRAFT SPECIALTIES INC. TRACKING #178788 WORK ORDER #178788 CRS #VT2R252L DATED 26/JAN/2024. IAW CL604 AMM 32-41-01. THIS CLEARS AMDL 41553.)						
32 40-00-206 Airframe INSPECTION #4 Main W #1328	RIGHT OUTBOARD DETAILED INSPECTION OF THE MAIN LANDING GEAR WHEELS	08-AUG-2024					
	Part Number	Serial Number	H: 8505.70				
	5012373	MAY11-3427	L: 3893				
	Notes (AVG MAN HRS: 8) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-206 RIGHT OUTBOARD DETAILED INSPECTION OF MAIN LANDING GEAR WHEEL BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED RIGHT OUTBOARD WHEEL P/N: 5012373, S/N: DEC99-1074. TIRE P/N: 027-697-0, S/N: 3171P05134. INSTALLED OVERHAULED WHEEL P/N: 5012373, S/N: MAY11-3427. NEW TIRE P/N: 027-697-0, S/N: 3171P05134 AIRCRAFT SPECIALTIES INC. TRACKING #178787 WORK ORDER #178787 CRS #VT2R252L DATED 29/JAN/2024. IAW CL604 AMM 32-41-01. THIS CLEARS AMDL 41554.)						
32 40-00-207 Airframe INSPECTION #2 Main W #1246	LEFT INBOARD RESTORATION (OVERHAUL) OF THE MAIN LANDING GEAR WHEELS	06-DEC-2024					
	Part Number	Serial Number	H: 8600.30				
	5012373	MAR04-1810	L: 3958				
	Notes (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-207 LEFT INBOARD RESTORATION OF THE MAIN LANDING GEAR WHEEL BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY REMOVED LEFT INBOARD WHEEL ASSEMBLY P/N 5012373 S/N MAY12-3695 WITH WORN TIRE P/N 027-697-0 S/N 1216P05046 AND INSTALLED OVERHAULED WHEEL ASSEMBLY P/N 5012373 S/N MAR04-1810 WITH NEW TIRE H27X825-14/16/210 P/N 027-697-0 S/N 4132P05029 BUILD UP ASSEMBLY. SERVICED TO MAX PRESSURE WITH NITROGEN. IAW BOMBARDIER CL 604 AMM 32-41-01 REF 8130-3. #200573194 BOEING DISTRIBUTION INC. 674 MADISON ST., CROWN POINT IN 46307 MFG CERT AAC# LQ5R024N DATED 21OCT24 AND CLEARS AMDL 41573)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 40-00-207 Airframe INSPECTION #1 Main W #2362	LEFT OUTBOARD RESTORATION (OVERHAUL) OF THE MAIN LANDING GEAR WHEELS	06-DEC-2024					
	Part Number	Serial Number	H: 8600.30				
	5012373	MAR01-1344	L: 3958				
	<p>Notes</p> <p>(UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-206 LEFT OUTBOARD RESTORATION OF THE MAIN LANDING GEAR WHEEL BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED LEFT OUTBOARD WHEEL ASSEMBLY P/N 5012373 S/N JAN95-0027 WITH WORN TIRE P/N 027-697-0 S/N 3181P05167 AND INSTALLED OVERHAULED WHEEL ASSEMBLY P/N 5012373 S/N MAR01-1344 WITH NEW TIRE H27X825-14/16/210 P/N 027-697-0 S/N 3313P05163 BUILD UP ASSEMBLY. SERVICED TO MAX PRESSURE WITH NITROGEN. IAW BOMBARDIER CL 604 AMM 32-41-01 REF 8130-3. #200567951 BOEING DISTRIBUTION INC. 674 MADISON ST., CROWN POINT IN 46307 MFG CERT AAC# LQ5R024N DATED 10SEP24 AND CLEARS AMDL 41572)</p>						
32 40-00-207 Airframe INSPECTION #3 Main W #1135	RIGHT INBOARD RESTORATION (OVERHAUL) OF THE MAIN LANDING GEAR WHEELS	08-AUG-2024					
	Part Number	Serial Number	H: 8505.70				
	5012373	FEB16-4347	L: 3893				
	<p>Notes</p> <p>(UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-207 RIGHT INBOARD RESTORATION (OVERHAUL) OF THE MAIN LANDING GEAR WHEELS BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED RIGHT INBOARD WHEEL P/N: 5012373, S/N: JUL97-0375. TIRE P/N: 027-697-0, S/N: 3270P05206. INSTALLED OVERHAULED WHEEL P/N: 5012373, S/N: FEB16-4347. NEW TIRE P/N: 027-697-0, S/N: 3194P05131 AIRCRAFT SPECIALTIES INC. TRACKING #178788 WORK ORDER #178788 CRS #VT2R252L DATED 26/JAN/2024. IAW CL604 AMM 32-41-01. THIS CLEARS AMDL 41553.)</p>						
32 40-00-207 Airframe INSPECTION #4 Main W #435	RIGHT OUTBOARD RESTORATION (OVERHAUL) OF THE MAIN LANDING GEAR WHEELS	08-AUG-2024					
	Part Number	Serial Number	H: 8505.70				
	5012373	MAY11-3427	L: 3893				
	<p>Notes</p> <p>(UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-207 RIGHT OUTBOARD RESTORATION (OVERHAUL) OF THE MAIN LANDING GEAR WHEELS BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED RIGHT OUTBOARD WHEEL P/N: 5012373, S/N: DEC99-1074. TIRE P/N: 027-697-0, S/N: 3171P05134. INSTALLED OVERHAULED WHEEL P/N: 5012373, S/N: MAY11-3427. NEW TIRE P/N: 027-697-0, S/N: 3171P05134 AIRCRAFT SPECIALTIES INC. TRACKING #178787 WORK ORDER #178787 CRS #VT2R252L DATED 29/JAN/2024. IAW CL604 AMM 32-41-01. THIS CLEARS AMDL 41554.)</p>						
32 40-00-208 Airframe INSPECTION LH Nose W #3530	LEFT DETAILED INSPECTION OF THE NOSE LANDING GEAR WHEELS	08-AUG-2024					
	Part Number	Serial Number	H: 8505.70				
	5010598	APR12-7988	L: 3893				
	<p>Notes</p> <p>(AVG MAN HRS: 8) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-208 LEFT DETAILED INSPECTION OF NOSE LANDING HEAR WHEEL BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED LEFT NOSE WHEEL P/N: 5010598, S/N: AUG03-5056. TIRE P/N: 031-614-0, S/N: 2336T00408. INSTALLED OVERHAULED WHEEL ASSY P/N: 5010598, S/N: APR12-7988. NEW TIRE P/N: 031-614-0, S/N: 2130T00349. SCR. TRACKING #011148.1 WORK ORDER #101KF022302 CRS #4SMR148C DATED 21/FEB/2023. IAW CL604 AMM 32-42-01. THIS CLEARS AMDL 41555.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 40-00-208 Airframe INSPECTION RH Nose W #2979	RIGHT DETAILED INSPECTION OF THE NOSE LANDING GEAR WHEELS Part Number Serial Number 5010598 JUL06-6261	08-AUG-2024 H: 8505.70 L: 3893					
Notes (AVG MAN HRS: 8) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-208 RIGHT DETAILED INSPECTION OF NOSE LANDING HEAR WHEEL BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED RIGHT NOSE WHEEL P/N: 5010598, S/N: AUG98-1691/S-JAN00-0063. TIRE P/N: 031-614-0, S/N: 3099T00502. INSTALLED OVERHAULED WHEEL ASSY P/N: 5010598, S/N: JUL06-6261. NEW TIRE P/N: 031-614-0, S/N: 1285T00445. SCR.N. TRACKING #010563.1 WORK ORDER #22-01376 CRS #4SMR148C DATED 08/DEC/2022. IAW CL604 AMM 32-42-01. THIS CLEARS AMDL 41556.)							
32 40-00-209 Airframe INSPECTION LH Nose W #3290	LEFT RESTORATION (OVERHAUL) OF THE NOSE LANDING GEAR WHEELS Part Number Serial Number 5010598 APR12-7988	08-AUG-2024 H: 8505.70 L: 3893					
Notes (AVG MAN HRS: 7.5) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-209 LEFT RESTORATION (OVERHAUL) OF THE NOSE LANDING GEAR WHEELS BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED LEFT NOSE WHEEL P/N: 5010598, S/N: AUG03-5056. TIRE P/N: 031-614-0, S/N: 2336T00408. INSTALLED OVERHAULED WHEEL ASSY P/N: 5010598, S/N: APR12-7988. NEW TIRE P/N: 031-614-0, S/N: 2130T00349. SCR.N. TRACKING #011148.1 WORK ORDER #101KF022302 CRS #4SMR148C DATED 21/FEB/2023. IAW CL604 AMM 32-42-01. THIS CLEARS AMDL 41555.) (NOTE: NOTE 17: THE ABSC WHEELS RECOMMENDED INSPECTION SCHEDULE FOUND IN THIS PROGRAM NOTE IS COPIED FROM ABSC GENERAL SERVICE LETTER GS-SL-36 REVISION NO.7. (REFER TO CMM 32-42-28 FOR MAIN							
32 40-00-209 Airframe INSPECTION RH Nose W #3155	RIGHT RESTORATION (OVERHAUL) OF THE NOSE LANDING GEAR WHEELS Part Number Serial Number 5010598 JUL06-6261	08-AUG-2024 H: 8505.70 L: 3893					
Notes (AVG MAN HRS: 7.5) (UPDATE NOTE: COMPLIED WITH INSPECTION TASK 32-40-00-209 RIGHT RESTORATION (OVERHAUL) OF THE NOSE LANDING GEAR WHEELS BY INSTALLATION OF OVERHAULED WHEEL ASSEMBLY. REMOVED RIGHT NOSE WHEEL P/N: 5010598, S/N: AUG98-1691/S-JAN00-0063. TIRE P/N: 031-614-0, S/N: 3099T00502. INSTALLED OVERHAULED WHEEL ASSY P/N: 5010598, S/N: JUL06-6261. NEW TIRE P/N: 031-614-0, S/N: 1285T00445. SCR.N. TRACKING #010563.1 WORK ORDER #22-01376 CRS #4SMR148C DATED 08/DEC/2022. IAW CL604 AMM 32-42-01. THIS CLEARS AMDL 41556.) (NOTE: NOTE 17: THE ABSC WHEELS RECOMMENDED INSPECTION SCHEDULE FOUND IN THIS PROGRAM NOTE IS COPIED FROM ABSC GENERAL SERVICE LETTER GS-SL-36 REVISION NO.7. (REFER TO CMM 32-42							
32 41-01 Airframe INSPECTION #2 Main W, #2 Brake #2946	MAIN WHEEL AXLE SPACER INSTALLATION AND ORIENTATION VERIFICATION (LEFT INBOARD) Part Number Serial Number 5012373 MAR04-1810						
32 41-01 Airframe INSPECTION #1 Brake, #1 Main W #3598	MAIN WHEEL AXLE SPACER INSTALLATION AND ORIENTATION VERIFICATION (LEFT OUTBOARD) Part Number Serial Number 5012373 MAR01-1344						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 41-01 Airframe INSPECTION #3 Main W, #3 Brake #2955	MAIN WHEEL AXLE SPACER INSTALLATION AND ORIENTATION VERIFICATION (RIGHT INBOARD) Part Number: 5012373 Serial Number: FEB16-4347						
32 41-01 Airframe INSPECTION #4 Main W, #4 Brake #2299	MAIN WHEEL AXLE SPACER INSTALLATION AND ORIENTATION VERIFICATION (RIGHT OUTBOARD) Part Number: 5012373 Serial Number: MAY11-3427						
32 50-00-201 Airframe INSPECTION PKG 400 Hour #63	OPERATIONAL TEST OF THE NOSEWHEEL STEERING SELECTOR AND ARMING VALVE Notes (AVG MAN HRS: 2) (TOL. ADJUSTMENT: 19.6 HRS) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00	H: 40.00		H: 8875.40	H: 180.30
32 50-00-202 Airframe INSPECTION PKG1200Hour #1674	NLG OPERATIONAL TEST OF THE NOSEWHEEL STEERING ELECTRONIC-CONTROL- MODULE (ECM), PART NO. 601-86100-13. VENDOR PART NO. 7040-13/15 Notes (AVG MAN HRS: 2) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
32 51-04-101 Airframe PART - Life Limited #3735	DISCARD OF THE NOSEWHEEL STEERING CONTROL POTENTIOMETER COUPLING SETSCREWS (POST SB 604-32-033) Notes Aligned with 96 M. Once SB 604-32-033 is completed tracking of setscrew discard will need adjusted.		M: 96			30-APR-2029	M: 34 D: 29
32 51-10-101 Airframe INSPECTION #2057	FUNCTIONAL TEST OF THE TRANSFER VALVE OF THE STEERING CONTROL MANIFOLD Notes (SOURCE: MPD, TLMC) (NOTE: PHASE-IN: FOR AIRCRAFT WITH 3600 HOURS OR MORE, AS OF THE DATE OF SEP 30/2024, THIS TASK MUST BE ACCOMPLISHED WITHIN 400 HOURS.)		H: 4000.00			H: 8957.60	H: 262.50



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
32 ZL-00-204 Airframe INSPECTION PKG 48 Month #3244	GENERAL VISUAL INSPECTION OF THE NOSE LANDING - GEAR DOOR - LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
32 ZL-00-205 Airframe INSPECTION PKG 48 Month #3544	GENERAL VISUAL INSPECTION OF THE NOSE LANDING - GEAR DOOR - RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
32 ZL-00-206 Airframe INSPECTION PKG 48 Month #2239	GENERAL VISUAL INSPECTION OF THE AFT NOSE LANDING - GEAR DOOR	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
32 ZL-00-207 Airframe INSPECTION PKG 48 Month #3263	GENERAL VISUAL INSPECTION OF THE MAIN LANDING - GEAR DOOR - LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
32 ZL-00-208 Airframe INSPECTION PKG 48 Month #2485	GENERAL VISUAL INSPECTION OF THE MAIN LANDING - GEAR DOOR - RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
33 Airframe PART #2616	AFT EMERGENCY LIGHTING POWER SUPPLY BATTERY						
	Part Number	Serial Number					
	61-0478-9	58676					
	Notes (APX COST: 0) (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 Airframe PART #2697	AFT FUSE UNIT, POWER SUPPLY, BEACON LIGHT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
33 Airframe PART #2098	AFT UNIT, POWER SUPPLY, EMERGENCY Part Number: 61-0478-9 Serial Number: NSN	26-MAY-2026			H: 8686.90 L: 3999		
	Notes (ZONE: BAGGAGE BAY) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
33 Airframe PART #111	CABIN UNIT, POWER SUPPLY, EMERGENCY Part Number: 60-1321-1 Serial Number: 23116	31-MAY-2025			H: 8649.70 L: 3986		
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
33 Airframe PART #3573	CENTER PEDESTAL LIGTHING CONTROL PANEL POTENTIOMETER Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
33 Airframe PART #1826	CO-PILOT MAP LIGHT Part Number: 2LA005163-20 Serial Number: 6559305	31-MAY-2025			H: 8649.70 L: 3986		
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
33 Airframe PART #2254	COCKPIT UNIT, POWER SUPPLY, EMERGENCY Part Number: 60-1321-1 Serial Number: 270757	31-MAY-2025			H: 8649.70 L: 3986		
33 Airframe PART #1621	CONTROL UNIT, PULSELITE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: AVIONIC BAY)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 Airframe PART #3106	CONTROLLER, LIGHTING Part Number Unknown Serial Number Unknown	15-OCT-1997					
	Notes (ZONE: CENTER PEDESTAL)						
33 Airframe PART #65	COPILOT LIGHT, READING, MAP Part Number Unknown Serial Number Unknown	15-OCT-1997					
33 Airframe PART #2512	FORWARD EMERGENCY LIGHTING POWER SUPPLY BATTERY Part Number 55-2198-1 Serial Number NSN	22-APR-2024 H: 8368.00 L: 3817					
	Notes (APX COST: 0) (UPDATE NOTE: REMOVED OLD BATTERY P/N 55-2198-1 S/N 59804 INSTALLATION OF NEW BATTERY PACKS P/N 55-2198-1 NSN IAW HONEYWELL EMERGENCY EXIT LIGHT POWER SUPPLY CMM TASK 33-50-42-400-801-A01. OPERATIONAL TEST SATISFACTORY.)						
33 Airframe PART #311	FORWARD LIGHTING POWER SUPPLY FORWARD GALLEY Part Number AL2000 Serial Number 4527	02-JUL-2021 H: 6939.60 L: 3034					
	Notes (ZONE: GALLEY) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)						
33 Airframe PART #2583	FWD UNIT, POWER SUPPLY, EMERGENCY Part Number 61-0478-9 Serial Number NSN	26-MAY-2026 H: 8686.90 L: 3999					
33 Airframe PART #14	LAV ORDINANCE LIGHT Part Number 1643-1-19 Serial Number 0406074	31-MAY-2025 H: 8649.70 L: 3986					
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 Airframe PART #215	LEFT LIGHT, ANTI-COLLISION Part Number: 2LA006178-03 Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: WING)						
33 Airframe PART #1929	LEFT NO.1 LIGHTING POWER SUPPLY Part Number: 61-0476-9 Serial Number: NA	26-JUL-2019 H: 6476.10 L: 2770					
33 Airframe PART #2656	LEFT UNIT, POWER SUPPLY, STROBE Part Number: 8ES005421-09 Serial Number: 1128	15-OCT-1997					
	Notes (ZONE: WING)						
33 Airframe PART #3707	LIGHT ASSY, TAIL ANTI-COLLISION Part Number: 2LA006181-01 Serial Number: 3523	30-JUN-2022 H: 7604.00 L: 3395					
	Notes (APX COST: 0) (UPDATE NOTE: REMOVED AFT NAVIGATION/STROBE LIGHT ASSEMBLY, P/N 2LA006181-01 S/N 493, AND INSTALLED NEW NAVIGATION/STROBE LIGHT ASSEMBLY, P/N 2LA006181-01 S/N 3523, IAW CL604 AMM REVISION 96 TASK 33-42-10-400-801. OPERATIONAL CHECK SATISFACTORY.)						
33 Airframe PART #1698	LOWER LIGHT, RED STROBE (BEACON LIGHT) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
33 Airframe PART #26	MID CABIN 1 EMERGENCY LIGHTING POWER SUPPLY Part Number: 61-0478-9 Serial Number: NSN	26-MAY-2026 H: 8686.90 L: 3999					
33 Airframe PART #1149	MID CABIN 1 EMERGENCY LIGHTING POWER SUPPLY BATTERY Part Number: 55-2198-1 Serial Number: NSN	22-APR-2024 H: 8368.00 L: 3817					
	Notes (APX COST: 0) (UPDATE NOTE: REMOVED OLD BATTERY P/N 55-2198-1 NSN INSTALLED OF NEW BATTERY PACKS P/N 55-2198-1 NSN IAW HONEYWELL EMERGENCY EXIT LIGHT POWER SUPPLY CMM TASK 33-50-42-400-801-A01. OPERATIONAL TEST SATISFACTORY.)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 Airframe PART #2635	MID EMERGENCY POWER SUPPLY BATTERY PACK Part Number: 61-0478-9 Serial Number: N/A	12-JAN-2018 H: 6249.00 L: 2676					
33 Airframe PART #2950	NAVIGATION LIGHTS TRANSFORMER Part Number: BP0338A Serial Number: Unknown	15-OCT-1997					
33 Airframe PART #1731	NO.1 A/C DIMMER Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
33 Airframe PART #2467	NO.1 LAV LIGHTING POWER SUPPLY Part Number: AL2000 Serial Number: 57391	06-JAN-2012 H: 4413.00 L: 1898					
33 Airframe PART #2750	NO.1 POWER SUPPLY Part Number: AL2000 Serial Number: 33011	26-NOV-2002 H: 1492.40 L: 551					
33 Airframe PART #369	NO.2 A/C DIMMER Part Number: 2-459-06 Serial Number: Unknown	15-OCT-1997					
33 Airframe PART #928	NO.2 POWER SUPPLY Part Number: AL2000 Serial Number: 33013	26-NOV-2002 H: 1492.40 L: 551					
33 Airframe PART #2480	NO.3 A/C DIMMER Part Number: 2-459-06 Serial Number: Unknown	15-OCT-1997					
33 Airframe PART #272	NO.3 POWER SUPPLY Part Number: AL2000 Serial Number: 32974	26-NOV-2002 H: 1492.40 L: 551					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 Airframe PART #1235	NO.4 A/C DIMMER Part Number 2-459-06 Serial Number Unknown	15-OCT-1997					
33 Airframe PART #2066	NO.4 POWER SUPPLY Part Number AL2000 Serial Number 32964	26-NOV-2002 H: 1492.40 L: 551					
33 Airframe PART #2935	NO.5 A/C DIMMER Part Number 2-459-06 Serial Number Unknown	15-OCT-1997					
33 Airframe PART #3395	NO.6 A/C DIMMER Part Number 2-459-06 Serial Number Unknown	15-OCT-1997					
33 Airframe PART #2231	NO.7 A/C DIMMER Part Number 2-459-06 Serial Number Unknown	15-OCT-1997					
33 Airframe PART #3618	NO.8 A/C DIMMER Part Number 2-459-06 Serial Number Unknown	15-OCT-1997					
33 Airframe PART #310	OVERHEAD POWER SUPPLY Part Number 449-2 Serial Number Unknown	15-OCT-1997					
33 Airframe PART #2846	PILOT LIGHT, READING, MAP Part Number Unknown Serial Number Unknown	15-OCT-1997					
33 Airframe PART #2799	POWER SUPPLY UNIT (LAV) Part Number AL2000 Serial Number 57395	06-JAN-2012 H: 4413.00 L: 1898					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 Airframe PART #1541	RIGHT LIGHT, ANTI-COLLISION Part Number: 2LA006178-03 Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: WING)						
33 Airframe PART #642	RIGHT UNIT, POWER SUPPLY, STROBE Part Number: 8ES005421-09 Serial Number: 1146	15-OCT-1997					
	Notes (ZONE: WING)						
33 Airframe PART #2002	UNIT, POWER SUPPLY, STROBE Part Number: 8ES005421-09 Serial Number: 1151	15-OCT-1997					
	Notes (ZONE: TAIL)						
33 Airframe PART #681	UPPER LIGHT, RED STROBE (BEACON LIGHT) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
33 Airframe PART #2130	UPPER LIGHTING POWER SUPPLY UPPER GALLEY #1 Part Number: AL2000 Serial Number: 5049	02-JUL-2021 H: 6939.60 L: 3034					
	Notes (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)						
33 Airframe PART #1791	UPPER LIGHTING POWER SUPPLY UPPER GALLEY #2 Part Number: AL2000 Serial Number: 5054	02-JUL-2021 H: 6939.60 L: 3034					
	Notes (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 50-00-002 Airframe INSPECTION PKG 12 Month #3377	EMERGENCY-LIGHTING POWER SUPPLY AND SYSTEM- TEST THE EMERGENCY-LIGHTING POWER SUPPLIES AND SYSTEM PER REFERENCE (REF 33-50-00)	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 11 D: 25
	Notes (TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
33 50-00-101 Airframe INSPECTION PKG 12 Month #739	FUNCTIONAL TEST MID CABIN L/H EMERGENCY LIGHTING POWER SUPPLY	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 11 D: 25
	Notes (AVG MAN HRS: 3)						
33 50-00-201 Airframe INSPECTION PKG 12 Month #2288	FWD FUNCTIONAL TEST OF THE EMERGENCY LIGHTS POWER SUPPLIES	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 11 D: 25
	Notes (AVG MAN HRS: 6) (TOL. ADJUSTMENT: -45D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: NOTE 18: THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION)						
33 50-00-202 Airframe INSPECTION PKG 12 Month #1005	OPERATIONAL TEST OF THE EMERGENCY LIGHTS	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 11 D: 25
	Notes (AVG MAN HRS: 1)						
33 51-51-711 Airframe INSPECTION #2308	EMERGENCY LIGHTING SYSTEM - OPERATIONAL TEST	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 11 D: 25
	Notes (TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
33 ERO-986602 Airframe INSPECTION #1336	DOME BOARDING LIGHT DEACTIVATION - TEMP REPAIR Notes (UPDATE NOTE: AT A PERIOD, NOT TO EXCEED 300 FLIGHT HOURS, THE DISCREPANCY MUST BE REPAIRED BY PART REPLACEMENT OF REPAIRED PER OEM OR ENGINEERING PROCEDURES.)	H: 8650.80	H: 300.00			H: 8950.80	H: 255.70
34 Airframe PART #614	(DBU), DATA BASE UNIT (DATA LOADER) Part Number Serial Number 822-3000-302 4DV3L7	27-DEC-2018				H: 6424.10 L: 2747	
34 Airframe PART #1470	AFT - LEFT PROBE, 3RD PITOT STATIC Part Number Serial Number 0851HF 373659	28-MAR-2018				H: 6319.00 L: 2697	
34 Airframe PART #3064	AFT ANTENNA, RADIO ALTIMETER (NO.1 SYSTEM) Part Number Serial Number S67-2002 Unknown	15-OCT-1997					
34 Airframe PART #3555	AFT ANTENNA, RADIO ALTIMETER (NO.2 SYSTEM) Part Number Serial Number Unknown Unknown	15-OCT-1997					
34 Airframe PART #257	AFT FUSE LIGHTNING DETECTION SYSTEM ANTENNA (TOP SKIN) Part Number Serial Number Unknown Unknown	15-OCT-1997					
34 Airframe PART #2437	AIS-360 Part Number Serial Number Unknown Unknown	15-OCT-1997					
34 Airframe PART #1775	ALTIMETER, STANDBY INDICATOR Part Number Serial Number 1611AM8 AH471	08-FEB-2023				H: 7925.20 L: 3563	
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 Airframe PART #2580	ANTENNA, DUAL ADF Part Number: 622-7384-001 Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: FWD LOWER FUSE)						
34 Airframe PART #2664	ANTENNA, GLIDESLOPE Part Number: S41422-2 Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: RADOME AREA)						
34 Airframe PART #3494	ANTENNA, MARKER BEACON Part Number: S35-1000-2 Serial Number: 2071	15-OCT-1997					
34 Airframe PART #3600	ANTENNA, WEATHER RADAR, RTA-854 Part Number: 622-8440-004 Serial Number: 1LVNB	22-NOV-2019 H: 6494.20 L: 2785					
	Notes (ZONE: RADOME) (APX COST: 1) (UPDATE NOTE: DUNCAN REPLACED UNIT W/ TESTED UNIT IAW 604 MM 34-41-01-000-801 SEE DUNCAN WO 73N5A)						
34 Airframe PART #2768	APM-5000 Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #2490	COMPASS, STANDBY, WITH LIGHT ASSY Part Number: PAI700-5V Serial Number: 62891	27-SEP-2017 H: 6177.60 L: 2644					
34 Airframe PART #724	DATA LINK UNIT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 Airframe PART #2068	EGPWS COMPUTER Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
Notes (ZONE: AVIONIC BAY)							
34 Airframe PART #1284	FWD - RIGHT SENSOR, TEMPERATURE, TOTAL Part Number: 102AH2AG Serial Number: A16006	15-OCT-1997					
34 Airframe PART #963	FWD ANTENNA, RADIO ALTIMETER (NO.1 SYSTEM) Part Number: 567-2002 Serial Number: 543-66526	14-MAR-2025 H: 8631.50 L: 3977					
Notes (UPDATE NOTE: COMPLIED WITH BY DIRECT MX AVIATION CRS FMSR378E ON WORK ORDER CRS250047 DATED 14 MARCH 2025)							
34 Airframe PART #1933	FWD ANTENNA, RADIO ALTIMETER (NO.2 SYSTEM) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #1953	GPS RECEIVER Part Number: 8432-50 Serial Number: 1842K853	27-DEC-2018 H: 6424.10 L: 2747					
34 Airframe PART #3528	GROUND PROXIMITY WARNING DISPLAY UNIT Part Number: 965-0976-003-216 Serial Number: 20408	28-JUL-2005 H: 2522.30 L: 983					
34 Airframe PART #2921	INDICATOR, MACH, AIRSPEED Part Number: 8059-2B Serial Number: Unknown	15-OCT-1997					
Notes (NOTE: APPLICABLE TO AIRCRAFT 5301 TO 5318 THAT ARE PRE SB 604-34-013)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 Airframe PART #1355	INDICATOR, STANDBY AIRSPEED Part Number: 273AS5 Serial Number: AK217	15-OCT-1997					
	Notes (NOTE: APPLICABLE TO AIRCRAFT POST SB 604-34-013)						
34 Airframe PART #2488	INDICATOR, STANDBY HORIZON Part Number: 501-1197-23 Serial Number: 6146	24-MAY-2016 H: 5737.30 L: 2490					
	Notes (ZONE: AVIONIC BAY)						
34 Airframe PART #3724	INSTRUMENT, INTEGRATED STANDBY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: AVIONIC BAY)						
34 Airframe PART #1234	LEFT AIR DATA REF (ARP4000) PANEL Part Number: 622-9819-006 Serial Number: 1131	15-OCT-1997					
34 Airframe PART #770	LEFT ANTENNA, L-BAND (ATC 1 / AFT UPPER) Part Number: S65-5366-7L Serial Number: 54232	14-JUL-2004 H: 2246.20 L: 857					
34 Airframe PART #149	LEFT ANTENNA, L-BAND (ATC 1 / FWD LOWER) Part Number: S65-5366-7L Serial Number: 37985	15-OCT-1997					
34 Airframe PART #2896	LEFT ANTENNA, VOR/LOC Part Number: S65-247170-7 Serial Number: 180-3449	22-JUL-2007 H: 3086.90 L: 1244					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 Airframe PART #934	LEFT DISPLAY CONTROL PANEL (DCP) Part Number: 622-9812-206 Serial Number: 938	28-JUL-2005 H: 2522.30 L: 983					
Notes (ZONE: CENTER PEDESTAL)							
34 Airframe PART #1983	LEFT NO.1 MODULE, AIRCRAFT PERSONALITY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #2217	LEFT NO.3 MODULE, AIRCRAFT PERSONALITY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #1181	LEFT PORT STATIC PRESSURE RT Part Number: ST315-3L Serial Number: AS10220209	11-JUL-2023 H: 8075.40 L: 3647					
Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)							
34 Airframe PART - Life Limited #3391	LEFT PROBE, PITOT STATIC, RVSM Part Number: 0856KV9 Serial Number: 222946	30-JUL-2005 H: 2522.30 L: 983	H: 9600.00		M: 0 H: 0.00 L: 0	H: 12122.30	H: 3427.20
Notes (RII ITEM) (AVG MAN HRS: 10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
34 Airframe PART #1440	LEFT RECEIVER, GPS (GPS 4000S) Part Number: 822-0931-003 Serial Number: 585	17-JAN-2024 H: 8242.90 L: 3740					
Notes (ZONE: POS 1 STA270) (UPDATE NOTE: WORK PERFORMED BY DUNCAN AVIATION CRS JGVR194F ON WO K77CA)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 Airframe PART #2787	LEFT RECEIVER, VOR/IIL/MKR/ADF, NAV-4000 Part Number: 622-7382-101 Serial Number: Unknown	15-OCT-1997					
Notes (ZONE: AVIONIC BAY)							
34 Airframe PART #3537	LEFT TRANSCEIVER, DME (DME-4000) Part Number: 622-7309-101 Serial Number: 1853	27-FEB-2021 H: 6820.60 L: 2975					
Notes (ZONE: AVIONIC BAY) (UPDATE NOTE: WORK COMPLETED BY BOCCA AIRCRAFT MAINTENANCE UNDER WO#OPF-CRS21-11079 DATED 27/FEB/2021.)							
34 Airframe PART #1514	LEFT TRANSPONDER, ATC MODE S Part Number: 622-9210-501 Serial Number: 3629	31-MAY-2025 H: 8649.70 L: 3986					
Notes (RII ITEM) (ZONE: FS260) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
34 Airframe PART #3590	LOWER ANTENNA, TCAS Part Number: S65-5366-7L Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #1641	LOWER ANTENNA, TCAS (CUSTOMER OPTION) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #3282	MD-302 Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #2331	MMT-125 RACK Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 Airframe PART #1204	NO.1 AFD-3700 Part Number Unknown Serial Number Unknown	15-OCT-1997					
34 Airframe PART #461	NO.1 ANTENNA, GPS Part Number S67-1575-52 Serial Number Unknown	15-OCT-1997					
34 Airframe PART #766	NO.1 ANTENNA, L-BAND (DME 1 / LOWER FWD.) Part Number S65-5366-7L Serial Number Unknown	15-OCT-1997					
34 Airframe PART #1797	NO.1 CCP-3500 Part Number Unknown Serial Number Unknown	15-OCT-1997					
34 Airframe PART #3438	NO.1 COMPUTER, AIR DATA (ADC850E) Part Number 822-0842-421 Serial Number 4692	22-NOV-2019 H: 6494.20 L: 2785					
	Notes (RII ITEM) (APX COST: 1) (UPDATE NOTE: DUNCAN REPLACED UNIT W/ TESTED UNIT IAW 604 MM 34-13-01-400-801 SEE DUNCAN WO 73N5A)						
34 Airframe PART #3688	NO.1 CONVERTER, RADIO ALTIMETER (RAC-870) Part Number Unknown Serial Number Unknown						
34 Airframe PART #1599	NO.1 INERTIAL REFERENCE UNIT (IRU) Part Number 465020-0400-0600 Serial Number 1957	20-APR-2006 H: 2605.60 L: 1024					
34 Airframe PART #1640	NO.1 MKP-3500 Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 Airframe PART #1472	NO.1 PANEL, IRS MODE SELECTOR UNIT Part Number: 856-0075-020 Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #2022	NO.1 PCM Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #1316	NO.1 RADIO ALTIMETER, TRANSCEIVER Part Number: 622-2855-011 Serial Number: 1KDU	14-MAR-2025 H: 8631.50 L: 3977					
Notes (APX COST: 0) (UPDATE NOTE: COMPLIED WITH BY DIRECT MX AVIATION CRS FMSR378E ON WORK ORDER CRS250047 DATED 14 MARCH 2025)							
34 Airframe PART #2049	NO.1 RECEIVER, VHF NAVIGATION (VIR-432) Part Number: 622-7194-201 Serial Number: 3782	15-OCT-1997					
34 Airframe PART #476	NO.1 SKP-3500 Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #632	NO.1 TRAY, MOUNTING, UMT-12 Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
Notes (ZONE: AFT BAY)							
34 Airframe PART #1733	NO.1 UNIT, DISPLAY CONTROL (CDU) Part Number: 822-0867-006 Serial Number: 288	19-SEP-2023 H: 8126.30 L: 3679					
Notes (ZONE: AVIONIC BAY) (APX COST: 0) (UPDATE NOTE: REMOVED FMS #1 P/N 822-0867-006 S/N 202 AND INSTALLED FMS #2 P/N 822-0867-006 S/N 288 IAW BOMBARDIER 604 AMM 34-61-01. OPERATIONAL CHECK COMPLETED AND PASSED. FOR TROUBLESHOOTING PURPOSES.)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 Airframe PART #2845	NO.1 WEATHER RADAR CONTROL PANEL (WXP4220) Part Number: 622-9932-002 Serial Number: 785	15-OCT-1997					
34 Airframe PART #1271	NO.2 AFD-3700 Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #1523	NO.2 ANTENNA, GPS Part Number: S67-1575-135 Serial Number: 512-33015	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)							
34 Airframe PART #1055	NO.2 ANTENNA, L-BAND (DME 2 / LOWER AFT.) Part Number: S65-5366-7L Serial Number: 37050	15-OCT-1997					
34 Airframe PART #3103	NO.2 CCP-3500 Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #2942	NO.2 COMPUTER, AIR DATA (ADC850E) Part Number: 822-0842-421 Serial Number: 272GL	02-JUL-2021 H: 6939.60 L: 3034					
Notes (RII ITEM) (UPDATE NOTE: OVERHAULED BY ROCKWELL COLLINS, INC. CRS NZ2R049L UNDER FORM TRACKING NUMBER 105936937 DATED 04 NOV 2020.)							
34 Airframe PART #560	NO.2 CONVERTER, RADIO ALTIMETER (RAC-870) (POST SB 604-34-005) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #3647	NO.2 INERTIAL REFERENCE UNIT (IRU) Part Number: 465020-0400-0600 Serial Number: 5029	27-APR-2012 H: 4524.00 L: 1940					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 Airframe PART #2431	NO.2 MKP-3500 Part Number Unknown Serial Number Unknown	15-OCT-1997					
34 Airframe PART #1684	NO.2 PANEL, IRS MODE SELECTOR UNIT Part Number Unknown Serial Number Unknown	15-OCT-1997					
34 Airframe PART #1976	NO.2 PCM Part Number Unknown Serial Number Unknown	15-OCT-1997					
34 Airframe PART #1636	NO.2 RADIO ALTIMETER, TRANSCEIVER (POST SB 604-34-005) Part Number Unknown Serial Number Unknown	15-OCT-1997					
34 Airframe PART #811	NO.2 RECEIVER, VHF NAVIGATION (VIR-432) Part Number 622-7194-201 Serial Number 3677	15-OCT-1997					
34 Airframe PART #1598	NO.2 SKP-3500 Part Number Unknown Serial Number Unknown	15-OCT-1997					
34 Airframe PART #851	NO.2 TRAY, MOUNTING, UMT-12 Part Number Unknown Serial Number Unknown	15-OCT-1997					
	Notes (ZONE: AFT BAY)						
34 Airframe PART #1553	NO.2 UNIT, DISPLAY CONTROL (CDU) Part Number 822-0867-006 Serial Number 202	19-SEP-2023 H: 8126.30 L: 3679					
	Notes (ZONE: AVIONIC BAY) (APX COST: 1) (UPDATE NOTE: REMOVED FMS #2 P/N 822-0867-006 S/N 288 AND INSTALLED FMS #1 P/N 822-0867-006 S/N 202 IAW BOMBARDIER 604 AMM 34-61-01. OPERATIONAL CHECK COMPLETED AND PASSED. FOR TROUBLESHOOTING PURPOSES.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 Airframe PART #401	NO.2 WEATHER RADAR CONTROL PANEL (WXP4220) (OPTIONAL - POST SB 604-34-006) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #1758	NO.3 AFD-3700 Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #2692	NO.3 INERTIAL REFERENCE UNIT (IRU) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #1824	NO.3 PANEL, IRS MODE SELECTOR UNIT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #1375	NO.3 TRANSMITTER, AOA (3RD VANE) Part Number: 856-0077-010 Serial Number: FK1068	15-OCT-1997					
34 Airframe PART #1963	NO.3 UNIT, DISPLAY CONTROL (CDU) Part Number: 822-0867-006 Serial Number: 130	19-SEP-2023			H: 8126.30 L: 3679		
	Notes (APX COST: 0)						
34 Airframe PART #3148	PROCESSOR, LDS (REAR FUSE) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: STA755 LBL 5.0)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 Airframe PART #2060	REAR FUSE LIGHTNING DETECTION SYSTEM ANTENNA Part Number: Unknown Serial Number: Unknown Notes (ZONE: STA745)	15-OCT-1997					
34 Airframe PART #1126	RIGHT AIR DATA REF (ARP4000) PANEL Part Number: 622-9819-006 Serial Number: 1049	15-OCT-1997					
34 Airframe PART #1732	RIGHT ANTENNA, L-BAND (ATC 2 / AFT UPPER) Part Number: S65-5366-7L Serial Number: Unknown	15-OCT-1997					
34 Airframe PART #1315	RIGHT ANTENNA, L-BAND (ATC 2 / FWD LOWER) Part Number: S65-5366-7L Serial Number: 38014	15-OCT-1997					
34 Airframe PART #1513	RIGHT ANTENNA, VOR/LOC Part Number: S65-247170-7 Serial Number: 180-3450	22-JUL-2007 H: 3086.90 L: 1244					
34 Airframe PART #3514	RIGHT DISPLAY CONTROL PANEL (DCP) Part Number: 622-9812-206 Serial Number: 897 Notes (ZONE: CENTER PEDESTAL)	28-MAR-2007 H: 2946.40 L: 1180					
34 Airframe PART #725	RIGHT NO.2 MODULE, AIRCRAFT PERSONALITY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 Airframe PART #357	RIGHT PORT STATIC PRESSURE RT Part Number ST315-3R Serial Number AS0921357 7	11-JUL-2023 H: 8075.40 L: 3647					
Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)							
34 Airframe PART - Life Limited #1856	RIGHT PROBE, PITOT STATIC, RVSM Part Number 856KV10 Serial Number 290535	27-JAN-2015 H: 5388.20 L: 2339	H: 9600.00		M: 1 H: 0.00	H: 14988.20	H: 6293.10
Notes (RII ITEM) (AVG MAN HRS: 10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
34 Airframe PART #1110	RIGHT RECEIVER, GPS (GPS 4000S) Part Number 822-0931-003 Serial Number 587	17-JAN-2024 H: 8242.90 L: 3740					
Notes (ZONE: POS 2 STA270) (UPDATE NOTE: WORK PERFORMED BY DUNCAN AVIATION CRS JGVR194F ON WO K77CA)							
34 Airframe PART #2603	RIGHT RECEIVER, VOR/IIL/MKR/ADF, NAV-4000 Part Number 622-7382-101 Serial Number Unknown	15-OCT-1997					
Notes (ZONE: AVIONIC BAY)							
34 Airframe PART #1174	RIGHT TRANSCEIVER, DME (DME-4000) Part Number 622-7309-101 Serial Number 358LL	29-JUL-2016 H: 5818.50 L: 2515					
Notes (ZONE: AVIONIC BAY)							
34 Airframe PART #1255	RIGHT TRANSPONDER, ATC MODE S Part Number 622-9210-501 Serial Number 4541	31-MAY-2025 H: 8649.70 L: 3986					
Notes (RII ITEM) (ZONE: FS260)							



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 Airframe PART #42	RTU-4220 Part Number Unknown Serial Number Unknown	15-OCT-1997					
34 Airframe PART #3019	TTR-4000, TCAS II COMPUTER (S/W VER 7.1) Part Number 822-2911-001 Serial Number 4R30X Notes (ZONE: AVIONIC BAY)	23-NOV-2015 H: 5626.30 L: 2447					
34 Airframe PART #1337	UPPER ANTENNA, TCAS (FWD MID FUSE) Part Number 622-8973-001 Serial Number 24200	15-OCT-1997					
34 Airframe PART #3689	UPPER GPS ANTENNA Part Number S67-1575-165 Serial Number 818-11407	27-DEC-2018 H: 6424.10 L: 2747					
34 Airframe PART #1009	VOR/LOC COUPLER Part Number Unknown Serial Number Unknown						
34 11-00-201 Airframe INSPECTION PKG 24 Month #2267	FUNCTIONAL TEST OF THE PITOT-STATIC SYSTEM Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: NOTE 3: TASK AND INTERVAL MAY BE PART OF THE OPERATOR'S NATIONAL REGULATIONS. WHENEVER A TASK HAS TWO INTERVALS, ONE BEING NOTE 3", THE GREATER INTERVAL IS RECOMMENDED. WHEN A NATIONAL REGULATION DOES NOT EXIST, THE MRB REPORT INTERVAL SHALL BE FOLLOWED.)	31-MAY-2025 H: 8649.70 L: 3986	M: 24			29-MAY-2027	M: 11 D: 28
34 11-00-202 Airframe INSPECTION PKG 24 Month #2422	DETAILED INSPECTION OF THE PITOT-STATIC PROBES Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: NOTE 3: TASK AND INTERVAL MAY BE PART OF THE OPERATOR'S NATIONAL REGULATIONS. WHENEVER A TASK HAS TWO INTERVALS, ONE BEING NOTE 3", THE GREATER INTERVAL IS RECOMMENDED. WHEN A NATIONAL REGULATION DOES NOT EXIST, THE MRB REPORT INTERVAL SHALL BE FOLLOWED.)	31-MAY-2025 H: 8649.70 L: 3986	M: 24			29-MAY-2027	M: 11 D: 28



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 11-00-203 Airframe INSPECTION PKG 24 Month #941	SERVICING OF THE VISUAL DRAINS	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		31-MAY-2027	M: 11 D: 30
	<p>Notes</p> <p>(AVG MAN HRS: 1.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: NOTE 3: TASK AND INTERVAL MAY BE PART OF THE OPERATOR'S NATIONAL REGULATORY REQUIREMENTS. WHEN A TASK HAS 2 INTERVALS, ONE BEING "NOTE 3", THE MOST RESTRICTIVE INTERVAL APPLIES. WHEN A NATIONAL REGULATORY REQUIREMENT DOES NOT EXIST, THE MRB REPORT INTERVAL SHALL BE FOLLOWED.)</p>						
34 12-00-201 Airframe INSPECTION PKG 24 Month #3222	FUNCTIONAL TEST OF THE STANDBY BAROMETRIC ALTIMETER INDICATOR	31-MAY-2025 H: 8649.70 L: 3986	M: 24			29-MAY-2027	M: 11 D: 28
	<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: NOTE 3: TASK AND INTERVAL MAY BE PART OF THE OPERATOR'S NATIONAL REGULATIONS. WHENEVER A TASK HAS TWO INTERVALS, ONE BEING NOTE 3", THE GREATER INTERVAL IS RECOMMENDED. WHEN A NATIONAL REGULATION DOES NOT EXIST, THE MRB REPORT INTERVAL SHALL BE FOLLOWED.)</p>						
34 12-00-202 Airframe INSPECTION PKG 24 Month #1679	FUNCTIONAL TEST OF THE STANDBY AIRPSEED INDICATOR (ASI)	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 11 D: 30
	<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
34 13-00-102* Airframe INSPECTION #2142	NO.1 FUNCTIONAL TEST OF THE AIR DATA COMPUTER (ADC), (POST SB 604-34-012, RVSM QUALIFIED A/C)	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 11 D: 30
	<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
34 13-00-102* Airframe INSPECTION #2873	NO.2 FUNCTIONAL TEST OF THE AIR DATA COMPUTER (ADC), (POST SB 604-34-012, RVSM QUALIFIED A/C)	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 11 D: 30
	<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 54-00-201 Airframe INSPECTION PKG 24 Month #975	OPERATIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) TRANSPONDER SELECT SWITCH	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 11 D: 30
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: NOTE 3: TASK AND INTERVAL MAY BE PART OF THE OPERATOR'S NATIONAL REGULATIONS. WHENEVER A TASK HAS TWO INTERVALS, ONE BEING NOTE 3", THE GREATER INTERVAL IS RECOMMENDED. WHEN A NATIONAL REGULATION DOES NOT EXIST, THE MRB REPORT INTERVAL SHALL BE FOLLOWED.)						
34 61-00-201 Airframe INSPECTION PKG3200Hour #548	OPERATIONAL TEST OF THE FLIGHT MANAGMENT SYSTEMS (FMS) INHIBIT SWITCH	16-JUN-2018 H: 6372.80 L: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 1)						
34 9000 Airframe INSPECTION #2883	JLAC AVIONICS INSPECTION #1	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
	Notes (ZONE: --) (AVG MAN HRS: 3) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
34 9001 Airframe INSPECTION #2160	JLAC AVIONICS INSPECTION #2	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 11 D: 30
	Notes (ZONE: --) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
34 9002 Airframe INSPECTION #466	JLAC AVIONICS INSPECTION #3	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 11 D: 30
	Notes (ZONE: --) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
34 9004 Airframe INSPECTION #638	RADIO STATION LICENSE REPLACE	04-NOV-2019 H: 6485.50 L: 2778				29-MAY-2029	M: 35 D: 28
	Notes (ZONE: --) (UPDATE NOTE: INSTALLED JET LINX RADIO STATION LICENSE ON BOARD AIRCRAFT.) (NOTE: EXPIRY DATE ON LICENSE)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 9999.1 Airframe INSPECTION #1263	EGPWS DATABASE UPDATE	29-OCT-2025 H: 8656.00 L: 3990	M: 12			31-OCT-2026	M: 4 D: 30
	Notes (ZONE: --) (UPDATE NOTE: WORK ACCOMPLISHED BY DIRECT MX CRS # FMSR378E DATED 10/29/2025 SEE WORK ORDER # CRS250482.)						
34 FAR 91.411 Airframe INSPECTION FAA #1808	ALTIMETER STANDBY INDICATOR TESTS AND INSPECTIONS PER FAR 91.411	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 11 D: 30
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: FAA)						
34 FAR 91.411 Airframe INSPECTION FAA #1028	NO.1 AIR DATA COMPUTER TESTS AND INSPECTIONS PER FAR 91.411 APPENDIX E OF PART 43	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 11 D: 30
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: FAA)						
34 FAR 91.411 Airframe INSPECTION FAA #1220	NO.2 AIR DATA COMPUTER TESTS AND INSPECTIONS PER FAR 91.411 APPENDIX E OF PART 43	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 11 D: 30
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: FAA)						
34 FAR 91.413 Airframe INSPECTION FAA #510	LEFT ATC TRANSPONDER TEST AND INSPECTIONS PER FAR 91.413 APPENDIX F OF PART 43.	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 11 D: 30
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: FAA)						
34 FAR 91.413 Airframe INSPECTION FAA #2207	RIGHT ATC TRANSPONDER TEST AND INSPECTIONS PER FAR 91.413 APPENDIX F OF PART 43	31-MAY-2025 H: 8649.70 L: 3986	M: 24			31-MAY-2027	M: 11 D: 30
	Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: FAA)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
34 ICA- DB1409003-CL604 Airframe INSPECTION #1765	GENERAL VISUAL INSPECTION OF WIRE/CABLES/RACKS/CONNECTORS ASSOCIATED WITH DIGITAL DISCREET ADAPTER OR AIRCRAFT FLIGHT ID ADAPTER AND ADS-B ANNUNCIATOR FOR CONDITION & SECURITY. REFERENCE CMD FLIGHT SOLUTIONS REPORT NO. DB1409003	19-DEC-2023 H: 8207.00 L: 3719	M: 60			19-DEC-2028	M: 30 D: 18
	<p>Notes</p> <p>(AVG MAN HRS: 2) (UPDATE NOTE: COMPLIED WITH INSPECTION ICA-DB1409003-CL604 GVI OF WIRE/CABLES/RACKS/CONNECTORS ASSOCIATED WITH DIGITAL DISCREET ADAPTER OR AIRCRAFT FLIGHT ID ADAPTER AND ADS-B ANNUNCIATOR FOR CONDITIONS & SECURITY. IAW CMD FLIGHT SOLUTIONS ICA REPORT NO. DB1409003.)</p>						
34 JLA-NDB34-(-JLCD) Airframe INSPECTION #1044	UPDATE NAV DATABASE (J6 AMERICAS)	14-MAY-2026 H: 8686.90 L: 3999				10-JUN-2026	M: 0 D: 9
	<p>Notes</p> <p>(AVG MAN HRS: 1)</p>						
34 JLA-RVSM34-(-JLCD) Airframe INSPECTION #1267	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) MONITORING REQUIREMENTS	01-NOV-2025 H: 8661.90	M: 24 H: 1000.00			01-NOV-2027 H: 9661.90	M: 17 D: 0 H: 966.80
	<p>Notes</p> <p>(AVG MAN HRS: 0.5) (UPDATE NOTE: VERIFIED RVSM HEIGHT MONITORING ACCURACY. LAST ADS-B APPROVAL RESULT TRUE 12/26/2022.)</p>						
35 Airframe PART #243	COCKPIT OXYGEN, DUAL, BOX ASSY					15-OCT-1997	
	Part Number	Serial Number					
	Unknown	Unknown					
35 Airframe PART #1030	COCKPIT PANEL, OXYGEN CONTROL, PASSENGER (CONSOLE - RIGHT)					15-OCT-1997	
	Part Number	Serial Number					
	Unknown	Unknown					
35 Airframe PART #2229	COCKPIT SWITCH, PRESSURE (CONSOLE - RIGHT)					15-OCT-1997	
	Part Number	Serial Number					
	Unknown	Unknown					
35 Airframe PART #1704	COCKPIT VALVE, SHUT-OFF (CONSOLE - RIGHT)					15-OCT-1997	
	Part Number	Serial Number					
	Unknown	Unknown					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 Airframe PART #1819	COPILOT BOX, STOWAGE, O2 MASK Part Number Unknown Serial Number Unknown	15-OCT-1997					
35 Airframe PART #2605	COPILOT MASK ASSY, OXYGEN REGULATOR Part Number MC10-13-03 Serial Number B119290	11-JUL-2023 H: 8075.40 L: 3647					
Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)							
35 Airframe PART #66	LOWER OXYGEN CYLINDER REGULATOR Part Number 803213-19 Serial Number C14100768	26-JUL-2019 H: 6476.10 L: 2770					
35 Airframe PART - Life Limited #1190	NO.1 OXYGEN CYLINDER Part Number 895-25015 Serial Number C23050903	05-JUL-2024 H: 8455.80 L: 3862	M: 180		M: 0	31-MAY-2038	M: 143 D: 30
Notes (ZONE: NOSE) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 376446) (NOTE: NOTE 11: FUNCTIONAL TESTING (HYDROSTATIC) SCHEDULES AND MAXIMUM LIFE LIMIT (DISCARD) OF THE OXYGEN CYLINDER SHALL BE IN ACCORDANCE WITH TABLE 1 (BASED ON PART NUMBERS AND DOT/CANADIAN MARKINGS). RESTORATION (OVERHAUL) SCHEDULE OF THE OXYGEN CYLINDER REGULATOR SHALL BE IN ACCORDANCE WITH TABLE 1 BELOW OR MAXIMUM OF SIX (6) YEARS FROM THE DATE NOTED IN THE LATEST CERTIFICATION DOCUMENT, AS APPLICABLE.)							
35 Airframe PART #192	NO.1 STOWAGE BOX Part Number MXP335-3 Serial Number Unknown	15-OCT-1997					
35 Airframe PART - Life Limited #3604	NO.2 OXYGEN CYLINDER Part Number 895-25015 Serial Number C23050901	05-JUL-2024 H: 8455.80 L: 3862	M: 180		M: 0	01-MAY-2038	M: 143 D: 0
Notes (ZONE: NOSE) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 376446) (NOTE: NOTE 11: FUNCTIONAL TESTING (HYDROSTATIC) AND DISCARD OF THE OXYGEN CYLINDERS SHALL BE ACCOMPLISHED IN ACCORDANCE WITH THE OPERATOR'S NATIONAL REQUIREMENTS. NOTE 18: THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION.)							
35 Airframe PART #486	NO.2 STOWAGE BOX Part Number MXP335-2 Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 Airframe PART #3587	PASSENGER OXYGEN CONTROLLER Part Number: RCA73-05 Serial Number: 183	25-FEB-2015 H: 5417.70 L: 2348					
35 Airframe PART #495	PILOT BOX, STOWAGE, O2 MASK Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
35 Airframe PART #496	PILOT MASK ASSY, OXYGEN REGULATOR Part Number: MC10-13-03 Serial Number: 58970I	11-JUL-2023 H: 8075.40 L: 3647					
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
35 Airframe PART #2638	SWITCH, PRESSURE, OXYGEN (S1WQ) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
35 Airframe PART #3475	SWITCH, PRESSURE, OXYGEN (S2WQ) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
35 Airframe PART #2613	SWITCH, PRESSURE, OXYGEN (S3WQ) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
35 Airframe PART #1054	SWITCH, PRESSURE, OXYGEN (S3WQ)(RIGHT) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
35 Airframe PART #1712	UPPER OXYGEN CYLINDER REGULATOR Part Number: 803213-19 Serial Number: C14100767	26-JUL-2019 H: 6476.10 L: 2770					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 00-00-201 Airframe INSPECTION #2185	NO.1 FUNCTIONAL (HYDROSTATIC) TEST UPPER OXYGEN CYLINDER/REGULATOR ASSEMBLY BOTTLE CYLINDER		M: 60			01-MAY-2028	M: 23 D: 0
35 00-00-201 Airframe INSPECTION #2475	NO.2 FUNCTIONAL (HYDROSTATIC) TEST LOWER OXYGEN CYLINDER/REGULATOR ASSEMBLY BOTTLE CYLINDER		M: 60			01-MAY-2028	M: 23 D: 0
35 00-00-202 Airframe INSPECTION PKG 36 Month #1062	OPERATIONAL TEST OF THE PASSENGER OXYGEN SYSTEM (EFFECTIVITY: 5301-5304, 5306, 5310, 5316, 5331 AND SUBS).	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
	Notes (AVG MAN HRS: 1.5) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
35 00-00-204 Airframe INSPECTION PKG 36 Month #3609	OPERATIONAL TEST OF THE CREW OXYGEN MASK	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
	Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
35 00-00-206 Airframe INSPECTION #2973	COPILOT RESTORATION OF THE CREW OXYGEN MASK REGULATOR ASSEMBLY	11-JUL-2023 H: 8075.40 L: 3647	M: 72	M: 1		22-FEB-2029	M: 32 D: 21
	Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: NOTE 18: THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION.)						
35 00-00-206 Airframe INSPECTION #134	PILOT RESTORATION OF THE CREW OXYGEN MASK REGULATOR ASSEMBLY	11-JUL-2023 H: 8075.40 L: 3647	M: 72	M: 1		22-FEB-2029	M: 32 D: 21
	Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: NOTE 18: THE TASK DUE TIME IS CALCULATED FROM THE DATE NOTED IN THE CERTIFICATION DOCUMENTATION.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 1000-003 Airframe PART #648	JUMP SEAT OXYGEN REGULATOR MASK ASSEMBLY Part Number Unknown Serial Number Unknown	15-OCT-1997					
35 1130-701 Airframe PART #3565	PORTABLE OXYGEN BOTTLE/REGULATOR Part Number 5600-9C1A-YON Serial Number P06060057	28-APR-2023 H: 8029.90 L: 3621					
Notes (UPDATE NOTE: COMPLIED WITH INSPECTION 351130-701A HYDROSTATIC CHECK BY INSTALLATION OF OVERHAULED OXYGEN BOTTLE P/N 5600-9C1A-YON S/N P06060057 IAW BOMBARDIER CL 604 AMM. OVERHAULED BY COMPRESSED GAS SYSTEM FORM TRACKING NUMBER A49753 WORK ORDER NUMBER C41393 CRS# 20XR229C DATED 26-APR-2023.)							
35 1130-701A Airframe INSPECTION #1750	PORTABLE OXYGEN BOTTLE/REGULATOR HYDROSTATIC CHECK	28-APR-2023 H: 8029.90 L: 3621	M: 60			30-APR-2028	M: 22 D: 29
Notes (UPDATE NOTE: COMPLIED WITH INSPECTION 351130-701A HYDROSTATIC CHECK BY INSTALLATION OF OVERHAULED OXYGEN BOTTLE P/N 5600-9C1A-YON S/N P06060057 IAW BOMBARDIER CL 604 AMM. OVERHAULED BY COMPRESSED GAS SYSTEM FORM TRACKING NUMBER A49753 WORK ORDER NUMBER C41393 CRS# 20XR229C DATED 26-APR-2023.)							
35 T.M5352-0256 Oxygen 1 Airframe INSPECTION #1738	OXYGEN SYSTEM OPERATIONAL & MASK DROP TEST. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
Notes (AVG MAN HRS: 2) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
35 T.M5352-0256 Oxygen 2 Airframe INSPECTION #84	OXYGEN SYSTEM MASK INSPECTION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
35 T.M5352-0256 Oxygen 3 Airframe INSPECTION #2088	OXYGEN SYSTEM LINES, FITTINGS AND HARDWARE INSPECTION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
35 T.M5352-0256 Oxygen 4 Airframe INSPECTION #1542	OXYGEN SYSTEM FLEXIBLE LINE INSPECTION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>							
35 T.M5352-0256 Oxygen 5 Airframe INSPECTION #1288	THERAPEUTIC OXYGEN MASK VISUAL INSPECTION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256.	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00			H: 9157.60	H: 462.50
<p>Notes</p> <p>(UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)</p>							
35 T.M5352-0256 Oxygen 6 Airframe INSPECTION #3285	PORTABLE OXYGEN BOTTLE ANNUAL INSPECTION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>							
35 T.M5352-0256 Oxygen 7 Airframe INSPECTION #2424	PORTABLE OXYGEN BOTTLE MASK ANNUAL INSPECTION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>							
35 T.M5352-0256 Oxygen 8 Airframe PART - Life Limited #1840	PORTABLE OXYGEN BOTTLE MASK OVERHAUL. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	07-APR-2026 H: 8670.40 L: 3995	M: 36		M: 0 H: 0.00 L: 0	31-MAR-2029	M: 33 D: 30
<p>Part Number</p> <p>10800A2F</p> <p>Serial Number</p> <p>NONE</p> <p>Notes</p> <p>(APX COST: 1,600)</p>							
36 APU PART #144	APU BLEED AIR CHECK VALVE					24-APR-1984	
<p>Part Number</p> <p>Unknown</p> <p>Serial Number</p> <p>Unknown</p> <p>Notes</p> <p>(AVG MAN HRS: 1.5)</p>							



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 Airframe PART #1868	BLEED AIR PANEL ASSY Part Number: 604-51162-1 Serial Number: Unknown	15-OCT-1997					
36 Airframe PART #601	DUCT ASSY, HIGH PRESSURE (14TH STAGE BLEED AIR) Part Number: 13852-101 Serial Number: Unknown	15-OCT-1997					
36 Airframe PART #407	LEFT BLEED AIR CLEANER ASSY Part Number: 600-97196-1 Serial Number: Unknown	15-OCT-1997					
36 Airframe PART #780	LEFT DUCT ASSY, BLEED AIR 10 TH STAGE (REAR FUSE) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
36 Airframe PART #775	LEFT ENGINE DUCT ASSY (10TH STAGE BLEED AIR)-LOW PRESSURE Part Number: 13850-105 Serial Number: Unknown	15-OCT-1997					
36 Airframe PART #1782	LEFT ENGINE DUCT, BLEED AIR (10TH STAGE) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
36 Airframe PART #3545	LEFT ENGINE DUCT, BLEED AIR (14TH STAGE) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
36 Airframe PART #1571	LEFT ENGINE VALVE, CHECK, BLEED AIR Part Number: 62490-7B Serial Number: 1472	15-OCT-1997					
36 Airframe PART #2107	LEFT LEAK CONTROL, BLEED AIR Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 Airframe PART #1845	LEFT NO.1 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #3046	LEFT NO.10 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #1061	LEFT NO.2 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #3287	LEFT NO.3 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #49	LEFT NO.4 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #2369	LEFT NO.5 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #885	LEFT NO.6 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #3381	LEFT NO.7 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #2426	LEFT NO.8 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 Airframe PART #2041	LEFT NO.9 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #3363	LEFT TRANSDUCER, PRESSURE (10TH STAGE) Part Number 600-59174-9 Serial Number 5624-5-133	15-OCT-1997					
36 Airframe PART #1851	LEFT VALVE, BLEED AIR SHUTOFF (14TH STAGE) Part Number 3289590-2 Serial Number 1205	15-OCT-1997					
36 Airframe PART - Life Limited #2193	LEFT VALVE, SHUT-OFF (ANTI-ICE) Part Number 3214442-4 Serial Number Unknown	15-OCT-1997	H: 13500.00		H: 0.00 L: 0	H: 13500.00	H: 4804.90
<p>Notes</p> <p>(AVG MAN HRS: 2.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>							
36 Airframe PART #2240	LEFT VALVE, SHUTOFF, BLEED AIR, MANIFOLD (10TH STAGE BLEED) Part Number 979998-1 Serial Number 1757	15-OCT-1997					
36 Airframe PART #3576	NO.1 ASSY DUCT Part Number Unknown Serial Number Unknown						
36 Airframe PART #146	NO.1 INSULATION COVER Part Number 601-80045-01 Serial Number 1-50636-028						
36 Airframe PART #731	NO.1 WING HEAT SENSING (A44WK A45WK) ELEMENT Part Number 35584-4-255 Serial Number Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 Airframe PART #497	NO.2 ASSY DUCT Part Number Unknown Serial Number Unknown						
36 Airframe PART #1543	NO.2 INSULATION COVER Part Number 601-80045-01 Serial Number 1787055505					16-JUN-2018 H: 6372.80 L: 2715	
36 Airframe PART #1158	NO.2 WING HEAT SENSING (A42WK A43WK) ELEMENT Part Number 35541-3-255 Serial Number Unknown					15-OCT-1997	
36 Airframe PART #3684	NO.3 WING HEAT SENSING (A40WK A41WK) ELEMENT Part Number 35552-3-255 Serial Number Unknown					15-OCT-1997	
36 Airframe PART #3702	NO.4 WING HEAT SENSING (A38WK A39WK) ELEMENT Part Number 35596-2-255 Serial Number Unknown					15-OCT-1997	
36 Airframe PART #682	RIGHT BLEED AIR CLEANER ASSY Part Number 600-97196-2 Serial Number Unknown					15-OCT-1997	
36 Airframe PART #2762	RIGHT DUCT ASSY, (STARTER) 10TH STAGE BLEED AIR Part Number 13854-103 Serial Number Unknown					15-OCT-1997	
36 Airframe PART #3501	RIGHT DUCT ASSY, BLEED AIR 10 TH STAGE (REAR FUSE) Part Number Unknown Serial Number Unknown					15-OCT-1997	
36 Airframe PART #76	RIGHT ENGINE DUCT ASSY (10TH STAGE BLEED AIR)-LOW PRESSURE Part Number 13850-105 Serial Number Unknown					15-OCT-1997	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 Airframe PART #782	RIGHT ENGINE DUCT, BLEED AIR (10TH STAGE) Part Number: 979998-2 Serial Number: 5427	25-MAY-2007 H: 3025.60 L: 1216					
36 Airframe PART #2105	RIGHT ENGINE DUCT, BLEED AIR (14TH STAGE) Part Number: Unknown Serial Number: Unknown					15-OCT-1997	
36 Airframe PART #1334	RIGHT ENGINE VALVE, CHECK, BLEED AIR Part Number: 62490-7B Serial Number: 1464					15-OCT-1997	
36 Airframe PART #39	RIGHT LEAK CONTROL, BLEED AIR Part Number: Unknown Serial Number: Unknown					15-OCT-1997	
36 Airframe PART #790	RIGHT NO.1 DUCT ASSY (REAR FUSE) Part Number: Unknown Serial Number: Unknown					15-OCT-1997	
36 Airframe PART #819	RIGHT NO.10 DUCT ASSY (REAR FUSE) Part Number: Unknown Serial Number: Unknown					15-OCT-1997	
36 Airframe PART #2128	RIGHT NO.2 DUCT ASSY (REAR FUSE) Part Number: Unknown Serial Number: Unknown					15-OCT-1997	
36 Airframe PART #2919	RIGHT NO.3 DUCT ASSY (REAR FUSE) Part Number: Unknown Serial Number: Unknown					15-OCT-1997	
36 Airframe PART #2434	RIGHT NO.4 DUCT ASSY (REAR FUSE) Part Number: Unknown Serial Number: Unknown					15-OCT-1997	



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 Airframe PART #330	RIGHT NO.5 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #3672	RIGHT NO.6 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #1185	RIGHT NO.7 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #226	RIGHT NO.8 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #1998	RIGHT NO.9 DUCT ASSY (REAR FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #399	RIGHT TRANSDUCER, PRESSURE (10TH STAGE) Part Number 600-59174-9 Serial Number 9005-9-232	22-APR-2024 H: 8368.00 L: 3817					
	<p>Notes</p> <p>(APX COST: 0) (UPDATE NOTE: REMOVED RIGHT PRESSURE TRANSDUCER P/N 600-59174-9 S/N 5691-5-367 AND INSTALLED NEW PRESSURE TRANSDUCER P/N 600-59174-9 S/N 9005-9-232 IAW BOMBARDIER CL 604 AMM 36-21-04. OPS CHECK GOOD NO DEFECTS NOTED A THIS TIME.)</p>						
36 Airframe PART #3241	RIGHT VALVE, BLEED AIR SHUTOFF (14TH STAGE) Part Number 3289590-2 Serial Number P-202	15-OCT-1997					
36 Airframe PART - Life Limited #2551	RIGHT VALVE, SHUT-OFF (ANTI-ICE) Part Number 3214442-4 Serial Number Unknown	15-OCT-1997	H: 13500.00		H: 0.00 L: 0	H: 13500.00	H: 4804.90
	<p>Notes</p> <p>(AVG MAN HRS: 2.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 Airframe PART #3559	RIGHT VALVE, SHUTOFF, BLEED AIR, MANIFOLD (10TH STAGE BLEED) Part Number Unknown Serial Number Unknown	15-OCT-1997					
36 Airframe PART #728	UPPER VALVE, BLEED, SHUTOFF, ISOLATION 10TH STAGE Part Number 604-97601-3 Serial Number 2269	11-AUG-2023 H: 8088.50 L: 3658					
	Notes (APX COST: 0) (UPDATE NOTE: REMOVED 10TH STAGE BLEED AIR ISOLATION VALVE, P/N 979998-1 S/N 1753, AND INSTALLED OVERHAULED ISOLATION VALVE, P/N 979998-3 S/N 2269, IAW CL604 AMM REVISION 100 TASK 36-11-04. ISOLATION VALVE OVERHAULED BY ACCESSORY TECHNOLOGIES CORPORATION CRS Y4AR0390, SEE FAA FORM 8130-3 TRACKING NUMBER 732120 UNDER WORK ORDER 5800729627 DATED 26-JUL-2023 FOR DETAILS. OPERATIONAL CHECK SATISFACTORY.)						
36 Airframe PART #196	VALVE, CHECK (10TH STAGE BLEED AIR) Part Number 600-97006-7 Serial Number 1776	15-OCT-1997					
36 Airframe PART #564	VALVE, ISOLATION SHUTOFF (14TH STAGE WING ANTI-ICE) Part Number 979626-3-1 Serial Number Unknown	15-OCT-1997					
36 11-00-301 Airframe INSPECTION PKG3200Hour #2631	RESTORATION (CLEANING) OF THE 10TH STAGE BLEED AIR SHUTOFF VALVE FILTER.	16-JUN-2018 H: 6372.80 L: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (ZONE: 311312) (ACCESS: 311BB)						
36 12-00-301 Airframe INSPECTION PKG3200Hour #2055	RESTORATION (CLEANING) OF THE 14TH STAGE BLEED AIR SHUTOFF VALVE FILTER.	16-JUN-2018 H: 6372.80 L: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (ZONE: 311312) (ACCESS: 311BB)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
36 21-00-101* Airframe INSPECTION #3452	FUNCTIONAL TEST OF THE LEADING EDGE THERMAL SWITCHES	12-APR-2013 H: 4782.30 L: 2063	H: 6400.00			H: 11182.30	H: 2487.20
	<p>Notes</p> <p>(ACCESS: 221CLF, 520AT, 620AT, 520BL, 620BL, 530BL, 630BL,) (AVG MAN HRS: 49) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. CONSIDERATION SHOULD BE GIVEN TO ACCOMPLISHING THIS TASK IN CONJUNCTION WITH TASK 57-10-00-208 WHICH REQUIRES THE REMOVAL OF THE WING LEADING EDGE. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)</p>						
38 Airframe PART #3645	GALLEY HEATER,WATER (TOWER ASSY) Part Number 8921082G5 Serial Number UEW07648					02-JUN-2005 H: 2522.30 L: 983	
38 Airframe PART #3313	GALLEY VALVE, WATER DRAIN Part Number Unknown Serial Number Unknown					15-OCT-1997	
38 Airframe PART #2552	NO.1 DRAIN MAST Part Number Unknown Serial Number Unknown					15-OCT-1997	
38 Airframe PART #1202	VALVE, DRAIN, WATER Part Number Unknown Serial Number Unknown					15-OCT-1997	
	<p>Notes</p> <p>(ZONE: TAIL TANK)</p>						
38 Airframe PART #2131	WATER FILTER Part Number TOA2 Serial Number NSN					28-MAR-2018 H: 6319.00 L: 2697	
38 T.M5352-0256 OVBD SVC Airframe INSPECTION #270	INSPECT OVERBOARD SERVICING FOR LEAKAGE, SPILLAGE, CORROSION. DOOR HINGES & LATCHES FOR WEAR AND SECURITY. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
	<p>Notes</p> <p>(UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
38 T.M5352-0256 Toilet 1 Airframe INSPECTION #1461	INSPECT TOILET ENCLOSURE AREA FOR SPILLAGE AND CORROSION. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	21-MAY-2026 H: 8686.90 L: 3999	M: 12			21-MAY-2027	M: 11 D: 20
Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
38 T.M5352-0256 Toilet 2 Airframe INSPECTION #1804	INSPECT TOILET FOR SECURITY OF ATTACHMENT TO FLOOR AND FRAME STRUCTURE. REFERENCE BOMBARDIER COMPLETION CENTRE REPORT NO. T.M5352-0256	11-JUL-2023 H: 8075.40 L: 3647	M: 48 H: 1600.00			11-JUL-2027 H: 9675.40	M: 13 D: 10 H: 980.30
Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)							
46 Airframe PART #2036	NO.1 ECU-3000, EXTERNAL COMPENSATION UNIT Part Number Unknown Serial Number Unknown					15-OCT-1997	
49 APU PART #156	AFT APU - IGNITER PLUG Part Number Unknown Serial Number Unknown					24-APR-1984	
49 APU PART #34	APU - APU COMBUSTION CAP LINER Part Number Unknown Serial Number Unknown						
49 APU PART #16	APU - APU SOLENOID VALVE Part Number Unknown Serial Number Unknown					24-APR-1984	
49 APU PART #110	APU - APU WIRING HARNESS Part Number Unknown Serial Number Unknown					24-APR-1984	
49 APU PART #40	APU - DRAIN AND REFILL OIL TANK Part Number Unknown Serial Number Unknown						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
49 APU PART #122	APU - FUEL NOZZLE ASSEMBLY Part Number Unknown Serial Number Unknown						
49 APU PART #152	APU - FUEL SHUT OFF VALVE Part Number Unknown Serial Number Unknown						
49 APU PART #108	APU - HOUSING ASSY Part Number Unknown Serial Number Unknown						
49 APU PART #148	APU - IGNITER PLUG Part Number Unknown Serial Number Unknown					24-APR-1984	
49 APU PART #59	APU - POWER SECTION Part Number Unknown Serial Number Unknown					24-APR-1984	
49 APU PART #139	APU - SENSOR Part Number Unknown Serial Number Unknown					24-APR-1984	
49 APU PART #112	APU - SENSOR PRESSURE Part Number Unknown Serial Number Unknown						
49 APU PART #63	APU - WIRING HARNESS Part Number Unknown Serial Number Unknown						
49 Airframe PART #3571	APU ECU- ELECTRONIC CONTROL UNIT Part Number 2117406-7 Serial Number 60-351					03-AUG-2005 H: 4090.10	



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
49 Airframe PART #580	APU EXHAUST ISOLATOR Part Number Unknown Serial Number Unknown						
49 Airframe PART #3489	APU EXHAUST NOZZLE ASSY Part Number Unknown Serial Number Unknown		15-OCT-1997				
49 APU PART #25	APU GTCP36-100[E] STARTER MOTOR Part Number Unknown Serial Number Unknown		24-APR-1984				
49 APU PART #120	APU HOURMETER Part Number Unknown Serial Number Unknown						
49 APU PART #62	APU LOW OIL PRESSURE SWITCH Part Number Unknown Serial Number Unknown		24-APR-1984				
49 Airframe PART #2149	BELLOWS ASSY, APU INLET (APU ENCLOSURE) Part Number Unknown Serial Number Unknown		15-OCT-1997				
49 Airframe PART #808	CHAMBER Part Number Unknown Serial Number Unknown		15-OCT-1997				
49 APU PART #17	COMBUSTION CHAMBER Part Number 3830037-6 Serial Number N/A		21-OCT-2024 H: 10142.00				

Notes

(APX COST: 0) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
49 APU PART - Life Limited #159	COMPRESSOR IMPELLER (APU) Part Number Unknown Serial Number Unknown Notes (AVG MAN HRS: 9)	17-OCT-2005	H: 100000.00	H: 40.00	H: 0.00 C: 0	H: 105108.00	H: 94801.00
49 APU PART #142	ELECTRIC CONTROL UNIT APU ECU Part Number Unknown Serial Number Unknown	24-APR-1984					
49 APU PART #77	FUEL CONTROL UNIT (FCU) Part Number Unknown Serial Number Unknown	24-APR-1984					
49 APU PART #9	FWD APU - IGNITER PLUG Part Number Unknown Serial Number Unknown	24-APR-1984					
49 APU PART #89	HOUSING SET Part Number Unknown Serial Number Unknown						
49 APU PART #170	IGNITION UNIT Part Number Unknown Serial Number Unknown	24-APR-1984					
49 Airframe PART #597	LEFT PANEL ASSY, APU FAULT INDICATOR (AFT FUSE) Part Number Unknown Serial Number Unknown	15-OCT-1997					
49 APU PART #27	LOW OIL PRESSURE SWITCH Part Number Unknown Serial Number Unknown	24-APR-1984					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
49 APU PART #71	OIL FILTER ELEMENT Part Number Unknown Serial Number Unknown	24-APR-1984					
49 APU PART #165	PNEUMATIC SHUTOFF LOAD CONTROL VALVE Part Number Unknown Serial Number Unknown	24-APR-1984					
49 APU PART #106	PNEUMATIC SURGE VALVE Part Number Unknown Serial Number Unknown	24-APR-1984					
49 APU PART - Life Limited #4	TURBINE IMPELLER (APU) Part Number Unknown Serial Number Unknown Notes (AVG MAN HRS: 9)	24-APR-1984	H: 10000.00	H: 40.00	H: 0.00	H: 16739.00	H: 6432.00
49 00-90-011 APU INSPECTION #5	VERIFY APU HOURS & CYCLES (ADD 6739 HOURS TO HOBBS) Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: UPDATED APU HOURS IN COMPLIANCE DATA. CURRENT: 10,289 HRS.)	14-MAY-2026 H: 10307.00	D: 30			13-JUN-2026	M: 0 D: 12
49 0020-0101 APU PART #134	APU - GEARBOX Part Number Unknown Serial Number Unknown	24-APR-1984					
49 0023-0101 APU PART #42	APU - THERMOCOUPLE (APU) Part Number Unknown Serial Number Unknown						
49 0023-0102 APU PART #114	APU - THERMOCOUPLE (APU) Part Number Unknown Serial Number Unknown	24-APR-1984					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
49 10-00-201 APU INSPECTION 050016 #84	DETAILED INSPECTION OF THE AUXILIARY POWER UNIT (APU) ENCLOSURE ASSEMBLY	21-OCT-2024 H: 10142.00	H: 600.00	H: 40.00		H: 10742.00	H: 435.00
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
49 12-01-201 APU INSPECTION 050026 #93	VISUAL CHECK OF THE AUXILIARY POWER UNIT (APU) SUPPORT SKID ASSEMBLY	03-JAN-2023 H: 9642.00	H: 2400.00	H: 40.00		H: 12042.00	H: 1735.00
	Notes (AVG MAN HRS: 3)						
49 20-00-201 APU INSPECTION 050016 #175	DETAILED INSPECTION OF THE AUXILIARY POWER UNIT (APU) COMBUSTION CHAMBER	21-OCT-2024 H: 10142.00	H: 600.00	H: 40.00		H: 10742.00	H: 435.00
	Notes (AVG MAN HRS: 8.5) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
49 20-00-205 APU INSPECTION 050026 #123	VISUAL CHECK OF THE AUXILIARY POWER UNIT (APU) CONTAINMENT RING	03-JAN-2023 H: 9642.00	H: 2400.00	H: 40.00		H: 12042.00	H: 1735.00
	Notes (AVG MAN HRS: 3)						
49 20-00-HSI APU INSPECTION 050021 #81	APU HOT SECTION - INSPECTION (HSI)	03-JAN-2023 H: 9642.00	H: 2100.00	H: 45.00		H: 11892.00	H: 1585.00
49 21-00-201 APU INSPECTION 050014. #117	DETAILED INSPECTION OF THE AUXILIARY POWER UNIT (APU) OIL DRAIN-PLUG MAGNETIC-ELEMENT	21-OCT-2024 H: 10142.00	H: 600.00	H: 40.00		H: 10442.00	H: 135.00
	Notes (AVG MAN HRS: 1.5) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
49 30-00-201 APU INSPECTION 050014. #91	DISCARD OF THE AUXILIARY POWER UNIT (APU) FUEL FILTER ELEMENT	05-JUL-2024 H: 10002.00	H: 400.00	H: 40.00		H: 10442.00	H: 135.00
	Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: 40 HRS) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)						
49 40-00-201 APU INSPECTION #32	RESTORATION (OVERHAUL) OF THE AUXILIARY POWER UNIT (APU) STARTER MOTOR ASSEMBLY	03-JAN-2023 H: 9642.00	H: 2100.00	H: 40.00		H: 11742.00	H: 1435.00
	Notes (AVG MAN HRS: 1)						
49 51-00-301 APU INSPECTION #57	RESTORATION (ON-WING CLEANING) OF THE AUXILIARY POWER UNIT (APU) LOAD CONTROL VALVE FILTER.						
	Notes (ZONE: 311312) (ACCESS: 311BB,BZ) (NOTE: NOTE: THIS TASK APPLIES TO FILTERS INSTALLED ON APU 36-150CL LOAD CONTROL VALVE PART NO. 3885091-4 ONLY.)						
49 80-00-201 APU INSPECTION 050020 #187	DETAILED INSPECTION OF THE AUXILIARY POWER UNIT (APU) EXHAUST NOZZLE	03-JAN-2023 H: 9642.00	H: 1200.00	H: 40.00		H: 10842.00	H: 535.00
	Notes (AVG MAN HRS: 6.5)						
49 80-00-202 APU INSPECTION 050020 #12	DETAILED INSPECTION OF THE AUXILIARY POWER UNIT (APU) EXHAUST DUCT	03-JAN-2023 H: 9642.00	H: 1200.00	H: 40.00		H: 10842.00	H: 535.00
	Notes (AVG MAN HRS: 6.5)						
49 80-00-203 APU INSPECTION 050020 #171	VISUAL CHECK OF THE AUXILIARY POWER UNIT (APU) EXHAUST SHIELD AND VISOR ASSEMBLY	03-JAN-2023 H: 9642.00	H: 1200.00	H: 40.00		H: 10842.00	H: 535.00
	Notes (AVG MAN HRS: 4.25)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 Airframe PART #2234	AFT SPRING ASSY, MOTOR (BAGGAGE BAY DOOR) Part Number: ML3844-12A Serial Number: 15377	15-JUL-2023					
	Notes (APX COST: 0) (UPDATE NOTE: REMOVED AFT BAGGAGE DOOR BALANCE SPRING ASSEMBLY, P/N UNKNOWN S/N UNKNOWN, AND INSTALLED NEW BALANCE SPRING ASSEMBLY, P/N ML3844-12A S/N 15377, IAW BOMBARDIER CL604 AMM REVISION 100 CHAPTER 53-13-13. OPERATIONAL CHECK SATISFACTORY.)						
52 Airframe PART #1982	COUPLING HALF Part Number: AE99118G Serial Number: NO SN	22-JUL-2017					
52 Airframe PART #261	DOOR ASSY, BAGGAGE BAY Part Number: 600-35027-159 Serial Number: Unknown	15-OCT-1997					
52 Airframe PART #1144	DOOR ASSY, EQUIPMENT BAY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: AFT FUSE)						
52 Airframe PART #2645	DOOR ASSY, OVERWING EXIT Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: MID FUSE - RIGHT)						
52 Airframe PART #2006	DOOR ASSY, PASSENGER Part Number: 600-31901-1003 Serial Number: Unknown	15-OCT-1997					
52 Airframe PART #753	FWD COUNTER BALANCE (PASSENGER DOOR), SPRING GAS Part Number: 601R31911-13 Serial Number: Unknown	02-JUL-2021					
	Notes (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 Airframe PART #1166	FWD SPRING ASSY, MOTOR (BAGGAGE BAY DOOR) Part Number Unknown Serial Number Unknown	15-OCT-1997					
52 Airframe PART #1702	HANDLE ASSY, BAGGAGE BAY DOOR Part Number Unknown Serial Number Unknown	15-OCT-1997					
52 Airframe PART #549	HANDLE ASSY, EXTERNAL (AFT EQUIPMENT BAY DOOR) Part Number Unknown Serial Number Unknown	15-OCT-1997					
52 Airframe PART #2100	LEFT DOOR ASSY,ACCESS, ELECTRONIC BAY Part Number 600-33039-3 Serial Number 7790133 Notes (ZONE: FS173 WL79 LBL10)	15-OCT-1997					
52 Airframe PART #540	NO.01 DOOR WARNING SYSTEM PROXIMITY SWITCH Part Number Unknown Serial Number Unknown	15-OCT-1997					
52 Airframe PART #1133	NO.02 DOOR WARNING SYSTEM PROXIMITY SWITCH Part Number Unknown Serial Number Unknown	15-OCT-1997					
52 Airframe PART #58	NO.03 DOOR WARNING SYSTEM PROXIMITY SWITCH Part Number Unknown Serial Number Unknown	15-OCT-1997					
52 Airframe PART #624	OVER-WING EMERGENCY EXIT EXIT-PULL SIGN Part Number BA670-47804-1 Serial Number 53930 Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)	31-MAY-2025 H: 8649.70 L: 3986					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 Airframe PART #2129	PASSENGER DOOR POWER ASSIST CABLE Part Number: 444-2440-105 Serial Number: NO SN	22-JUL-2017 H: 6094.20 L: 2615					
52 Airframe PART #2977	PASSENGER DOOR SEAL Part Number: 600-31913-1 Serial Number: NSN	03-AUG-2015 H: 5528.10 L: 2396					
52 Airframe PART #3378	PASSENGER DOOR, OUTER HANDLE ASSY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
52 Airframe PART #3442	RIGHT DOOR ASSY,ACCESS, ELECTRONIC BAY Part Number: 600-33039-4 Serial Number: 7790149	15-OCT-1997					
	Notes (ZONE: FS173 WL79 RBL10)						
52 10-00-201 Airframe INSPECTION PKG2400Hour #740	FUNCTIONAL TEST OF THE PASSENGER-DOOR LATCH MECHANISM Notes (AVG MAN HRS: 5)	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
52 10-00-202 Airframe INSPECTION PKG 400 Hour #1634	LUBRICATION OF THE PASSENGER DOOR (EXTERNAL) Notes (AVG MAN HRS: 2) (TOL. ADJUSTMENT: 19.6 HRS) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)	05-JUL-2024 H: 8455.80 L: 3862	H: 400.00	H: 40.00		H: 8875.40	H: 180.30
52 10-00-205 Airframe INSPECTION PKG1600Hour #3361	LUBRICATION OF THE PASSENGER DOOR (INTERNAL) (A/C 5301 TO 5315 POST SB 604-52-002 AND 5316 AND SUBS) Notes (AVG MAN HRS: 10.6) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.) (NOTE: A/C 5301 TO 5315 POST SB 604-52-002 AND 5316 AND SUBS)	08-FEB-2023 H: 7925.20 L: 3563	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 11-00-101* Airframe INSPECTION #945	SPECIAL DETAILED INSPECTION OF THE PASSENGER DOOR HINGE		L: 5315			L: 5315	L: 1313
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
52 11-00-102* Airframe INSPECTION #1473	DETAILED INSPECTION OF THE PASSENGER DOOR FLAP CUTOUT		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
52 11-00-202 Airframe INSPECTION PKG 48 Month #2671	DETAILED INSPECTION OF THE FITTINGS AND ATTACHMENTS OF THE PASSENGER DOOR	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
52 11-00-203 Airframe INSPECTION PKG 96 Month #3230	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE PASSENGER DOOR	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 20.4)						
52 20-00-201 Airframe INSPECTION PKG 36 Month #2433	OPERATIONAL TEST OF THE LATCH MECHANISM OF THE OVERWING EMERGENCY-EXIT DOOR	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
	Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 20-00-202 Airframe INSPECTION PKG 36 Month #884	FUNCTIONAL TEST OF THE EXIT-PULL SIGN	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
	Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
52 20-00-203 Airframe INSPECTION PKG 24 Month #3368	LUBRICATION OF THE EMERGENCY EXIT DOOR	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		31-MAY-2027	M: 11 D: 30
	Notes (AVG MAN HRS: 2.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
52 21-00-202 Airframe INSPECTION PKG 48 Month #1459	DETAILED INSPECTION OF THE LATCH FITTINGS AND DOOR STOPS OF THE OVERWING EMERGENCY-EXIT DOOR.	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
52 21-00-203 Airframe INSPECTION PKG 48 Month #1708	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE OVERWING EMERGENCY-EXIT DOOR	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
52 31-00-202 Airframe INSPECTION PKG 48 Month #1873	DETAILED INSPECTION OF THE STOP FITTINGS OF THE CARGO COMPARTMENT DOOR	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 31-00-203 Airframe INSPECTION PKG 96 Month #1709	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE CARGO COMPARTMENT DOOR	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 5)						
52 40-00-201 Airframe INSPECTION PKG1200Hour #3599	OPERATIONAL TEST OF THE ADG DOOR OPERATING MECHANISM	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
	Notes (AVG MAN HRS: 3) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
52 45-00-301 Airframe INSPECTION 05M006 #3056	LUBRICATION OF THE SERVICE DOOR LOCKS.	26-MAY-2026 H: 8686.90 L: 3999	M: 6	D: 18		26-NOV-2026	M: 5 D: 25
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH LUBRICATION OF THE SERVICE DOORS LOCKS IAW BOMBARDIER CL 604 AMM 52-45-00.)						
52 ZL-00-206 Airframe INSPECTION PKG 48 Month #2053	GENERAL VISUAL INSPECTION OF THE PASSENGER DOOR - EXTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
52 ZL-00-207 Airframe INSPECTION PKG 48 Month #2349	GENERAL VISUAL INSPECTION OF THE PASSENGER DOOR - INTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 13.4) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
52 ZL-00-208 Airframe INSPECTION PKG 96 Month #729	GENERAL VISUAL INSPECTION OF THE OVERWING EMERGENCY - EXIT DOOR - EXTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3)						
52 ZL-00-209 Airframe INSPECTION PKG 48 Month #1071	GENERAL VISUAL INSPECTION OF THE OVERWING EMERGENCY - EXIT DOOR - INTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
52 ZL-00-210 Airframe INSPECTION PKG 48 Month #1773	GENERAL VISUAL INSPECTION OF THE CARGO COMPARTMENT DOOR - EXTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
52 ZL-00-211 Airframe INSPECTION PKG 48 Month #837	GENERAL VISUAL INSPECTION OF THE CARGO COMPARTMENT DOOR - INTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 Airframe PART #776	FLIGHT DATA RECORDER (FDR) MOUNTING TRAY					15-OCT-1997	
	Part Number	Serial Number					
	Unknown	Unknown					
53 Airframe PART #3194	FUSELAGE ASSY, REAR					15-OCT-1997	
	Part Number	Serial Number					
	Unknown	Unknown					
53 Airframe PART #707	FWD - LEFT KEEL, LONGERON					15-OCT-1997	
	Part Number	Serial Number					
	Unknown	Unknown					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 Airframe PART #2816	FWD - LEFT LINK, KEEL MEMBER Part Number Unknown Serial Number Unknown	15-OCT-1997					
53 Airframe PART #396	FWD - RIGHT KEEL, LONGERON Part Number Unknown Serial Number Unknown	15-OCT-1997					
53 Airframe PART #1254	FWD - RIGHT LINK, KEEL MEMBER Part Number Unknown Serial Number Unknown	15-OCT-1997					
53 Airframe PART #328	GA - MID FUSELAGE - STA 439 TO 621 STRUCTURE Part Number 600-31000-1005PE Serial Number 5352	15-OCT-1997					
53 Airframe PART #2897	LEFT LINK ASSY, PICK UP, WING TO FUSELAGE Part Number Unknown Serial Number Unknown	15-OCT-1997					
53 Airframe PART #3697	MID FUSELAGE FLOOR PANEL Part Number Unknown Serial Number Unknown Notes (ZONE: RBL42.90 BETWEEN FS424.00 AND FS559.00,)	15-OCT-1997					
53 Airframe PART #2307	RADOME ASSY Part Number 601R33038-963 Serial Number Unknown Notes (ZONE: FS144 BL0 WL70)	15-OCT-1997					
53 Airframe PART #843	RIGHT LINK ASSY, PICK UP, WING TO FUSELAGE Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 00-00-9001 Airframe INSPECTION #430	INSPECT IRRIDIUM CONNECTOR FEED-THRU HOLE	20-JAN-2006 H: 2527.20 L: 986	L: 3980			L: 4966	L: 964
53 00-00-9002 Airframe INSPECTION #2838	INSPECT IRIDIUM ANTENNA ATTACHMENT HOLES	20-JAN-2006 H: 2527.20 L: 986	L: 3980			L: 4966	L: 964
53 10-00-101* Airframe INSPECTION #3451	DETAILED INSPECTION OF THE FUSELAGE SKIN AT THE NLG CUTOUT - FS235		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 2) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 10-00-102* Airframe INSPECTION #1918	DETAILED INSPECTION OF THE FORWARD PRESSURE BULKHEAD WEB - FS202		L: 6900			L: 6900	L: 2898
	Notes (AVG MAN HRS: 6.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 10-00-103* Airframe INSPECTION #866	DETAILED INSPECTION OF THE FRAME - FS220		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 10-00-104* Airframe INSPECTION #2910	DETAILED INSPECTION OF THE WINDOW LOWER SILL - FS235, FS249 AND FS264	01-NOV-2022 H: 7820.30 L: 3509	L: 1545			L: 5054	L: 1052
	Notes (AVG MAN HRS: 17) (UPDATE NOTE: WORK PERFORMED BY KEYSTONE AVIATION SHANE NAIL A&P 3036309 AND JAMIE MAUCH A&P 3113329) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 10-00-105* Airframe INSPECTION #3448	DETAILED INSPECTION OF THE WINDOW LOWER SILL - FS209	21-OCT-2024 H: 8557.60 L: 3931	L: 1933			L: 5864	L: 1862
	Notes (AVG MAN HRS: 6) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 10-00-106* Airframe INSPECTION #1488	DETAILED INSPECTION OF THE WINDOW UPPER SILL - FS234, BL2.5	11-JUL-2023 H: 8075.40 L: 3647	L: 755			L: 4402	L: 400
	Notes (AVG MAN HRS: 7) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 10-00-107* Airframe INSPECTION #2363	DETAILED INSPECTION OF THE FORWARD PRESSURE BULKHEAD - VERTICAL STIFFENER BL22		L: 5545			L: 5545	L: 1543
	Notes (AVG MAN HRS: 4.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 10-00-110* Airframe INSPECTION #2282	DETAILED INSPECTION OF THE FORWARD PRESSURE BULKHEAD VERTICAL MEMBER - WL79.5 AND WL93, BL22		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 8.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 10-00-111* Airframe INSPECTION #1725	SPECIAL DETAILED INSPECTION OF THE FUSELAGE FRAME - FS235 UPPER CAP ANGLE, BL8		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 7) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE: AS PER BOMBARDIER TECHNICAL PUBLICATIONS, THIS TASK IS THE SAME AS THE CL604 NDT TASK. AS SUCH, THE CL604 PDF FILE IS ATTACHED. (REF. USER COMMENT NO. UC16-03-44, DATED MAR. 31, 2016))						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 10-00-112* Airframe INSPECTION #571	DETAILED INSPECTION OF THE FLOOR CONNECTION CLIPS - FS202.75, BL13		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 12) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
53 10-00-113* Airframe INSPECTION #3209	SPECIAL DETAILED INSPECTION OF THE FORWARD PRESSURE BULKHEAD WEB - WL79.5 TO WL91.7		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 11) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 4: AMTOSS/NDT NO. WAS NOT AVAILABLE FOR PUBLICATION OF THIS DOCUMENT AND WILL BE PROVIDED IN DUE TIME AT OPPORTUNITY OF REVISION OF THIS DOCUMENT.)</p>						
53 10-00-114* Airframe INSPECTION #285	DETAILED INSPECTION OF THE NLG BEAM, WEB BELOW DRAG BEAM - FS210 TO FS215, UPPER CAP - FS210 AND LOWER CAP - FS224		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 2) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
53 10-00-115* Airframe INSPECTION #54	DETAILED INSPECTION OF THE NLG DRAG STRUT - FS213, AND THE NLG BEAM VERTICAL STIFFENER CLIP - FS215		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 8.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
53 10-00-119* Airframe INSPECTION #888	SPECIAL DETAILED INSPECTION OF THE PILOTS FLOOR WEB ADJACENT TO THE PRESSURE BULKHEAD - FS203, BL16		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 10-00-121* Airframe INSPECTION #317	DETAILED INSPECTION OF THE FORWARD PRESSURE-BULKHEAD CAP-ANGLE AFT-SIDE - FS202.75.		L: 6941			L: 6941	L: 2939
	<p>Notes</p> <p>(NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. PHASE-IN: FOR AIRCRAFT WITH 5741 LANDINGS OR LESS, THIS TASK MUST BE ACCOMPLISHED AT OR BEFORE 6941 LANDINGS. FOR AIRCRAFT BETWEEN 5741 LANDINGS AND 8800 LANDINGS, THIS TASK MUST BE ACCOMPLISHED WITHIN 1200 LANDINGS, BUT NOT LATER THAN 9400 LANDINGS, WHICHEVER COMES FIRST. FOR AIRCRAFT WITH MORE THAN 8800 LANDINGS, THIS TASK MUST BE ACCOMPLISHED WITHIN 600 LANDINGS.)</p>						
53 10-00-201 Airframe INSPECTION PKG 48 Month #3633	DETAILED INSPECTION OF THE INTERNAL FUSELAGE, FRAMES AND FORWARD BULKHEAD - FS169.00 TO FS202.75	31-MAY-2025	M: 48 H: 8649.70 L: 3986	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 5.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
53 10-00-203 Airframe INSPECTION PKG 48 Month #2176	DETAILED INSPECTION OF THE INTERNAL FUSELAGE (SKINS AND STRUCTURE) - FS202.75 TO FS280.00 BELOW THE FLOOR	31-MAY-2025	M: 48 H: 8649.70 L: 3986	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 11) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
53 10-00-204 Airframe INSPECTION PKG 48 Month #2541	DETAILED INSPECTION OF THE INTERNAL FUSELAGE, SKIN AND STRUCTURE - FS202.75 TO FS280.00 ABOVE THE FLOOR	31-MAY-2025	M: 48 H: 8649.70 L: 3986	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 20.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
53 10-00-208 Airframe INSPECTION PKG 48 Month #212	DETAILED INSPECTION OF THE BEAMS, CROSSMEMBERS AND PANELS OF THE FLOOR STRUCTURE - FS169 TO FS280	31-MAY-2025	M: 48 H: 8649.70 L: 3986	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 18.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 10-00-210 Airframe INSPECTION PKG 48 Month #1087	DETAILED INSPECTION OF THE FORWARD JACKING POINT - FS278	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 10-00-212 Airframe INSPECTION PKG 48 Month #2922	DETAILED INSPECTION OF THE NLG WHEEL WELL STRUCTURE	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 10-00-213 Airframe INSPECTION PKG 48 Month #3582	DETAILED INSPECTION OF THE NLG INTERNAL BOX STRUCTURE - FS169 TO FS235	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 4.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 10-00-218 Airframe INSPECTION PKG 96 Month #1090	DETAILED INSPECTION OF THE AFT SIDE OF THE PILOT BULKHEAD AND FRAME - FS280.00 ABOVE WL73.50 (FLOOR LEVEL)	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 54)						
53 20-00-101* Airframe INSPECTION #479	SPECIAL DETAILED INSPECTION OF THE END POST OF THE SIDE-WINDOW - FS280		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-102* Airframe INSPECTION #116	DETAILED INSPECTION OF THE STRUCTURE AROUND THE CABIN WINDOWS		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 231, 232) (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-103* Airframe INSPECTION #1689	DETAILED INSPECTION OF THE FOUR CORNERS AND STRUCTURE AROUND THE OVERWING EMERGENCY EXIT		L: 7800			L: 7800	L: 3798
	Notes (ACCESS: 841AR) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-104* Airframe INSPECTION #3437	SPECIAL DETAILED INSPECTION OF THE CUTOUTS FOR THE CABIN WINDOWS		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-105* Airframe INSPECTION #463	DETAILED INSPECTION OF THE STRINGER SPLICE - STRINGER 3, FS473		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-106* Airframe INSPECTION #3199	DETAILED INSPECTION OF THE SKIN AND THE STRINGER SPLICE - STRINGER 0.0, FS599		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-107* Airframe INSPECTION #1970	DETAILED INSPECTION OF THE SKIN SPLICE - STRINGER 0.0, FS439		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-108* Airframe INSPECTION #3431	DETAILED INSPECTION OF THE FUSELAGE FRAMES - FS220, FS235, FS250, FS265, FS280, FS295, FS310, FS321.5, FS333, FS349, FS364, FS379, FS394, FS409, FS439, FS450, FS461.5, FS484, FS499, FS529, FS544, FS559, FS574, FS589 AND FS605		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 30) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-109* Airframe INSPECTION #249	SPECIAL DETAILED INSPECTION OF THE STRUCTURE AROUND THE PASSENGER DOOR		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 4: AMTOSS/NDT NO. WAS NOT AVAILABLE FOR PUBLICATION OF THIS DOCUMENT AND WILL BE PROVIDED IN DUE TIME AT OPPORTUNITY OF REVISION OF THIS DOCUMENT.)						
53 20-00-110* Airframe INSPECTION #3534	DETAILED INSPECTION OF THE STRUCTURE AROUND THE OVERWING EMERGENCY EXIT - STRINGER 9, FS450		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-111* Airframe INSPECTION #2494	SPECIAL DETAILED INSPECTION OF THE STRUCTURE AROUND THE BAGGAGE DOOR		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-112* Airframe INSPECTION #1356	SPECIAL DETAILED INSPECTION OF THE KEEL LONGERON LINKS AND THE BOLTS - FS395.75		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 13) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-113* Airframe INSPECTION #1218	DETAILED INSPECTION OF THE PASSENGER DOOR FRAMES - FS310 AND FS349		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-114* Airframe INSPECTION #2626	SPECIAL DETAILED INSPECTION OF THE CORNER OF THE PRESSURE SKIN - FS409 TO FS559, WL73		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 12) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-115* Airframe INSPECTION #1436	SPECIAL DETAILED INSPECTION OF THE WING-TO-FUSELAGE ATTACHMENT FRAME - FS424, WL73		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 231, 232) (ACCESS: 161DL, 162CL) (AVG MAN HRS: 9) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-116* Airframe INSPECTION #1310	DETAILED INSPECTION OF THE WING-TO-FUSELAGE ATTACHMENT FRAME - FS513, BL16		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 165) (ACCESS: 163AZ, 164AZ) (AVG MAN HRS: 12) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-117* Airframe INSPECTION #1814	SPECIAL DETAILED INSPECTION OF THE LONGITUDINAL FLOOR BEAMS - FS513		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-118* Airframe INSPECTION #420	DETAILED INSPECTION OF THE LONGITUDINAL FLOOR BEAMS - FS484, BL18		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 23) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-119* Airframe INSPECTION #1624	DETAILED INSPECTION OF THE WING-TO-FUSELAGE ATTACHMENT LUGS - FS424 FS473 AND FS513		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 16) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-120* Airframe INSPECTION #1425	DETAILED INSPECTION OF THE SKIN SPLICE - STRINGER 8, FS424 TO FS439		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-121* Airframe INSPECTION #1056	DETAILED INSPECTION OF THE LONGERON ASSEMBLY - UNDER FLOOR, FS513, BL45		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 161, 162, 163, 164, 231, 232) (ACCESS: 231NLF, QLF) (AVG MAN HRS: 13) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-122* Airframe INSPECTION #3717	DETAILED INSPECTION OF THE TIE BEAM, PRESSURE FLOOR-TO-WING - FS460		L: 5904			L: 5904	L: 1902
	Notes (AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-123* Airframe INSPECTION #2261	DETAILED INSPECTION OF THE STRINGER SPLICE - STRINGER 13, FS513		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-125* Airframe INSPECTION #2572	SPECIAL DETAILED INSPECTION OF THE WING-TO-FUSELAGE ATTACHMENT FRAME - FS513		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 231, 232) (AVG MAN HRS: 5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-126* Airframe INSPECTION #2459	SPECIAL DETAILED INSPECTION OF THE KEEL LONGERON.		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 20) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-127* Airframe INSPECTION #1048	DETAILED INSPECTION OF THE OVERWING FLOOR INTERCOSTAL - FS421, FS427, FS439, FS448.85, FS461.5, FS469.58, FS476.72 AND FS484		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 22) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-128* Airframe INSPECTION #315	DETAILED INSPECTION OF THE FRAME-TO-LONGERON CLEATS - FS439, FS461, FS484, FS499, FS529 AND FS544		L: 6695			L: 6695	L: 2693
	Notes (AVG MAN HRS: 190) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-129* Airframe INSPECTION #2975	DETAILED INSPECTION OF THE PRESSURE BOX OF THE FORWARD KEEL BEAM - FS409.00 (A/C 5301 TO 5352, PRE SB 604-53-006)						
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE: REF: AD CF-97-16 AND FAA AD 97-24-02)						
53 20-00-130* Airframe INSPECTION #1251	DETAILED INSPECTION OF THE TENSION CLIP, BULB ANGLE, BEAMS AND THE AFT SKIN PANEL OF THE FORWARD AUXILIARY TANK		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 20) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-134* Airframe INSPECTION #3315	SPECIAL DETAILED INSPECTION OF THE ACCESS DOORS ON THE FORWARD AUXILIARY TANK		L: 6300			L: 6300	L: 2298
	Notes (AVG MAN HRS: 20) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-135* Airframe INSPECTION #1594	DETAILED INSPECTION OF THE FORWARD PRESSURE SKIN PANEL AND THE FORWARD ATTACHMENT ANGLES OF THE FORWARD AUXILIARY TANK		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-136* Airframe INSPECTION #530	SPECIAL DETAILED INSPECTION OF THE FORWARD PRESSURE SKIN PANEL OF THE FORWARD AUXILIARY TANK		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 2) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-140* Airframe INSPECTION #393	SPECIAL DETAILED INSPECTION OF THE AREA AROUND THE CUTOUTS THAT FOLLOW: (1) TCAS ANTENNAS AT FS301.95, BL0.0 AND FS326, BL2.93L (2) ATC ANTENNA AT FS401.47, BL8.89L AND 8.89R (3) DUAL GPS ANTENNA AT FS284.1, BL14L & 14R (4) LOWER BEACON LIGHT AT FS565.5, BL30.67L (5) DRAIN MAST AT FS611 STRINGER 24R TO 25R (6) POTABLE WATER FILL ADAPTOR AT FS599, STRINGER 19R TO 20R		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-141* Airframe INSPECTION #1940	SPECIAL DETAILED INSPECTION OF THE AREA AROUND THE CUTOUTS THAT FOLLOW: (1) THIRD VHF COMM ANTENNA AT FS549.29, BL0.0 (2) LIGHTNING SENSOR SYSTEM (LSS) ANTENNA AT FS521.5, BL3.35L (3) AFIS ANTENNA AT FS478.5, BL3.35R (4) UPPER BEACON LIGHT AT FS431.5, BL0.0		L: 5889			L: 5889	L: 1887
	Notes (AVG MAN HRS: 7.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-142* Airframe INSPECTION #2048	DETAILED INSPECTION OF THE AREA AROUND THE CUTOUTS THAT FOLLOW: (1) SECOND RADIO ALTIMETER ANTENNA AT FS633.5, BL3R (2) ELT ANTENNA AT FS723.15, BL12.57 (3) FLIGHT PHONE ANTENNA AT FS764, BL0.0		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-143* Airframe INSPECTION #1431	DETAILED INSPECTION OF THE PRESSURE BULKHEAD - FS409, BL12L TO BL12R (A/C 5353 TO 5431, PRE SB 604-53-006)						
	Notes (AVG MAN HRS: 1)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-144* Airframe INSPECTION #2587	SPECIAL DETAILED INSPECTION OF THE PRESSURE BULKHEAD - FS409.00, LBL9.00 TO RBL9.00.	15-OCT-1997	L: 7800			L: 7800	L: 3798
	Notes (ZONE: 141, 142) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-145* Airframe INSPECTION #817	SPECIAL DETAILED INSPECTION OF THE MACHINED STRAP - FS409.00, LBL6.00 TO RBL6.00.	15-OCT-1997	L: 7800			L: 7800	L: 3798
	Notes (ZONE: 141, 142) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-146* Airframe INSPECTION #341	SPECIAL DETAILED INSPECTION OF THE FUSELAGE FRAME CAP - FS409.00, LBL18.00 TO TO RBL18.00.	15-OCT-1997	L: 7800			L: 7800	L: 3798
	Notes (ZONE: 141, 142) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-147* Airframe INSPECTION #240	DETAILED INSPECTION OF THE STOPS, FITTINGS AND ATTACHMENTS OF THE OVERWING EMERGENCY EXIT		L: 4760			L: 4760	L: 758
	Notes (AVG MAN HRS: 2) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 20-00-148* Airframe INSPECTION #610	SPECIAL DETAILED INSPECTION OF THE PRESSURE BULKHEAD FS409, BL9L TO BL9R (A/C 5353 TO 5431 PRE SB 604-53-006)						
	Notes (AVG MAN HRS: 2)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-149* Airframe INSPECTION #2992	SPECIAL DETAILED INSPECTION OF THE IRIDIUM SATCOM ANTENNA INSTALLATION (IF INSTALLED), FS338.00, STRINGER 0 TO 1R		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
53 20-00-163* Airframe INSPECTION #3269	SPECIAL DETAILED INSPECTION OF THE WING-TO-FUSELAGE PINS		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(SOURCE: MPD, TLMC) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. PHASE-IN: FOR AIRCRAFT WITH LESS THAN 7000 LANDINGS, THIS TASK MUST BE ACCOMPLISHED AT OR BEFORE 7800 LANDINGS. FOR AIRCRAFT WITH MORE THAN 7000 LANDINGS BUT NOT MORE THAN 10500 LANDINGS, THIS TASK MUST BE ACCOMPLISHED WITHIN 1500 LANDINGS BUT NOT LATER THAN 11500 LANDINGS. FOR AIRCRAFT WITH MORE THAN 10500 LANDINGS, THIS TASK MUST BE ACCOMPLISHED WITHIN 1000 LANDINGS.)</p>						
53 20-00-186* Airframe INSPECTION #3043	DETAILED INSPECTION OF THE WING-TO-FUSELAGE ATTACHMENT LUGS AND BOLTS - FS424		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
53 20-00-188* Airframe INSPECTION #1269	SPECIAL DETAILED INSPECTION OF THE UPPER LATCH PINS OF THE PASSENGER DOOR		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-192* Airframe INSPECTION #2767	SPECIAL DETAILED INSPECTION OF THE SKIN CIRCUMFERENTIAL SPLICE AT FS559.00, BETWEEN STRINGERS 10L AND 10R.		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 0) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. PHASE-IN: FOR AIRCRAFT WITH LESS THAN 4800 LANDINGS, THIS TASK MUST BE ACCOMPLISHED BEFORE 7800 LANDINGS. FOR AIRCRAFT WITH 4800 LANDINGS OR MORE BUT LESS THAN 7800 LANDINGS, THIS TASK MUST BE ACCOMPLISHED WITHIN 3000 LANDINGS BUT BEFORE 9800 LANDINGS. FOR AIRCRAFT WITH 7800 LANDINGS OR MORE BUT LESS THAN 9800 LANDINGS, THIS TASK MUST BE ACCOMPLISHED WITHIN 2000 LANDINGS BUT BEFORE 10800 LANDINGS. FOR AIRCRAFT WITH 9800 LANDINGS OR MORE, THIS TASK MUST BE ACCOMPLISHED WITHIN 1000 LANDINGS.)</p>						
53 20-00-201 Airframe INSPECTION PKG 48 Month #756	DETAILED INSPECTION OF THE SILLS, FRAMES AND EXTERNAL SKIN AROUND THE PASSENGER DOOR CUTOUT	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 44.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
53 20-00-202 Airframe INSPECTION PKG 48 Month #2695	DETAILED INSPECTION OF THE FITTINGS AND THE HINGE ON THE FUSELAGE FOR THE PASSENGER DOOR	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 4.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
53 20-00-203 Airframe INSPECTION PKG 48 Month #3551	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE - FS280 TO FS409, AS VISIBLE WITH THE FLOOR PANELS INSTALLED	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 12.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
53 20-00-204 Airframe INSPECTION PKG 96 Month #517	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE - FS280 TO FS409	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 100.5)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-205 Airframe INSPECTION PKG 96 Month #2515	DETAILED INSPECTION OF THE INTERNAL FUSELAGE (SKINS AND STRUCTURE) - FS280.00 TO FS621.00 ABOVE THE FLOOR	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3)						
53 20-00-206 Airframe INSPECTION PKG 48 Month #3186	DETAILED INSPECTION OF THE LOWER INTERNAL SKIN AND FUSELAGE STRUCTURE - FS280 TO FS409, AS VISIBLE WITH THE FLOOR PANELS INSTALLED	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 14.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 20-00-207 Airframe INSPECTION PKG 96 Month #1259	DETAILED INSPECTION OF THE INTERNAL MID-FUSELAGE (SKIN AND STRUCTURE, FS409.00 BULKHEAD FORWARD FACE AND THE EXTERNAL SURFACES OF THE FORWARD-AUXILIARY FUEL TANK) - FS280.00 TO FS409.00 BELOW THE FLOOR	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 153.5)						
53 20-00-210 Airframe INSPECTION PKG 96 Month #2266	DETAILED INSPECTION OF THE INTERNAL FORWARD KEEL BEAM - FS364 TO FS394	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3)						
53 20-00-211 Airframe INSPECTION PKG 96 Month #3558	DETAILED INSPECTION OF THE FORWARD KEEL BEAM PRESSURE BOX AND KEEL BEAM LUGS AND LINKS - FS394 TO FS409	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 7)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-212 Airframe INSPECTION PKG 48 Month #636	DETAILED INSPECTION OF THE AFT KEEL BEAM - FS513 TO FS559	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 4.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 20-00-216 Airframe INSPECTION PKG 96 Month #313	DETAILED INSPECTION OF THE AFT FACE OF THE FRAME BELOW THE FLOOR -FS409	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 14.5)						
53 20-00-217 Airframe INSPECTION PKG 96 Month #2035	DETAILED INSPECTION OF THE SILLS, FRAMES AND EXTERNAL SKIN AROUND THE EMERGENCY-EXIT DOOR CUTOUT	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 5)						
53 20-00-218 Airframe INSPECTION PKG 48 Month #3218	DETAILED INSPECTION OF THE FITTINGS OF THE EMERGENCY-EXIT DOOR	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.8) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 20-00-220 Airframe INSPECTION PKG 48 Month #1746	DETAILED INSPECTION OF THE FLOOR SILL AREA OVER THE WING BOX - FS409 TO FS559	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 156.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-221 Airframe INSPECTION PKG 96 Month #2163	DETAILED INSPECTION OF THE WING-TO-FUSELAGE ATTACHMENT LUG - FS424	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 9)						
53 20-00-222 Airframe INSPECTION PKG 96 Month #3570	DETAILED INSPECTION OF THE WING-TO-FUSELAGE ATTACHMENT LUG - FS473.15	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 5)						
53 20-00-223 Airframe INSPECTION PKG 96 Month #1206	DETAILED INSPECTION OF THE FRAME BELOW THE FLOOR - FS513	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 13)						
53 20-00-224 Airframe INSPECTION PKG 48 Month #2723	DETAILED INSPECTION OF WING-TO-FUSELAGE ATTACHMENT LINK - FS513	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 4.6) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 20-00-225 Airframe INSPECTION PKG 96 Month #471	DETAILED INSPECTION OF THE WING-TO-FLOOR TIE BEAM - FS460	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 13)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-226 Airframe INSPECTION PKG 48 Month #1736	DETAILED INSPECTION OF THE UPPER SURFACE OF THE PRESSURE FLOOR SKIN PANEL - FS409 TO FS559 AND BL36L TO BL36R	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 170.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 20-00-227 Airframe INSPECTION PKG 48 Month #2886	DETAILED INSPECTION OF THE LOWER SURFACE OF THE PRESSURE FLOOR SKIN PANEL - FS409 TO FS559 AND BL36L TO BL36R	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 13.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 20-00-228 Airframe INSPECTION PKG 96 Month #123	DETAILED INSPECTION OF THE PRESSURE FLOOR SUPPORT BEAMS - FS409 TO FS559, BL0.0, BL9, BL18.6, BL27 AND BL35.4	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 159.5)						
53 20-00-229 Airframe INSPECTION PKG 96 Month #297	DETAILED INSPECTION OF THE UNDERFLOOR LONGERON ASSEMBLY - FS409 TO FS559	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 21.5)						
53 20-00-230 Airframe INSPECTION PKG 96 Month #685	DETAILED INSPECTION OF THE MLG UPLOCK STRUCTURE - FS513 TO FS559 BELOW WL73 (LH AND RH)	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 9)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 20-00-232 Airframe INSPECTION PKG 96 Month #380	DETAILED INSPECTION OF THE INTERNAL SURFACES OF THE FORWARD AUXILIARY TANK	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 68.5)						
53 20-00-233 Airframe INSPECTION PKG 48 Month #1726	LUBRICATION OF THE WING-TO-FUSELAGE ATTACHMENT LINKS - FS513.00	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 4.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 30-00-101* Airframe INSPECTION #3036	DETAILED INSPECTION OF THE BULB ANGLE STIFFENER, FORWARD PRESSURE SKIN PANEL AND FORWARD ATTACHMENT ANGLES OF THE AFT AUXILIARY TANK		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-102* Airframe INSPECTION #1695	DETAILED INSPECTION OF THE BEAMS AND THE FUEL SKIN PANELS OF THE AFT AUXILIARY TANK		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 16) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-104* Airframe INSPECTION #2384	SPECIAL DETAILED INSPECTION OF THE ACCESS DOORS ON THE AFT AUXILIARY TANK		L: 6375			L: 6375	L: 2373
	Notes (AVG MAN HRS: 20) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-106* Airframe INSPECTION #73	SPECIAL DETAILED INSPECTION OF THE FORWARD PRESSURE SKIN PANEL OF THE AFT AUXILIARY FUEL TANK		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 12) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-110* Airframe INSPECTION #2628	DETAILED INSPECTION OF THE STRINGER SPLICE AT THE REAR PRESSURE BULKHEAD - FS621		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-111* Airframe INSPECTION #1160	DETAILED INSPECTION OF THE FRAME ASSEMBLY PRESSURE BULKHEAD - FS621		L: 6695			L: 6695	L: 2693
	Notes (AVG MAN HRS: 4.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-113* Airframe INSPECTION #1759	DETAILED INSPECTION OF THE REAR PRESSURE BULKHEAD WEB FEED-THROUGH HOLES AND CUTOUTS	02-JUL-2021	L: 1548			L: 4582	L: 580
	Notes (AVG MAN HRS: 2.5) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-114* Airframe INSPECTION #207	DETAILED INSPECTION OF THE STRINGER SPLICE - FS718, STRINGER 1L AND 1R		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 18) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-115* Airframe INSPECTION #1212	DETAILED INSPECTION OF THE REAR PRESSURE BULKHEAD FRAME CAP - FS621		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-116* Airframe INSPECTION #3492	DETAILED INSPECTION OF THE FUSELAGE FRAME - VS55.625%, STRINGER 5		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-117* Airframe INSPECTION #3215	SPECIAL DETAILED INSPECTION OF THE CAP ANGLE OF THE FUSELAGE FRAME - FS755		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-118* Airframe INSPECTION #762	SPECIAL DETAILED INSPECTION OF THE DRAG ANGLE OF THE FUSELAGE FRAME - FS755		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-119* Airframe INSPECTION #2578	DETAILED INSPECTION OF THE FUSELAGE FRAME AT THE FRONT SPAR ATTACHMENT OF THE VERTICAL STABILIZER - FS755		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-120* Airframe INSPECTION #2696	SPECIAL DETAILED INSPECTION OF THE VERTICAL STIFFENERS OF THE REAR PRESSURE BULKHEAD		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 14.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 4: AMTOSS/NDT NO. WAS NOT AVAILABLE FOR PUBLICATION OF THIS DOCUMENT AND WILL BE PROVIDED IN DUE TIME AT OPPORTUNITY OF REVISION OF THIS DOCUMENT.)						
53 30-00-121* Airframe INSPECTION #2173	SPECIAL DETAILED INSPECTION OF THE FLOOR BEAM ATTACHMENT TO THE PRESSURE BULKHEAD - FS621		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 14) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 4: AMTOSS/NDT NO. WAS NOT AVAILABLE FOR PUBLICATION OF THIS DOCUMENT AND WILL BE PROVIDED IN DUE TIME AT OPPORTUNITY OF REVISION OF THIS DOCUMENT.)						
53 30-00-122* Airframe INSPECTION #458	SPECIAL DETAILED INSPECTION OF THE TRANSVERSE BEAM, AFT OF THE PRESSURE BULKHEAD - FS621, BL27		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-123* Airframe INSPECTION #621	SPECIAL DETAILED INSPECTION OF THE UPPER CAP OF THE PYLON SPAR - FS625.3		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-124* Airframe INSPECTION #1974	SPECIAL DETAILED INSPECTION OF THE UPPER CAP OF THE PYLON SPAR AT THE FUSELAGE FRAME ATTACHMENT - FS672.2		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 7) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-125* Airframe INSPECTION #2027	SPECIAL DETAILED INSPECTION OF THE UPPER CAP OF THE ENGINE SUPPORT BEAM - FS625.3		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-126* Airframe INSPECTION #3685	DETAILED INSPECTION OF THE FRAME SPLICE - FS672.2, STRINGER 6		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-129* Airframe INSPECTION #3153	DETAILED INSPECTION OF THE FUSELAGE STRINGER SPLICE - FS625.3, STRINGER 0.0		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-130* Airframe INSPECTION #3251	SPECIAL DETAILED INSPECTION OF THE SPLICE ANGLE OF THE OUTER FLANGE CAP - FS625.3		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 311, 312) (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. PHASE-IN FOR AIRCRAFT WITH 6800 LANDINGS OR LESS, THIS TASK MUST BE ACCOMPLISHED AT OR BEFORE 7800 LANDINGS. FOR AIRCRAFT WITH MORE THAN 6800 LANDINGS, THIS TASK MUST BE ACCOMPLISHED WITHIN 1000 LANDINGS, BUT NOT LATER THAN 8800 LANDINGS, WHICHEVER COMES FIRST.)						
53 30-00-131* Airframe INSPECTION #1696	DETAILED INSPECTION OF THE INTERCOSTALS AND CLIPS - FS621 TO FS625.3, PRESSURE BULKHEAD VERTICAL STIFFENERS - FS621, AND THE STIFFENING ANGLES ON THE ENGINE SUPPORT BEAM - FS625.3		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 311, 312) (ACCESS: 311BB) (AVG MAN HRS: 3.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-134* Airframe INSPECTION #119	DETAILED INSPECTION OF THE FUSELAGE FRAME WEB - FS755, BL5.5 AND WL131		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 3.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
53 30-00-135* Airframe INSPECTION #1969	DETAILED INSPECTION OF THE STRUCTURE ADJACENT TO THE OVERBOARD LAVATORY SERVICES	06-DEC-2007	L: 6142			L: 6142	L: 2140
	<p>Notes</p> <p>(AVG MAN HRS: 2.5) (MANUAL ADJUSTMENT: -1295 LDG) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
53 30-00-137* Airframe INSPECTION #2945	SPECIAL DETAILED INSPECTION OF THE DRAG ANGLE - VS67.5%		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
53 30-00-138* Airframe INSPECTION #792	DETAILED INSPECTION OF THE SPLICES AND STRINGERS (L&R) BETWEEN FRAMES - VS55.625% AND VS67.5%		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
53 30-00-139* Airframe INSPECTION #1648	SPECIAL DETAILED INSPECTION OF THE REAR PRESSURE BULKHEAD WEB CUTOUT - RBL13.05, WL63.80 (POST SB 604-53-008 PART B)						
	<p>Notes</p> <p>(AVG MAN HRS: 1)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-154* Airframe INSPECTION #526	SPECIAL DETAILED INSPECTION OF THE REAR PRESSURE BULKHEAD WEB - FS621.00 FWD FACE		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-155* Airframe INSPECTION #1522	DETAILED INSPECTION OF THE ENGINE SUPPORT BEAM		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-158* Airframe INSPECTION #2250	DETAILED INSPECTION OF THE FUSELAGE SKIN AROUND THE LDS ANTENNA BETWEEN FS736.00 AND FS755.00, AND STRINGERS 26R AND 26L, (POST SB 604-34-063) OR (POST SB 604-34-066)	15-OCT-1997	L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-159* Airframe INSPECTION #108	SPECIAL DETAILED INSPECTION OF THE SPLICE STRAP AND SKIN AT STRINGER 20L AND 20R BETWEEN FS559.00 AND FS621.00		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 171, 172) (ACCESS: 195AL, 196AR, 195BB, 241ELF, 241FLF, 241ERF, 242FR) (AVG MAN HRS: 11.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
53 30-00-160* Airframe INSPECTION #3011	DETAILED INSPECTION OF THE FUSELAGE STRUCTURE FOR HYDRAULIC SYSTEM NO. 3 ACCUMULATOR AT FS574.00 (POST SB 604-29-013)						
	Notes (ZONE: 195,196) (ACCESS: 191AL) (AVG MAN HRS: 4)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-161* Airframe INSPECTION #689	DETAILED INSPECTION OF THE SPLICE ANGLE OF THE OUTER FLANGE CAP - FS625.3	15-OCT-1997	L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(ZONE: 311, 312) (AVG MAN HRS: 0) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. PHASE-IN FOR AIRCRAFT WITH 6800 LANDINGS OR LESS, THIS TASK MUST BE ACCOMPLISHED AT OR BEFORE 7800 LANDINGS. FOR AIRCRAFT WITH MORE THAN 6800 LANDINGS, THIS TASK MUST BE ACCOMPLISHED WITHIN 1000 LANDINGS, BUT NOT LATER THAN 8800 LANDINGS, WHICHEVER COMES FIRST.)</p>						
53 30-00-201 Airframe INSPECTION PKG 48 Month #1793	DETAILED INSPECTION OF THE AFT FACE OF THE PRESSURE BULKHEAD BELOW THE FLOOR - FS559	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 138.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
53 30-00-202 Airframe INSPECTION PKG 48 Month #3535	DETAILED INSPECTION OF THE FORWARD FACE OF THE PRESSURE BULKHEAD BELOW THE FLOOR - FS559	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 12.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
53 30-00-203 Airframe INSPECTION PKG 48 Month #3661	DETAILED INSPECTION OF THE AFT FACE OF THE REAR PRESSURE BULKHEAD - FS621	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 3.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						
53 30-00-204 Airframe INSPECTION PKG 96 Month #1077	DETAILED INSPECTION OF THE STABILIZER DRAG ANGLES - FS700 TO FS820, AND STRINGER 2L AND 2R	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 4)</p>						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-205 Airframe INSPECTION PKG 96 Month #2865	DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR PRESSURE BULKHEAD ABOVE THE FLOOR - FS621	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3)						
53 30-00-206 Airframe INSPECTION PKG 96 Month #505	DETAILED INSPECTION OF THE PROFILE PLATES OF THE FLOOR SUPPORT STRUCTURE - FS559 TO FS621	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 176.5)						
53 30-00-207 Airframe INSPECTION PKG 48 Month #3051	DETAILED INSPECTION OF THE PROFILE PLATES OF THE FLOOR SUPPORT STRUCTURE - FS621	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 30-00-208 Airframe INSPECTION PKG 96 Month #3030	DETAILED INSPECTION OF THE ENGINE SUPPORT BEAM STRUCTURE	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2.5)						
53 30-00-209 Airframe INSPECTION PKG 96 Month #1068	DETAILED INSPECTION OF THE INTERNAL AFT FUSELAGE (SKIN AND STRUCTURE, FS621.00 BULKHEAD FORWARD FACE AND THE EXTERNAL SURFACES OF THE AFT-AUXILIARY FUEL TANK) - FS559.00 TO FS621.00 BELOW THE FLOOR	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 164.5)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-211 Airframe INSPECTION PKG 48 Month #1015	DETAILED INSPECTION OF THE TRACK SUPPORTS NEAR, AND THE SILLS AND FRAMES AROUND, THE CARGO COMPARTMENT DOOR CUTOUT	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 12.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
53 30-00-213 Airframe INSPECTION PKG 48 Month #1049	DETAILED INSPECTION OF THE FITTINGS OF THE CARGO COMPARTMENT DOOR	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
53 30-00-215 Airframe INSPECTION PKG 48 Month #1956	DETAILED INSPECTION OF THE INTERNAL SKIN AND FUSELAGE STRUCTURE - FS621 TO FS755	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 3.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
53 30-00-216 Airframe INSPECTION PKG 48 Month #107	DETAILED INSPECTION OF THE FORWARD FACE OF THE FRAME - FS755	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
53 30-00-217 Airframe INSPECTION PKG 48 Month #2233	DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE APU EXHAUST CUTOUT	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 30-00-219 Airframe INSPECTION PKG 96 Month #1151	DETAILED INSPECTION OF THE EXTERNAL SIDE SKIN PANELS OF THE FUSELAGE - FS559 TO FS755 AND STRINGER 6L TO 20L AND 6R TO 20R COVERED BY PYLON	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 9)						
53 30-00-222 Airframe INSPECTION PKG 96 Month #2009	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE AFT AUXILIARY TANK	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 24)						
53 30-00-223 Airframe INSPECTION PKG 96 Month #13	SPECIAL DETAILED INSPECTION OF THE SKIN AND FUSELAGE STRUCTURE - FS718.00 TO FS755.00	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1)						
53 43-00-202 Airframe INSPECTION PKG 48 Month #141	DETAILED INSPECTION OF THE AFT FACE OF THE FRAME - VS67.5%	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 43-00-203 Airframe INSPECTION PKG 48 Month #694	DETAILED INSPECTION OF THE INTERNAL SKIN AND FUSELAGE STRUCTURE - FS755 TO VS67.5%	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 50-00-201 Airframe INSPECTION PKG 96 Month #2279	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE TAIL TANK	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3)						
53 50-00-202 Airframe INSPECTION PKG 96 Month #2389	DETAILED INSPECTION OF THE FLOOR STRUCTURE OF THE TAIL TANK	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1.5)						
53 50-00-203 Airframe INSPECTION PKG 96 Month #605	DETAILED INSPECTION OF THE FORWARD FACE OF THE FUEL TAIL TANK FORWARD BULKHEAD	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1.5)						
53 50-00-204 Airframe INSPECTION PKG 96 Month #3434	DETAILED INSPECTION OF THE AFT FACE OF THE TAIL TANK AFT BULKHEAD	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1.5)						
53 CERTDOC-008813.1 Airframe INSPECTION #1347	FREEFLIGHT GPS ANTENNA HIGH FREQUENCY EDDY CURRENT INSPECTION. REF. DUNCAN AVIATION DOC. NO. CERTDOC-008813	27-DEC-2018 H: 6424.10 L: 2747	L: 8600			L: 11347	L: 7345
53 CERTDOC-008813.2 Airframe INSPECTION #1060	FREEFLIGHT GPS ANTENNA FATIGUE LIFE LIMIT. REF. DUNCAN AVIATION DOC. NO. CERTDOC-008813	27-DEC-2018 H: 6424.10 L: 2747	L: 15600			L: 18347	L: 14345



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 ICA 110808030.1 Airframe INSPECTION #427	HIGH FREQUENCY EDDY CURRENT INSPECTION OF AIRCELL FORWARD ATG ANTENNA FEED THROUGH PER DUNCAN AVIATION DOC. NO. 110808030	09-APR-2013 H: 4782.30 L: 2063	L: 8900			L: 10963	L: 6961
53 ICA 110808030.2 Airframe INSPECTION #3462	HIGH FREQUENCY EDDY CURRENT INSPECTION OF AIRCELL AFT ATG ANTENNA FEED THROUGH PER DUNCAN AVIATION DOC. NO. 110808030	09-APR-2013 H: 4782.30 L: 2063	L: 25000			L: 27063	L: 23061
53 ZL-00-201 Airframe INSPECTION PKG 48 Month #1587	GENERAL VISUAL INSPECTION OF THE NOSE RADOME - EXTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
53 ZL-00-202 Airframe INSPECTION PKG 48 Month #252	GENERAL VISUAL INSPECTION OF THE NOSE RADOME - INTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
53 ZL-00-203 Airframe INSPECTION PKG 96 Month #3121	GENERAL VISUAL INSPECTION OF THE NOSE COMPARTMENT - LOWER EXTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 0.7)							
53 ZL-00-204 Airframe INSPECTION PKG 96 Month #1116	GENERAL VISUAL INSPECTION OF THE NOSE COMPARTMENT - LOWER INTERNAL LH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 1.5)							



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 ZL-00-205 Airframe INSPECTION PKG 48 Month #36	GENERAL VISUAL INSPECTION OF THE NOSE COMPARTMENT - LOWER INTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 2) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
53 ZL-00-206 Airframe INSPECTION PKG 48 Month #2161	GENERAL VISUAL INSPECTION OF THE NLG WHEEL WELL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 3.8) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
53 ZL-00-207 Airframe INSPECTION PKG 96 Month #2967	GENERAL VISUAL INSPECTION OF THE FORWARD AVIONICS AND FLIGHT CONTROLS COMPARTMENT - EXTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 1)							
53 ZL-00-208 Airframe INSPECTION PKG 48 Month #2822	GENERAL VISUAL INSPECTION OF THE FORWARD AVIONICS AND FLIGHT CONTROLS COMPARTMENT - INTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
53 ZL-00-209 Airframe INSPECTION PKG 48 Month #825	GENERAL VISUAL INSPECTION OF THE FORWARD AVIONICS AND FLIGHT CONTROLS COMPARTMENT - INTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 ZL-00-210 Airframe INSPECTION PKG 48 Month #1230	GENERAL VISUAL INSPECTION OF THE MAIN AVIONICS COMPARTMENT - EXTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
53 ZL-00-211 Airframe INSPECTION PKG 48 Month #2414	GENERAL VISUAL INSPECTION OF THE MAIN AVIONICS COMPARTMENT - INTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 3.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
53 ZL-00-212 Airframe INSPECTION PKG 48 Month #1545	GENERAL VISUAL INSPECTION OF THE MID-FUSELAGE - LOWER EXTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 2) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
53 ZL-00-213 Airframe INSPECTION PKG 96 Month #994	GENERAL VISUAL INSPECTION OF THE LOWER SURFACE OF THE PRESSURE-FLOOR FROM FS409 TO FS559	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 15)							
53 ZL-00-214 Airframe INSPECTION PKG 48 Month #3339	GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR WHEEL WELL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 9) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 ZL-00-215 Airframe INSPECTION PKG 96 Month #634	GENERAL VISUAL INSPECTION OF THE MID-FUSELAGE BETWEEN THE PRESSURE FLOOR AND THE CABIN FLOOR - LOWER INTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 170.5)						
53 ZL-00-216 Airframe INSPECTION PKG 96 Month #2346	GENERAL VISUAL INSPECTION OF THE AFT COMPARTMENT AND AFT WING-TO-FUSELAGE FAIRING - EXTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1.5)						
53 ZL-00-217 Airframe INSPECTION PKG 24 Month #2448	GENERAL VISUAL INSPECTION OF THE MID-FUSELAGE COMPARTMENT - LOWER INTERNAL (FS589.0 TO FS621.0)	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		31-MAY-2027	M: 11 D: 30
	Notes (AVG MAN HRS: 7) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 ZL-00-218 Airframe INSPECTION PKG 96 Month #3463	GENERAL VISUAL INSPECTION OF THE FORWARD EQUIPMENT COMPARTMENT - EXTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.3)						
53 ZL-00-219 Airframe INSPECTION PKG 96 Month #1338	GENERAL VISUAL INSPECTION OF THE FORWARD EQUIPMENT COMPARTMENT - INTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3.4)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 ZL-00-220 Airframe INSPECTION PKG 24 Month #971	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT - EXTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 24	M: 1		31-MAY-2027	M: 11 D: 30
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 ZL-00-221 Airframe INSPECTION PKG 48 Month #394	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT - INTERNAL WITHOUT REMOVAL OF THE HEADLINER AND THE GLARESHIELD	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 14.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 ZL-00-222 Airframe INSPECTION PKG 96 Month #3616	GENERAL VISUAL INSPECTION OF THE PASSENGER COMPARTMENT - EXTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1)						
53 ZL-00-223 Airframe INSPECTION 05M192 #2021	GENERAL VISUAL INSPECTION OF THE PASSENGER COMPARTMENT - INTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 192	M: 1		13-APR-2029	M: 34 D: 12
53 ZL-00-224 Airframe INSPECTION PKG 96 Month #368	GENERAL VISUAL INSPECTION OF THE CARGO COMPARTMENT - EXTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.6)						
53 ZL-00-225 Airframe INSPECTION PKG 96 Month #256	GENERAL VISUAL INSPECTION OF THE CARGO COMPARTMENT - INTERNAL WITHOUT REMOVAL OF THE HEADLINER	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 25)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 ZL-00-226 Airframe INSPECTION 05M192 #3650	GENERAL VISUAL INSPECTION OF THE CARGO COMPARTMENT - INTERNAL WITH THE HEADLINER REMOVED	02-JUL-2021 H: 6939.60 L: 3034	M: 192	M: 1		13-APR-2029	M: 34 D: 12
53 ZL-00-227 Airframe INSPECTION PKG 48 Month #96	GENERAL VISUAL INSPECTION OF THE AFT EQUIPMENT COMPARTMENT - EXTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 ZL-00-228 Airframe INSPECTION PKG 12 Month #804	GENERAL VISUAL INSPECTION OF THE AFT EQUIPMENT COMPARTMENT - INTERNAL	26-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		26-MAY-2027	M: 11 D: 25
	Notes (AVG MAN HRS: 1.5) (TOL. ADJUSTMENT: -37D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 ZL-00-229 Airframe INSPECTION PKG 96 Month #861	GENERAL VISUAL INSPECTION OF THE FUSELAGE/STABILIZER SECTION - EXTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.9)						
53 ZL-00-230 Airframe INSPECTION PKG 48 Month #1248	GENERAL VISUAL INSPECTION OF THE FUSELAGE/STABILIZER SECTION - INTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 ZL-00-231 Airframe INSPECTION PKG 48 Month #1023	GENERAL VISUAL INSPECTION OF THE TAIL CONE - EXTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
53 ZL-00-232 Airframe INSPECTION PKG 48 Month #2441	GENERAL VISUAL INSPECTION OF THE TAIL CONE - INTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
53 ZL-00-233 Airframe INSPECTION PKG 96 Month #378	GENERAL VISUAL INSPECTION OF THE MID-FUSELAGE COMPARTMENT - LOWER INTERNAL (FS559.0 TO FS621.0)	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 160.5)						
54 Airframe PART #2765	LEFT LEADING EDGE PYLON SEAL					15-OCT-1997	
	Part Number	Serial Number					
	Unknown	Unknown					
54 50-00-101* Airframe INSPECTION #1688	DETAILED INSPECTION OF THE PYLON UPPER SKIN - FS682		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
54 50-00-102* Airframe INSPECTION #1139	DETAILED INSPECTION OF THE UPPER SPLICE OF THE PYLON CANTED RIB - FS672.2		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
54 50-00-103* Airframe INSPECTION #1786	SPECIAL DETAILED INSPECTION OF THE AFT ENGINE-MOUNT UPPER-CAP FROM FS672.00 TO FS682.00		L: 7800			L: 7800	L: 3798
	Notes (ACCESS: 412EB, 422EB) (AVG MAN HRS: 100) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
54 50-00-201 Airframe INSPECTION PKG 96 Month #534	DETAILED INSPECTION OF THE FORWARD ENGINE-MOUNT SPAR ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3)						
54 50-00-203 Airframe INSPECTION PKG 96 Month #3596	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE PYLON	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 11.5)						
54 50-00-204 Airframe INSPECTION PKG 96 Month #1448	DETAILED INSPECTION OF THE AFT ENGINE-MOUNT SUPPORT STRUCTURE	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3)						
54 ZL-00-201 Airframe INSPECTION PKG 48 Month #2789	GENERAL VISUAL INSPECTION OF THE PYLON - EXTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
54 ZL-00-202 Airframe INSPECTION PKG 48 Month #2409	GENERAL VISUAL INSPECTION OF THE PYLON - EXTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
54 ZL-00-203 Airframe INSPECTION PKG 48 Month #1479	GENERAL VISUAL INSPECTION OF THE PYLON LEADING EDGE - INTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 2.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
54 ZL-00-204 Airframe INSPECTION PKG 48 Month #2080	GENERAL VISUAL INSPECTION OF THE PYLON LEADING EDGE - INTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 2.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
54 ZL-00-205 Airframe INSPECTION PKG 48 Month #1901	GENERAL VISUAL INSPECTION OF THE PYLON MID-SECTION - INTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
54 ZL-00-206 Airframe INSPECTION PKG 48 Month #1419	GENERAL VISUAL INSPECTION OF THE PYLON MID-SECTION - INTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
54 ZL-00-207 Airframe INSPECTION PKG 96 Month #2693	GENERAL VISUAL INSPECTION OF THE PYLON TRAILING EDGE - INTERNAL LH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 3.5)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
54 ZL-00-208 Airframe INSPECTION PKG 96 Month #2392	GENERAL VISUAL INSPECTION OF THE PYLON TRAILING EDGE - INTERNAL RH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3.5)						
55 Airframe PART #1666	LEFT ELEVATOR ASSY Part Number 600-24025-1011 Serial Number 5352					15-OCT-1997	
55 Airframe PART #3594	RIGHT ELEVATOR ASSY Part Number 600-24025-1012 Serial Number 5352					15-OCT-1997	
55 Airframe PART #3416	STABILIZER, HORIZONTAL Part Number 600-23025-1019 Serial Number 9148812					15-OCT-1997	
55 10-00-101* Airframe INSPECTION #2866	DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER BATHTUB FITTING		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 24) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 10-00-102* Airframe INSPECTION #2522	SPECIAL DETAILED INSPECTION OF THE UPPER CAP AND SKIN OF THE REAR SPAR OF THE HORIZONTAL STABILIZER - RIB 1		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 12.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 10-00-103* Airframe INSPECTION #3176	DETAILED INSPECTION OF THE CENTERLINE RIB UPPER CAP OF THE HORIZONTAL STABILIZER - FS886		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 10.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 10-00-105* Airframe INSPECTION #5	DETAILED INSPECTION OF THE REAR SPAR UPPER CAP AND SPLICE AT BL0.0 OF THE HORIZONTAL STABILIZER		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 332, 342) (ACCESS: 326AL, AR, BT) (AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 10-00-106* Airframe INSPECTION #2807	SPECIAL DETAILED INSPECTION OF THE PIVOT FITTING LUGS OF THE HORIZONTAL STABILIZER ON THE HORIZONTAL STABILIZER SIDE		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 36) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 10-00-107* Airframe INSPECTION #2874	DETAILED INSPECTION OF THE UPPER CAP SPLICE OF THE FRONT SPAR OF THE HORIZONTAL STABILIZER- BL6		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 9.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 10-00-108* Airframe INSPECTION #103	DETAILED INSPECTION OF THE UPPER SKIN PANEL AT STRINGER 1 OF THE HORIZONTAL STABILIZER - BL6		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 12) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 10-00-109* Airframe INSPECTION #1511	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER REAR SPAR WEB SPLICE - BLO		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 10-00-201 Airframe INSPECTION PKG 48 Month #1844	DETAILED INSPECTION OF THE UPPER FACE OF THE TOP CANTED RIB AND THE RIB FITTINGS OF THE VERTICAL STABILIZER AND THE ATTACHMENT FITTINGS AND SKIN SPLICES OF THE HORIZONTAL STABILIZER	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 9) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
55 10-00-202 Airframe INSPECTION PKG 96 Month #875	DETAILED INSPECTION OF THE FRONT SPAR OF THE HORIZONTAL STABILIZER	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 22)						
55 10-00-203 Airframe INSPECTION PKG 96 Month #2881	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER (INTERNAL SKINS, STRUCTURE, REAR SPAR AND HINGE FITTINGS) AND THE ELEVATOR (FORWARD FACE OF THE FRONT SPAR, HINGE FITTINGS AND BOLTS)	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 30)						
55 10-00-207 Airframe INSPECTION PKG 48 Month #1466	DETAILED INSPECTION OF THE INNER PIVOT PIN OF THE HORIZONTAL STABILIZER	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 23) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 20-00-101* Airframe INSPECTION #3131	SPECIAL DETAILED INSPECTION OF THE PCU FITTINGS AND THE HINGE FITTINGS OF THE ELEVATOR	08-FEB-2023 H: 7925.20 L: 3563	L: 3600			L: 7163	L: 3161
	Notes (AVG MAN HRS: 38) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 20-00-102* Airframe INSPECTION #1385	DETAILED INSPECTION OF THE ELEVATOR SKINS AND FRONT SPAR		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 38) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 20-00-103* Airframe INSPECTION #1384	DETAILED INSPECTION OF THE ELEVATOR HINGE BOLTS		L: 4800			L: 4800	L: 798
	Notes (AVG MAN HRS: 36) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 20-00-202 Airframe INSPECTION PKG 48 Month #902	DETAILED INSPECTION OF THE EXTERNAL SURFACES OF THE ELEVATOR	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
55 30-00-101* Airframe INSPECTION #3611	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL STABILIZER PIVOT FITTING LUGS ON THE VERTICAL STABILIZER SIDE		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 19.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 30-00-102* Airframe INSPECTION #409	SPECIAL DETAILED INSPECTION OF THE STRINGER EXTENSION FITTING OF THE VERTICAL STABLOIZER AT VS31.875%		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 30-00-103* Airframe INSPECTION #1482	SPECIAL DETAILED INSPECTION OF THE PIVOT LUGS OF THE PITCH TRIM ACTUATOR ON THE VERTICAL STABILIZER SIDE		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 50) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 30-00-104* Airframe INSPECTION #696	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER FRONT SPAR TO THE FUSELAGE ATTACHMENT FITTINGS		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 311, 312, 325) (ACCESS: 323AT, 324AT, 326AT, EL, ER) (AVG MAN HRS: 29.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 30-00-105* Airframe INSPECTION #2549	DETAILED INSPECTION OF THE VERTICAL STABILIZER STRINGER SPLICE - VS55.625% AT RIB 3 AND VS31.875% AT RIB 2		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 325) (ACCESS: 325AL, AR, BL, BR, HR) (AVG MAN HRS: 4.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 30-00-106* Airframe INSPECTION #1036	DETAILED INSPECTION OF THE SKIN CUTOUT AT THE ACCESS HOLES BETWEEN RIBS 1 AND 3, VS31.875% AND VS43.75% OF THE VERTICAL STABILIZER		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 30-00-107* Airframe INSPECTION #3017	SPECIAL DETAILED INSPECTION OF THE REAR SPAR CAPS OF THE VERTICAL STABILIZER		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 30-00-108* Airframe INSPECTION #1409	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR CAPS AT RIB 1 AND SPLICE STRAPS LH/RH OF THE VERTICAL STABILIZER		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 325) (ACCESS: 324AT) (AVG MAN HRS: 13) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 30-00-109* Airframe INSPECTION #1988	GENERAL VISUAL INSPECTION OF THE REAR-SPAR WEB OF THE VERTICAL STABILIZER- RIB 7		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 2) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 30-00-110* Airframe INSPECTION #1855	SPECIAL DETAILED INSPECTION OF THE MID-SPAR CAPS OF THE VERTICAL STABILIZER		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 30-00-111* Airframe INSPECTION #1358	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER FRONT SPAR TO FRAME ATTACHMENT FITTINGS LOWER LEGS - FS755.00.		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 351, 352) (ACCESS: 311BB) (AVG MAN HRS: 4.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 30-00-113* Airframe INSPECTION #3607	SPECIAL DETAILED INSPECTION OF THE SKIN CUTOUT AT THE ACCESS HOLE BETWEEN RIBS 4 AND 5, VS25.9375% AND VS31.875% OF THE VERTICAL STABILIZER		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 325) (ACCESS: 325AR, BR) (AVG MAN HRS: 5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 30-00-115* Airframe INSPECTION #1445	DETAILED INSPECTION OF THE PITCH TRIM ACTUATOR PIVOT LUGS SUPPORT PLATES ON THE VERTICAL STABILIZER SIDE		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 23) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 30-00-201 Airframe INSPECTION PKG 96 Month #1728	DETAILED INSPECTION OF THE VERTICAL-STABILIZER (FORWARD SIDE OF THE FRONT SPAR, ATTACHMENT FITTINGS AND THE SPLICE STRAP)	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 22.5)						
55 30-00-206 Airframe INSPECTION PKG 96 Month #1257	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE VERTICAL STABILIZER	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 38.5)						
55 40-00-101* Airframe INSPECTION #2582	DETAILED INSPECTION OF THE HINGES AND PCU BOLTS OF THE RUDDER		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 31) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 40-00-102* Airframe INSPECTION #2446	DETAILED INSPECTION OF THE SKINS AND FRONT SPAR OF THE RUDDER. A/C 5301 TO 5526 AND A/C 5534		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 40-00-103* Airframe INSPECTION #2978	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKINS AND FRONT SPAR OF THE RUDDER						
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 4: AMTOSS/NDT NO. WAS NOT AVAILABLE FOR PUBLICATION OF THIS DOCUMENT AND WILL BE PROVIDED IN DUE TIME AT OPPORTUNITY OF REVISION OF THIS DOCUMENT.)						
55 40-00-104* Airframe INSPECTION #1400	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER TO RUDDER HINGE FITTINGS AND PCU ATTACHMENT LUGS		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 29) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
55 40-00-201 Airframe INSPECTION PKG 48 Month #1392	DETAILED INSPECTION OF THE EXTERNAL SURFACES OF THE RUDDER	31-MAY-2025	M: 48 H: 8649.70 L: 3986	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
55 40-00-202 Airframe INSPECTION PKG 96 Month #3415	DETAILED INSPECTION OF THE RUDDER (FORWARD FACE OF THE FRONT SPAR AND HINGE BOLTS) AND THE VERTICAL STABILIZER (AFT FACE OF THE REAR SPAR AND RUDDER HINGE FITTINGS)	02-JUL-2021	M: 96 H: 6939.60 L: 3034	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 22)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 ZL-00-201 Airframe INSPECTION PKG 48 Month #3300	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER ASSEMBLY - EXTERNAL	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
55 ZL-00-202 Airframe INSPECTION PKG 96 Month #1815	GENERAL VISUAL INSPECTION OF THE RAM AIR INTAKE AND DORSAL FAIRING - INTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 10.8)						
55 ZL-00-203 Airframe INSPECTION PKG 96 Month #2454	GENERAL VISUAL INSPECTION OF THE LEADING EDGE OF THE VERTICAL STABILIZER - INTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 22)						
55 ZL-00-204 Airframe INSPECTION PKG 96 Month #3350	GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER - INTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 12)						
55 ZL-00-205 Airframe INSPECTION PKG 96 Month #2123	GENERAL VISUAL INSPECTION OF THE TIP OF THE VERTICAL STABILIZER - INTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 16.5)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 ZL-00-206 Airframe INSPECTION PKG 96 Month #462	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER - EXTERNAL LH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1)						
55 ZL-00-207 Airframe INSPECTION PKG 96 Month #2925	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER - EXTERNAL RH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1)						
55 ZL-00-208 Airframe INSPECTION PKG 96 Month #3433	GENERAL VISUAL INSPECTION OF THE LEADING EDGE OF THE HORIZONTAL STABILIZER - INTERNAL LH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 4.8)						
55 ZL-00-209 Airframe INSPECTION PKG 96 Month #3483	GENERAL VISUAL INSPECTION OF THE LEADING EDGE OF THE HORIZONTAL STABILIZER - INTERNAL RH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3.8)						
55 ZL-00-210 Airframe INSPECTION PKG 96 Month #3560	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER - INTERNAL LH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 7)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
55 ZL-00-211 Airframe INSPECTION PKG 96 Month #2933	GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER - INTERNAL RH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 7)						
56 Airframe PART #1333	CABIN EMERGENCY EXIT WINDOW Part Number 172800-07 Serial Number Unknown					15-OCT-1997	
56 Airframe PART #749	LEFT NO.1 PANE, WINDOW Part Number 172800-05 Serial Number Unknown					15-OCT-1997	
	Notes (ZONE: FS371)						
56 Airframe PART #3382	LEFT NO.2 PANE, WINDOW Part Number 172800-05 Serial Number Unknown					15-OCT-1997	
	Notes (ZONE: FS401)						
56 Airframe PART #1210	LEFT NO.3 PANE, WINDOW Part Number 172800-05 Serial Number Unknown					15-OCT-1997	
	Notes (ZONE: FS431)						
56 Airframe PART #304	LEFT NO.4 PANE, WINDOW Part Number 172800-05 Serial Number Unknown					15-OCT-1997	
	Notes (ZONE: FS461)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 Airframe PART #938	LEFT NO.5 PANE, WINDOW Part Number: 172800-05 Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: FS491)						
56 Airframe PART #2753	LEFT NO.6 PANE, WINDOW Part Number: 172800-05 Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: FS521)						
56 Airframe PART #1282	LEFT NO.7 PANE, WINDOW Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: FS536)						
56 Airframe PART #468	LEFT WINDOW, SIDE Part Number: 600-33030-27 Serial Number: 10207	30-JUN-2022 H: 7604.00 L: 3395					
	Notes (APX COST: 0) (UPDATE NOTE: WORK PERFORMED BY KEYSTONE AVIATION UNDER W/O NC-1221024, SEE MAINTENANCE LOG ENTRY DATED 30-JUN-2022 FOR DETAILS.)						
56 Airframe PART #2907	LEFT WINDSHIELD ASSY Part Number: LA604-33030-025 Serial Number: 10501	08-MAY-2026 H: 8686.90 L: 3999					
56 Airframe PART #2235	RIGHT NO.1 PANE, WINDOW Part Number: 172800-05 Serial Number: Unknown	15-OCT-1997					
	Notes (ZONE: FS340)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 Airframe PART #298	RIGHT NO.2 PANE, WINDOW Part Number 172800-05 Serial Number Unknown Notes (ZONE: FS371)	15-OCT-1997					
56 Airframe PART #472	RIGHT NO.3 PANE, WINDOW Part Number 172800-05 Serial Number Unknown Notes (ZONE: FS401)	15-OCT-1997					
56 Airframe PART #1847	RIGHT NO.4 PANE, WINDOW Part Number 172800-05 Serial Number Unknown Notes (ZONE: FS431)	15-OCT-1997					
56 Airframe PART #1904	RIGHT NO.5 PANE, WINDOW Part Number 172800-05 Serial Number Unknown Notes (ZONE: FS461)	15-OCT-1997					
56 Airframe PART #3355	RIGHT NO.6 PANE, WINDOW Part Number Unknown Serial Number Unknown Notes (ZONE: FS491)	15-OCT-1997					
56 Airframe PART #2032	RIGHT NO.7 PANE, WINDOW Part Number Unknown Serial Number Unknown Notes (ZONE: FS521)	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 Airframe PART #986	RIGHT NO.8 PANE, WINDOW Part Number Unknown Serial Number Unknown	15-OCT-1997					
Notes (ZONE: FS536)							
56 Airframe PART #1812	RIGHT WINDOW, SIDE Part Number 600-33030-28 Serial Number 7988	27-MAY-2005 H: 2522.30 L: 983					
56 Airframe PART #700	RIGHT WINDSHIELD ASSY Part Number 604-33030-26 Serial Number 20990	05-APR-2023 H: 7999.50 L: 3609					
Notes (APX COST: 0) (UPDATE NOTE: REMOVED RIGHT WINDSHIELD ASSY. P/N: 604-33030-26, S/N: 20062. INSTALLED NEW RIGHT WINDSHIELD P/N: 604-33030-26, S/N: 20990. IAW CL604 AMM 56-11-01. COMPLIED WITH LEAK CHECK, NO LEAKS NOTED. IAW CL604 AMM 56-10-00. COMPLIED WITH OPERATIONAL CHECK OF ANTI-ICE SYSTEM, SYSTEM OPS CHECKS GOOD. IAW CL604 AMM 30-41-00. THIS CLEARS AMDL 33420.)							
56 10-00-101* Airframe INSPECTION #897	DETAILED INSPECTION OF THE WINDSHIELD AND SIDE WINDOW - LOWER T-PLATES	11-JUL-2023 H: 8075.40 L: 3647	L: 755			L: 4402	L: 400
Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
56 10-00-102* Airframe INSPECTION #2138	DETAILED INSPECTION OF THE SIDE WINDOW - 4 BUSHING HOLES	21-OCT-2024 H: 8557.60 L: 3931	L: 300			L: 4231	L: 229
Notes (AVG MAN HRS: 3) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
56 10-00-103* Airframe INSPECTION #2313	DETAILED INSPECTION OF THE WINDSHIELD AND SIDE WINDOW - BUSHING HOLES	21-OCT-2024 H: 8557.60 L: 3931	L: 600			L: 4531	L: 529
Notes (AVG MAN HRS: 7) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 10-00-104* Airframe INSPECTION #2145	LEFT SPECIAL DETAILED INSPECTION OF THE BOLTS AT THE WINDSHIELD AND SIDE WINDOW T-PLATES - SIDE WINDOW	30-JUN-2022 H: 7604.00 L: 3395	L: 1200			L: 4595	L: 593
	<p>Notes</p> <p>(AVG MAN HRS: 34) (UPDATE NOTE: WORK PERFORMED BY KEYSTONE AVIATION UNDER W/O NC-1221024, SEE MAINTENANCE LOG ENTRY DATED 30-JUN-2022 FOR DETAILS.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. IT IS ACCEPTABLE TO REPLACE THE BOLTS WITH NEW BOLTS IN LIEU OF THIS INSPECTION)</p>						
56 10-00-104* Airframe INSPECTION #3031	LEFT SPECIAL DETAILED INSPECTION OF THE BOLTS AT THE WINDSHIELD AND SIDE WINDOW T-PLATES - WINDSHIELD	30-JUN-2022 H: 7604.00 L: 3395	L: 1200			L: 4595	L: 593
	<p>Notes</p> <p>(AVG MAN HRS: 34) (UPDATE NOTE: WORK PERFORMED BY KEYSTONE AVIATION SHANE NAIL A&P 3036309 UNDER WO NC-1221024) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. IT IS ACCEPTABLE TO REPLACE THE BOLTS WITH NEW BOLTS IN LIEU OF THIS INSPECTION)</p>						
56 10-00-104* Airframe INSPECTION #52	RIGHT SPECIAL DETAILED INSPECTION OF THE BOLTS AT THE WINDSHIELD AND SIDE WINDOW T-PLATES - SIDE WINDOW	01-NOV-2022 H: 7820.30 L: 3509	L: 1200			L: 4709	L: 707
	<p>Notes</p> <p>(AVG MAN HRS: 34) (UPDATE NOTE: WORK PERFORMED BY KEYSTONE AVIATION SHANE NAIL A&P 3036309 AND JAMIE MAUCH A&P 3113329) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. IT IS ACCEPTABLE TO REPLACE THE BOLTS WITH NEW BOLTS IN LIEU OF THIS INSPECTION)</p>						
56 10-00-104* Airframe INSPECTION #3608	RIGHT SPECIAL DETAILED INSPECTION OF THE BOLTS AT THE WINDSHIELD AND SIDE WINDOW T-PLATES - WINDSHIELD	01-NOV-2022 H: 7820.30 L: 3509	L: 1200			L: 4709	L: 707
	<p>Notes</p> <p>(AVG MAN HRS: 34) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. IT IS ACCEPTABLE TO REPLACE THE BOLTS WITH NEW BOLTS IN LIEU OF THIS INSPECTION)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 10-00-105* Airframe INSPECTION #3329	LEFT SPECIAL DETAILED INSPECTION OF THE ATTACHMENT BOLTS FOR THE WINDSHIELD AND SIDE WINDOW - LEFT SIDE WINDOW	30-JUN-2022 H: 7604.00 L: 3395	L: 4800			L: 8195	L: 4193
	<p>Notes</p> <p>(AVG MAN HRS: 40) (UPDATE NOTE: WORK PERFORMED BY KEYSTONE AVIATION UNDER W/O NC-1221024, SEE MAINTENANCE LOG ENTRY DATED 30-JUN-2022 FOR DETAILS.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. IT IS ACCEPTABLE TO REPLACE THE BOLTS WITH NEW BOLTS IN LIEU OF THIS INSPECTION)</p>						
56 10-00-105* Airframe INSPECTION #521	LEFT SPECIAL DETAILED INSPECTION OF THE ATTACHMENT BOLTS FOR THE WINDSHIELD AND SIDE WINDOW - LEFT WINDSHIELD		L: 4800			L: 4800	L: 798
	<p>Notes</p> <p>(AVG MAN HRS: 40) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. IT IS ACCEPTABLE TO REPLACE THE BOLTS WITH NEW BOLTS IN LIEU OF THIS INSPECTION)</p>						
56 10-00-105* Airframe INSPECTION #1132	RIGHT SPECIAL DETAILED INSPECTION OF THE ATTACHMENT BOLTS FOR THE WINDSHIELD AND SIDE WINDOW - RIGHT SIDE WINDOW		L: 4800			L: 4800	L: 798
	<p>Notes</p> <p>(AVG MAN HRS: 40) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. IT IS ACCEPTABLE TO REPLACE THE BOLTS WITH NEW BOLTS IN LIEU OF THIS INSPECTION)</p>						
56 10-00-105* Airframe INSPECTION #3261	RIGHT SPECIAL DETAILED INSPECTION OF THE ATTACHMENT BOLTS FOR THE WINDSHIELD AND SIDE WINDOW - RIGHT WINDSHIELD	15-OCT-1997	L: 4800			L: 4800	L: 798
	<p>Notes</p> <p>(AVG MAN HRS: 40) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. IT IS ACCEPTABLE TO REPLACE THE BOLTS WITH NEW BOLTS IN LIEU OF THIS INSPECTION)</p>						
56 LAI-ICA-123.1 Airframe INSPECTION #3740	Left Cockpit PMA Windshield Visual Inspection. Reference Lee Aerospace Document Number LAI-ICA-123 Reference Number LAI-ICA-123	08-MAY-2026 H: 8686.90 L: 3999	H: 300.00	H: 40.00		H: 8986.90	H: 291.80



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
56 LAI-ICA-123.2 Airframe INSPECTION #3741	Left Cockpit PMA Windshield DryView Rain Repellant Coating Inspection. Reference Lee Aerospace Document Number LAI-ICA-123 Reference Number LAI-ICA-123	08-MAY-2026 H: 8686.90 L: 3999	M: 12	M: 1		31-MAY-2027	M: 11 D: 30
56 LAI-ICA-123.3 Airframe INSPECTION #3742	Left Cockpit PMA Windshield Heater Functional Test. Reference Lee Aerospace Document Number LAI-ICA-123 Reference Number LAI-ICA-123	08-MAY-2026 H: 8686.90 L: 3999	H: 1200.00	H: 40.00		H: 9886.90	H: 1191.80
57 Airframe PART #798	FLAP CANOE FAIRING Part Number 600-10153-24 Serial Number D648773	30-APR-2014 H: 5145.60 L: 2230					
57 Airframe PART #1393	FLIGHT SPOILER DETENT MICRO SWITCH Part Number MS27216-2 Serial Number N/A	12-DEC-2017 H: 6234.10 L: 2670					
57 Airframe PART #1926	LEFT FITTING ASSEMBLY, MLG SIDE BRACE Part Number Unknown Serial Number Unknown	15-OCT-1997					
57 Airframe PART #1177	LEFT FITTING ASSY (WING) Part Number Unknown Serial Number Unknown	15-OCT-1997					
57 Airframe PART #1971	LEFT FLAP ASSY, INBOARD Part Number 600-14002-1001 Serial Number 9723204	15-OCT-1997					
57 Airframe PART #3564	LEFT GROUND SPOILER ASSY Part Number 600-10502-41 Serial Number 1016149	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 Airframe PART - Life Limited #1805	LEFT SHAFT, MLG SIDE BRACE FITTING Part Number 601R10237-3 Serial Number 0025	23-MAR-2017 H: 5979.10 L: 2576	L: 60000		M: 5 H: 0.00 L: 0	L: 62576	L: 58574
Notes (ZONE: FS515 WL57 LBL13) (AVG MAN HRS: 18) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
57 Airframe PART #596	LEFT SPOILER ASSY Part Number 600-10602-61 Serial Number 1016175					15-OCT-1997	
57 Airframe PART #2813	RIGHT FITTING ASSEMBLY, MLG SIDE BRACE Part Number Unknown Serial Number Unknown					15-OCT-1997	
57 Airframe PART #1966	RIGHT FITTING ASSY (WING) Part Number Unknown Serial Number Unknown					15-OCT-1997	
57 Airframe PART #1455	RIGHT FLAP ASSY, INBOARD Part Number 600-14002-1002 Serial Number 9723169					15-OCT-1997	
57 Airframe PART #2491	RIGHT GROUND SPOILER ASSY Part Number 600-10502-42 Serial Number 1016163					15-OCT-1997	
57 Airframe PART - Life Limited #413	RIGHT SHAFT, MLG SIDE BRACE FITTING Part Number 601R10237-3 Serial Number 0024	23-MAR-2017 H: 5979.10 L: 2576	L: 60000		M: 5 H: 0.00 L: 0	L: 62576	L: 58574
Notes (ZONE: FS515 WL57 RBL13) (AVG MAN HRS: 18) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)							
57 Airframe PART #2604	RIGHT SPOILER ASSY Part Number 600-10602-62 Serial Number 1016187					15-OCT-1997	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-101* Airframe INSPECTION #1388	DETAILED INSPECTION OF THE LOWER WING PLANK - CENTERLINE SPLICE, STRINGERS 15 AND 16		L: 6407			L: 6407	L: 2405
	Notes (AVG MAN HRS: 1) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-102* Airframe INSPECTION #2761	DETAILED INSPECTION OF THE LOWER WING PLANK - CENTERLINE SPLICE, WS242 AND WS264		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-103* Airframe INSPECTION #118	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - SKIN SPLICE STRINGERS 15 AND 16	05-JUL-2024	L: 1966			L: 5828	L: 1826
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-104* Airframe INSPECTION #2033	DETAILED INSPECTION OF THE LOWER WING PLANK - WS45, WS199 AND WS220		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-105* Airframe INSPECTION #1222	DETAILED INSPECTION OF THE LOWER WING PLANK - FRONT SPAR SPLICE WS29.42		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 23) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-106* Airframe INSPECTION #544	DETAILED INSPECTION OF THE LOWER WING PLANK - FRONT SPAR WS45		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 23) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-107* Airframe INSPECTION #1948	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - WS45, STRINGER 10	02-JUL-2021 H: 6939.60 L: 3034	L: 1416			L: 4450	L: 448
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-108* Airframe INSPECTION #1867	DETAILED INSPECTION OF THE LOWER WING PLANK - FUEL DRAIN HOLE WS45, STRINGER 17		L: 4644			L: 4644	L: 642
	Notes (AVG MAN HRS: 1) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-109* Airframe INSPECTION #895	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK AT THE REAR SPAR - WS45 AND WS47		L: 1771			L: 6897	L: 2895
	Notes (AVG MAN HRS: 11) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-110* Airframe INSPECTION #288	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - WS45, STRINGERS 14 AND 15	02-JUL-2021 H: 6939.60 L: 3034	L: 1368			L: 4402	L: 400
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-111* Airframe INSPECTION #1954	DETAILED INSPECTION OF THE LOWER WING PLANK - WS65, WS94, WS106.4 AND WS127.5		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-112* Airframe INSPECTION #325	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - WS65, STRINGER 17	21-OCT-2024 H: 8557.60 L: 3931	L: 1307			L: 5238	L: 1236
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-114* Airframe INSPECTION #228	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK AT THE REAR SPAR - WS59 TO WS65		L: 5297			L: 5297	L: 1295
	Notes (AVG MAN HRS: 2) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-115* Airframe INSPECTION #568	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK NEAR THE MLG TRUNNION - WS65, AND THE AUXILIARY SPAR ACCESS HOLE		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 7) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-117* Airframe INSPECTION #2993	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - WS85.5, STRINGERS 14 TO 17	05-JUL-2024 H: 8455.80 L: 3862	L: 883			L: 4745	L: 743
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-123* Airframe INSPECTION #3575	DETAILED INSPECTION OF THE LOWER WING PLANK AT THE REAR SPAR - WS148.00	21-OCT-2024 H: 8557.60 L: 3931	L: 1372			L: 5303	L: 1301
	Notes (AVG MAN HRS: 3) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-124* Airframe INSPECTION #3145	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - WS148, STRINGERS 8 TO 10 AND STRINGER 15	02-JUL-2021 H: 6939.60 L: 3034	L: 1719			L: 4753	L: 751
	Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK COMPLETED BY DUNCAN AVIATION-LNK UNDER WO#FFMB.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-126* Airframe INSPECTION #918	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - WS148, STRINGER 19		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-127* Airframe INSPECTION #1772	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK AT THE AFT EDGE - WS163 TO WS170.5		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-128* Airframe INSPECTION #1396	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - WS163, STRINGER 15	11-JUL-2023 H: 8075.40 L: 3647	L: 1200			L: 4847	L: 845
	Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-129* Airframe INSPECTION #1937	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK AT THE REAR SPAR - WS178 AND WS189		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-132* Airframe INSPECTION #854	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK AT THE REAR SPAR - WS166		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-133* Airframe INSPECTION #1657	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK AT THE REAR SPAR - WS217 AND WS222		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-134* Airframe INSPECTION #2404	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK AROUND THE ACCESS HOLE - WS220, STRINGER 10	11-JUL-2023	L: 1809			L: 5456	L: 1454
	Notes (AVG MAN HRS: 8.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-135* Airframe INSPECTION #1816	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK AT THE REAR SPAR - WS219		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-137* Airframe INSPECTION #3188	DETAILED INSPECTION OF THE LOWER WING PLANK - WS238 AND WS242		L: 5740			L: 5740	L: 1738
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-141* Airframe INSPECTION #302	DETAILED INSPECTION OF THE LOWER WING PLANK AT THE REAR SPAR - WS242 AND WS260		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-145* Airframe INSPECTION #490	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK AROUND THE ACCESS HOLE - WS112, STRINGER 10		L: 6158			L: 6158	L: 2156
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-146* Airframe INSPECTION #2630	DETAILED INSPECTION OF THE WING-TO-FUSELAGE ATTACHMENT LUGS - FS424 AND FS513		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 16) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 10-00-147* Airframe INSPECTION #181	DETAILED INSPECTION OF THE WING-TO-FUSELAGE ATTACHMENT LUG - FS473, BL45		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-148* Airframe INSPECTION #2223	DETAILED INSPECTION OF THE WING UPPER SURFACE		L: 4800			L: 4800	L: 798
	<p>Notes</p> <p>(AVG MAN HRS: 18) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
57 10-00-149* Airframe INSPECTION #791	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE WING BOX		L: 4800			L: 4800	L: 798
	<p>Notes</p> <p>(AVG MAN HRS: 72) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
57 10-00-152* Airframe INSPECTION #1692	DETAILED INSPECTION OF THE LOWER WING PLANK AT THE BUTT STRAP AT THE FRONT AND REAR SPAR - WS314.5		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 14) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
57 10-00-153* Airframe INSPECTION #520	DETAILED INSPECTION OF THE LOWER WING PLANK - WS88.0	11-JUL-2023	L: 792			L: 4439	L: 437
	<p>Notes</p> <p>(AVG MAN HRS: 4) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
57 10-00-154* Airframe INSPECTION #890	DETAILED INSPECTION OF THE LOWER WING PLANK - WS242.0	21-OCT-2024	L: 952			L: 4883	L: 881
	<p>Notes</p> <p>(AVG MAN HRS: 2) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-201 Airframe INSPECTION PKG 96 Month #2330	DETAILED INSPECTION OF THE EXTERNAL CENTER WING (FRONT SPAR AND THE BAYONET FITTING) - LWS50.00 TO RWS50.00	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 12)						
57 10-00-202 Airframe INSPECTION PKG 48 Month #465	DETAILED INSPECTION OF THE INTERNAL CENTER WING (SPARS, RIB AND WING PLANK SURFACES) - LWS45.00 TO RWS45.00	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 10-00-204 Airframe INSPECTION PKG 96 Month #1094	DETAILED INSPECTION OF THE EXTERNAL CENTER WING (REAR SPAR AND UPPER WING PLANK, MLG SIDE BRACE FITTING AND REAR SPAR BAYONET-FITTING) - LWS48.00 TO RWS48.00	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 29)						
57 10-00-208 Airframe INSPECTION PKG 48 Month #964	DETAILED INSPECTION OF THE FORWARD FACE OF THE FRONT SPAR OF THE WING - WS50 TO WS353	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 24) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 10-00-209 Airframe INSPECTION PKG 48 Month #1866	DETAILED INSPECTION OF THE INTERNAL WING (FRONT SPAR, REAR SPAR, WING PLANKS, STRUCTURE AND THE MLG MOUNTING FITTINGS) - WS45.00 TO CANTED WS314.50	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 63.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-211 Airframe INSPECTION PKG 48 Month #2958	DETAILED INSPECTION OF THE AFT FACE OF THE REAR SPAR OF THE WING - WS48 TO WS353	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 28) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 10-00-213 Airframe INSPECTION PKG 48 Month #1059	DETAILED INSPECTION OF THE INTERNAL SKIN AND THE WING STRUCTURE - CANTED WS314.5 TO WS353	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 15) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 10-00-217 Airframe INSPECTION PKG 48 Month #3246	DETAILED INSPECTION OF THE INTERNAL WING (AUXILIARY SPAR, PLANKS, SKINS,STRUCTURE AND THE MLG TRUNNION FITTING) - WS48.00 TO WS139.90	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 9) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 10-00-224 Airframe INSPECTION PKG 96 Month #3206	DETAILED INSPECTION OF THE WING-TO-FUSELAGE ATTACHMENT FITTINGS AND BOLTS - FS424.00, FS473.15 AND FS513.00	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 24.5)						
57 10-00-227 Airframe INSPECTION PKG 96 Month #3001	DETAILED INSPECTION OF THE ATTACHMENT FITTINGS OF THE FLAP HINGE BOX OF THE INBOARD FLAP - WS76.5 AND WS127.25	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 17.5)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-228 Airframe INSPECTION PKG 96 Month #2089	DETAILED INSPECTION OF THE ATTACHMENT FITTINGS OF THE FLAP HINGE BOX OF THE OUTBOARD FLAP - WS178, WS220 AND WS264	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 12)						
57 10-00-229 Airframe INSPECTION PKG 96 Month #239	DETAILED INSPECTION OF THE AILERON (EXTERNAL SURFACES, WING-TO-AILERON HINGE FITTINGS, HINGE BOLTS AND ANTI-FLOAT TORSION BAR)	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 19.8)						
57 10-00-230 Airframe INSPECTION PKG 96 Month #664	DETAILED INSPECTION OF THE HINGE FITTINGS FOR THE GROUND SPOILER	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1)						
57 10-00-231 Airframe INSPECTION PKG 96 Month #3293	DETAILED INSPECTION OF THE HINGE FITTINGS FOR THE FLIGHT SPOILER	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1)						
57 10-00-401-1 Airframe INSPECTION #142	DETAILED INSPECTION LEFT WING FUEL TANK WATER DRAIN HOLE AT WS 5.00 FWD PER TLMC	11-JUL-2023 H: 8075.40 L: 3647	L: 680			L: 4327	L: 325
	Notes (AVG MAN HRS: 0.25) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
57 10-00-401-2 Airframe INSPECTION #268	DETAILED INSPECTION RIGHT WING FUEL TANK WATER DRAIN HOLE AT WS 5.00 FWD PER TLMC	11-JUL-2023 H: 8075.40 L: 3647	L: 792			L: 4439	L: 437
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 10-00-401-3 Airframe INSPECTION #734	DETAILED INSPECTION LEFT WING FUEL TANK WATER DRAIN HOLE AT WS 48.00 PER TLMC	11-JUL-2023 H: 8075.40 L: 3647	L: 792			L: 4439	L: 437
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
57 30-00-101* Airframe INSPECTION #2688	DETAILED INSPECTION OF THE EXTERNAL SURFACES OF THE WING TIP		L: 4800			L: 4800	L: 798
	Notes (AVG MAN HRS: 12) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 30-00-201 Airframe INSPECTION PKG 96 Month #1264	DETAILED INSPECTION OF THE SKIN, SPARS, ATTACHMENT FITTINGS, AND INTERNAL STRUCTURE OF THE WINGLET	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (ZONE: 561, 562, 661, 662) (ACCESS: 560AB, BB, DB, 660AB, BB, DB) (AVG MAN HRS: 8)						
57 50-00-101* Airframe INSPECTION #3221	SPECIAL DETAILED INSPECTION OF THE OUTBOARD FLAP FRONT SPAR		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 50-00-102* Airframe INSPECTION #2965	SPECIAL DETAILED INSPECTION OF THE VANE TANGS (END SUPPORT) OF THE OUTBOARD FLAP		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 50-00-103* Airframe INSPECTION #1936	SPECIAL DETAILED INSPECTION OF THE FORWARD LUGS OF THE OUTBOARD FLAP		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 50-00-104* Airframe INSPECTION #2502	SPECIAL DETAILED INSPECTION OF THE FORWARD UPPER LUGS OF THE OUTBOARD FLAP ARM - WS220		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 11) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 50-00-105* Airframe INSPECTION #3061	SPECIAL DETAILED INSPECTION OF THE VANE MID-SUPPORT FITTINGS OF THE OUTBOARD FLAP		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 4) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 50-00-106* Airframe INSPECTION #1607	DETAILED INSPECTION OF THE VANE SUPPORT FITTING OF THE OUTBOARD FLAP		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 50-00-107* Airframe INSPECTION #85	SPECIAL DETAILED INSPECTION OF THE FORWARD LUGS OF THE INBOARD FLAP		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 19.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 50-00-108* Airframe INSPECTION #1324	SPECIAL DETAILED INSPECTION OF THE INBOARD FLAP HINGE BOXES		L: 5300			L: 5300	L: 1298
	Notes (AVG MAN HRS: 20) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 50-00-109* Airframe INSPECTION #2997	SPECIAL DETAILED INSPECTION OF THE INBOARD FLAP FRONT SPAR		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 574, 674) (ACCESS: 571AB, 671AB, 571EB,...) (AVG MAN HRS: 27) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE 4: AMTOSS/NDT NO. WAS NOT AVAILABLE FOR PUBLICATION OF THIS DOCUMENT AND WILL BE PROVIDED IN DUE TIME AT OPPORTUNITY OF REVISION OF THIS DOCUMENT.)						
57 50-00-110* Airframe INSPECTION #158	SPECIAL DETAILED INSPECTION OF THE WING/RIB BACKUP FITTING OF THE INBOARD FLAPS - WS127.25		L: 7240			L: 7240	L: 3238
	Notes (AVG MAN HRS: 17) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 50-00-111* Airframe INSPECTION #55	DETAILED INSPECTION OF THE INBOARD FLAP - VANE SUPPORT ATTACHMENT BRACKETS		L: 7200			L: 7200	L: 3198
	Notes (AVG MAN HRS: 11) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. A/C 5301 TO 5499, POST SB A604-27-007 WITH EITHER (1) NO GAPS/CRACKS AT ORIGINAL BRACKET (2) BRACKET REPLACED (WITH OR WITHOUT SHIMS) (SEE NOTE 2) INTERVAL IS T 7800 LANDINGS WITH REPEAT AT 1800 LANDINGS (3) ORIGINAL BRACKET WITH SHIMS ADDED (SEE NOTE 2) INTERVAL IS T 1800 LANDINGS WITH REPEAT AT 1800 LANDINGS A/C 5500 AND SUBS INTERVAL IS T 7800 LANDINGS WITH REPEAT AT 1800 LANDINGS NOTE: 1. INSPECTIONS ARE TO BE DONE AT PAIRS OF BRACKETS AND INTERVALS WILL BE DICTATED BY THE ONE BRACKET WHICH HAS T						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 50-00-112* Airframe INSPECTION #253	SPECIAL DETAILED INSPECTION OF THE CARRIAGES OF THE INBOARD FLAP VANE		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 7.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 50-00-113* Airframe INSPECTION #827	SPECIAL DETAILED INSPECTION OF THE INBOARD FLAP ARMS		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 11) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 50-00-116* Airframe INSPECTION #635	SPECIAL DETAILED INSPECTION OF THE INTERMEDIATE SUPPORT OF THE OUTBOARD FLAP VANE		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 50-00-117* Airframe INSPECTION #2680	SPECIAL DETAILED INSPECTION OF THE SUPPORT STRUTS OF THE OUTBOARD FLAP VANE		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 50-00-118* Airframe INSPECTION #3137	SPECIAL DETAILED INSPECTION OF THE END RAMPS OF THE OUTBOARD FLAP VANE		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 50-00-119* Airframe INSPECTION #1405	SPECIAL DETAILED INSPECTION OF THE FLAP HINGE BOLTS		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 49) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
57 50-00-121* Airframe INSPECTION #1993	SPECIAL DETAILED INSPECTION OF THE FORWARD LUGS OF THE INBOARD FLAP HINGE BOX		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>						
57 50-00-122* Airframe INSPECTION #1499	DISCARD OF THE LEFT INBOARD FLAP FASTENERS - HINGE-BOX WING FORWARD-FITTING		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 6) (SOURCE: 05-10-10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE: FOR AIRCRAFT POST SB A604-57-006 OR SB A605-57-004 (PART B) THAT HAVE REPLACED ALL 16 FASTENERS, THE 7800 L INTERVAL STARTS AT THE INCORPORATION DATE OF THE SERVICE BULLETIN)</p>						
57 50-00-122* Airframe INSPECTION #608	DISCARD OF THE RIGHT INBOARD FLAP FASTENERS - HINGE-BOX WING FORWARD-FITTING		L: 7800			L: 7800	L: 3798
	<p>Notes</p> <p>(AVG MAN HRS: 6) (SOURCE: 05-10-10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY. NOTE: FOR AIRCRAFT POST SB A604-57-006 OR SB A605-57-004 (PART B) THAT HAVE REPLACED ALL 16 FASTENERS, THE 7800 L INTERVAL STARTS AT THE INCORPORATION DATE OF THE SERVICE BULLETIN)</p>						
57 50-00-201 Airframe INSPECTION PKG 48 Month #319	DETAILED INSPECTION OF THE INBOARD FLAP AND INBOARD FLAP VANE (EXTERNAL SURFACES)	31-MAY-2025	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	<p>Notes</p> <p>(AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 50-00-202 Airframe INSPECTION PKG 96 Month #2746	DETAILED INSPECTION OF THE INBOARD FLAP (EXTERNAL SKINS, ATTACHMENT LUGS AND HINGE ARMS)	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 12)						
57 50-00-204 Airframe INSPECTION #2172	DETAILED INSPECTION OF THE VANE ACTUATOR SLIDING BEAMS AND CARRIAGES OF THE INBOARD FLAP		L: 7000	L: 40		L: 7000	L: 2998
	Notes (AVG MAN HRS: 13)						
57 50-00-206 Airframe INSPECTION PKG 48 Month #622	DETAILED INSPECTION OF THE OUTBOARD FLAP (EXTERNAL SURFACES) AND THE OUTBOARD FLAP VANE (EXTERNAL SURFACES AND SUPPORT FITTINGS)	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 50-00-207 Airframe INSPECTION PKG 96 Month #1836	DETAILED INSPECTION OF THE OUTBOARD FLAP (EXTERNAL SKINS, ATTACHMENT LUGS AND HINGE ARMS)	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 14)						
57 50-00-210 Airframe INSPECTION PKG 48 Month #3025	DETAILED INSPECTION OF THE FLAP HINGE BOXES OF THE INBOARD FLAP	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 10.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 50-00-211 Airframe INSPECTION PKG 48 Month #2679	DETAILED INSPECTION OF THE FLAP HINGE BOXES OF THE OUTBOARD FLAP	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 29.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 50-00-212 Airframe INSPECTION #1744	DETAILED INSPECTION OF THE ATTACHMENT BOLTS FOR THE FLAP HINGE BOXES AND THE FLAP HINGE ARMS OF THE INBOARD FLAP		L: 7800	L: 40		L: 7800	L: 3798
	Notes (AVG MAN HRS: 21)						
57 50-00-213 Airframe INSPECTION #3619	DETAILED INSPECTION OF THE ATTACHMENT BOLTS FOR THE FLAP HINGE BOXES AND THE FLAP HINGE ARMS OF THE OUTBOARD FLAP		L: 7800	L: 40		L: 7800	L: 3798
	Notes (AVG MAN HRS: 30)						
57 50-00-214 Airframe INSPECTION #2205	DETAILED INSPECTION OF THE VANE SUPPORT STRAPS OF THE OUTBOARD FLAP		L: 7800	L: 40		L: 7800	L: 3798
	Notes (AVG MAN HRS: 11)						
57 50-00-215 Airframe INSPECTION #114	DETAILED INSPECTION OF THE FRONT SPAR OF THE OUTBOARD FLAP		L: 7800	L: 40		L: 7800	L: 3798
	Notes (AVG MAN HRS: 11)						
57 52-01-101* Airframe INSPECTION #919	SPECIAL DETAILED INSPECTION OF THE OUTBOARD FLAP WING/HINGE-FORWARD BOX FITTINGS		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 32.5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 52-01-102* Airframe INSPECTION #2707	SPECIAL DETAILED INSPECTION OF THE HINGE-BOX FORWARD LUGS OF THE OUTBOARD FLAP		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 30) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 52-01-103* Airframe INSPECTION #3369	SPECIAL DETAILED INSPECTION OF THE HINGE BOX SUPPORTS OF THE OUTBOARD FLAP		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 30) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 60-00-101* Airframe INSPECTION #1053	DETAILED INSPECTION OF THE AILERON	08-FEB-2023	L: 1867			L: 5430	L: 1428
	Notes (AVG MAN HRS: 7) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 60-00-102* Airframe INSPECTION #61	DETAILED INSPECTION OF THE AILERON UPPER AND LOWER SKINS AND FRONT SPAR		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 60-00-103* Airframe INSPECTION #395	DETAILED INSPECTION OF THE HINGE BOLTS OF THE AILERON		L: 4800			L: 4800	L: 798
	Notes (AVG MAN HRS: 15) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 70-00-101* Airframe INSPECTION #900	SPECIAL DETAILED INSPECTION OF THE FLIGHT SPOILER	01-NOV-2022	L: 1200			L: 4709	L: 707
	Notes (AVG MAN HRS: 45) (UPDATE NOTE: WORK PERFORMED BY KEYSTONE AVIATION SHANE NAIL A&P 3036309 AND JAMIE MAUCH A&P 3113329) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 70-00-102* Airframe INSPECTION #2158	DETAILED INSPECTION OF THE UPPER AND LOWER SKINS OF THE FLIGHT SPOILER		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 70-00-103* Airframe INSPECTION #3568	DETAILED INSPECTION OF THE HINGE BOLTS OF THE FLIGHT SPOILER		L: 4800			L: 4800	L: 798
	Notes (AVG MAN HRS: 40) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
57 70-00-201 Airframe INSPECTION PKG 48 Month #2722	DETAILED INSPECTION OF THE EXTERNAL SURFACES AND FORWARD FACE OF THE FRONT SPAR OF THE GROUND SPOILER	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 70-00-202 Airframe INSPECTION PKG 48 Month #3704	SPECIAL DETAILED INSPECTION OF THE BONDED SKINS OF THE GROUND SPOILER	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 70-00-203 Airframe INSPECTION PKG 48 Month #287	DETAILED INSPECTION OF THE EXTERNAL SURFACES AND FORWARD FACE OF THE FRONT SPAR OF THE FLIGHT SPOILER	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 70-00-204 Airframe INSPECTION PKG 48 Month #2109	SPECIAL DETAILED INSPECTION OF THE BONDED SKINS OF THE FLIGHT SPOILER	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 70-00-205 Airframe INSPECTION PKG 96 Month #880	DETAILED INSPECTION OF THE HINGE BOLTS OF THE GROUND SPOILER	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 1)						
57 70-00-206 Airframe INSPECTION PKG 96 Month #960	DETAILED INSPECTION OF THE HINGE BOLTS OF THE FLIGHT SPOILER	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3)						
57 ZL-00-201 Airframe INSPECTION PKG 48 Month #3700	GENERAL VISUAL INSPECTION OF THE WING CENTER SECTION - EXTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 12.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 ZL-00-202 Airframe INSPECTION PKG 48 Month #1233	GENERAL VISUAL INSPECTION OF THE WING CENTER SECTION - EXTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 12.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 ZL-00-203 Airframe INSPECTION PKG 96 Month #1881	GENERAL VISUAL INSPECTION OF THE FRONT SPAR OF THE WING CENTER SECTION - EXTERNAL	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 15)						
57 ZL-00-204 Airframe INSPECTION PKG 96 Month #3362	GENERAL VISUAL INSPECTION OF THE WING CENTER SECTION - INTERNAL LH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2)						
57 ZL-00-205 Airframe INSPECTION PKG 96 Month #323	GENERAL VISUAL INSPECTION OF THE WING CENTER SECTION - INTERNAL RH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2)						
57 ZL-00-206 Airframe INSPECTION PKG 48 Month #273	GENERAL VISUAL INSPECTION OF THE INBOARD LEADING EDGE OF THE WING - EXTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 ZL-00-207 Airframe INSPECTION PKG 48 Month #1894	GENERAL VISUAL INSPECTION OF THE INBOARD LEADING EDGE OF THE WING - EXTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 ZL-00-208 Airframe INSPECTION PKG 96 Month #788	GENERAL VISUAL INSPECTION OF THE INBOARD LEADING EDGE OF THE WING - INTERNAL LH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 12)						
57 ZL-00-209 Airframe INSPECTION PKG 96 Month #2058	GENERAL VISUAL INSPECTION OF THE INBOARD LEADING EDGE OF THE WING - INTERNAL RH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 12)						
57 ZL-00-210 Airframe INSPECTION PKG 48 Month #1045	GENERAL VISUAL INSPECTION OF THE OUTBOARD LEADING EDGE OF THE WING - EXTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 ZL-00-211 Airframe INSPECTION PKG 48 Month #2504	GENERAL VISUAL INSPECTION OF THE OUTBOARD LEADING EDGE OF THE WING - EXTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 ZL-00-212 Airframe INSPECTION PKG 96 Month #41	GENERAL VISUAL INSPECTION OF THE OUTBOARD LEADING EDGE OF THE WING - INTERNAL LH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (ZONE: 520, 530) (ACCESS: 520EL, 530AL, AZ, BL, BZ, CL, CZ, DL, DZ, EZ, FZ,) (AVG MAN HRS: 15.5)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 ZL-00-213 Airframe INSPECTION PKG 96 Month #2618	GENERAL VISUAL INSPECTION OF THE OUTBOARD LEADING EDGE OF THE WING - INTERNAL RH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (ZONE: 620, 630) (ACCESS: 620EL, 630AL, AZ, BL, BZ, CL, CZ, DL, DZ, EZ, FZ,) (AVG MAN HRS: 15.5)						
57 ZL-00-214 Airframe INSPECTION PKG 48 Month #1412	GENERAL VISUAL INSPECTION OF THE WING FROM WS47 TO WS148 - EXTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 6.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 ZL-00-215 Airframe INSPECTION PKG 48 Month #3523	GENERAL VISUAL INSPECTION OF THE WING FROM WS47 TO WS148 - EXTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 6.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
57 ZL-00-216 Airframe INSPECTION PKG 96 Month #1002	GENERAL VISUAL INSPECTION OF THE WING FROM WS45 TO WS148 - INTERNAL LH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 13.5)						
57 ZL-00-217 Airframe INSPECTION PKG 96 Month #554	GENERAL VISUAL INSPECTION OF THE WING FROM WS45 TO WS148 - INTERNAL RH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 13.5)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 ZL-00-218 Airframe INSPECTION PKG 48 Month #2102	GENERAL VISUAL INSPECTION OF THE WING FROM WS148 TO WS353 - EXTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 8) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
57 ZL-00-219 Airframe INSPECTION PKG 48 Month #3308	GENERAL VISUAL INSPECTION OF THE WING FROM WS148 TO WS353 - EXTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 8) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
57 ZL-00-220 Airframe INSPECTION PKG 96 Month #1532	GENERAL VISUAL INSPECTION OF THE WING FROM WS148 TO WS353 - INTERNAL LH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 22)							
57 ZL-00-221 Airframe INSPECTION PKG 96 Month #765	GENERAL VISUAL INSPECTION OF THE WING FROM WS148 TO WS353 - INTERNAL RH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 22)							
57 ZL-00-222 Airframe INSPECTION PKG 48 Month #683	GENERAL VISUAL INSPECTION OF THE WINGLET - EXTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 ZL-00-223 Airframe INSPECTION PKG 48 Month #2495	GENERAL VISUAL INSPECTION OF THE WINGLET - EXTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
57 ZL-00-226 Airframe INSPECTION PKG 48 Month #183	GENERAL VISUAL INSPECTION OF THE INBOARD TRAILING EDGE OF THE WING - EXTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 10) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
57 ZL-00-227 Airframe INSPECTION PKG 48 Month #1170	GENERAL VISUAL INSPECTION OF THE INBOARD TRAILING EDGE OF THE WING - EXTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 10) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
57 ZL-00-228 Airframe INSPECTION PKG 36 Month #2643	GENERAL VISUAL INSPECTION OF THE WING TRAILING EDGE - INTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
Notes (AVG MAN HRS: 0.5) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
57 ZL-00-229 Airframe INSPECTION PKG 36 Month #275	GENERAL VISUAL INSPECTION OF THE WING TRAILING EDGE - INTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
Notes (AVG MAN HRS: 0.5) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
57 ZL-00-230 Airframe INSPECTION PKG 48 Month #2553	GENERAL VISUAL INSPECTION OF THE OUTBOARD TRAILING EDGE OF THE WING - EXTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
<p>Notes</p> <p>(AVG MAN HRS: 7) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>							
57 ZL-00-231 Airframe INSPECTION PKG 48 Month #1401	GENERAL VISUAL INSPECTION OF THE OUTBOARD TRAILING EDGE OF THE WING - EXTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
<p>Notes</p> <p>(AVG MAN HRS: 7) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)</p>							
57 ZL-00-234 Airframe INSPECTION PKG 96 Month #1700	GENERAL VISUAL INSPECTION OF THE AILERON SHROUD - INTERNAL LH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
<p>Notes</p> <p>(AVG MAN HRS: 3)</p>							
57 ZL-00-235 Airframe INSPECTION PKG 96 Month #2563	GENERAL VISUAL INSPECTION OF THE AILERON SHROUD - INTERNAL RH	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
<p>Notes</p> <p>(AVG MAN HRS: 3)</p>							
71 Airframe PART #1606	CORE PANEL RH COWL	Part Number 228-50082-156	Serial Number C0223	15-OCT-1997			
71 Airframe PART #1492	CORE PANEL RH COWL	Part Number 228-50082-155	Serial Number C0223	15-OCT-1997			
71 Airframe PART #2237	LEFT COWL INSTL, INLET (I/R FLEX SHAFT)	Part Number 228-50020-113	Serial Number Unknown	15-OCT-1997			



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 Airframe PART #2694	LEFT DOOR INSTL, LOWER, TRANSLATING COWL Part Number: 228-50208-237 Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #1354	LEFT DOOR INSTL, UPPER, TRANSLATING COWL Part Number: 228-50207-259 Serial Number: C0224	15-OCT-1997					
71 Airframe PART #1345	LEFT ENGINE BIFURCATOR INSTL, FIXED CORE COWL Part Number: 228-50300-805 Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #3682	LEFT ENGINE BOLT ASSY, FORWARD MOUNT (LOWER) Part Number: 601-37040-17PP Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #3584	LEFT ENGINE BOLT ASSY, FORWARD MOUNT (UPPER) Part Number: 601-37040-17PP Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #1458	LEFT ENGINE FITTING ASSY, THRUST Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #88	LEFT ENGINE LINK ASSY Part Number: 601-37016-5 Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #623	LEFT ENGINE SHAFT, THRUST Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #2375	LEFT FITTING ASSY, FWD ENGINE MOUNT YOKE Part Number: 601-37015-7PE Serial Number: Unknown	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 Airframe PART #2372	LEFT PANEL, ACCESS, NOSE COWL, LOWER Part Number: 228-50081-141 Serial Number: C0224	15-OCT-1997					
71 Airframe PART #953	LEFT PANEL, ACCESS, NOSE COWL, UPPER Part Number: 228-50080-801 Serial Number: C0223	15-OCT-1997					
71 Airframe PART #2663	LEFT PANEL, SIDE, NOSE COWL FIXED, INSTL Part Number: 228-50082-809 Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #2477	LEFT POWERPLANT, DEMOUNTABLE Part Number: 604-60001-1 Serial Number: 5352	15-OCT-1997					
71 Airframe PART #1156	LOWER DOOR ASSY, LOWER (LEFT) Part Number: 228-50162-417 Serial Number: C0234	15-OCT-1997					
71 Airframe PART #1118	LOWER DOOR INSTL, CORE COWL, UPPER (LEFT) Part Number: 228-50142-601 Serial Number: C0233	15-OCT-1997					
71 Airframe PART #590	RIGHT COWL INSTL, INLET (I/R FLEX SHAFT) Part Number: 228-50020-113 Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #259	RIGHT DOOR INSTL, LOWER, TRANSLATING COWL Part Number: 228-50208-238 Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #1803	RIGHT DOOR INSTL, UPPER, TRANSLATING COWL Part Number: 228-50207-260 Serial Number: C0225	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 Airframe PART #2082	RIGHT ENGINE BIFURCATOR INSTL, FIXED CORE COWL Part Number: 228-50300-806 Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #2774	RIGHT ENGINE BOLT ASSY, FORWARD MOUNT (LOWER) Part Number: 601-37040-17PP Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #122	RIGHT ENGINE BOLT ASSY, FORWARD MOUNT (UPPER) Part Number: 601-37040-17PP Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #1552	RIGHT ENGINE FITTING ASSY, THRUST Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #574	RIGHT ENGINE LINK ASSY Part Number: 601-37016-5 Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #2911	RIGHT ENGINE SHAFT, THRUST Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #1973	RIGHT FITTING ASSY, FWD ENGINE MOUNT YOKE Part Number: 601-37015-8PE Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #1608	RIGHT PANEL, ACCESS, NOSE COWL, LOWER Part Number: 228-50081-142 Serial Number: C0221	15-OCT-1997					
71 Airframe PART #2579	RIGHT PANEL, ACCESS, NOSE COWL, UPPER Part Number: 228-50080-802 Serial Number: C0225	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 Airframe PART #1676	RIGHT PANEL, SIDE, NOSE COWL FIXED, INSTL Part Number: 228-50082-810 Serial Number: Unknown	15-OCT-1997					
71 Airframe PART #2651	RIGHT POWERPLANT, DEMOUNTABLE Part Number: 604-60001-2 Serial Number: 5352	15-OCT-1997					
71 Airframe PART #2624	UPPER DOOR ASSY, LOWER (RIGHT) Part Number: 228-50162-418 Serial Number: C0224	15-OCT-1997					
71 Airframe PART #366	UPPER DOOR INSTL, CORE COWL, UPPER (RIGHT) Part Number: 228-50142-602 Serial Number: C0231	15-OCT-1997					
71 10-00-101* Airframe INSPECTION #543	SPECIAL DETAILED INSPECTION OF THE ENGINE NACELLE JOINT Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)		L: 7800			L: 7800	L: 3798
71 10-00-102* Airframe INSPECTION #177	SPECIAL DETAILED INSPECTION OF THE SUPPORT FITTING OF THE NOSE COWL ACTUATOR Notes (AVG MAN HRS: 10) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)		L: 4400			L: 4400	L: 398
71 10-00-103* Airframe INSPECTION #726	SPECIAL DETAILED INSPECTION OF THE TRACK SUPPORT ASSEMBLY AND FLANGE OF THE SERVICE PYLON Notes (AVG MAN HRS: 9) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)		L: 7800			L: 7800	L: 3798



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 12-00-202 Airframe INSPECTION PKG2400Hour #2934	DETAILED INSPECTION OF THE CORE BLOW-OUT DOORS.	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 4.5)						
71 12-00-203 Airframe INSPECTION PKG 600 Hour #2295	GENERAL VISUAL INSPECTION OF THE DRAINS MAST AND CHANNELS	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 1.5) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
71 12-00-204 Airframe INSPECTION PKG 600 Hour #300	OPERATIONAL TEST OF THE DRAINS MAST AND CHANNELS	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 1.5) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
71 12-00-205 Airframe INSPECTION PKG 96 Month #1050	DETAILED INSPECTION OF THE HINGE FITTINGS OF THE CORE COWL DOOR	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 4.5)						
71 13-00-201 Airframe INSPECTION PKG2400Hour #2760	DETAILED INSPECTION OF THE THRUST REVERSER SLIDER BLOCKS	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 49.5)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 13-00-202 Airframe INSPECTION PKG 96 Month #2039	DETAILED INSPECTION OF THE SERVICE PYLON CASTING AND SUPPORT RAILS	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 9)						
71 20-00-101* Airframe INSPECTION #3446	SPECIAL DETAILED INSPECTION OF THE YOKE OF THE FORWARD ENGINE MOUNT		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
71 20-00-102* Airframe INSPECTION #1266	SPECIAL DETAILED INSPECTION OF THE THRUST FITTING OF THE AFT ENGINE MOUNT		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 6) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
71 20-00-103* Airframe INSPECTION #2333	SPECIAL DETAILED INSPECTION OF THE LINK AND BOLTS OF THE FORWARD ENGINE MOUNT		L: 7800			L: 7800	L: 3798
	Notes (ZONE: 432, 442) (ACCESS: 412AT, 422CT) (AVG MAN HRS: 5) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
71 20-00-202 Airframe INSPECTION PKG 96 Month #2003	DETAILED INSPECTION OF THE FORWARD ENGINE MOUNT YOKE AND LINK ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 4)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 20-00-203 Airframe INSPECTION PKG 96 Month #2276	DETAILED INSPECTION OF THE AFT ENGINE MOUNT ASSEMBLY	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 4)						
71 21-01-220-801 Airframe INSPECTION #1105	DETAILED INSPECTION OF THE FORWARD ENGINE MOUNTS						
71 21-01-220-801 Airframe INSPECTION #460	DETAILED INSPECTION OF THE FORWARD ENGINE MOUNTS						
71 22-01-220-802 Airframe INSPECTION #115	DETAILED INSPECTION OF THE AFT ENGINE MOUNTS						
71 22-01-220-802 Airframe INSPECTION #3136	DETAILED INSPECTION OF THE AFT ENGINE MOUNTS						
71 30-00-201 Airframe INSPECTION PKG3200Hour #1069	GENERAL VISUAL INSPECTION OF THE ENGINE FIRE SEALS	16-JUN-2018 H: 6372.80 L: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 9.5)						
71 61-00-202 Airframe INSPECTION PKG 800 Hour #2146	LUBRICATION OF THE BALLSCREW-ACTUATORS SUPPORT-BUSHINGS	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
	Notes (AVG MAN HRS: 3.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 61-00-203 Airframe INSPECTION PKG3200Hour #3538	DETAILED INSPECTION OF THE BALLSCREW ACTUATOR SUPPORT FITTINGS	16-JUN-2018 H: 6372.80 L: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 5.5)						
71 61-00-205 Airframe INSPECTION #143	DETAILED INSPECTION OF THE ATTACHMENT RING OF THE NOSE INLET COWL		L: 7800	L: 40		L: 7800	L: 3798
	Notes (AVG MAN HRS: 7)						
71 ZL-00-201 Airframe INSPECTION PKG 48 Month #1861	GENERAL VISUAL INSPECTION OF THE NACELLE - EXTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
71 ZL-00-202 Airframe INSPECTION PKG 48 Month #1865	GENERAL VISUAL INSPECTION OF THE NACELLE - EXTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
71 ZL-00-203 Airframe INSPECTION PKG 36 Month #877	GENERAL VISUAL INSPECTION OF THE NOSE INLET ACCESS-COWL - INSIDE LH	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
	Notes (ZONE: 432) (ACCESS: 432AB, AT) (AVG MAN HRS: 5) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
71 ZL-00-204 Airframe INSPECTION PKG 36 Month #2895	GENERAL VISUAL INSPECTION OF THE NOSE INLET ACCESS-COWL - INSIDE RH	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
	Notes (ZONE: 442) (ACCESS: 442AB, AT) (AVG MAN HRS: 5) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
71 ZL-00-205 Airframe INSPECTION PKG 48 Month #1547	GENERAL VISUAL INSPECTION OF THE TRANSLATING COWL - INTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
71 ZL-00-206 Airframe INSPECTION PKG 48 Month #1415	GENERAL VISUAL INSPECTION OF THE TRANSLATING COWL - INTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
71 ZL-00-207 Airframe INSPECTION PKG 36 Month #2398	GENERAL VISUAL INSPECTION OF THE CORE COWL - INTERNAL LH	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
Notes (AVG MAN HRS: 7) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
71 ZL-00-208 Airframe INSPECTION PKG 36 Month #1527	GENERAL VISUAL INSPECTION OF THE CORE COWL - INTERNAL RH	31-MAY-2025 H: 8649.70 L: 3986	M: 36	M: 1		24-APR-2028	M: 22 D: 23
Notes (AVG MAN HRS: 7) (TOL. ADJUSTMENT: -36D) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)							
72 Engine 1 PART #404	ACCESSORY GEARBOX					15-OCT-1997	
	Part Number	Serial Number					
	6014T81G28	SAPG2993					
72 Engine 2 PART #552	ACCESSORY GEARBOX					15-OCT-1997	
	Part Number	Serial Number					
	6014T81G28	SAPG2308					
72 Engine 1 PART #744	ACCESSORY GEARBOX ASSEMBLY MODULE					15-OCT-1997	
	Part Number	Serial Number					
	Unknown	Unknown					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 2 PART #368	ACCESSORY GEARBOX ASSEMBLY MODULE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #398	AFT FAN CASE ASSEMBLY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #942	AFT FAN CASE ASSEMBLY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #70	AGB CARBON SEAL Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #715	AGB CARBON SEAL Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #677	BALANCE PISTON STATIONARY AIR SEAL Part Number: 6037T99G07 Serial Number: TWGG1704	13-OCT-2009 H: 3725.60 C: 1574					
72 Engine 2 PART #446	BALANCE PISTON STATIONARY AIR SEAL Part Number: 6037T99G07 Serial Number: TWGG22Y3	13-OCT-2009 H: 3725.60 C: 1574					
72 Engine 1 PART - Life Limited #134	BLISK, STAGE 1 COMPRESSOR ROTOR Part Number: 5087T84P01 Serial Number: GLHK5EL6	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
72 Engine 2 PART - Life Limited #478	BLISK, STAGE 1 COMPRESSOR ROTOR Part Number: 5087T84P01 Serial Number: GLHK5EL5	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART #197	COMBUSTER/HIGH PRESSURE TURBINE ASSEMBLY MODULE Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #365	COMBUSTER/HIGH PRESSURE TURBINE ASSEMBLY MODULE Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #358	COMBUSTION FRAME Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #626	COMBUSTION FRAME Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #600	COMBUSTION INNER SHELL LINER Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #952	COMBUSTION INNER SHELL LINER Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #553	COMBUSTION LINER Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #904	COMBUSTION LINER Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #777	COMBUSTION LINER DOME Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 2 PART #422	COMBUSTION LINER DOME Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #221	COMBUSTION OUTER SHELL LINER Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #497	COMBUSTION OUTER SHELL LINER Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #803	COMPRESSOR ASSEMBLY MODULE Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #223	COMPRESSOR ASSEMBLY MODULE Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #233	COMPRESSOR CASE ASSEMBLY Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #267	COMPRESSOR CASE ASSEMBLY Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #96	COMPRESSOR ROTOR Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #661	COMPRESSOR ROTOR Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART - Life Limited #575	CONE, TURBINE DRIVE Part Number: 5023T40P03 Serial Number: BCM50397	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 2 PART - Life Limited #873	CONE, TURBINE DRIVE Part Number: 5023T40P03 Serial Number: BCM50217	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 1 PART #670	CONTAINMENT CASE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #395	CONTAINMENT CASE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART - Life Limited #254	COUPLING, OUTER TORQUE Part Number: 5079T64P05 Serial Number: GATCTYFP	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
72 Engine 2 PART - Life Limited #533	COUPLING, OUTER TORQUE Part Number: 5079T64P05 Serial Number: GATCTYJV	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
72 Engine 1 PART - Life Limited #516	DISK, FAN Part Number: 6078T57G05 Serial Number: GEE13968	15-OCT-1997	C: 30000		H: 0.00 C: 0	C: 30000.00	C: 25997
72 Engine 2 PART - Life Limited #88	DISK, FAN Part Number: 6078T57G05 Serial Number: GEE13966	15-OCT-1997	C: 30000		H: 0.00 C: 0	C: 30000.00	C: 25997



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART - Life Limited #821	DISK, STAGE 1 TURBINE Part Number 5079T52P09 Serial Number GATCTNKD	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
Notes (NOTE: FOR CF34-3A1 ENGINES MODIFIED TO SB 72-0050)							
72 Engine 2 PART - Life Limited #742	DISK, STAGE 1 TURBINE Part Number 5079T52P09 Serial Number GATCTWV1	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
Notes (NOTE: FOR CF34-3A1 ENGINES MODIFIED TO SB 72-0050)							
72 Engine 1 PART - Life Limited #415	DISK, STAGE 2 COMPRESSOR ROTOR Part Number 6036T91P02 Serial Number GATCTJE3	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 2 PART - Life Limited #305	DISK, STAGE 2 COMPRESSOR ROTOR Part Number 6036T91P02 Serial Number GATCTN9D	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 1 PART - Life Limited #641	DISK, STAGE 2 TURBINE Part Number 5079T73P02 Serial Number GATCTVTA	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
Notes (NOTE: FOR CF34-3A1 ENGINES MODIFIED TO SB 72-0050)							
72 Engine 2 PART - Life Limited #499	DISK, STAGE 2 TURBINE Part Number 5079T73P02 Serial Number GATCV0HY	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
Notes (NOTE: FOR CF34-3A1 ENGINES MODIFIED TO SB 72-0050)							
72 Engine 1 PART - Life Limited #883	DISK, STAGE 3 TURBINE Part Number 6078T91P01 Serial Number GATCTN15	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 2 PART - Life Limited #314	DISK, STAGE 3 TURBINE Part Number 6078T91P01 Serial Number GATCT1RV	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 1 PART - Life Limited #353	DISK, STAGE 4 TURBINE Part Number 6078T02P03 Serial Number GATCTYM D	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
	Notes (NOTE: STAGE 4 TURBINE DISKS PN 6078T02P03 WITH THE PART SERIAL NUMBERS REFERENCED IN SB 72-0098 (LATEST REVISION), WERE SUBJECTED TO AN INTERNAL REPAIR OF THE BOLT FLANGES (SCALLOPED). THESE DISKS MUST BE REMOVED AND SCRAPPED AT THE NEXT EXPOSURE, BUT NOT LATER THAN 17,000-CYCLES)						
72 Engine 2 PART - Life Limited #688	DISK, STAGE 4 TURBINE Part Number 6078T02P03 Serial Number GATCV0M3	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
	Notes (NOTE: STAGE 4 TURBINE DISKS PN 6078T02P03 WITH THE PART SERIAL NUMBERS REFERENCED IN SB 72-0098 (LATEST REVISION), WERE SUBJECTED TO AN INTERNAL REPAIR OF THE BOLT FLANGES (SCALLOPED). THESE DISKS MUST BE REMOVED AND SCRAPPED AT THE NEXT EXPOSURE, BUT NOT LATER THAN 17,000-CYCLES)						
72 Engine 1 PART - Life Limited #266	DISK, STAGE 5 TURBINE Part Number 6078T92P01 Serial Number GATCTNRV	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
	Notes (NOTE: STAGE 5 TURBINE DISKS PN 6078T92P01, WITH THE PART SERIAL NUMBERS REFERENCED IN SB 72-0098 (LATEST REVISION), WERE SUBJECTED TO AN INTERNAL REPAIR OF THE BOLT FLANGES (SCALLOPED). THESE DISKS MUST BE REMOVED AND SCRAPPED AT THE NEXT EXPOSURE, BUT NOT LATER THAN 15,000-CYCLES)						
72 Engine 2 PART - Life Limited #195	DISK, STAGE 5 TURBINE Part Number 6078T92P01 Serial Number GATCTPJR	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
	Notes (NOTE: STAGE 5 TURBINE DISKS PN 6078T92P01, WITH THE PART SERIAL NUMBERS REFERENCED IN SB 72-0098 (LATEST REVISION), WERE SUBJECTED TO AN INTERNAL REPAIR OF THE BOLT FLANGES (SCALLOPED). THESE DISKS MUST BE REMOVED AND SCRAPPED AT THE NEXT EXPOSURE, BUT NOT LATER THAN 15,000-CYCLES)						
72 Engine 1 PART - Life Limited #281	DISK, STAGE 6 TURBINE Part Number 6078T89P01 Serial Number GATCJU28	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
	Notes (NOTE: STAGE 6 TURBINE DISKS PN 6078T89P01, WITH THE PART SERIAL NUMBERS REFERENCED IN SB 72-0098 (LATEST REVISION), WERE SUBJECTED TO AN INTERNAL REPAIR OF THE BOLT FLANGES (SCALLOPED). THESE DISKS MUST BE REMOVED AND SCRAPPED AT THE NEXT EXPOSURE, BUT NOT LATER THAN 15,000-CYCLES)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 2 PART - Life Limited #759	DISK, STAGE 6 TURBINE Part Number: 6078T89P01 Serial Number: GATCTY01	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
Notes (NOTE: STAGE 6 TURBINE DISKS PN 6078T89P01, WITH THE PART SERIAL NUMBERS REFERENCED IN SB 72-0098 (LATEST REVISION), WERE SUBJECTED TO AN INTERNAL REPAIR OF THE BOLT FLANGES (SCALLOPED). THESE DISKS MUST BE REMOVED AND SCRAPPED AT THE NEXT EXPOSURE, BUT NOT LATER THAN 15,000-CYCLES)							
72 Engine 1 PART - Life Limited #452	DISK, STAGE 9 COMPRESSOR ROTOR Part Number: 6087T01P03 Serial Number: GATCAM35	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 2 PART - Life Limited #388	DISK, STAGE 9 COMPRESSOR ROTOR Part Number: 6087T01P03 Serial Number: GATCTLWR	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 1 PART #544	FAN ASSEMBLY MODULE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #383	FAN ASSEMBLY MODULE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #783	FAN SPEED SENSOR Part Number: 4021T56P03 Serial Number: GDBB309A	15-OCT-1997					
72 Engine 2 PART #277	FAN SPEED SENSOR Part Number: 4021T56P03 Serial Number: GDBB784A	15-OCT-1997					
72 Engine 1 PART #628	FRONT COMPRESSOR FRAME Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 2 PART #253	FRONT COMPRESSOR FRAME Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #175	FWD FAN CASE ASSEMBLY Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #291	FWD FAN CASE ASSEMBLY Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #71	HIGH PRESSURE TURBINE (HPT) OUTER CASING Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #232	HIGH PRESSURE TURBINE (HPT) OUTER CASING Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #27	HIGH PRESSURE TURBINE (HPT) STATOR ASSEMBLY Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #78	HIGH PRESSURE TURBINE (HPT) STATOR ASSEMBLY Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #196	HIGH PRESSURE TURBINE (HPT) INNER CASING Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #306	HIGH PRESSURE TURBINE (HPT) INNER CASING Part Number 5099T00G05 Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART #895	HIGH PRESSURE TURBINE (HPT) ROTOR ASSEMBLY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #465	HIGH PRESSURE TURBINE (HPT) ROTOR ASSEMBLY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #629	HPT ROTATING AIR SEAL Part Number: 4019T60G03 Serial Number: B1WYB8TV	07-OCT-2009 H: 3725.60 C: 1574					
72 Engine 2 PART #280	HPT ROTATING AIR SEAL Part Number: 4019T60G03 Serial Number: B1WYB8U5	07-OCT-2009 H: 3725.60 C: 1574					
72 Engine 1 PART #238	LEFT THERMOCOUPLE ASSEMBLY Part Number: 6030T41P01 Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #44	LEFT THERMOCOUPLE ASSEMBLY Part Number: 6030T41P01 Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #318	LOW PRESSURE TURBINE (LPT) CASING Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #907	LOW PRESSURE TURBINE (LPT) CASING Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #630	LOW PRESSURE TURBINE (LPT) ROTOR ASSEMBLY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 2 PART #818	LOW PRESSURE TURBINE (LPT) ROTOR ASSEMBLY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #219	LOW PRESSURE TURBINE (LPT) STATOR ASSEMBLY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #787	LOW PRESSURE TURBINE (LPT) STATOR ASSEMBLY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #118	LOW PRESSURE TURBINE (LPT) TRANSITION ASSEMBLY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #204	LOW PRESSURE TURBINE (LPT) TRANSITION ASSEMBLY Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #116	LOW PRESSURE TURBINE (LPT) TRANSITION CASE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #370	LOW PRESSURE TURBINE (LPT) TRANSITION CASE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #766	MODULE ASSEMBLY, LOW PRESSURE TURBINE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #796	MODULE ASSEMBLY, LOW PRESSURE TURBINE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART #208	NO.1 BALL BEARING Part Number Unknown	Serial Number Unknown	15-OCT-1997				
72 Engine 2 PART #558	NO.1 BALL BEARING Part Number Unknown	Serial Number Unknown	15-OCT-1997				
72 Engine 1 PART #6	NO.1 BALL DUPLEX BEARING Part Number Unknown	Serial Number Unknown	15-OCT-1997				
72 Engine 2 PART #802	NO.1 BALL DUPLEX BEARING Part Number Unknown	Serial Number Unknown	15-OCT-1997				
72 Engine 1 PART #573	NO.1 FAN BLADE Part Number 6018T30P14	Serial Number Unknown	15-OCT-1997				
72 Engine 2 PART #59	NO.1 FAN BLADE Part Number 6018T30P14	Serial Number Unknown	15-OCT-1997				
72 Engine 1 PART #716	NO.1 NOZZLE STAGE Part Number Unknown	Serial Number Unknown	15-OCT-1997				
72 Engine 2 PART #753	NO.1 NOZZLE STAGE Part Number Unknown	Serial Number Unknown	15-OCT-1997				
72 Engine 1 PART #37	NO.10 FAN BLADE Part Number 6018T30P14	Serial Number Unknown	15-OCT-1997				



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 2 PART #443	NO.10 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #235	NO.11 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #856	NO.11 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #547	NO.12 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #712	NO.12 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #568	NO.13 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #631	NO.13 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #40	NO.14 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #126	NO.14 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART #41	NO.15 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #732	NO.15 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #2	NO.16 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #912	NO.16 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #287	NO.17 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #41	NO.17 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #649	NO.18 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #672	NO.18 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #555	NO.19 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 2 PART #411	NO.19 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #151	NO.2 BALL BEARING Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #653	NO.2 BALL BEARING Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #475	NO.2 BALL DUPLEX BEARING Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #502	NO.2 BALL DUPLEX BEARING Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #109	NO.2 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #22	NO.2 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #350	NO.20 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #24	NO.20 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART #203	NO.21 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #922	NO.21 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #314	NO.22 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #369	NO.22 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #190	NO.23 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #23	NO.23 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #262	NO.24 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #906	NO.24 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #874	NO.25 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 2 PART #362	NO.25 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #354	NO.26 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #459	NO.26 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #263	NO.27 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #295	NO.27 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #463	NO.28 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #831	NO.28 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #611	NO.3 BALL BEARING Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #482	NO.3 BALL BEARING Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART #82	NO.3 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #839	NO.3 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #351	NO.4 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #427	NO.4 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #53	NO.4 ROLLER BEARING Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #545	NO.4 ROLLER BEARING Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #427	NO.5 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #522	NO.5 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #439	NO.5 ROLLER BEARING Part Number 5042T13P04 Serial Number FCAS9374	12-OCT-2009 H: 3725.60 C: 1574					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 2 PART #571	NO.5 ROLLER BEARING Part Number: 5042T13P04 Serial Number: FCAS5709	12-OCT-2009					
72 Engine 1 PART #746	NO.6 FAN BLADE Part Number: 6018T30P14 Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #38	NO.6 FAN BLADE Part Number: 6018T30P14 Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #449	NO.6 ROLLER BEARING Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #192	NO.6 ROLLER BEARING Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #80	NO.7 FAN BLADE Part Number: 6018T30P14 Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #94	NO.7 FAN BLADE Part Number: 6018T30P14 Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #382	NO.7 ROLLER BEARING Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #158	NO.7 ROLLER BEARING Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART #659	NO.8 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #101	NO.8 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #734	NO.9 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #392	NO.9 FAN BLADE Part Number 6018T30P14 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART - Life Limited #331	PLATE, STAGE 1 AFT COOLING Part Number 5123T02P01 Serial Number NCE6425F Notes (NOTE: FOR CF34-3A1 ENGINES MODIFIED TO SB 72-0050)	15-OCT-1997	C: 14000		H: 0.00 C: 0	C: 14000.00	C: 9997
72 Engine 2 PART - Life Limited #53	PLATE, STAGE 1 AFT COOLING Part Number 5123T02P01 Serial Number NCE6295F Notes (NOTE: FOR CF34-3A1 ENGINES MODIFIED TO SB 72-0050)	15-OCT-1997	C: 14000		H: 0.00 C: 0	C: 14000.00	C: 9997
72 Engine 1 PART - Life Limited #711	PLATE, STAGE 1 FRONT COOLING Part Number 5079T65P06 Serial Number NCE6348F	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
72 Engine 2 PART - Life Limited #174	PLATE, STAGE 1 FRONT COOLING Part Number 5079T65P06 Serial Number NCE6840F	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART - Life Limited #379	PLATE, STAGE 2 FRONT COOLING Part Number 5079T55P04 Serial Number NCE4207E	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
Notes (NOTE: FOR CF34-3A1 ENGINES MODIFIED TO SB 72-0050)							
72 Engine 2 PART - Life Limited #550	PLATE, STAGE 2 FRONT COOLING Part Number 5079T55P04 Serial Number NCE6295F	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
Notes (NOTE: FOR CF34-3A1 ENGINES MODIFIED TO SB 72-0050)							
72 Engine 1 PART - Life Limited #422	PLATE, STAGE 2 REAR COOLING Part Number 5079T56P02 Serial Number NCE4010F	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
72 Engine 2 PART - Life Limited #476	PLATE, STAGE 2 REAR COOLING Part Number 5079T56P02 Serial Number NCE9350F	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
72 Engine 1 PART #939	POWER TAKEOFF DRIVE ASSEMBLY Part Number 6037T72G18 Serial Number SAPG3349	15-OCT-1997					
72 Engine 2 PART #706	POWER TAKEOFF DRIVE ASSEMBLY Part Number 6037T72G18 Serial Number SAPG3360	15-OCT-1997					
72 Engine 1 PART #448	RIGHT THERMOCOUPLE ASSEMBLY Part Number 6030T40P01 Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #457	RIGHT THERMOCOUPLE ASSEMBLY Part Number 6030T40P01 Serial Number Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART #730	ROTOR FAN Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #709	ROTOR FAN Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART #212	RUNNER SEAL Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #925	RUNNER SEAL Part Number 4019T60G03 Serial Number Unknown	15-OCT-1997					
72 Engine 1 PART - Life Limited #485	SEAL, BALANCE PISTON AIR Part Number 5079T63P02 Serial Number GATCTVVD Notes (NOTE: FOR CF34-3A1 ENGINES MODIFIED TO SB 72-0050)	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 2 PART - Life Limited #775	SEAL, BALANCE PISTON AIR Part Number 5079T63P02 Serial Number GATCTV8 Notes (NOTE: FOR CF34-3A1 ENGINES MODIFIED TO SB 72-0050)	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 1 PART - Life Limited #106	SEAL, COMPRESSOR DISCHARGE ROTATING Part Number 4019T38P01 Serial Number PAMV3176	15-OCT-1997	C: 30000		H: 0.00 C: 0	C: 30000.00	C: 25997
72 Engine 2 PART - Life Limited #509	SEAL, COMPRESSOR DISCHARGE ROTATING Part Number 4019T38P01 Serial Number PAMV5930	15-OCT-1997	C: 30000		H: 0.00 C: 0	C: 30000.00	C: 25997



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART - Life Limited #154	SEAL, STAGE 3 AND 4 TURBINE Part Number 5023T59P02 Serial Number PAMV2947	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 2 PART - Life Limited #924	SEAL, STAGE 3 AND 4 TURBINE Part Number 5023T59P02 Serial Number PAMV2967	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 1 PART - Life Limited #108	SEAL, STAGE 4 AND 5 TURBINE Part Number 5023T67P01 Serial Number PAMV6647	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 2 PART - Life Limited #668	SEAL, STAGE 4 AND 5 TURBINE Part Number 5023T67P01 Serial Number PAMV6634	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 1 PART - Life Limited #168	SEAL, STAGE 5 AND 6 TURBINE Part Number 5023T64P02 Serial Number PAMV6597	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 2 PART - Life Limited #463	SEAL, STAGE 5 AND 6 TURBINE Part Number 5023T64P02 Serial Number PAMV9107	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 1 PART - Life Limited #674	SHAFT, COMPRESSOR FORWARD Part Number 5037T01P04 Serial Number GATCTDH2	15-OCT-1997	C: 30000		H: 0.00 C: 0	C: 30000.00	C: 25997
72 Engine 2 PART - Life Limited #81	SHAFT, COMPRESSOR FORWARD Part Number 5037T01P04 Serial Number GATCTDH M	15-OCT-1997	C: 30000		H: 0.00 C: 0	C: 30000.00	C: 25997
72 Engine 1 PART - Life Limited #702	SHAFT, COMPRESSOR ROTOR REAR Part Number 6087T03P03 Serial Number GEE13744	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 2 PART - Life Limited #921	SHAFT, COMPRESSOR ROTOR REAR Part Number 6087T03P03 Serial Number GEE13736	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 1 PART - Life Limited #213	SHAFT, FAN DRIVE Part Number 6036T78P02 Serial Number BCM51061	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
72 Engine 2 PART - Life Limited #107	SHAFT, FAN DRIVE Part Number 6036T78P02 Serial Number BCM50443	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
72 Engine 1 PART - Life Limited #163	SHAFT, FORWARD FAN Part Number 6078T51P02 Serial Number GATCTW49	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
72 Engine 2 PART - Life Limited #905	SHAFT, FORWARD FAN Part Number 6078T51P02 Serial Number GATCTW F	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
72 Engine 1 PART - Life Limited #431	SHAFT, HPT ROTOR Part Number 5079T62P02 Serial Number GEE13598	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
72 Engine 2 PART - Life Limited #403	SHAFT, HPT ROTOR Part Number 5079T62P02 Serial Number GEE13568	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
72 Engine 1 PART - Life Limited #157	SHAFT, TURBINE REAR Part Number 6030T72P02 Serial Number PAMV5636	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 2 PART - Life Limited #288	SHAFT, TURBINE REAR Part Number 6030T72P02 Serial Number PAMV5623	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART - Life Limited #306	SPOOL, STAGE 10-14 COMPRESSOR ROTOR Part Number: 5087T46P02 Serial Number: GATCTNRK	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 2 PART - Life Limited #425	SPOOL, STAGE 10-14 COMPRESSOR ROTOR Part Number: 5087T46P02 Serial Number: GATCTTYD	15-OCT-1997	C: 15000		H: 0.00 C: 0	C: 15000.00	C: 10997
72 Engine 1 PART - Life Limited #14	SPOOL, STAGE 3-8 COMPRESSOR ROTOR Part Number: 6078T56P04 Serial Number: GATCTWTF	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
	Notes (NOTE: SUBJECT TO INSPECTION BY AIRWORTHINESS DIRECTIVE 2004-26-02 AND AMOC DATED FEBRUARY 14, 2005)						
72 Engine 2 PART - Life Limited #627	SPOOL, STAGE 3-8 COMPRESSOR ROTOR Part Number: 6078T56P04 Serial Number: GATCTWTF E	15-OCT-1997	C: 20000		H: 0.00 C: 0	C: 20000.00	C: 15997
	Notes (NOTE: SUBJECT TO INSPECTION BY AIRWORTHINESS DIRECTIVE 2004-26-02 AND AMOC DATED FEBRUARY 14, 2005)						
72 Engine 1 PART #890	STAGE 1 HPT BLADE SET Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #183	STAGE 1 HPT BLADE SET Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 1 PART #941	STAGE 2 HPT BLADE SET Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
72 Engine 2 PART #398	STAGE 2 HPT BLADE SET Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 1 PART #892	TRANSITION TURBINE SEAL AND LINER Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 Engine 2 PART #832	TRANSITION TURBINE SEAL AND LINER Part Number Unknown Serial Number Unknown	15-OCT-1997					
72 00-00 Engine 1 INSPECTION #952	Engine Run - Prevent Storage Program Requirements (for each engine)	26-MAY-2026 H: 8686.90 C: 4000	D: 30			25-JUN-2026	M: 0 D: 24
72 00-00 Engine 2 INSPECTION #955	Engine Run - Prevent Storage Program Requirements (for each engine)	26-MAY-2026 H: 8686.90 C: 4000	D: 30			25-JUN-2026	M: 0 D: 24
72 00-CUS-9020 Airframe INSPECTION #2884	PERFORMANCE CHECK ENGINE TREND MONITORING DATA (NON GROUNDING) Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH ECTM DATA DOWNLOAD AND SENT TO CAMP FOR TRACKING.)	14-MAY-2026 H: 8686.90 L: 3999	M: 1			14-JUN-2026	M: 0 D: 13
72 20-00-201 Engine 1 INSPECTION PKG 600 Hour #413	GENERAL VISUAL INSPECTION OF THE FAN BLADES Notes (AVG MAN HRS: 2) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)	21-OCT-2024 H: 8557.60 C: 3932	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
72 20-00-201 Engine 2 INSPECTION PKG 600 Hour #876	GENERAL VISUAL INSPECTION OF THE FAN BLADES Notes (AVG MAN HRS: 2) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)	21-OCT-2024 H: 8557.60 C: 3932	H: 600.00	H: 40.00		H: 9125.20	H: 430.10



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 20-00-202 Engine 1 INSPECTION PKG 600 Hour #896	GENERAL VISUAL INSPECTION OF THE FAN SPINNER	21-OCT-2024 H: 8557.60 C: 3932	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
Notes (AVG MAN HRS: 1.5) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)							
72 20-00-202 Engine 2 INSPECTION PKG 600 Hour #139	GENERAL VISUAL INSPECTION OF THE FAN SPINNER	21-OCT-2024 H: 8557.60 C: 3932	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
Notes (AVG MAN HRS: 1.5) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)							
72 20-00-207 Engine 1 INSPECTION #660	DETAILED INSPECTION OF THE ENGINE MASTER CHIP DETECTOR INDICATOR	09-SEP-2024 H: 8541.00 C: 3921	H: 200.00	H: 20.00		H: 8741.00	H: 45.90
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: COMPLIED WITH INSPECTION 72-20-00-207 DETAILED INSPECTION OF THE ENGINE MASTER CHIP DETECTOR INDICATOR. IAW CL604 AMM 72-20-00. NO DEFECTS NOTED.)							
72 20-00-207 Engine 2 INSPECTION #218	DETAILED INSPECTION OF THE ENGINE MASTER CHIP DETECTOR INDICATOR	09-SEP-2024 H: 8541.00 C: 3921	H: 200.00	H: 20.00		H: 8741.00	H: 45.90
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: COMPLIED WITH INSPECTION 72-20-00-207 DETAILED INSPECTION OF THE ENGINE MASTER CHIP DETECTOR INDICATOR. IAW CL604 AMM 72-20-00. NO DEFECTS NOTED.)							
72 20-00-208 Engine 1 INSPECTION PKG3200Hour #624	GENERAL VISUAL INSPECTION OF THE ENGINE FAN CASE FORWARD MOUNTS	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
Notes (AVG MAN HRS: 8)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 20-00-208 Engine 2 INSPECTION PKG3200Hour #262	GENERAL VISUAL INSPECTION OF THE ENGINE FAN CASE FORWARD MOUNTS	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 8)						
72 20-00-210 Engine 1 INSPECTION PKG 600 Hour #171	GENERAL VISUAL INSPECTION OF THE FAN SHROUD CORE MATERIAL	21-OCT-2024 H: 8557.60 C: 3932	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 2) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
72 20-00-210 Engine 2 INSPECTION PKG 600 Hour #239	GENERAL VISUAL INSPECTION OF THE FAN SHROUD CORE MATERIAL	21-OCT-2024 H: 8557.60 C: 3932	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 2) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
72 20-00-211 Engine 1 INSPECTION PKG1200Hour #66	GENERAL VISUAL INSPECTION OF THE EXTERIOR OF THE ENGINE FAN CASE AND BLADE-CONTAINMENT CASE	21-OCT-2024 H: 8557.60 C: 3932	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
	Notes (AVG MAN HRS: 6) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
72 20-00-211 Engine 2 INSPECTION PKG1200Hour #793	GENERAL VISUAL INSPECTION OF THE EXTERIOR OF THE ENGINE FAN CASE AND BLADE-CONTAINMENT CASE	21-OCT-2024 H: 8557.60 C: 3932	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
	Notes (AVG MAN HRS: 6) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 30-00-202 Engine 1 INSPECTION PKG3200Hour #97	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE COMPRESSOR BLADES	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 12)						
72 30-00-202 Engine 2 INSPECTION PKG3200Hour #703	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE COMPRESSOR BLADES	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 12)						
72 30-00-204 Engine 1 INSPECTION PKG3200Hour #7	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE VARIABLE AND STATIONARY VANES	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 12)						
72 30-00-204 Engine 2 INSPECTION PKG3200Hour #797	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE VARIABLE AND STATIONARY VANES	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 12)						
72 30-00-205 Engine 1 INSPECTION PKG 800 Hour #799	LUBRICATION OF THE VARIABLE-GEOMETRY LINKAGE ROD END BEARINGS	11-JUL-2023 H: 8075.40 C: 3648	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
	Notes (AVG MAN HRS: 0.25) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 30-00-205 Engine 2 INSPECTION PKG 800 Hour #576	LUBRICATION OF THE VARIABLE-GEOMETRY LINKAGE ROD END BEARINGS	11-JUL-2023 H: 8075.40 C: 3648	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
	Notes (AVG MAN HRS: 10) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
72 40-00-201 Engine 1 INSPECTION PKG3200Hour #393	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE COMBUSTOR LINER	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 12)						
72 40-00-201 Engine 2 INSPECTION PKG3200Hour #842	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE COMBUSTOR LINER	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 12)						
72 40-00-202 Engine 1 INSPECTION PKG3200Hour #619	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE STAGE 1 NOZZLE	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 12)						
72 40-00-202 Engine 2 INSPECTION PKG3200Hour #615	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE STAGE 1 NOZZLE	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 12)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 40-00-205 Engine 1 INSPECTION PKG 600 Hour #501	GENERAL VISUAL INSPECTION OF THE THERMAL BLANKET	21-OCT-2024 H: 8557.60 C: 3932	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
Notes (AVG MAN HRS: 11) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)							
72 40-00-205 Engine 2 INSPECTION PKG 600 Hour #722	GENERAL VISUAL INSPECTION OF THE THERMAL BLANKET	21-OCT-2024 H: 8557.60 C: 3932	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
Notes (AVG MAN HRS: 11) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)							
72 40-00-207 Engine 1 INSPECTION PKG3200Hour #399	GENERAL VISUAL INSPECTION OF THE REAR MAIN MOUNT	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
Notes (AVG MAN HRS: 9.5)							
72 40-00-207 Engine 2 INSPECTION PKG3200Hour #412	GENERAL VISUAL INSPECTION OF THE REAR MAIN MOUNT	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
Notes (AVG MAN HRS: 9.5)							
72 50-00-201 Engine 1 INSPECTION PKG3200Hour #576	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE HIGH-PRESSURE-TURBINE STAGE 1 AND 2 ROTOR BLADES	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
Notes (AVG MAN HRS: 12)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 50-00-201 Engine 2 INSPECTION PKG3200Hour #366	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE HIGH-PRESSURE-TURBINE STAGE 1 AND 2 ROTOR BLADES	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 12)						
72 50-00-208 Engine 1 INSPECTION PKG2400Hour #572	VISUAL CHECK OF THE EXHAUST CENTERBODY	02-JUL-2021 H: 6939.60 C: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 9.5)						
72 50-00-208 Engine 2 INSPECTION PKG2400Hour #323	VISUAL CHECK OF THE EXHAUST CENTERBODY	02-JUL-2021 H: 6939.60 C: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 9.5)						
72 CF34BJ-780-602 Engine 1 INSPECTION #447	MANDATORY PERIODIC INSPECTION OF VARIABLE GEOMETRY SYSTEM - DO A FUNCTIONAL CHECK OF THE VARIABLE GEOMETRY SYSTEM	05-OCT-2025	M: 48			05-OCT-2029	M: 40 D: 4
	Notes (SOURCE: CF34 SERVICE MANUAL)						
72 CF34BJ-780-602 Engine 2 INSPECTION #889	MANDATORY PERIODIC INSPECTION OF VARIABLE GEOMETRY SYSTEM - DO A FUNCTIONAL CHECK OF THE VARIABLE GEOMETRY SYSTEM	05-OCT-2025	M: 48			05-OCT-2029	M: 40 D: 4
	Notes (SOURCE: CF34 SERVICE MANUAL)						
72 Engine 1 Airframe PART #578	GENERAL ELECTRIC - CF34-3B	Part Number 6089T11G01	Serial Number 872215				



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
72 Engine 2 Airframe PART #3358	GENERAL ELECTRIC - CF34-3B Part Number: 6089T11G01 Serial Number: 872216						
73 Engine 1 PART #103	COMPRESSOR INLET TEMPERATURE SENSOR Part Number: 4071T72P01 Serial Number: WYG94374					15-OCT-1997	
73 Engine 2 PART #25	COMPRESSOR INLET TEMPERATURE SENSOR Part Number: 4071T72P01 Serial Number: WYG94693					15-OCT-1997	
73 Engine 1 PART #162	ENGINE - COMPRESSOR INLET TEMPERATURE SENSOR Part Number: 4071T72P01 Serial Number: Unknown					15-OCT-1997	
73 Engine 2 PART #42	ENGINE - COMPRESSOR INLET TEMPERATURE SENSOR Part Number: 4071T72P01 Serial Number: Unknown					15-OCT-1997	
73 Engine 1 PART #224	FUEL PUMP Part Number: 6078T39P04 Serial Number: CGWT0783					15-OCT-1997	
73 Engine 2 PART #527	FUEL PUMP Part Number: 6078T39P04 Serial Number: CGWT0778					15-OCT-1997	
73 Airframe PART #7	LEFT CONTROL AMPLIFIER Part Number: Unknown Serial Number: Unknown					15-OCT-1997	
73 Airframe PART #1103	LEFT ENGINE METER, FUEL FLOW Part Number: 9-127-68 Serial Number: 8590					28-MAR-2018 H: 6319.00 L: 2697	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 Airframe PART #3578	LEFT ENGINE SWITCH, PRESSURE, FUEL PUMP Part Number: 7G1058 Serial Number: Unknown	15-OCT-1997					
73 Airframe PART #2137	LEFT HARNESS, N1 AMPLIFIER YELLOW Part Number: 5071T98P03 Serial Number: LMDK9230	15-OCT-1997					
73 Engine 1 PART #119	MAIN FUEL CONTROL (MFC) Part Number: 6078T55P26 Serial Number: WYG94591	13-APR-2013 H: 4782.30 C: 2063					
73 Engine 2 PART #935	MAIN FUEL CONTROL (MFC) Part Number: 6078T55P26 Serial Number: WYG94609	13-APR-2013 H: 4782.30 C: 2063					
73 Airframe PART #1686	RIGHT CONTROL AMPLIFIER Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
73 Airframe PART #876	RIGHT ENGINE METER, FUEL FLOW Part Number: 9-127-83 Serial Number: AC2868	28-MAR-2018 H: 6319.00 L: 2697					
73 Airframe PART #424	RIGHT ENGINE SWITCH, PRESSURE, FUEL PUMP Part Number: 7G1058 Serial Number: Unknown	15-OCT-1997					
73 Airframe PART #2892	RIGHT HARNESS, N1 AMPLIFIER YELLOW Part Number: 5071T98P03 Serial Number: LMDK9226	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 10-00-201 Engine 1 INSPECTION PKG1200Hour #780	DISCARD OF THE FUEL FILTER ELEMENT	08-FEB-2023 H: 7925.20 C: 3564	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
Notes (AVG MAN HRS: 10) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)							
73 10-00-201 Engine 2 INSPECTION PKG1200Hour #636	DISCARD OF THE FUEL FILTER ELEMENT	08-FEB-2023 H: 7925.20 C: 3564	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
Notes (AVG MAN HRS: 10) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)							
73 10-00-202 Engine 1 INSPECTION PKG1200Hour #110	VISUAL CHECK OF THE ENGINE FUEL-FILTER MECHANICAL ACTUAL-BYPASS INDICATOR	21-OCT-2024 H: 8557.60 C: 3932	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
Notes (AVG MAN HRS: 9) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)							
73 10-00-202 Engine 2 INSPECTION PKG1200Hour #498	VISUAL CHECK OF THE ENGINE FUEL-FILTER MECHANICAL ACTUAL-BYPASS INDICATOR	21-OCT-2024 H: 8557.60 C: 3932	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
Notes (AVG MAN HRS: 9) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)							
73 10-00-204 Engine 1 INSPECTION PKG2400Hour #786	DETAILED INSPECTION OF THE ENGINE FUEL MANIFOLD	02-JUL-2021 H: 6939.60 C: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
Notes (AVG MAN HRS: 10)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 10-00-204 Engine 2 INSPECTION PKG2400Hour #936	DETAILED INSPECTION OF THE ENGINE FUEL MANIFOLD	02-JUL-2021 H: 6939.60 C: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 10)						
73 10-00-205 Engine 1 INSPECTION PKG3200Hour #772	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE FUEL INJECTORS	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 12)						
73 10-00-205 Engine 2 INSPECTION PKG3200Hour #347	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE FUEL INJECTORS	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 12)						
73 10-00-301 Engine 1 INSPECTION #63	DETAILED INSPECTION OF THE FUEL FILTER ELEMENT.						
	Notes (ACCESS: 434AB, AT, 444AB, AT) (AVG MAN HRS: 3) (NOTE: NOTE: THIS IS A ONE-TIME ITEM ONLY FOR NEW OR OVERHAULED ENGINES. THE ORIGINAL FILTERS CAN BE RE-INSTALLED PROVIDED THEY ARE CLEAN WITH NO EVIDENCE OF CONTAMINATION OR DEBRIS.)						
73 10-00-301 Engine 2 INSPECTION #619	DETAILED INSPECTION OF THE FUEL FILTER ELEMENT.						
	Notes (ACCESS: 434AB, AT, 444AB, AT) (AVG MAN HRS: 3) (NOTE: NOTE: THIS IS A ONE-TIME ITEM ONLY FOR NEW OR OVERHAULED ENGINES. THE ORIGINAL FILTERS CAN BE RE-INSTALLED PROVIDED THEY ARE CLEAN WITH NO EVIDENCE OF CONTAMINATION OR DEBRIS.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
73 20-00-201 Engine 1 INSPECTION PKG3200Hour #820	DETAILED INSPECTION OF THE MAIN FUEL CONTROL	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 10.5)						
73 20-00-201 Engine 2 INSPECTION PKG3200Hour #577	DETAILED INSPECTION OF THE MAIN FUEL CONTROL	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 10.5)						
74 Engine 1 PART #341	(A) IGNITER PLUG Part Number 4096T38P10 Serial Number UNLJ6314	23-MAR-2017 H: 5979.10 C: 2576					
74 Engine 2 PART #673	(A) IGNITER PLUG Part Number 4096T38P10 Serial Number UNLJ6308	23-MAR-2017 H: 5979.10 C: 2576					
74 Engine 1 PART #26	(B) IGNITER PLUG Part Number 4096T38P10 Serial Number UNLJ6340	23-MAR-2017 H: 5979.10 C: 2576					
74 Engine 2 PART #353	(B) IGNITER PLUG Part Number 4096T38P10 Serial Number UNJ9U099	23-MAR-2017 H: 5979.10 C: 2576					
74 Engine 1 PART #679	FAN INLET TEMPERATURE SENSOR Part Number 4033T65P03 Serial Number Unknown	15-OCT-1997					
74 Engine 2 PART #583	FAN INLET TEMPERATURE SENSOR Part Number 4033T65P03 Serial Number Unknown	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
74 Airframe PART #796	INVERTER, STATIC (AFT FUSE) Part Number ASH671-2 Serial Number Unknown	15-OCT-1997					
74 Engine 1 PART #699	LEFT IGNITION, LEAD (GREY) Part Number Unknown Serial Number Unknown	15-OCT-1997					
74 Engine 2 PART #595	LEFT IGNITION, LEAD (GREY) Part Number Unknown Serial Number Unknown	15-OCT-1997					
74 Engine 1 PART #95	NO.1 IGNITION EXCITER Part Number 9238M66P08 Serial Number UNNEF956	15-OCT-1997					
74 Engine 2 PART #799	NO.1 IGNITION EXCITER Part Number 9238M66P08 Serial Number UNNEF953	15-OCT-1997					
74 Engine 1 PART #237	NO.2 IGNITION EXCITER Part Number 9238M66P08 Serial Number UNNEF952	15-OCT-1997					
74 Engine 2 PART #338	NO.2 IGNITION EXCITER Part Number 9238M66P08 Serial Number UNNEF955	15-OCT-1997					
74 Engine 1 PART #514	RIGHT IGNITION, LEAD (BLACK) Part Number Unknown Serial Number Unknown	15-OCT-1997					
74 Engine 2 PART #84	RIGHT IGNITION, LEAD (BLACK) Part Number Unknown Serial Number Unknown	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
75 Airframe PART #2297	#1 ENG 10 O'CLOCK VG ACTUATOR Part Number 5050T37G01 Serial Number Unknown	15-OCT-1997					
75 Airframe PART #618	#1 ENG 2 O'CLOCK VG ACTUATOR Part Number 5050T37G01 Serial Number Unknown	15-OCT-1997					
75 Airframe PART #1506	#2 ENG 10 O'CLOCK VG ACTUATOR Part Number 5050T37G01 Serial Number Unknown	15-OCT-1997					
75 Airframe PART #231	#2 ENG 2 O'CLOCK VG ACTUATOR Part Number 5050T37G01 Serial Number Unknown	15-OCT-1997					
75 Engine 1 PART #279	B-SUMP REGULATOR VALVE Part Number 4060T81G03 Serial Number Unknown	15-OCT-1997					
75 Engine 2 PART #123	B-SUMP REGULATOR VALVE Part Number 4060T81G03 Serial Number Unknown	15-OCT-1997					
75 Engine 1 PART #436	ENGINE - PRESSURE REGULATOR VALVE ASSEMBLY Part Number 4020T35G04 Serial Number Unknown	15-OCT-1997					
75 Engine 2 PART #486	ENGINE - PRESSURE REGULATOR VALVE ASSEMBLY Part Number 4020T35G04 Serial Number Unknown	15-OCT-1997					
76 Airframe PART #3165	LEFT CABLE, AUTO THROTTLE RETARDER (ATR) Part Number 1600980-005 Serial Number 675	15-OCT-1997					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
76 Airframe PART #2050	LEFT ENGINE CONTROL ASSY, THROTTLE PUSH/PULL Part Number: 1603730-007 Serial Number: 1161	21-APR-2005 H: 2522.30 L: 983					
76 Airframe PART #3519	LEFT ENGINE GEARBOX ASSY, THROTTLE CONTROL Part Number: 2100140-007 Serial Number: 253	15-OCT-1997					
76 Airframe PART #2194	LEFT PUSH-PULL ASSY, FWD (THROTTLE CABLE) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
76 Airframe PART #2772	LEFT PUSH/PULL ASSY, AFT (THROTTLE CABLE) Part Number: 1600730-001 Serial Number: Unknown	15-OCT-1997					
76 Airframe PART #656	LEFT THROTTLE CABLE Part Number: Unknown Serial Number: Unknown						
76 Airframe PART #3552	MOUNTING TRAY ASSEMBLY Part Number: Unknown Serial Number: Unknown						
76 Airframe PART #321	QUADRANT, ENGINE THROTTLE Part Number: 601R90601-11 Serial Number: FR280 Notes (ZONE: CENTER PEDESTAL)	15-OCT-1997					
76 Airframe PART #2007	QUADRANT, ENGINE THROTTLE HANDLE Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
76 Airframe PART #3233	RIGHT CABLE, AUTO THROTTLE RETARDER (ATR) Part Number: 1600980-007 Serial Number: 954	11-JUL-2023 H: 8075.40 L: 3647					
Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)							
76 Airframe PART #2808	RIGHT ENGINE CONTROL ASSY, THROTTLE PUSH/PULL Part Number: 1603730-005 Serial Number: 924	14-JUL-2004 H: 2246.20 L: 857					
76 Airframe PART #1906	RIGHT ENGINE GEARBOX ASSY, THROTTLE CONTROL Part Number: 2100140-010 Serial Number: 2238	11-JUL-2023 H: 8075.40 L: 3647					
Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)							
76 Airframe PART #1630	RIGHT PUSH-PULL ASSY, FWD (THROTTLE CABLE) Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
76 Airframe PART #3071	RIGHT PUSH/PULL ASSY, AFT (THROTTLE CABLE) Part Number: 1600730-001 Serial Number: Unknown	15-OCT-1997					
76 Airframe PART #2792	RIGHT THROTTLE CABLE Part Number: Unknown Serial Number: Unknown						
76 0130 Airframe INSPECTION #2590	DOWNLOAD ECTM	13-MAR-2025 H: 8631.50 L: 3977	L: 50			L: 4027	L: 25
Notes (ZONE: --) (UPDATE NOTE: COMPLIED WITH ENGINE TREND MONITOR DOWNLOAD) (NOTE: SEND AN EMAIL WITH THE .ENG FILE TO GEAEREMOTESERVICES@AE.GE.COM WITH THE SUBJECT LINE CLXXXX. (PLEASE REPLACE THE XS WITH THE AIRCRAFT SERIAL NUMBER))							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
76 11-00-101** Airframe INSPECTION #194	LEFT ENGINE FUNCTIONAL TEST OF THE ENGINE THROTTLE CONTROL GEARBOX	11-JUL-2023 H: 8075.40 L: 3647	H: 1000.00			H: 9075.40	H: 380.30
	<p>Notes</p> <p>(UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY.)</p>						
76 11-00-101** Airframe INSPECTION #2569	RIGHT ENGINE FUNCTIONAL TEST OF THE ENGINE THROTTLE CONTROL GEARBOX	11-JUL-2023 H: 8075.40 L: 3647	H: 1000.00			H: 9075.40	H: 380.30
	<p>Notes</p> <p>(AVG MAN HRS: 12) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: ** (TWO STARS) SHOWS THAT THE TASK INTERVAL CAN BE ADJUSTED TO AGREE WITH AN OPERATOR'S APPROVED ESCALATION PRACTICES OR AN APPROVED RELIABILITY PROGRAM, BUT THE TASK CAN NOT BE CHANGED OR DELETED WITHOUT PRIOR APPROVAL OF THE AIRWORTHINESS AUTHORITY. THE ALLOWABLE EXTENSION OF 40 HRS IS AN EXCEPTIONAL SHORT TERM EXTENSION WHICH IS DEFINED AS AN INCREASE IN A CMR INTERVAL THAT CAN BE USED WHEN AN UNCONTROLLABLE OR UNEXPECTED SITUATION OCCURS. REPEATED USE OF EXTENSIONS SHOULD NOT BE USED AS A SUBSTITUTE FOR GOOD MANAGEMENT PRACTICES.)</p>						
76 11-00-201 Engine 1 INSPECTION PKG3200Hour #22	FUNCTIONAL TEST OF THE GEARBOX ASSEMBLY	16-JUN-2018 H: 6372.80 C: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	<p>Notes</p> <p>(AVG MAN HRS: 11)</p>						
76 11-00-201 Engine 2 INSPECTION PKG3200Hour #493	FUNCTIONAL TEST OF THE GEARBOX ASSEMBLY	16-JUN-2018 H: 6372.80 C: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	<p>Notes</p> <p>(AVG MAN HRS: 11)</p>						
76 11-01-204 Airframe INSPECTION PKG1200Hour #2939	GENERAL VISUAL INSPECTION OF THE ENGINE THROTTLE PUSH/PULL CONTROL-ASSEMBLY	21-OCT-2024 H: 8557.60 L: 3931	H: 1200.00	H: 40.00		H: 9757.60	H: 1062.50
	<p>Notes</p> <p>(AVG MAN HRS: 12) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)</p>						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
77 Engine 1 PART #541	AMPLIFIER CONTROLLER Part Number Unknown Serial Number Unknown	15-OCT-1997					
77 Engine 2 PART #421	AMPLIFIER CONTROLLER Part Number Unknown Serial Number Unknown	15-OCT-1997					
77 Engine 2 PART #118	BLUE ELECTRICAL HARNESS Part Number 1697M50G04 Serial Number LMDY4219	16-AUG-2023 H: 8092.80 C: 3661					
	Notes (UPDATE NOTE: REMOVED AND REPLACED #2 BLUE ENGINE HARNESS WITH TESTED UNIT PER CF34BJ SM 72-00-00 MAINTENANCE TASK 24 BLUE HARNESS REPAIR/ REPLACEMENT. P/N ON/OFF 1697M50G04 S/N OFF UNKNOWN ON LMDY4219. TESTED BY BARFIELD PRECISION ELECTRONICS LLC CRS# PRZR073K WORK ORDER # R43074 DATED ON 11/JUL/2023. OPS CHECK GOOD.)						
77 Airframe PART #3124	CONDITIONER, ENGINE VIBRATION SIGNAL Part Number 601-50910-19 Serial Number 100205	21-SEP-2021 H: 7063.80 L: 3109					
	Notes (ZONE: AVIONIC BAY) (APX COST: 4,675) (UPDATE NOTE: REMOVED VIBRATION SIGNAL CONDITIONER, P/N 601-50910-13 S/N 059779, AND INSTALLED REPAIRED SIGNAL CONDITIONER, P/N 601-50910-19 S/N 100205, IAW CL604 AMM REVISION 93, TASK 77-31-04-400-801. OPERATIONAL CHECK SATISFACTORY. SIGNAL CONDITIONER REPAIRED BY DUNCAN AVIATION, CRS JGVR194F, SEE WORK ORDER 83SUA, FORM TRACKING NUMBER 83SUA0001001001 DATED 11 MAY 2021 FOR DETAILS.)						
77 Airframe PART #2113	LEFT ENGINE ACCELEROMETER, ENGINE VIBRATION Part Number 6233M30A Serial Number 22030	02-MAR-2023 H: 7947.70 L: 3578					
	Notes (UPDATE NOTE: WORK PERFORMED BY BOMBARDIER CRS# KW3R646L UNDER WO 257233)						
77 Airframe PART #2649	RIGHT ENGINE ACCELEROMETER, ENGINE VIBRATION Part Number 6233M30A Serial Number 10676	02-MAR-2023 H: 7947.70 L: 3578					
	Notes (APX COST: 0) (UPDATE NOTE: WORK PERFORMED BY BOMBARDIER CRS# KW3R646L UNDER WO 257233)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 Engine 1 PART #652	EXHAUST FRAME Part Number Unknown Serial Number Unknown	15-OCT-1997					
78 Engine 2 PART #679	EXHAUST FRAME Part Number Unknown Serial Number Unknown	15-OCT-1997					
78 Airframe PART #595	LEFT ENGINE FAIRING ASSY, EXHAUST NOZZLE Part Number 228-50181-245 Serial Number C0461	15-OCT-1997					
78 Airframe PART #1198	LEFT ENGINE POWER DRIVE UNIT, THRUST REVERSER Part Number Unknown Serial Number Unknown	15-OCT-1997					
78 Airframe PART #3662	LEFT ENGINE THRUST REVERSER, STOW SWITCH Part Number Unknown Serial Number Unknown	15-OCT-1997					
78 Airframe PART - Life Limited #935	LEFT INBOARD ACTUATOR, GEARBOX BALLSCREW (LOWER) Part Number 228-58111-111 Serial Number Unknown	15-OCT-1997	H: 50000.00		H: 0.00	H: 50000.00	H: 41304.90
<p>Notes</p> <p>(ZONE: 430) (ACCESS: 432AB, 432AT) (AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)</p>							
78 Airframe PART - Life Limited #3151	LEFT INBOARD ACTUATOR, GEARBOX BALLSCREW (UPPER) Part Number 228-58111-111 Serial Number Unknown	15-OCT-1997	H: 50000.00		H: 0.00	H: 50000.00	H: 41304.90
<p>Notes</p> <p>(ZONE: 430) (ACCESS: 432AB, 432AT)</p>							
78 Airframe PART #2529	LEFT MODULE, LOWER Part Number 228-50100-247 Serial Number C0226	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 Airframe PART #2322	LEFT MODULE, UPPER Part Number: 228-50100-399 Serial Number: C0226	15-OCT-1997					
78 Airframe PART #3556	LEFT NO.1 SHAFT ASSY (I/R FLEX SHAFT) Part Number: 121754-6 Serial Number: 4972460A	15-OCT-1997					
78 Airframe PART #173	LEFT NO.1 SHAFT, FLEX DRIVE (I/R FLEX SHAFT) Part Number: 121754-2 Serial Number: 6972513	15-OCT-1997					
78 Airframe PART #9	LEFT NO.2 SHAFT ASSY (I/R FLEX SHAFT) Part Number: 121754-2 Serial Number: 5972476	15-OCT-1997					
78 Airframe PART #778	LEFT NO.2 SHAFT, FLEX DRIVE (I/R FLEX SHAFT) Part Number: 121754-5 Serial Number: 2972393A	15-OCT-1997					
78 Airframe PART #2015	LEFT NO.3 SHAFT ASSY (I/R FLEX SHAFT) Part Number: 121754-3 Serial Number: 011313019206	12-APR-2013 H: 4782.30 L: 2063					
78 Airframe PART #95	LEFT NOZZLE ASSY, EXHAUST Part Number: 228-55030-113 Serial Number: C0442	15-OCT-1997					
78 Airframe PART - Life Limited #408	LEFT OUTBOARD ACTUATOR, GEARBOX BALLSCREW (LOWER) Part Number: 228-58111-111 Serial Number: Unknown	15-OCT-1997	H: 50000.00		H: 0.00	H: 50000.00	H: 41304.90

Notes

(ZONE: 430) (ACCESS: 432AB, 432AT) (AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 Airframe PART - Life Limited #1082	LEFT OUTBOARD ACTUATOR, GEARBOX BALLSCREW (UPPER) Part Number: 228-58111-111 Serial Number: Unknown	15-OCT-1997	H: 50000.00		H: 0.00	H: 50000.00	H: 41304.90
Notes (ZONE: 430) (ACCESS: 432AB, 432AT)							
78 Airframe PART #3224	LEFT PNEUMATIC DRIVE UNIT Part Number: 126758-7 Serial Number: 1439	10-DEC-2012	H: 4722.30 L: 2033				
78 Airframe PART #1546	LEFT REVERSER INSTL, THRUST Part Number: 228-50200-803 Serial Number: C0223	15-OCT-1997					
78 Airframe PART #332	LOWER FAIRING Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
78 Airframe PART #1577	RIGHT ENGINE FAIRING ASSY, EXHAUST NOZZLE Part Number: 228-50181-245 Serial Number: C0462	15-OCT-1997					
78 Airframe PART #1601	RIGHT ENGINE POWER DRIVE UNIT, THRUST REVERSER Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
78 Airframe PART #2184	RIGHT ENGINE THRUST REVERSER, STOW SWITCH Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
78 Airframe PART - Life Limited #531	RIGHT INBOARD ACTUATOR, GEARBOX BALLSCREW (LOWER) Part Number: 228-58111-111 Serial Number: Unknown	15-OCT-1997	H: 50000.00		H: 0.00	H: 50000.00	H: 41304.90
Notes (ZONE: 440) (ACCESS: 442AB, 442AT)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 Airframe PART - Life Limited #3426	RIGHT INBOARD ACTUATOR, GEARBOX BALLSCREW (UPPER) Part Number: 228-58111-111 Serial Number: Unknown	15-OCT-1997	H: 50000.00		H: 0.00	H: 50000.00	H: 41304.90
Notes (ZONE: 440) (ACCESS: 442AB, 442AT)							
78 Airframe PART #651	RIGHT MODULE, LOWER Part Number: 228-50100-248 Serial Number: C0229	15-OCT-1997					
78 Airframe PART #1837	RIGHT MODULE, UPPER Part Number: 228-50100-400 Serial Number: C0229	15-OCT-1997					
78 Airframe PART #2247	RIGHT NO.1 SHAFT ASSY (I/R FLEX SHAFT) Part Number: 121754-6 Serial Number: 101213018902	12-APR-2013	H: 4782.30 L: 2063				
78 Airframe PART #2538	RIGHT NO.1 SHAFT, FLEX DRIVE (I/R FLEX SHAFT) Part Number: 121754-2 Serial Number: 6972516	15-OCT-1997					
78 Airframe PART #327	RIGHT NO.2 SHAFT ASSY (I/R FLEX SHAFT) Part Number: 121754-2 Serial Number: 0113130194117	12-APR-2013	H: 4782.30 L: 2063				
78 Airframe PART #3435	RIGHT NO.2 SHAFT, FLEX DRIVE (I/R FLEX SHAFT) Part Number: 121754-5 Serial Number: 080713014158	12-APR-2013	H: 4782.30 L: 2063				
78 Airframe PART #2890	RIGHT NO.3 SHAFT ASSY (I/R FLEX SHAFT) Part Number: 121754-3 Serial Number: 6971348	15-OCT-1997					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 Airframe PART #1453	RIGHT NOZZLE ASSY, EXHAUST Part Number: 228-55030-113 Serial Number: C0441	15-OCT-1997					
78 Airframe PART - Life Limited #227	RIGHT OUTBOARD ACTUATOR, GEARBOX BALLSCREW (LOWER) Part Number: 228-58111-111 Serial Number: Unknown Notes (ZONE: 440) (ACCESS: 442AB, 442AT)	15-OCT-1997	H: 50000.00		H: 0.00	H: 50000.00	H: 41304.90
78 Airframe PART - Life Limited #491	RIGHT OUTBOARD ACTUATOR, GEARBOX BALLSCREW (UPPER) Part Number: 228-58111-111 Serial Number: Unknown Notes (ZONE: 440) (ACCESS: 442AB, 442AT)	15-OCT-1997	H: 50000.00		H: 0.00	H: 50000.00	H: 41304.90
78 Airframe PART #1450	RIGHT PNEUMATIC DRIVE UNIT Part Number: 126758-8 Serial Number: 4507	14-DEC-2017 H: 6236.60 L: 2672					
78 Airframe PART #3022	RIGHT REVERSER INSTL, THRUST Part Number: 228-50200-804 Serial Number: C0237	15-OCT-1997					
78 10-00-201 Airframe INSPECTION 05H6400 #244	DETAILED INSPECTION OF THE EXHAUST NOZZLE ASSEMBLY	16-JUN-2018 H: 6372.80 L: 2715	H: 6400.00	H: 40.00		H: 12795.00	H: 4099.90
78 30-00-101* Airframe INSPECTION #857	SPECIAL DETAILED INSPECTION OF THE AFT LUG OF THE MAIN TRACK OF THE THRUST REVERSER Notes (AVG MAN HRS: 7) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)		L: 7800			L: 7800	L: 3798



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 30-00-102* Airframe INSPECTION #879	SPECIAL DETAILED INSPECTION OF THE MAIN TRACKS LOWER FLANGE OF THE THRUST REVERSER		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 7) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
78 30-00-103* Airframe INSPECTION #3210	SPECIAL DETAILED INSPECTION OF THE MAIN UPPER AND LOWER PYLON TRACK		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 9) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
78 30-00-202 Airframe INSPECTION PKG 800 Hour #69	LUBRICATION OF THE THRUST-REVERSER BALLSCREW ACTUATORS	11-JUL-2023 H: 8075.40 L: 3647	H: 800.00	H: 40.00		H: 8875.40	H: 180.30
	Notes (AVG MAN HRS: 6.5) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851)						
78 30-00-203 Airframe INSPECTION PKG2400Hour #3073	LUBRICATION OF THE THRUST-REVERSER FLEXSHAFTS	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 14)						
78 30-00-204 Airframe INSPECTION PKG2400Hour #1137	DETAILED INSPECTION OF THE FLEXSHAFT DRIVE	02-JUL-2021 H: 6939.60 L: 3034	H: 2400.00	H: 40.00		H: 9339.60	H: 644.50
	Notes (AVG MAN HRS: 10)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 30-00-205 Airframe INSPECTION PKG3200Hour #2738	FUNCTIONAL TEST OF THE AUTO-THROTTLE RETARDER SYSTEM, THROTTLE LOCKS AND BELLCRANK	16-JUN-2018 H: 6372.80 L: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 4)						
78 30-00-206 Airframe INSPECTION PKG 96 Month #537	DETAILED INSPECTION OF THE MAIN PYLON TRACKS OF THE THRUST-REVERSER	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 6)						
78 30-00-207 Airframe INSPECTION PKG 96 Month #2825	DETAILED INSPECTION OF THE THRUST-REVERSER MAIN TRACKS	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2)						
78 30-00-208 Airframe INSPECTION PKG 96 Month #1312	DETAILED INSPECTION OF THE ATTACHMENT FITTINGS FOR THE THRUST-REVERSER MAIN TRACKS	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2)						
78 30-00-209 Airframe INSPECTION PKG 96 Month #1434	DETAILED INSPECTION OF THE SUPPORT FITTINGS OF THE THRUST-REVERSER BALLSCREW ACTUATORS	02-JUL-2021 H: 6939.60 L: 3034	M: 96	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 2)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 34-07-101* Airframe INSPECTION #1276	SPECIAL DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE MAIN TRACK OF THE THRUST REVERSER		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 8) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
78 34-07-102* Airframe INSPECTION #1935	DETAILED INSPECTION OF THE SUPPORT BED FOR THE UPPER AND LOWER PYLONTRACK ON THE SERVICE PYLON		L: 7800			L: 7800	L: 3798
	Notes (AVG MAN HRS: 3) (NOTE: * (ONE STAR) SHOWS THAT THE TASK IS MANDATORY AND CANNOT BE CHANGED, ESCALATED (INCREASED) OR DELETED WITHOUT THE APPROVAL OF THE CERTIFICATION AIRWORTHINESS AUTHORITY.)						
78 Left Airframe PART #459	PYLON TRACKS COVER ASSY (INNER) Part Number Unknown Serial Number Unknown		15-OCT-1997				
78 Right Airframe PART #1145	PYLON TRACKS COVER ASSY (OUTER) Part Number Unknown Serial Number Unknown		15-OCT-1997				
78 ZL-00-201 Airframe INSPECTION PKG 48 Month #1848	GENERAL VISUAL INSPECTION OF THE TORQUE BOX OF THE THRUST REVERSER - INTERNAL LH		31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1	13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
78 ZL-00-202 Airframe INSPECTION PKG 48 Month #2314	GENERAL VISUAL INSPECTION OF THE TORQUE BOX OF THE THRUST REVERSER - INTERNAL RH		31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1	13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 3) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
78 ZL-00-203 Airframe INSPECTION PKG 48 Month #2539	GENERAL VISUAL INSPECTION OF THE EXHAUST NOZZLE FAIRING-ASSEMBLY LH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 7.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
78 ZL-00-204 Airframe INSPECTION PKG 48 Month #305	GENERAL VISUAL INSPECTION OF THE EXHAUST NOZZLE FAIRING-ASSEMBLY RH	31-MAY-2025 H: 8649.70 L: 3986	M: 48	M: 1		13-APR-2029	M: 34 D: 12
	Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025)						
79 Airframe PART #3634	#1 ENG OIL FILTER SENSOR Part Number: 4060T64P01 Serial Number: Unknown					15-OCT-1997	
79 Airframe PART #3389	#2 ENG OIL FILTER SENSOR Part Number: 4060T64P01 Serial Number: Unknown					15-OCT-1997	
79 Engine 1 PART #234	A-SUMP SCAVENGE PUMP Part Number: 4018T11P02 Serial Number: Unknown					15-OCT-1997	
79 Engine 2 PART #379	A-SUMP SCAVENGE PUMP Part Number: 4018T11P02 Serial Number: Unknown					15-OCT-1997	
79 Engine 1 PART #728	BOARD - CHIP DETECTOR/OIL FILTER BYPASS INDICATOR Part Number: Unknown Serial Number: Unknown						
79 Engine 2 PART #385	BOARD - CHIP DETECTOR/OIL FILTER BYPASS INDICATOR Part Number: Unknown Serial Number: Unknown						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 Airframe PART #309	CONTROL, SIGNAL (OIL REPLENISHMENT SYSTEM) Part Number: 30027-0000-02 Serial Number: Unknown	15-OCT-1997					
79 Engine 1 PART #773	HEAT EXCHANGER Part Number: 6087T05P02 Serial Number: SCKB0670	15-OCT-1997					
79 Engine 2 PART #431	HEAT EXCHANGER Part Number: 6087T05P02 Serial Number: SCKB0681	15-OCT-1997					
79 Airframe PART #1241	LEFT ENGINE PROBE, OIL LEVEL Part Number: 601-63903-15 Serial Number: 4429 Notes (APX COST: 0) (UPDATE NOTE: REMOVED LEFT ENGINE OIL TANK LEVEL PROBE, P/N 601-63903-7 S/N 1172, AND INSTALLED REPAIRED OIL TANK PROBE, P/N 601-63903-15 S/N 4429, IAW CL-604 AMM TASK 79-12-16-400-801. OPERATIONAL AND LEAK TEST SATISFACTORY. OIL PROBE REPAIRED BY SIMMOND'S PRECISION PRODUCTS CERTIFICATE NUMBER CV1R074K W/O 42616854 BBW7324 FORM TRACKING NUMBER 8648729.)	25-FEB-2020 H: 6560.10 L: 2832					
79 Airframe PART #2991	LEFT ENGINE SWITCH, OIL PRESSURE, QEC Part Number: 1153P0012 Serial Number: 1401	15-OCT-1997					
79 Airframe PART #1697	LEFT ENGINE VALVE, CHECK Part Number: 2810044-101 Serial Number: 1361	15-OCT-1997					
79 Airframe PART #3144	LEFT NO.1 TEMPERATURE BULB Part Number: MS28034-3 Serial Number: Unknown	15-OCT-1997					
79 Airframe PART #3660	LEFT NO.2 TEMPERATURE BULB Part Number: Unknown Serial Number: Unknown	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 Airframe PART #1377	LEFT TRANSDUCER, ENGINE OIL PRESSURE Part Number: 601-50919-9 Serial Number: 8496-6-162	05-FEB-2018 H: 6283.60 L: 2685					
79 Engine 1 PART #870	LUBE AND SCAVENGE PUMP Part Number: 6087T04P06 Serial Number: NMADB340	26-NOV-2002 H: 1492.40					
79 Engine 2 PART #828	LUBE AND SCAVENGE PUMP Part Number: 6087T04P06 Serial Number: NMADB441	26-NOV-2002 H: 1492.40					
79 Engine 1 PART #610	OIL FILTER Part Number: 4012T16P01 Serial Number: Unknown	15-OCT-1997					
79 Engine 2 PART #941	OIL FILTER Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
79 Engine 1 PART #182	OIL FILTER BYPASS SENSOR Part Number: 4060T64P01 Serial Number: Unknown	15-OCT-1997					
79 Engine 2 PART #592	OIL FILTER BYPASS SENSOR Part Number: 4060T64P04 Serial Number: APFK8692	16-JUN-2018 H: 6372.80 C: 2711					
79 Airframe PART #2528	OIL TANK Part Number: Unknown Serial Number: Unknown	15-OCT-1997					
79 Airframe PART #3173	PUMP (OIL REPLENISHMENT SYSTEM) Part Number: 601-63901-1 Serial Number: 10AM121	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 Airframe PART #1691	RIGHT ENGINE PROBE, OIL LEVEL Part Number 601-63903-7 Serial Number 1207	01-NOV-2016 H: 5880.00 L: 2541					
79 Airframe PART #236	RIGHT ENGINE SWITCH, OIL PRESSURE, QEC Part Number 1153P0012 Serial Number 1415	15-OCT-1997					
79 Airframe PART #3309	RIGHT ENGINE VALVE, CHECK Part Number 2810044-101 Serial Number 1356	15-OCT-1997					
79 Airframe PART #1001	RIGHT NO.1 TEMPERATURE BULB Part Number MS28034-3 Serial Number Unknown	15-OCT-1997					
79 Airframe PART #2932	RIGHT NO.2 TEMPERATURE BULB Part Number Unknown Serial Number Unknown	15-OCT-1997					
79 Airframe PART #1886	RIGHT TRANSDUCER, ENGINE OIL PRESSURE Part Number 601-50919-9 Serial Number Unknown	15-OCT-1997					
79 Airframe PART #2407	TANK, OIL, SUB-ASSY (OIL REPLENISHMENT SYSTEM) Part Number Unknown Serial Number Unknown	15-OCT-1997					
79 Airframe PART #1387	VALVE, SELECTOR (OIL REPLENISHMENT SYSTEM) Part Number 601-63902-1 Serial Number 7031835	15-OCT-1997					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 00-00-203 Engine 1 INSPECTION PKG 600 Hour #785	VISUAL CHECK OF THE OIL-FILTER IMPENDING-BYPASS INDICATOR.	21-OCT-2024 H: 8557.60 C: 3932	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)							
79 00-00-203 Engine 2 INSPECTION PKG 600 Hour #143	VISUAL CHECK OF THE OIL-FILTER IMPENDING-BYPASS INDICATOR.	21-OCT-2024 H: 8557.60 C: 3932	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
Notes (AVG MAN HRS: 1) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)							
79 00-00-204 Engine 1 INSPECTION PKG1200Hour #412	DISCARD OF THE OIL FILTER ELEMENT.	08-FEB-2023 H: 7925.20 C: 3564	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
Notes (AVG MAN HRS: 10) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)							
79 00-00-204 Engine 2 INSPECTION PKG1200Hour #573	DISCARD OF THE OIL FILTER ELEMENT.	08-FEB-2023 H: 7925.20 C: 3564	H: 1600.00	H: 40.00		H: 9525.20	H: 830.10
Notes (AVG MAN HRS: 10) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)							
79 00-00-205 Engine 1 INSPECTION PKG3200Hour #480	FUNCTIONAL TEST OF THE OIL-FILTER IMPENDING-BYPASS SENSOR	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
Notes (AVG MAN HRS: 12)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 00-00-205 Engine 2 INSPECTION PKG3200Hour #358	FUNCTIONAL TEST OF THE OIL-FILTER IMPENDING-BYPASS SENSOR	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 12)						
79 00-00-206 Engine 1 INSPECTION PKG3200Hour #491	FUNCTIONAL TEST OF THE ENGINE MASTER CHIP DETECTOR	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 7.5)						
79 00-00-206 Engine 2 INSPECTION PKG3200Hour #311	FUNCTIONAL TEST OF THE ENGINE MASTER CHIP DETECTOR	16-JUN-2018 H: 6372.80 C: 2711	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 7.5)						
79 00-00-207 Engine 1 INSPECTION PKG 600 Hour #861	VISUAL CHECK OF THE C-SUMP DRAIN OUTLET	21-OCT-2024 H: 8557.60 C: 3932	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 0.5) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
79 00-00-207 Engine 2 INSPECTION PKG 600 Hour #68	VISUAL CHECK OF THE C-SUMP DRAIN OUTLET	21-OCT-2024 H: 8557.60 C: 3932	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (AVG MAN HRS: 0.5) (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
79 00-00-208 Engine 1 INSPECTION PKG3200Hour #365	DETAILED INSPECTION OF THE C-SUMP SCAVENGE SCREENS (PRE GE SB 79-0018)	16-JUN-2018 H: 6372.80 C: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 3.5)						
79 00-00-208 Engine 2 INSPECTION PKG3200Hour #870	DETAILED INSPECTION OF THE C-SUMP SCAVENGE SCREENS (PRE GE SB 79-0018)	16-JUN-2018 H: 6372.80 C: 2715	H: 3200.00	H: 40.00		H: 9569.60	H: 874.50
	Notes (AVG MAN HRS: 3.5)						
80 Airframe PART #469	LEFT ENGINE VALVE, ATS Part Number 898930-10 Serial Number 4007				03-JUL-2010 H: 3880.90 L: 1650		
80 Airframe PART #3670	LEFT STARTER, AIR TURBINE Part Number 3505188-9 Serial Number 3505188-7502				11-AUG-2023 H: 8088.50 L: 3658		
	Notes (APX COST: 0) (UPDATE NOTE: REMOVED RIGHT ATS P/N: 3505188-9, S/N: 3892. INSTALLED REPAIRED ATS P/N: 3505188-9, S/N: 3505188-7502 HONEYWELL INTERNATIONAL INC. TRACKING #20230012862358Y15, WORK ORDER #5800715217346591392, CRS #ZN3R030M, DATED 18 MAY 2023. RAN AIRCRAFT SYSTEM STILL FAILS ON THE RIGHT. SWAPPED ATS FROM RIGHT P/N: 3505188-9, S/N: 3505188-7502 TO LEFT. LEFT P/N: 3505188-9, S/N: 3792 TO THE RIGHT. RAN AIRCRAFT SYSTEM STILL FAILED ON THE RIGHT. IAW CL604 AMM 80-11-01.)						
80 Airframe PART #3421	LEFT SWITCH, ASSY (PRESS SPEED SWITCH - N1 AMP) Part Number 128646-6 Serial Number 20409				04-MAY-2020 H: 6562.30 L: 2835		
	Notes (APX COST: 0) (UPDATE NOTE: REMOVED LEFT STARTER SPEED SWITCH ASSEMBLY, P/N 128646-5-1 S/N 10502, AND INSTALLED REPAIRED STARTER SPEED SWITCH ASSEMBLY, P/N 128646-6 S/N 20409, IAW CL 604 AMM REV. 87 TASK 80-11-10-400-801. OPERATIONAL CHECK SATISFACTORY.)						
80 Airframe PART #1390	RIGHT ENGINE VALVE, ATS Part Number 898930-10 Serial Number 4906				09-MAY-2024 H: 8393.90 L: 3827		
	Notes (APX COST: 0) (UPDATE NOTE: WORK ACCOMPLISHED BY KEITH CHAPMAN, A&P 3551627 REGENT AIRCRAFT MX WO# 20062 ON 5/09/2024)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
80 Airframe PART #1237	RIGHT STARTER, AIR TURBINE Part Number Serial Number 3505188-9 3792	11-AUG-2023 H: 8088.50 L: 3658					
	Notes (APX COST: 810.7) (UPDATE NOTE: REMOVED RIGHT ATS P/N: 3505188-9, S/N: 3892. INSTALLED REPAIRED ATS P/N: 3505188-9, S/N: 3505188-7502 HONEYWELL INTERNATIONAL INC. TRACKING #20230012862358Y15, WORK ORDER #5800715217346591392, CRS #ZN3R030M, DATED 18 MAY 2023. RAN AIRCRAFT SYSTEM STILL FAILS ON THE RIGHT. SWAPPED ATS FROM RIGHT P/N: 3505188-9, S/N: 3505188-7502 TO LEFT. LEFT P/N: 3505188-9, S/N: 3792 TO THE RIGHT. RAN AIRCRAFT SYSTEM STILL FAILED ON THE RIGHT. IAW CL604 AMM 80-11-01.)						
80 Airframe PART #1183	RIGHT SWITCH, ASSY (PRESS SPEED SWITCH - N1 AMP) Part Number Serial Number 128646-5-1 10657	11-AUG-2023 H: 8088.50 L: 3658					
	Notes (AVG MAN HRS: 0.9) (APX COST: 18.6) (UPDATE NOTE: REMOVED RIGHT SPEED SWITCH P/N: 128646-5-1, S/N: 10436. INSTALLED REPAIRED SPEED SWITCH P/N: 128646-5-1, S/N: 10657. HONEYWELL INTERNATIONAL INC. TRACKING #890002576690Y15310961411, WORK ORDER #5800277177310961249, CRS #ZX4R716M, DATED APR 03 2012. SYSTEM OPS CHECKS GOOD. IAW CL604 AMM 80-11-10.)						
80 11-00-202 Airframe INSPECTION PKG 600 Hour #94	DETAILED INSPECTION OF THE DRAIN-PLUG MAGNETIC CHIP-DETECTOR	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
80 11-00-203 Airframe INSPECTION PKG 600 Hour #2497	DISCARD OF THE AIR TURBINE STARTER (ATS) OIL	21-OCT-2024 H: 8557.60 L: 3931	H: 600.00	H: 40.00		H: 9125.20	H: 430.10
	Notes (TOL. ADJUSTMENT: -32.4 HRS) (UPDATE NOTE: COMPLIED WITH BY BOMBARDIER TUCSON SERVICE CENTER, CRS # KW3R646L , WORK ORDER 1899605.)						
100 0001 Airframe INSPECTION #3028	PAINT	27-DEC-2018 H: 6424.10 L: 2747					
100 0002 Airframe INSPECTION #503	INTERIOR						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
100 AFM0000 Airframe INSPECTION #1296	VERIFY REVISION STATUS OF AFM	14-MAY-2026 H: 8686.90 L: 3999	D: 30			13-JUN-2026	M: 0 D: 12
	Notes (ZONE: --) (AVG MAN HRS: 1) (UPDATE NOTE: UPDATED AFM ON IPAD)						
100 C164-161128 Airframe INSPECTION #1078	REVIEW BOMBARDIER CHALLENGER 604 TLMC REV 27 (MPD REV 27) DATED NOV 28/2016.	29-DEC-2016 H: 5894.40 L: 2549					
100 JLA-PF-0020 (- JLCD) Airframe INSPECTION #3325	PERFORM PREFLIGHT INSPECTION	26-MAY-2026 H: 8686.90 L: 3999	D: 10			05-JUN-2026	M: 0 D: 4
	Notes (ZONE: --) (AVG MAN HRS: 3) (UPDATE NOTE: COMPLIED WITH PREFLIGHT CHECKLIST)						
102 JLA-Programs- Electronic or Paper Pilot M Airframe INSPECTION #3321	VERIFY AIRCRAFT PILOT MANUALS ARE ELECTRONIC OR PAPER [TYPE ONE OF THE FOLLOWING UNDER NOTE ON THE COMPLIANCE PAGE "PAPER", "ELECTRONIC", "BOTH"]	03-FEB-2023					
	Notes (UPDATE NOTE: ELECTRONIC)						
102 JLA-Programs- REG-Aircraft-FAA Airframe INSPECTION FAA #2092	FAA 14 CFR PART 47 - AIRCRAFT REGISTRATION (HARD CARD)	29-AUG-2024	M: 84			30-SEP-2028	M: 27 D: 29
	Notes (ISSUING AUTHORITY: FAA)						
102 JLA-Programs- REG-NOAA-Aircraft Airframe INSPECTION #2659	406 MHZ ELT-NOAA REGISTRATION RENEWAL (25-NOAA)	24-SEP-2025	M: 24			24-SEP-2027	M: 15 D: 23
	Notes (UPDATE NOTE: ELT HEX 2DC843BB5EFFBFF)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
102 JLA-Programs-REG-NOAA-Life Raft-1 Airframe INSPECTION #999	#1 LIFE RAFT 406 MHZ ELT-NOAA REGISTRATION RENEWAL (25-NOAA)	02-JUL-2025	M: 24			02-JUL-2027	M: 13 D: 1
	Notes (UPDATE NOTE: ELT HEX ADCC408DE8001BD)						
102 JLA-Programs-REG-NOAA-Life Raft-2 Airframe INSPECTION #2390	#2 LIFE RAFT 406 MHZ ELT-NOAA REGISTRATION RENEWAL (25-NOAA)	24-SEP-2025	M: 24			24-SEP-2027	M: 15 D: 23
	Notes (UPDATE NOTE: ELT HEX ADCC08883700401)						
102 JLA-Programs-SUBS-WIFI-Gogo Airframe INSPECTION #1038	GOGO; ATG5000 C1 BOX - JLA FLEET PLAN IRIDIUM VOICE-BRONZE	11-NOV-2019					
102 JLA-Programs-WARR-APU Airframe INSPECTION #3677	APU PROGRAM (NON-GROUNDING) MSPG 440140218	27-NOV-2023	M: 60			11-DEC-2028	M: 30 D: 10
	Notes (ZONE: --) (APX COST: 359.33)						
105 JLA-Aborted Take-off/Diversion/Deviation Airframe INSPECTION #3543	ABORTED TAKE-OFF/DIVERSION/DEVIATION - MAINTENANCE CONTROL MECHANICAL CONFIRMATION	15-MAR-2024					
	Notes (UPDATE NOTE: KSUS - MCC CONTROLLER THOMAS WRIGHT A&P 3264332, PILOT JEFF HARRIS ATP 3464385 PILOT CALLED TO REPORT THAT HE HAD A "WHITE DOOR LIGHT" ON POWER UP FOR TAKE OFF. TAKEOFF WAS ABORTED, AND THE PILOT RETURNED TO THE TAXI WAY. HE STATED THAT HE ASKED GROUND CONTROL FOR PERMISSION TO DEPLANE AT CHECK THE EXTERNAL OF THE AIRCRAFT. THE PILOT STATED THAT HE FOUND WHAT APPEARED TO BE AN UNSECURE LATCH ON THE EXTERNAL AIRCRAFT REFUEL DOOR. HE SECURED THE LATCH AND REPORTED THAT THE LIGHT WENT OUT. HE STATED THAT HE WAS CONFIDENT THAT THE ISSUE WAS RESOLVED. THE AIRCRAFT WAS RELEASED TO CONTINUE ON TO IT'S NEXT DESTINATION) (NOTE: NOTE: REVIEW AND UNDERSTAND JLA GMM SECTION 8.11						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
106 Airframe PART #267	NO.1 LIFE RAFT (PERMANENT) PAX: 10 Part Number Serial Number RAF1210-311T1 1121062491 H	28-AUG-2024					
	Notes (AVG MAN HRS: 2) (APX COST: 0) (UPDATE NOTE: INSTALLED OVERHAULED #1 LIFE RAFT P/N: RAF1210-311T1, S/N: 1121062491H, SAFETECH USA INC. TRACKING #WSM2411359, WORK ORDER #WSM241135924294, CRS #WV1R599K, DATED 29-JUL-2024. HYDRO DATE: 07/2024, NEXT HYDRO DUE: 07/2029. ELT S/N: 24321, ELT BEACON ID: 09082. ELT BATTERY EXP: 03/2029. HEX ID: ADCC408DE8001BD. NEXT LIFE RAFT SERVICE DATE 07/2027.)						
106 Airframe PART #1975	NO.2 LIFE RAFT (PERMANENT) PAX: 10 Part Number Serial Number RAF1210-305T1 1054KO/10 53KO	10-APR-2024					
	Notes (AVG MAN HRS: 2.5) (APX COST: 0) (UPDATE NOTE: INSTALLED OVERHAULED NO. 2 LIFE RAFT P/N RAF1210-305T1 S/N 1054KO ON AIRCRAFT AFTER OVERHAUL. LIFE RAFT OVERHAULED BY SAFETECH FORM TRACKING NUMBER WSM2400108 WORK ORDER WSM2400108 RO-6340-N530BD CRS# WV1R599K DATED 29-MAR-2024)						
107 JLA-Value Documentation. Airframe INSPECTION #1991	DOCUMENT VALUE, SAVINGS, ETC.						
108 Airframe PART #3515	RENTAL ENGINE/APU REMOVAL - NOTIFY INSURANCE (CLAIMS@JETLINX.COM) (NON GROUNDING) Part Number Serial Number Unknown Unknown						
109 JLA-ATG Obsolescence Airframe INSPECTION #82	(NON-GROUNDING ITEM) ATG WIFI SYSTEM UPGRADE DUE TO OBSOLESCENCE. GOGO ATG SYSTEM WILL NOT HAVE AVAILABLE SUBSCRIPTION STARTING JANUARY 1, 2025. PLACE THIS TASK INTO THE RESPECTIVE WORK ORDER. SIGN OFF THE TASK IN THE WORK ORDER ONCE THE UPGRADE HAS BEEN LOCKED IN WITH THE MAINTENANCE VENDOR.	26-DEC-2025					
IS600-11-0001 RA Airframe SB - Open #1245	KIT - REGISTRATION PLATE INSTL. PAX DOOR SURROUND						
IS600-11-0001 RB Airframe SB - Open #1225	KIT - REGISTRATION PLATE INSTL. PAX DOOR SURROUND						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
IS600-28-0002 RA Airframe SB - Open #2273	KIT - METAL WING FUEL ACCESS PANELS - ALTERNATIVE INSTL						
IS600-29-0001 RA Airframe SB - Superseded #3272	KIT - HYDRAULIC SYSTEM #1 & #2: AFT EQUIPMENT BAY - IMPROVEMENT TO HYDRAULIC LINES VIBRATION DAMAGE PREVENTION						
	Notes .SEE REVISION B.						
IS600-29-0001 RB-1 Airframe SB - Open #3725	KIT - HYDRAULIC SYSTEM #1 & #2: AFT EQUIPMENT BAY - IMPROVEMENT TO HYDRAULIC LINES VIBRATION DAMAGE PREVENTION						
	Notes .OPEN						
IS600-29-0002 RA Airframe SB - Open #1323	KIT - INTRO OF ELBOW FITTING ON ECOLOGY BOTTLE FOR THE HYDRAULIC RESEVOIR #3						
	Notes .OPEN -						
IS600-33-0001 RA Airframe SB - Open #446	KIT - INTRODUCTION, REAR NAVIGATION LIGHT SPIRAL CORD / BOOT (SERVICE LOOP)						
IS600-34-0001 RA Airframe SB - Open #2736	KIT - INTRODUCTION OF ALTERNATE ANTENNA INSTALLATIONS WITH CONDUCTIVE GASKETS						
	Notes .OPEN -						
IS600-52-0001 RA Airframe SB - Open #1485	INSTALLATION OF ALTERNATE FASTENERS FOR LOWER ELECTRONICS BAY ACCESS DOOR, NOSE COMPARTMENT						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
IS600-52-0003 RA Airframe SB - Open #3112	PASSENGER DOOR-REWORK HINGE PANEL ASSY 600-31980-1023 TO PROVIDE ALTERNATE PART FOR 600-31980-1011						
IS600-52-0004 Airframe SB - Complied With #684	MAIN PASSENGER DOOR SEAL - INTRODUCTION OF DRAIN HOLES					03-AUG-2015 H: 5528.10 L: 2396	
IS600-52-0004 RA Airframe SB - Open #751	MAIN PASSENGER DOOR SEAL - INTRODUCTION OF DRAIN HOLES						
IS600-53-0002 RA Airframe SB - Open #232	ALTERNATIVE CRES FASTENERS FOR DOOR ASSY FWD FUSELAGE						
IS600-54-0001 RA Airframe SB - Open #2593	PYLON TRAILING EDGE ATTACHMENT MODIFICATION						
IS600-57-0001 RA Airframe SB - Open #1880	KIT-FLAP BOX HINGE BUSHINGS INSTL - IMPROVED CORROSION PROTECTION						
IS604-32-0001 RA Airframe SB - Open #1129	KIT, INTRODUCTION OF AN OVER-INFLATION PRESSURE RELEASE PLUG ON NLG WHEEL ASSY.						
SB 36-49-8361 R4 APU SB - Open #15	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE RIVET PN M24243/6A401H WITH RIVET PN 627-504-9209 ON 36-150 ENGINE MODELS						
	Notes (AVG MAN HRS: 1) (NOTE: EFFECTIVITY: SEE PAR. 1.A FOR MORE INFORMATION. COMPLIANCE: THIS SERVICE BULLETIN, RECOMMENDED BY HONEYWELL, IS DONE AT THE NEXT ACCESS TO THE PARTS.)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 3615880-49-8149 APU SB - Open #74	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS						
SB 3615880-49-8149 R1 APU SB - Open #19	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS						
SB 3615880-49-8149 R2 APU SB - Open #104	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS						
SB 3615880-49-8149 R3 APU SB - Open #101	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS						
	Notes (AVG MAN HRS: 1.5)						
SB 3822101-49-8148 APU SB - Open #28	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, P/N 3822101-1, ON MULTIPLE APU'S						
SB 3822101-49-8148 R1 APU SB - Open #119	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, P/N 3822101-1, ON MULTIPLE APU'S						
SB 3822101-49-8148 R2 APU SB - Open #78	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, P/N 3822101-1, ON MULTIPLE APU'S						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 3822101-49-8148 R3 APU SB - Open #124	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, P/N 3822101-1, ON MULTIPLE APU'S Notes (AVG MAN HRS: 1)						
SB 3842064-49-8193 APU SB - Open #36	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS PN 3842064-1 AND PN 3842064-5 ON MULTIPLE AUXILIARY POWER UNITS (APUS)						
SB 3842064-49-8193 R1 APU SB - Open #38	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS PN 3842064-1 AND PN 3842064-5 ON MULTIPLE AUXILIARY POWER UNITS (APUS) Notes (NOTE: HONEYWELL RECOMMENDS THIS SERVICE BULLETIN BE DONE FOR THE BALANCE REPAIR OF TURBINE ROTORS, PN 3842064-1 AND PN 3842064-5.)						
SB 3842368-49-8147 R1 APU SB - Open #88	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTOR, PN 3842368-1, ON MULTIPLE APUS						
SB 3842368-49-8147 R2 APU SB - Open #99	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTOR, PN 3842368-1, ON MULTIPLE APUS						
SB 3842368-49-8147 R3 APU SB - Open #181	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTOR, P/N 3842368-1, ON MULTIPLE APU'S Notes (NOTE: COMPLIANCE: HONEYWELL RECOMMENDS THIS SERVICE BULLETIN BE DONE FOR THE BALANCE REPAIR OF TURBINE ROTOR, PN 3842368-1.)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 3880021-49-8188 R APU SB - Open #102	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REWORK FLUID PRESSURE REGULATING VALVE, PN 3880021-2, -5 THRU -17 TO PN 70721587-5, ON MULTIPLE APUS Notes (AVG MAN HRS: 5)						
SB 3882600-49-7973 APU SB - Open #68	MAIN FUEL CONTROL UNIT (FCU) - CHECK NAMEPLATE FOR LATEST CHANGE NUMBER. INSTALL FUEL FLOW DEFLECTOR, PN 70720001-1 ON THE FUEL CONTROL DIFFERENTIAL PRESSURE (DELTA P) SLEEVE AS REQUIRED AT NEXT APU SHOP VISIT						
SB 3882600-49-7973 R1 APU SB - Open #146	MAIN FUEL CONTROL UNIT (FCU) - CHECK NAMEPLATE FOR LATEST CHANGE NUMBER. INSTALL FUEL FLOW DEFLECTOR, PN 70720001-1 ON THE FUEL CONTROL DIFFERENTIAL PRESSURE (DELTA P) SLEEVE AS REQUIRED AT NEXT APU SHOP VISIT						
SB 3882600-49-7973 R2 APU SB - Open #151	MAIN FUEL CONTROL UNIT (FCU) - CHECK NAMEPLATE FOR LATEST CHANGE NUMBER. INSTALL FUEL FLOW DEFLECTOR, PN 70720001-1 ON THE FUEL CONTROL DIFFERENTIAL PRESSURE (DELTA P) SLEEVE AS REQUIRED AT NEXT APU SHOP VISIT Notes (AVG MAN HRS: 1)						
SB 49-6052 APU SB - Open #121	IMPROVE HOT SECT LIFE, INC IMPROVED TURB RTR						
SB 49-6057 APU SB - Open #69	IMPROVE HOT SECT LIFE, INC IMPROVED TURB NOZ						
SB 49-6074 APU SB - Open #178	INCORPORATE TURBINE ROTOR 3842088-1						
SB 49-6106 APU SB - Open #136	INC TURBINE ROTOR 3615880-1						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 49-7308 APU SB - Open #24	EXCHANGE OF SPECIFIC ROLLER BEARINGS, PART NO. 3842004-1 MANUFACTURED BY FAG CANADA						
SB 49-7933 R APU SB - Open #3	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB 49-7933 R1 APU SB - Open #8	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB 49-7933 R10 APU SB - Open #145	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB 49-7933 R2 APU SB - Open #182	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB 49-7933 R3 APU SB - Open #183	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB 49-7933 R4 APU SB - Open #80	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB 49-7933 R5 APU SB - Open #147	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB 49-7933 R6 APU SB - Open #66	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 49-7933 R7 APU SB - Open #47	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB 49-7933 R8 APU SB - Open #184	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB 49-7933 R9 APU SB - Open #109	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB 49-7997 APU SB - Open #192	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES. Notes (ZONE: .)						
SB 49-7997 R1 APU SB - Open #60	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						
SB 49-7997 R2 APU SB - Open #21	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						
SB 49-7997 R3 APU SB - Open #141	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						
SB 49-7997 R4 APU SB - Open #44	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 49-7997 R5 APU SB - Open #130	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						
SB 49-7997 R6 APU SB - Open #129	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						
SB 49-7997 R7 APU SB - Recurring #87	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES					10-APR-2026 H: 10289.00	
SB 49-8252 APU SB - Open #155	AIRBORNE - AUXILIARY POWER UNIT (APU) - APPROVED FUELS FOR HONEYWELL COMMERCIAL APUS						
SB 49-8252 R1 APU SB - Open #82	AIRBORNE - AUXILIARY POWER UNIT (APU) - APPROVED FUELS FOR HONEYWELL COMMERCIAL APUS						
SB 49-8252 R2 APU SB - Open #133	AIRBORNE - AUXILIARY POWER UNIT (APU) - APPROVED FUELS FOR HONEYWELL COMMERCIAL APUS						
SB 604-11-001 Airframe SB - Open #3089	MODIFICATION - INCREASED MTOW TO 48,200 LB (21,863 KG)						
SB 604-11-001 R1 Airframe SB - Open #92	MODIFICATION - INCREASED MTOW TO 48,200 LB (21,863 KG)						
	Notes (AVG MAN HRS: 1)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-11-002 PART A Airframe SB - Open #3093	MODIFICATION - REPLACE DECAL ON THE REFUEL/DEFUEL CONTROL PANELS Notes (AVG MAN HRS: 0.5)						
SB 604-11-002 PART B Airframe SB - Open #2891	MODIFICATION - REPLACE DECAL ON THE REFUEL/DEFUEL CONTROL PANELS Notes (AVG MAN HRS: 0.5)						
SB 604-11-002 Airframe SB - Open #2546	MODIFICATION - REPLACE DECAL ON THE REFUEL/DEFUEL CONTROL PANELS						
SB 604-11-003 Airframe SB - Open #3533	MODIFICATION - GERMAN REGISTRATION REQUIREMENTS						
SB 604-11-003 R1 Airframe SB - Open #920	MODIFICATION - GERMAN REGISTRATION REQUIREMENTS						
SB 604-11-003 R2 Airframe SB - Open #3225	MODIFICATION - GERMAN REGISTRATION REQUIREMENTS Notes (AVG MAN HRS: 9)DECLINED						
SB 604-11-004 Airframe SB - Superseded #3049	MODIFICATION - RUSSIAN CERTIFICATION REQUIREMENTS Notes .SEE REVISION 1.						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-11-004 R1 Airframe SB - Open #2940	MODIFICATION - RUSSIAN CERTIFICATION REQUIREMENTS						
	Notes (AVG MAN HRS: 2)DECLINED						
SB 604-11-005 Airframe SB - Open #1184	MODIFICATION - PASSENGER/CREW DOOR - PLACARD REPLACEMENT						
	Notes (AVG MAN HRS: 1)						
SB 604-11-006 Airframe SB - Open #3716	MODIFICATION - BRAZILIAN CERTIFICATION REQUIREMENTS						
	Notes (AVG MAN HRS: 22)						
SB 604-11-007 Airframe SB - Open #3141	CANCELLED PRIOR TO ISSUE						
SB 604-11-008 Airframe SB - Superseded #1146	MODIFICATION - ARGENTINIAN CERTIFICATION REQUIREMENTS						
	Notes .SEE REVISION 1.						
SB 604-11-008 R1 Airframe SB - Open #2837	MODIFICATION - ARGENTINIAN CERTIFICATION REQUIREMENTS						
	Notes (AVG MAN HRS: 12)DECLINED						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-11-010 Airframe SB - Open #1544	MODIFICATION - FUSELAGE PLACARDS AND MARKINGS - ADDITION OF STOW ROD WARNING DECAL ON UPPER CORE COWL DOOR Notes (AVG MAN HRS: 1)						
SB 604-11-011 Airframe SB - Open #2094	MODIFICATION - EXTERIOR PLACARDS AND MARKINGS - CERTIFICATION REQUIREMENTS FOR THE PEOPLES REPUBLIC OF CHINA Notes (AVG MAN HRS: 1)						
SB 604-11-012 PART B Airframe SB - N/A #2615	MODIFICATION - WING PLACARDS AND MARKINGS - PAINTED OVERWING ANTI-SLIP WALKWAY					26-NOV-2002 H: 1515.00 L: 551	
SB 604-11-012 PART A Airframe SB - N/A #3159	SPECIAL CHECK - WING PLACARDS AND MARKINGS - PAINTED OVERWING ANTI-SLIP WALKWAY					26-NOV-2002 H: 1515.20 L: 551	
SB 604-11-012 Airframe SB - Open #2666	SPECIAL CHECK/MODIFICATION - WING PLACARDS AND MARKINGS - PAINTED OVERWING ANTI-SLIP WALKWAY						
SB 604-11-012 R1 PART B Airframe SB - Open #2877	MODIFICATION - WING PLACARDS AND MARKINGS - PAINTED OVERWING ANTI-SLIP WALKWAY Notes (AVG MAN HRS: 9)						
SB 604-11-012 R1 PART A Airframe SB - Open #2450	SPECIAL CHECK - WING PLACARDS AND MARKINGS - PAINTED OVERWING ANTI-SLIP WALKWAY Notes (AVG MAN HRS: 0.25)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-11-012 R1 Airframe SB - Open #2654	SPECIAL CHECK/MODIFICATION - WING PLACARDS AND MARKINGS - PAINTED OVERWING ANTI-SLIP WALKWAY						
SB 604-11-013 Airframe SB - Complied With #1645	SPECIAL CHECK/MODIFICATION - WING PLACARDS AND MARKINGS - POSSIBILITY OF MISSING OVERWING REFUELING DECAL					12-APR-2013 H: 4782.30 L: 2063	
	Notes (AVG MAN HRS: 1) (NOTE: RECOMMENDED AT THE NEXT AIRCRAFT PAINT JOB OR WITHIN 7 YEARS FROM RELEASE OF THIS SERVICE BULLETIN, WHICHEVER COMES FIRST.)						
SB 604-11-014 Airframe SB - Superseded #3408	MODIFICATION - NOSE LANDING GEAR (NLG) - TOWING STRAP PLACARD INSTALLATION						
	Notes (AVG MAN HRS: 1).SEE REVISION 1.						
SB 604-11-014 R1 Airframe SB - Open #3185	MODIFICATION - NOSE LANDING GEAR (NLG) - TOWING STRAP PLACARD INSTALLATION						
	Notes (AVG MAN HRS: 1)DECLINED						
SB 604-11-015 Airframe SB - Open #2440	MODIFICATION - SERVICE DOORS AND FLIGHT COMPARTMENT, PLACARDS AND MARKINGS - INSTALL FUEL SPILLAGE PREVENTION PLACARD FOR THE REFUEL/DEFUEL CONTROL PANEL (S)						
	Notes (AVG MAN HRS: 0.5)DECLINED						
SB 604-11-016 Airframe SB - Superseded #2757	STAGE 4 NOISE LEVELS STANDARDS - CERTIFICATION						
	Notes (AVG MAN HRS: 1) (APX COST: 10,000).SEE REVISION 1.						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-11-016 R1 Airframe SB - Open #1080	STAGE 4 NOISE LEVELS STANDARDS - CERTIFICATION						
	Notes (AVG MAN HRS: 1) (APX COST: 2,500)DECLINED						
SB 604-11-016 R2 Airframe SB - Open #2377	STAGE 4 NOISE LEVELS STANDARDS - CERTIFICATION						
	Notes (AVG MAN HRS: 1)						
SB 604-20-001 Airframe SB - Complied With #701	SPECIAL CHECK/REWORK - WIRES AND CABLES - INSPECT ELECTRICAL HARNESES BEHIND THE PILOT, CENTER AND COPILOT INSTRUMENT PANELS FOR CHAFING					12-JUL-2004 H: 2246.30 L: 857	
	Notes (AVG MAN HRS: 4)						
SB 604-21-001 Airframe SB - N/A #524	MODIFICATION - STANDBY CABIN ALTITUDE INDICATOR - NIGHT VISIBILITY IMPROVEMENT						
	Notes (AVG MAN HRS: 1)						
SB 604-21-002 Airframe SB - Open #3553	MODIFICATION - AIR CONDITIONING UNITS (ACU) - ACUS INHIBIT DURING EITHER ENGINE START						
SB 604-21-002 R1 Airframe SB - Open #3133	MODIFICATION - AIR CONDITIONING UNITS (ACU) - ACUS INHIBIT DURING EITHER ENGINE START						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-21-002 R2 Airframe SB - Open #2253	MODIFICATION - AIR CONDITIONING UNITS (ACU) - ACUS INHIBIT DURING EITHER ENGINE START Notes (AVG MAN HRS: 55) (NOTE: RETROACTIVE ACTION THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT ON WHICH THE BASIC ISSUE OF THIS SERVICE BULLETIN WAS DONE: DO SB 604-21-008 TO REPLACE THE EXISTING RELAYS WITH 5-SECOND DELAY RELAYS K9HG AND K10HG.)						
SB 604-21-003 PART A Airframe SB - Open #139	MODIFICATION - FLIGHT COMPARTMENT DISTRIBUTION - DUCT REPLACEMENT BELOW THE SIDE CONSOLES Notes (AVG MAN HRS: 8)						
SB 604-21-003 Airframe SB - Open #583	MODIFICATION - FLIGHT COMPARTMENT DISTRIBUTION - DUCT REPLACEMENT BELOW THE SIDE CONSOLES						
SB 604-21-003 PART B Airframe SB - Open #3372	MODIFICATION - FLIGHT COMPARTMENT DISTRIBUTION - DUCT REPLACEMENT BELOW THE SIDE CONSOLES Notes (AVG MAN HRS: 8)						
SB 604-21-004 Airframe SB - Open #3213	MODIFICATION - PRESSURIZATION CONTROL SYSTEM - ALLOW AIRCRAFT OPERATION AT HIGH FIELD ELEVATION						
SB 604-21-004 R1 Airframe SB - Open #974	MODIFICATION - PRESSURIZATION CONTROL SYSTEM - ALLOW AIRCRAFT OPERATION AT HIGH FIELD ELEVATION						
SB 604-21-004 R2 Airframe SB - Open #153	MODIFICATION - PRESSURIZATION CONTROL SYSTEM - ALLOW AIRCRAFT OPERATION AT HIGH FIELD ELEVATION						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-21-004 R3 Airframe SB - Open #450	MODIFICATION - PRESSURIZATION CONTROL SYSTEM - ALLOW AIRCRAFT OPERATION AT HIGH FIELD ELEVATION Notes (AVG MAN HRS: 44) (NOTE: AIRCRAFT, SERIAL NO. 5305 HAD THIS MODIFICATION INSTALLED THROUGH THE PROOF ISSUES OF THE BASIC AND REVISION 01 SERVICE BULLETINS AND IT MEETS ALL THE REQUIREMENTS OF THIS BULLETIN)DECLINED						
SB 604-21-005 Airframe SB - Open #2833	CANCELLED PRIOR TO ISSUE						
SB 604-21-006 PART B Airframe SB - Complied With #2701	REWORK - PRESSURIZATION CONTROL - CHECK VALVES, PART NO. 2770080-102 INSTALLATION Notes (AVG MAN HRS: 2)					23-NOV-1999 H: 485.00 L: 193	
SB 604-21-006 PART A Airframe SB - Complied With #2352	SPECIAL CHECK - PRESSURIZATION CONTROL - CHECK VALVES, PART NO. 2770080-102 INSTALLATION Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.)					08-FEB-2023 H: 7925.20 L: 3563	
SB 604-21-006 Airframe SB - Open #1534	SPECIAL CHECK/REWORK - PRESSURIZATION CONTROL - CHECK VALVES, PART NO. 2770080-102 INSTALLATION						
SB 604-21-007 Airframe SB - Open #943	MODIFICATION - TEMPERATURE CONTROL - PREVENTION OF ICE FORMATION DOWNSTREAM OF AIR CONDITIONING UNITS (ACU) Notes (AVG MAN HRS: 2)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-21-008 Airframe SB - Open #2592	MODIFICATION - AIR CONDITIONING UNITS - REPLACEMENT OF EXISTING RELAYS K2000HG AND K2001HG WITH 5 SECOND DELAY RELAYS						
SB 604-21-008 R1 Airframe SB - Superseded #2677	MODIFICATION - AIR CONDITIONING UNITS - REPLACEMENT OF EXISTING RELAYS K2000HG AND K2001HG WITH 5 SECOND DELAY RELAYS Notes .SEE REVISION 2.						
SB 604-21-008 R2 Airframe SB - Open #2423	MODIFICATION - AIR CONDITIONING UNITS - REPLACEMENT OF EXISTING RELAYS K2000HG AND K2001HG WITH 5 SECOND DELAY RELAYS Notes (AVG MAN HRS: 15)						
SB 604-21-009 Airframe SB - Superseded #3401	SPECIAL CHECK/REWORK - CORROSION PREVENTION - ACU EXHAUST DUCT FLANGE & FUSELAGE SKIN MATING SURFACES Notes (AVG MAN HRS: 8).SEE REVISION 1.						
SB 604-21-009 R1 Airframe SB - Superseded #2719	SPECIAL CHECK/REWORK - CORROSION PREVENTION - ACU EXHAUST DUCT FLANGE & FUSELAGE SKIN MATING SURFACES Notes (AVG MAN HRS: 8) (NOTE: CUSTOMERS WHO DO NOT COMPLY WITH THIS SERVICE BULLETIN DURING THE RECOMMENDED COMPLIANCE PERIOD (12 MONTHS FROM THE BASIC ISSUE RELEASE DATE), SHOULD TAKE NOTE THAT IF CORROSION DEVELOPS DURING THE BASIC OR STRUCTURAL WARRANTY PERIOD OF THEIR AIRCRAFT, THEIR WARRANTY CLAIM MAY BE DENIED AS PER ARTICLE 15.4 OF THEIR JET PURCHASE AGREEMENT).SEE REVISION 2.						
SB 604-21-009 R2 Airframe SB - Complied With #3394	SPECIAL CHECK/REWORK - CORROSION PREVENTION - ACU EXHAUST DUCT FLANGE & FUSELAGE SKIN MATING SURFACES Notes (AVG MAN HRS: 8)					23-MAR-2017 H: 5979.10 L: 2576	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-21-010 Airframe SB - Superseded #2370	MODIFICATION - ENTRY AREA HEAT - ENTRY AREA HEATER SUPPORT MODIFICATION						
	Notes (AVG MAN HRS: 25).SEE REVISION 1.						
SB 604-21-010 Part A Airframe SB - Superseded #3346	MODIFICATION - ENTRY AREA HEAT - ENTRY AREA HEATER SUPPORT MODIFICATION - DO THE MODIFICATION OF THE ENTRY AREA HEATER INSTALLATION AS PER K604-99002-1						
	Notes (AVG MAN HRS: 15).SEE REVISION 1.						
SB 604-21-010 Part B Airframe SB - Superseded #1742	MODIFICATION - ENTRY AREA HEAT - ENTRY AREA HEATER SUPPORT MODIFICATION - DO THE MODIFICATION OF THE ENTRY AREA HEATER INSTALLATION AS PER K604-99002-3						
	Notes (AVG MAN HRS: 10).SEE REVISION 1.						
SB 604-21-010 R1 Airframe SB - N/A #1172	MODIFICATION - ENTRY AREA HEAT - ENTRY AREA HEATER SUPPORT MODIFICATION						
	Notes (AVG MAN HRS: 25).TO AIRCRAFT S/N	13-FEB-2017					H: 5969.40 L: 2571
SB 604-21-010 R1 PART A Airframe SB - N/A #3410	MODIFICATION - ENTRY AREA HEAT - ENTRY AREA HEATER SUPPORT MODIFICATION - DO THE MODIFICATION OF THE ENTRY AREA HEATER INSTALLATION AS PER K604-99002-1						
	Notes (AVG MAN HRS: 15).TO AIRCRAFT S/N	13-FEB-2017					H: 5969.40 L: 2571
SB 604-21-010 R1 PART B Airframe SB - N/A #2373	MODIFICATION - ENTRY AREA HEAT - ENTRY AREA HEATER SUPPORT MODIFICATION - DO THE MODIFICATION OF THE ENTRY AREA HEATER INSTALLATION AS PER K604-99002-3						
	Notes (AVG MAN HRS: 10).TO AIRCRAFT S/N	13-FEB-2017					H: 5969.40 L: 2571



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-21-010 R2 Airframe SB - Open #169	MODIFICATION - ENTRY AREA HEAT - ENTRY AREA HEATER SUPPORT MODIFICATION Notes (AVG MAN HRS: 25)						
SB 604-21-010 R2 PART A Airframe SB - Open #2061	MODIFICATION - ENTRY AREA HEAT - ENTRY AREA HEATER SUPPORT MODIFICATION - DO THE MODIFICATION OF THE ENTRY AREA HEATER INSTALLATION AS PER K604-99002-1 Notes (AVG MAN HRS: 15)						
SB 604-21-010 R2 PART B Airframe SB - Open #1465	MODIFICATION - ENTRY AREA HEAT - ENTRY AREA HEATER SUPPORT MODIFICATION - DO THE MODIFICATION OF THE ENTRY AREA HEATER INSTALLATION AS PER K604-99002-3 Notes (AVG MAN HRS: 10)						
SB 604-21-010 R3 Airframe SB - Open #3406	MODIFICATION - ENTRY AREA HEAT - ENTRY AREA HEATER SUPPORT MODIFICATION Notes (AVG MAN HRS: 25)						
SB 604-21-010 R3 PART A Airframe SB - Open #2099	MODIFICATION - ENTRY AREA HEAT - ENTRY AREA HEATER SUPPORT MODIFICATION - DO THE MODIFICATION OF THE ENTRY AREA HEATER INSTALLATION AS PER K604-99002-1 Notes (AVG MAN HRS: 15)						
SB 604-21-010 R3 PART B Airframe SB - Open #3314	MODIFICATION - ENTRY AREA HEAT - ENTRY AREA HEATER SUPPORT MODIFICATION - DO THE MODIFICATION OF THE ENTRY AREA HEATER INSTALLATION AS PER K604-99002-3 Notes (AVG MAN HRS: 10)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-22-001 Airframe SB - Open #1795	MODIFICATION - AUTOMATIC FLIGHT CONTROL SYSTEM - ENABLE THE AUTOPILOT/FLIGHT DIRECTOR SYNCHRONIZATION FUNCTION Notes (AVG MAN HRS: 1)						
SB 604-22-002 Airframe SB - Complied With #1477	MODIFICATION - AUTOMATIC FLIGHT CONTROL SYSTEM - INTRODUCTION OF FLIGHT CONTROL COMPUTER (FCC) 822-0809-410/-510 TO CORRECT PREMATURE TRANSITION FROM AUTOPILOT TO ALTITUDE CAPTURE Notes (AVG MAN HRS: 6)	13-JUN-2005					H: 2522.30 L: 983
SB 604-22-003 Airframe SB - N/A #671	SPECIAL CHECK/REWORK - AUTOPILOT - BREAKAWAY TORQUE OF AILERON SERVO MOUNT CLUTCH Notes (AVG MAN HRS: 4).TO AIRCRAFT S/N	13-FEB-2017					H: 5969.40 L: 2571
SB 604-22-006 Airframe SB - Complied With #351	MODIFICATION - AUTOMATIC FLIGHT CONTROL SYSTEM - INTRODUCTION OF FLIGHT CONTROL COMPUTER (FCC) 822-0809-610/-710 TO DECREASE THE TAKEOFF PITCH ANGLE Notes (AVG MAN HRS: 5)	03-JUN-2009					H: 3637.60 L: 1526
SB 604-22-007 Airframe SB - Superseded #3033	SPECIAL CHECK / MODIFICATION - YAW DAMPER SYSTEM - AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS) WIRING CHANGE TO PREVENT UN-COMMANDED YAW DAMPER/LINEAR ACTUATOR MOTION AFTER POWER SUPPLY FAILURE Notes (AVG MAN HRS: 50).SEE REVISION 1.						
SB 604-22-007 R1 PART B Airframe SB - Open #1671	MODIFICATION - YAW DAMPER SYSTEM - AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS) WIRING CHANGE TO PREVENT UN-COMMANDED YAW DAMPER/LINEAR ACTUATOR MOTION AFTER POWER SUPPLY FAILURE Notes (AVG MAN HRS: 50)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-22-007 R1 PART A Airframe SB - Open #1842	SPECIAL CHECK - YAW DAMPER SYSTEM - AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS) WIRING CHANGE TO PREVENT UN-COMMANDED YAW DAMPER/LINEAR ACTUATOR MOTION AFTER POWER SUPPLY FAILURE						
	Notes (AVG MAN HRS: 0.5)						
SB 604-22-007 R1 Airframe SB - Complied With #2406	SPECIAL CHECK / MODIFICATION - YAW DAMPER SYSTEM - AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS) WIRING CHANGE TO PREVENT UN-COMMANDED YAW DAMPER/LINEAR ACTUATOR MOTION AFTER POWER SUPPLY FAILURE	02-JUL-2021					
	Notes (AVG MAN HRS: 50.5) (UPDATE NOTE: SB 604-22-007 R1 "SPECIAL CHECK / MODIFICATION - YAW DAMPER SYSTEM - AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS) WIRING CHANGE TO PREVENT UN-COMMANDED YAW DAMPER / LINEAR ACTUATOR MOTION AFTER POWER SUPPLY FAILURE." PARTS A AND B. VISUALLY INSPECTED LH AND RH YAW DAMPER LINEAR ACTUATOR P/N'S AND S/N'S. REF DUNCAN WO FFMB LH YAW DAMPER LINEAR ACTUATOR P/N 622-9968-002 S/N 818 RH YAW DAMPER LINEAR ACTUATOR P/N 622-9968-102 S/N 3R30W).SB 604-22-007 R1 "SPECIAL CHECK / MODIFICATION - YAW DAMPER SYSTEM - AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS) WIRING CHANGE TO PREVENT UN-COMMANDED YAW DAMPER / LINEAR ACTUATOR MOTION AFTER POWER SUPPLY FAILURE." PARTS A AND B. VISUALLY	H: 6939.60 L: 3034					
SB 604-23-001 Airframe SB - Open #3027	SPECIAL CHECK - COCKPIT VOICE RECORDER (CVR) - AUDIO LEVELS						
	Notes (AVG MAN HRS: 1)						
SB 604-23-002 Airframe SB - Open #2492	MODIFICATION - THIRD VHF COMMUNICATION SYSTEM (VHF 3) - INSTALLATION						
SB 604-23-002 R1 Airframe SB - Open #2011	MODIFICATION - THIRD VHF COMMUNICATION SYSTEM (VHF 3) - INSTALLATION						
	Notes (AVG MAN HRS: 161)						
SB 604-23-004 Airframe SB - Open #2034	MODIFICATION - VERY HIGH FREQUENCY (VHF) COMMUNICATION SYSTEM - INTRODUCTION OF THE 8.33 KHZ VHF CHANNEL SPACING						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-23-004 R1 Airframe SB - Open #1820	MODIFICATION - VERY HIGH FREQUENCY (VHF) COMMUNICATION SYSTEM - INTRODUCTION OF THE 8.33 KHZ VHF CHANNEL SPACING Notes (AVG MAN HRS: 7.5)						
SB 604-23-005 Airframe SB - Open #303	MODIFICATION - VOICE RECORDING SYSTEM - INSTALL A NEW SOLID-STATE, 120 MINUTE COCKPIT VOICE RECORDER (CVR) SYSTEM						
SB 604-23-005 PART A Airframe SB - Open #3023	MODIFICATION - VOICE RECORDING SYSTEM - INSTALL A NEW SOLID-STATE, 120 MINUTE COCKPIT VOICE RECORDER (CVR) SYSTEM						
SB 604-23-005 PART B Airframe SB - Open #3686	MODIFICATION - VOICE RECORDING SYSTEM - INSTALL A NEW SOLID-STATE, 120 MINUTE COCKPIT VOICE RECORDER (CVR) SYSTEM						
SB 604-23-005 R1 Airframe SB - Open #3238	MODIFICATION - VOICE RECORDING SYSTEM - INSTALL A NEW SOLID-STATE, 120 MINUTE COCKPIT VOICE RECORDER (CVR) SYSTEM						
SB 604-23-005 R1 PART A Airframe SB - Open #2506	MODIFICATION - VOICE RECORDING SYSTEM - INSTALL A NEW SOLID-STATE, 120 MINUTE COCKPIT VOICE RECORDER (CVR) SYSTEM Notes (AVG MAN HRS: 22)						
SB 604-23-005 R1 PART B Airframe SB - Open #22	MODIFICATION - VOICE RECORDING SYSTEM - INSTALL A NEW SOLID-STATE, 120 MINUTE COCKPIT VOICE RECORDER (CVR) SYSTEM Notes (AVG MAN HRS: 1)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-23-006 Airframe SB - Open #967	MODIFICATION - STATIC DISCHARGER - INSTALLATION OF ADDITIONAL WINGLET STATIC DISCHARGER						
	Notes (AVG MAN HRS: 3.5)DECLINED						
SB 604-23-007 Airframe SB - Open #2312	MODIFICATION - GENERAL - IRIDIUM ANTENNA INSTALLATION						
	Notes (NOTE: THIS INFORMATION SHEET IS ISSUED TO INFORM OPERATORS THAT THE SB 604-23-007 WILL ONLY BE MADE AVAILABLE TO OPERATORS WHO HAVE PURCHASED THE SERVICE BULLETIN IN CONJUNCTION WITH THE IRIDIUM SYSTEM AS PART OF THE AIRCRAFT INTERIOR COMPLETION SUPPLEMENTAL TYPE CERTIFICATE (STC) . THIS SERVICE BULLETIN WILL NO LONGER BE MADE AVAILABLE, BUT BY REQUEST ONLY THROUGH THE STC.)DECLINED						
SB 604-23-011 Airframe SB - N/A #2894	MODIFICATION - DE-ACTIVATION OF THE ACTIVE NOISE AND VIBRATION CONTROL SYSTEM (ANVC)					13-FEB-2017 H: 5969.40 L: 2571	
	Notes (AVG MAN HRS: 4).TO AIRCRAFT S/N						
SB 604-23-012 Airframe SB - N/A #2181	MODIFICATION - REMOVAL OF THE ACTIVE NOISE AND VIBRATION CONTROL SYSTEM (ANVC)					13-FEB-2017 H: 5969.40 L: 2571	
	Notes (AVG MAN HRS: 150).TO AIRCRAFT S/N						
SB 604-23-013 Airframe SB - Superseded #128	MODIFICATION - SATELLITE COMMUNICATION SYSTEM (SATCOM) - INSTALLATION OF THE FUTURE AIR NAVIGATION SYSTEM (FANS) AND TRUE NORTH IRIDIUM SATELLITE COMMUNICATION SYSTEM						
	Notes (AVG MAN HRS: 235) (NOTE: CONTROLLED EFFECTIVITY NOTE: THIS SERVICE BULLETIN IS IN REFERENCE TO ADVISORY WIRE AW600-23-2447, REV 03. 2. WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATEST, MUST BE USED: - BOMBARDIER AEROSPACE, AIRPLANE FLIGHT MANUAL SUPPLEMENT, BAS63045019, REVISION NC.).SEE REVISION 1.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-23-013 R1 Airframe SB - Open #102	MODIFICATION - SATELLITE COMMUNICATION SYSTEM (SATCOM) - INSTALLATION OF THE FUTURE AIR NAVIGATION SYSTEM (FANS) AND TRUE NORTH IRIDIUM SATELLITE COMMUNICATION SYSTEM						
	Notes (AVG MAN HRS: 235) (NOTE: CONTROLLED EFFECTIVITY NOTE: THIS SERVICE BULLETIN IS IN REFERENCE TO ADVISORY WIRE AW600-23-2447, REV 03. 2. WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATEST, MUST BE USED: - BOMBARDIER AEROSPACE, AIRPLANE FLIGHT MANUAL SUPPLEMENT, BAS63045019, REVISION NC.)DECLINED						
SB 604-23-013 R2 Airframe SB - Open #2069	MODIFICATION - SATELLITE COMMUNICATION SYSTEM (SATCOM) - INSTALLATION OF THE FUTURE AIR NAVIGATION SYSTEM (FANS) AND TRUE NORTH IRIDIUM SATELLITE COMMUNICATION SYSTEM						
	Notes (AVG MAN HRS: 235) (NOTE: CONTROLLED EFFECTIVITY PREREQUISITE SERVICE BULLETINS NOTE: THIS SERVICE BULLETIN IS IN REFERENCE TO ADVISORY WIRE AW600-23-2447, REV 03. 3. WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATEST, MUST BE USED: - BOMBARDIER AEROSPACE, AIRPLANE FLIGHT MANUAL SUPPLEMENT, BAS63045019, REVISION NC.)						
SB 604-23-013 R3 Airframe SB - Open #3195	MODIFICATION - SATELLITE COMMUNICATION SYSTEM (SATCOM) - INSTALLATION OF THE FUTURE AIR NAVIGATION SYSTEM (FANS) AND TRUE NORTH IRIDIUM SATELLITE COMMUNICATION SYSTEM						
	Notes (AVG MAN HRS: 235) (NOTE: CONTROLLED EFFECTIVITY PREREQUISITE SERVICE BULLETINS NOTE: THIS SERVICE BULLETIN IS IN REFERENCE TO ADVISORY WIRE AW600-23-2447, REV 03. 3. WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATEST, MUST BE USED: - BOMBARDIER AEROSPACE, AIRPLANE FLIGHT MANUAL SUPPLEMENT, BAS63045019, REVISION NC.)						
SB 604-23-014 Airframe SB - Superseded #2439	MODIFICATION - SATELLITE COMMUNICATION SYSTEM (SATCOM) - INSTALLATION OF THE FUTURE AIR NAVIGATION SYSTEM (FANS) AND ICS-220A IRIDIUM SATELLITE COMMUNICATION SYSTEM						
	Notes (AVG MAN HRS: 235) (NOTE: CONTROLLED EFFECTIVITY NOTE: THIS SERVICE BULLETIN IS IN REFERENCE TO ADVISORY WIRE AW600-23-2447, REV 03. 2. WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUE THAT FOLLOWS OR LATEST, MUST BE USED: - BOMBARDIER AEROSPACE, AIRPLANE FLIGHT MANUAL SUPPLEMENT, BAS63045019, REVISION NC.)SEE REVISION 1.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-23-014 R1 Airframe SB - Open #2963	MODIFICATION - SATELLITE COMMUNICATION SYSTEM (SATCOM) - INSTALLATION OF THE FUTURE AIR NAVIGATION SYSTEM (FANS) AND ICS-220A IRIDIUM SATELLITE COMMUNICATION SYSTEM						
	Notes (AVG MAN HRS: 235) (NOTE: CONTROLLED EFFECTIVITY NOTE: THIS SERVICE BULLETIN IS IN REFERENCE TO ADVISORY WIRE AW600-23-2447, REV 03. 2. WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUE THAT FOLLOWS OR LATEST, MUST BE USED: - BOMBARDIER AEROSPACE, AIRPLANE FLIGHT MANUAL SUPPLEMENT, BAS63045019, REVISION NC.)DECLINED						
SB 604-23-014 R2 Airframe SB - Open #2577	MODIFICATION - SATELLITE COMMUNICATION SYSTEM (SATCOM) - INSTALLATION OF THE FUTURE AIR NAVIGATION SYSTEM (FANS) AND ICS-220A IRIDIUM SATELLITE COMMUNICATION SYSTEM						
	Notes (AVG MAN HRS: 235) (NOTE: CONTROLLED EFFECTIVITY NOTE: 1. THIS SERVICE BULLETIN IS IN REFERENCE TO ADVISORY WIRE AW600-23-2447, REV 03. 2. WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUE THAT FOLLOWS OR LATEST, MUST BE USED: - BOMBARDIER AEROSPACE, AIRPLANE FLIGHT MANUAL SUPPLEMENT, BAS63045019, REVISION NC.)						
SB 604-23-014 R3 Airframe SB - Open #1561	MODIFICATION - SATELLITE COMMUNICATION SYSTEM (SATCOM) - INSTALLATION OF THE FUTURE AIR NAVIGATION SYSTEM (FANS) AND ICS-220A IRIDIUM SATELLITE COMMUNICATION SYSTEM						
	Notes (AVG MAN HRS: 235) (NOTE: CONTROLLED EFFECTIVITY PREREQUISITE SERVICE BULLETINS NOTE: 1. THIS SERVICE BULLETIN IS IN REFERENCE TO ADVISORY WIRE AW600-23-2447, REV 03. 2. WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUE THAT FOLLOWS OR LATEST, MUST BE USED: - BOMBARDIER AEROSPACE, AIRPLANE FLIGHT MANUAL SUPPLEMENT, BAS63045019, REVISION NC.)						
SB 604-23-014 R4 Airframe SB - Open #2783	MODIFICATION - SATELLITE COMMUNICATION SYSTEM (SATCOM) - INSTALLATION OF THE FUTURE AIR NAVIGATION SYSTEM (FANS) AND ICS-220A IRIDIUM SATELLITE COMMUNICATION SYSTEM						
	Notes (AVG MAN HRS: 235) (NOTE: EFFECTIVITY: REFER CESB INFORMATION SHEET ATTACHED TO FOR AUTHORIZED AIRCRAFT SERIAL NUMBERS. PREREQUISITE: SEE NOTE 4 IN PARAGRAPH 1, PLANNING INFORMATION.)						
SB 604-23-016 Airframe SB - Open #1792	MODIFICATION - COCKPIT VOICE RECORDER (CVR) SYSTEM - INSTALLATION OF RECORDER INDEPENDENT POWER SUPPLY (RIPS) FOR CVR						
	Notes (AVG MAN HRS: 3) (NOTE: EFFECTIVITY: CL-600-2B16 AIRCRAFT, SERIAL NO. 5301 TO 5494 POST SB 604-23-005, AND 5495 TO 5665.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-24-001 Airframe SB - Open #1878	MODIFICATION - AIRCRAFT AIR DRIVEN GENERATOR (ADG) - ADDITION OF A TIME DELAY RELAY						
SB 604-24-001 R1 Airframe SB - N/A #1703	MODIFICATION - AIRCRAFT AIR DRIVEN GENERATOR (ADG) - ADDITION OF A TIME DELAY RELAY	13-FEB-2017					H: 5969.40 L: 2571
	Notes (AVG MAN HRS: 35) (NOTE: THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT THAT HAVE DONE THIS MODIFICATION WITH THE ORIGINAL ISSUE OF THIS SERVICE BULLETIN: (1) DO THE TESTING AS GIVEN IN PARAGRAPH 2.C.).TO AIRCRAFT S/N						
SB 604-24-002 Airframe SB - Open #2054	MODIFICATION - DC ELECTRICAL LOAD DISTRIBUTION SYSTEM - FLIGHT MANAGEMENT SYSTEM (FMS) POWER SOURCE CHANGE TO DC BATTERY BUS						
	Notes (AVG MAN HRS: 30)						
SB 604-24-003 Airframe SB - Complied With #1952	MODIFICATION - BATTERY SYSTEM - ADDITION OF PROTECTIVE RESISTORS	17-NOV-1999					H: 477.00 L: 185
	Notes (AVG MAN HRS: 2.5) (NOTE: THIS SERVICE BULLETIN IS NOT NECESSARY FOR AIRCRAFT THAT HAVE AN APU BATTERY, PART NO. 600-59151-11, AND A MAIN BATTERY, PART NO. 601R59041-3, INSTALLED.)						
SB 604-24-004 Airframe SB - Complied With #2188	MODIFICATION - BATTERY SYSTEM - INSTALLATION OF BATTERY CHARGER OUTPUT PROTECTION	11-SEP-2000					H: 674.00 L: 257
SB 604-24-004 PART B Airframe SB - Open #1195	MODIFICATION - BATTERY SYSTEM - INSTALLATION OF BATTERY CHARGER OUTPUT PROTECTION						
	Notes (AVG MAN HRS: 1)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-24-004 PART A Airframe SB - Open #3454	MODIFICATION - BATTERY SYSTEM - INSTALLATION OF BATTERY CHARGER OUTPUT PROTECTION Notes (AVG MAN HRS: 8)						
SB 604-24-005 Airframe SB - Complied With #3546	MODIFICATION - BATTERY SYSTEM - ADDITION OF A WATER SHIELD OVER BATTERY SYSTEM CHARGERS	25-MAR-2001					H: 807.00 L: 307
SB 604-24-005 R1 Airframe SB - Open #2943	MODIFICATION - BATTERY SYSTEM - ADDITION OF A WATER SHIELD OVER BATTERY SYSTEM CHARGERS Notes (AVG MAN HRS: 6) (NOTE: RETROACTIVE ACTION FOR AIRCRAFT THAT HAVE DONE THE BASIC ISSUE OF THIS SERVICE BULLETIN AND THOSE AIRCRAFT THAT HAVE BEEN MODIFIED TO MEET THE INTENT OF THIS SERVICE BULLETIN BY RNIEO (REFER TO PARAGRAPH 1.C., NOTE 1), IT IS RECOMMENDED THAT THE ACTIONS THAT FOLLOW ARE DONE SO THAT THE GENERATOR HARNESS DOES NOT RUB ON THE WATER SHIELD: (1) REMOVE THE APU AND MAIN BATTERY CHARGERS. REFER TO TASK 24-32-07-000-801. (2) INSTALL THE STANDOFF, PART NO. WSI-332A-15NHW (OR B0204037AL-15W), ON THE WATER SHIELD WITH TWO RIVETS, PART NO. MS20470AD4-5A AS GIVEN IN KIT DRAWING K604-53076, ZONE 4C, DETAIL A. (3) INSTALL THE APU AND MAIN BATTERY CHARGERS. REFER TO TASK 24-						
SB 604-24-006 Airframe SB - Open #322	MODIFICATION - INTEGRATED DRIVE GENERATOR (IDG) SYSTEM - PROTECTION OF IDG HARNESS INSIDE PYLON						
SB 604-24-006 R1 Airframe SB - Complied With #987	MODIFICATION - INTEGRATED DRIVE GENERATOR (IDG) SYSTEM - PROTECTION OF IDG HARNESS INSIDE PYLON Notes (AVG MAN HRS: 7)	11-SEP-2000					H: 674.00 L: 257



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-24-006 R1 Airframe SB - Complied With #2857	MODIFICATION-INTEGRATED DRIVE GENERATOR (IDG) SYSTEM-PROTECTION OF IDG HARNES INSIDE PYLON	11-SEP-2000 H: 674.00 L: 257					
	Notes B(2) LEFT						
SB 604-24-006 R1 Airframe SB - Complied With #126	MODIFICATION-INTEGRATED DRIVE GENERATOR (IDG) SYSTEM-PROTECTION OF IDG HARNES INSIDE PYLON.	11-SEP-2000 H: 674.00 L: 257					
	Notes B(2) RIGHT						
SB 604-24-006 R1 Airframe SB - Complied With #1249	MODIFICATION-INTEGRATED DRIVE GENERATOR (IDG) SYSTEM-PROTECTION OF IDG HARNES INSIDE PYLON.	11-SEP-2000 H: 674.00 L: 257					
	Notes B(1) LEFT						
SB 604-24-010 PART B Airframe SB - N/A #904	REWORK - INTEGRATED DRIVE GENERATOR (IDG) SYSTEM AND AUXILIARY AC GENERATION SYSTEM - REPLACEMENT OF FAULTILY MANUFACTURED IDG AND APU GENERATORS	28-NOV-2002					
	Notes (AVG MAN HRS: 8).BY EFFECTIVITY						
SB 604-24-010 PART C Airframe SB - N/A #2449	REWORK - INTEGRATED DRIVE GENERATOR (IDG) SYSTEM AND AUXILIARY AC GENERATION SYSTEM - REPLACEMENT OF FAULTILY MANUFACTURED IDG AND APU GENERATORS	28-NOV-2002					
	Notes (AVG MAN HRS: 3).BY EFFECTIVITY						
SB 604-24-010 PART A Airframe SB - Complied With #2970	SPECIAL CHECK - INTEGRATED DRIVE GENERATOR (IDG) SYSTEM AND AUXILIARY AC GENERATION SYSTEM - REPLACEMENT OF FAULTILY MANUFACTURED IDG AND APU GENERATORS	24-MAY-2005 H: 2522.30 L: 983					
	Notes (AVG MAN HRS: 1).NO FURTHER ACTION REQUIRED						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-24-010 Airframe SB - Open #2667	SPECIAL CHECK/REWORK - INTEGRATED DRIVE GENERATOR (IDG) SYSTEM AND AUXILIARY AC GENERATION SYSTEM - REPLACEMENT OF FAULTILY MANUFACTURED IDG AND APU GENERATORS Notes (NOTE: COMPLIANCE IT IS RECOMMENDED THAT THE SPECIAL CHECK/REWORK IS DONE IN LESS THAN 1200 FLIGHT HRS FROM UNIT INITIAL INSTALLATION.)						
SB 604-24-011 Airframe SB - Open #1019	CANCELLED PRIOR TO ISSUE						
SB 604-24-012 Airframe SB - N/A #3521	SPECIAL CHECK/REWORK - AC ELECTRICAL POWER DISTRIBUTION - CHECK FOR PROPER INSTALLATION OF TERMINAL LUGS ON RELAY K2XD Notes (AVG MAN HRS: 4).TO AIRCRAFT S/N	13-FEB-2017					
		H: 5969.40					
		L: 2571					
SB 604-24-013 Airframe SB - N/A #1626	MODIFICATION - JUNCTION BOXES - REPLACEMENT OF THE AC ESS BUS VOLTAGE SENSING RELAY Notes .TO AIRCRAFT S/N	13-FEB-2017					
		H: 5969.40					
		L: 2571					
SB 604-24-013 R1 Airframe SB - N/A #1668	MODIFICATION - JUNCTION BOXES - REPLACEMENT OF THE AC ESS BUS VOLTAGE SENSING RELAY Notes (AVG MAN HRS: 1.5).TO AIRCRAFT S/N	13-FEB-2017					
		H: 5969.40					
		L: 2571					
SB 604-24-014 PART C Airframe SB - Open #2611	SPECIAL CHECK/IDENTIFICATION OF THE ADG Notes (AVG MAN HRS: 1.5)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-24-014 Airframe SB - N/A #889	SPECIAL CHECK/REWORK - EMERGENCY AC GENERATION SYSTEM - REWORK AIR DRIVEN GENERATOR (ADG) AND TEST AIRCRAFT INTERFACE HARNESS	13-FEB-2017 H: 5969.40 L: 2571					
	Notes .TO AIRCRAFT S/N						
SB 604-24-014 PART A Airframe SB - Open #2901	SPECIAL CHECK/REWORK - RESISTANCE CHECK ON HARNESS PART NO. 604-57025-5 OR PART NO. 604-57025-951 BETWEEN THE ADG AND ADG GCU						
	Notes (AVG MAN HRS: 8.5)						
SB 604-24-014 PART B Airframe SB - Open #2560	SPECIAL CHECK/REWORK OF THE ADG EXCITER AND THE PMG						
	Notes (AVG MAN HRS: 6)						
SB 604-24-015 Airframe SB - N/A #3349	SPECIAL CHECK/REWORK - GENERAL - CIRCUIT BREAKER PANEL 1 THRU 4 ELECTRICAL TERMINATION UNDERTORQUED	13-FEB-2017 H: 5969.40 L: 2571					
	Notes (AVG MAN HRS: 4).TO AIRCRAFT S/N						
SB 604-24-016 Airframe SB - N/A #3665	MODIFICATION - EMERGENCY AC GENERATION SYSTEM - INTRODUCTION OF THE AIR DRIVEN GENERATOR (ADG) RESTOW PUMP PART NO. 604-90800-21	13-FEB-2017 H: 5969.40 L: 2571					
	Notes .TO AIRCRAFT S/N						
SB 604-24-016 R1 Airframe SB - N/A #1339	MODIFICATION - EMERGENCY AC GENERATION SYSTEM - INTRODUCTION OF THE AIR DRIVEN GENERATOR (ADG) RESTOW PUMP PART NO. 604-90800-21	13-FEB-2017 H: 5969.40 L: 2571					
	Notes (AVG MAN HRS: 3).TO AIRCRAFT S/N						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-24-019 Airframe SB - N/A #1633	MODIFICATION - EMERGENCY AC GENERATION SYSTEM - REIDENTIFICATION OF ADG						
	Notes (AVG MAN HRS: 2).BY EFFECTIVITY						
SB 604-24-020 Airframe SB - Superseded #3679	MODIFICATION - JUNCTION BOXES - APU GENERATOR EXCITER WIRING CHANGE TO PERMIT IDG MMEL RELIEF						
	Notes .SEE REVISION 1.						
SB 604-24-020 R1 Airframe SB - Open #290	MODIFICATION - JUNCTION BOXES - APU GENERATOR EXCITER WIRING CHANGE TO PERMIT IDG MMEL RELIEF						
	Notes (AVG MAN HRS: 12)DECLINED						
SB 604-24-021 Airframe SB - N/A #20	SPECIAL CHECK/MODIFICATION - EMERGENCY AC GENERATION SYSTEM - REPLACE SUSPECT BALANCE SCREWS ON ADG					13-FEB-2017 H: 5969.40 L: 2571	
	Notes (AVG MAN HRS: 9.5).TO AIRCRAFT S/N						
SB 604-24-022 Airframe SB - Superseded #1402	SPECIAL CHECK/REWORK - JUNCTION BOXES - INSPECTION OF JB5 FOR CHAFING CONDITION BETWEEN +28VDC POWER CABLE AND OIL DETECTION PCB WHEN OPTIONAL UTILITY BUS WIRING IS INSTALLED						
	Notes .SEE REVISION 1.						
SB 604-24-022 R1 Airframe SB - Complied With #1928	SPECIAL CHECK/REWORK - JUNCTION BOXES - INSPECTION OF JB5 FOR CHAFING CONDITION BETWEEN +28VDC POWER CABLE AND OIL DETECTION PCB WHEN OPTIONAL UTILITY BUS WIRING IS INSTALLED (SEE SB FOR FULL LIST OF EFFECTIVITY)					26-JUL-2010 H: 3912.80 L: 1666	
	Notes (AVG MAN HRS: 3).IAW THE SB INSPECTED WIRING AND CHIP DETECTOR PCB INSIDE OF JBS PER SB INSTRUCTIONS, NO DEFECTS NOTED AND NO ACTION REQUIRED.						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-24-023 Airframe SB - N/A #2713	MODIFICATION - EMERGENCY AC GENERATION SYSTEM - REPLACE THE AIR DRIVEN GENERATOR (ADG) GENERATOR CONTROL UNIT (GCU)	13-FEB-2017 H: 5969.40 L: 2571					
	Notes (AVG MAN HRS: 1).TO AIRCRAFT S/N						
SB 604-24-024 Airframe SB - Complied With #1331	MODIFICATION - AIR-DRIVEN GENERATOR (ADG) SYSTEM - REPLACEMENT OF ADG POWER FEEDER CABLE	15-APR-2013 H: 4783.30 L: 2064					
	Notes (AVG MAN HRS: 24)						
SB 604-24-026 Airframe SB - Complied With #3427	SPECIAL CHECK/REWORK - INTEGRATED DRIVE GENERATOR (IDG) AND HYDRAULIC SYSTEMS NO.1 AND NO. 2 - AFT EQUIPMENT BAY RIGHT IDG POWER CABLE AND ADJACENT HYDRAULIC LINES SUPPORT BRACKETS	12-APR-2013 H: 4782.30 L: 2063					
SB 604-24-026 R1 Airframe SB - Complied With #1256	SPECIAL CHECK/REWORK - INTEGRATED DRIVE GENERATOR (IDG) AND HYDRAULIC SYSTEMS NO.1 AND NO. 2 - AFT EQUIPMENT BAY RIGHT IDG POWER CABLE AND ADJACENT HYDRAULIC LINES SUPPORT BRACKETS	14-JAN-2016 H: 5673.20 L: 2461					
	Notes (AVG MAN HRS: 20) (NOTE: RETROACTIVE ACTION AIRCRAFT, SERIAL NOS. 5452 AND 5569, THAT ALREADY PERFORMED THE BASIC ISSUE OF THIS SERVICE BULLETIN IN CONJUNCTION WITH SRPSA 30806 OR 27512, DO NOT MEET THE INTENT OF THIS REVISION 01 AND SHOULD INCORPORATE KIT DRAWING K601-85032 IN ORDER TO MEET THE 0.5" MINIMUM CLEARANCE. ALL OTHER AIRCRAFT WHICH HAVE INCORPORATED THE BASIC ISSUE HAVE MET THE INTENT OF THE SERVICE BULLETIN, REVISION 01.).INSPECTED AREA PER FORFORMING REF BOMBARDIER S/B 604-24-026 REV 1, DATED 1-13-14, NO DAMAGE OF WIRES OR CLAMPS						
SB 604-25-001 Airframe SB - Open #1960	MODIFICATION - FERRY FLIGHT KIT - REMOVAL OF THE FERRY FLIGHT KIT						
	Notes (AVG MAN HRS: 13)						
SB 604-25-002 Airframe SB - N/A #556	SPECIAL CHECK/MODIFICATION - PILOT'S AND COPILOT'S SEAT - PREVENT INADVERTENT RESET OF CIRCUIT BREAKER WHEN CREW SEAT IS POSITIONED IN FULL AFT POSITION	13-FEB-2017 H: 5969.40 L: 2571					
	Notes (AVG MAN HRS: 2).TO AIRCRAFT S/N						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-25-003 Airframe SB - Complied With #714	MODIFICATION - FLIGHT COMPARTMENT PANELS - REPLACEMENT OF CAMLOC FASTENERS ON RUDDER PEDAL PROTECTION PANELS	26-MAY-2005 H: 2522.30 L: 983					
	Notes (AVG MAN HRS: 4).NO FURTHER ACTION REQUIRED						
SB 604-25-004 Airframe SB - Open #3232	SPECIAL CHECK/MODIFICATION - EMERGENCY EQUIPMENT - REMOVAL OF ESSEX SMOKE HOOD (PART NO. MR-10008N) AND REPLACEMENT OF PLACARDS						
	Notes (AVG MAN HRS: 2)						
SB 604-25-004 R1 Airframe SB - N/A #1827	SPECIAL CHECK/MODIFICATION - EMERGENCY EQUIPMENT - REMOVAL OF ESSEX SMOKE HOOD (PART NO. MR-10008N) AND REPLACEMENT OF PLACARDS	20-MAY-2024 H: 8412.90 L: 3840					
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: BOMBARDIER SERVICE BULLETIN 604-25-004 REV 1 DATED SEPT 22, 2021 IS NOT APPLICABLE DUE TO NO PART NUMBER MR-10008N SMOKE HOODS INSTALLED ON THE AIRCRAFT.)						
SB 604-26-001 Airframe SB - Open #2972	CANCELLED PRIOR TO ISSUE						
SB 604-26-002 Airframe SB - Superseded #2905	MODIFICATION/INSPECTION - ENGINE FIRE/OVERHEAT DETECTION SYSTEM - IMPROVED HARNES ROUTING FOR JET PIPE SENSING ELEMENT						
	Notes .SEE REVISION 1.						
SB 604-26-002 R1 Airframe SB - Open #525	MODIFICATION/INSPECTION - ENGINE FIRE/OVERHEAT DETECTION SYSTEM - IMPROVED HARNES ROUTING FOR JET PIPE SENSING ELEMENT						
	Notes (AVG MAN HRS: 3)DECLINED						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-26-003 Airframe SB - Open #433	MODIFICATION - ENGINE FIRE / OVERHEAT DETECTION SYSTEM - INTRODUCTION OF FIRE SENSING ELEMENT PART NO. 244-11645 WITH OPTIONAL CONNECTORS						
	Notes (AVG MAN HRS: 8)DECLINED						
SB 604-26-004 PART B Airframe SB - N/A #600	SPECIAL CHECK/MODIFICATION - DETECTION - RESISTANCE TEST AND REPLACEMENT OF COMBUSTION ZONE SENSING ELEMENTS WHERE REQUIRED						
	Notes (AVG MAN HRS: 12).BY SERIAL NUMBER	18-DEC-2008					
		H: 3551.80					
		L: 1484					
SB 604-26-004 Airframe SB - Open #1875	SPECIAL CHECK/MODIFICATION - DETECTION - RESISTANCE TEST AND REPLACEMENT OF COMBUSTION ZONE SENSING ELEMENTS WHERE REQUIRED						
SB 604-26-004 PART A Airframe SB - N/A #1557	SPECIAL CHECK/MODIFICATION - DETECTION - RESISTANCE TEST AND REPLACEMENT OF COMBUSTION ZONE SENSING ELEMENTS WHERE REQUIRED						
	Notes (AVG MAN HRS: 4).BY SERIAL NUMBER	18-DEC-2008					
		H: 3551.80					
		L: 1484					
SB 604-26-006 Airframe SB - Open #2599	MODIFICATION - PORTABLE FIRE EXTINGUISHING SYSTEM - INSTALLATION OF NON-HALON FIRE EXTINGUISHER						
SB 604-26-006 Part D Airframe SB - Open #2408	MODIFICATION - PORTABLE FIRE EXTINGUISHING SYSTEM - INSTALLATION OF NON-HALON FIRE EXTINGUISHER - INSTALLATION OF FIRE EXTINGUISHER IN THE AFT CABIN, AT THE AFT LHS BULKHEAD, AFT LHS STORAGE CABINET, AFT LAVATORY, AND AFT WARDROBE						
	Notes (AVG MAN HRS: 6)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-26-006 Part B Airframe SB - Open #2788	MODIFICATION - PORTABLE FIRE EXTINGUISHING SYSTEM - INSTALLATION OF NON-HALON FIRE EXTINGUISHER - INSTALLATION OF NON-HALON FIRE EXTINGUISHER IN THE COCKPIT						
	Notes (AVG MAN HRS: 1)						
SB 604-26-006 Part C Airframe SB - Open #443	MODIFICATION - PORTABLE FIRE EXTINGUISHING SYSTEM - INSTALLATION OF NON-HALON FIRE EXTINGUISHER - INSTALLATION OF NON-HALON FIRE EXTINGUISHER IN THE FORWARD CABIN, ENTRANCE ENCLOSURE, AND AT THE FWD BULKHEAD						
	Notes (AVG MAN HRS: 4)						
SB 604-26-006 Part E Airframe SB - Open #3276	MODIFICATION - PORTABLE FIRE EXTINGUISHING SYSTEM - INSTALLATION OF NON-HALON FIRE EXTINGUISHER - MODIFICATION OF EMERGENCY EQUIPMENT LOCATION PLACARD						
	Notes (AVG MAN HRS: 1)						
SB 604-26-006 Part A Airframe SB - Open #87	MODIFICATION - PORTABLE FIRE EXTINGUISHING SYSTEM - INSTALLATION OF NON-HALON FIRE EXTINGUISHER - REMOVAL OF HALON FIRE EXTINGUISHER						
	Notes (AVG MAN HRS: 4)						
SB 604-27-001 Airframe SB - Open #2366	MODIFICATION - FLAP SYSTEM - INTRODUCTION OF THE NEW PROXIMITY SWITCH IN BRAKE DETECTOR UNIT (BDU)						
	Notes (AVG MAN HRS: 5)						
SB 604-27-003 Airframe SB - Open #2728	SPECIAL CHECK/REWORK - CONTROL-COLUMN TORQUE-TUBE - SUPPORT BEARINGS AND PITCH DISCONNECT CABLE						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-27-003 PART A Airframe SB - N/A #3038	SPECIAL CHECK/REWORK - CONTROL-COLUMN TORQUE-TUBE - SUPPORT BEARINGS AND PITCH DISCONNECT CABLE	17-MAR-2002 H: 1222.00					
	Notes (AVG MAN HRS: 2).BY SERIAL NUMBER						
SB 604-27-003 PART C Airframe SB - N/A #1743	SPECIAL CHECK/REWORK - CONTROL-COLUMN TORQUE-TUBE - SUPPORT BEARINGS AND PITCH DISCONNECT CABLE	17-MAR-2002 H: 1222.00					
	Notes (AVG MAN HRS: 32).BY SERIAL NUMBER						
SB 604-27-003 PART D Airframe SB - Open #2196	SPECIAL CHECK/REWORK - CONTROL-COLUMN TORQUE-TUBE - SUPPORT BEARINGS AND PITCH DISCONNECT CABLE	15-OCT-1997					
	Notes (AVG MAN HRS: 3)						
SB 604-27-003 PART B Airframe SB - N/A #2122	SPECIAL CHECK/REWORK - CONTROL-COLUMN TORQUE-TUBE - SUPPORT BEARINGS AND PITCH DISCONNECT CABLE						
	Notes (AVG MAN HRS: 2) (NOTE: PART D RECOMMENDED BEFORE THE NEXT FLIGHT, IF NECESSARY AS A RESULT OF PART B.)						
SB 604-27-004 Airframe SB - Complied With #133	SPECIAL CHECK/MODIFICATION - RUDDER CONTROL SYSTEM - RUDDER CONTROL CABLE CLEARANCE	20-NOV-2001 H: 1035.00 L: 398					
	Notes (AVG MAN HRS: 4.5)						
SB 604-27-005 Airframe SB - Complied With #2260	MODIFICATION - STALL PROTECTION SYSTEM - DORMANT FAILURES IN THE STALL PROTECTION COMPUTER	12-MAY-2005 H: 2522.30 L: 983					



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-27-005 R1 Airframe SB - Complied With #3256	MODIFICATION - STALL PROTECTION SYSTEM - DORMANT FAILURES IN THE STALL PROTECTION COMPUTER	12-MAY-2005 H: 2522.30 L: 983					
	Notes .PREVIOUSLY C/W ORIGINAL SB 604-27-005 N/C ON MAY 12/2005 AT ACTT 2522.3 LDGS 983						
SB 604-27-005 R2 Airframe SB - Complied With #905	MODIFICATION - STALL PROTECTION SYSTEM - DORMANT FAILURES IN THE STALL PROTECTION COMPUTER	12-MAY-2005 H: 2522.30 L: 983					
	Notes (AVG MAN HRS: 2).PREVIOUSLY C/W ORIGINAL SB 604-27-005 N/C ON MAY 12/2005 AT ACTT 2522.3 LDGS 983						
SB 604-27-007 Airframe SB - Open #675	SPECIAL CHECK/REWORK - FLAP CONTROL SYSTEM - EXAMINE FLAP HINGE ARM FITTINGS FOR GAPS						
SB 604-27-008 Airframe SB - Open #793	SPECIAL CHECK/REWORK - FLAP CONTROL SYSTEM - EXAMINE FLAP HINGE ARM FITTINGS FOR GAPS						
	Notes (AVG MAN HRS: 22)						
SB 604-27-009 Airframe SB - Open #599	MODIFICATION - ELEVATOR CONTROL SYSTEM - INTRODUCTION OF PITCH FEEL SIMULATOR WITH INCREASED STICK FORCE IN HIGH "G" MANEUVER FOR CAA CERTIFICATION						
	Notes (AVG MAN HRS: 8) (NOTE: EMBODIMENT OF THIS MODIFICATION IS REQUIRED FOR AIRCRAFT OPERATION, UNDER UNITED KINGDOM CIVIL AVIATION AUTHORITY (CAA) REGISTRATION.)						
SB 604-27-012 Airframe SB - Complied With #797	MODIFICATION - ELEVATOR CONTROL SYSTEM - INTRODUCTION OF PITCH FEEL SIMULATORS WITH INCREASED STICK FORCE						
	Notes .PER REV 1						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-27-012 R1 Airframe SB - Complied With #1152	MODIFICATION - ELEVATOR CONTROL SYSTEM - INTRODUCTION OF PITCH FEEL SIMULATORS WITH INCREASED STICK FORCE	23-AUG-2006 H: 2749.80 L: 1084					
	Notes (AVG MAN HRS: 8) (NOTE: RETROACTIVE ACTION THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT ON WHICH THE BASIC ISSUE OF THIS SERVICE BULLETIN WAS DONE AND HAVE PITCH FEEL SIMULATORS (PFS), PART NO. 600-92300-59 (TRW, PART NO. TY1741-51A) INSTALLED. NOTE : IF PFS, PART NO. 600-92300-61 (GOODRICH, PART NO. TY1741-52A) WERE INSTALLED, NO RETROACTIVE ACTION IS NECESSARY. FOR AIRCRAFT THAT HAD NEW PFS WITH ZERO HOURS INSTALLED, THIS RETROACTIVE ACTION MUST BE ACCOMPLISHED IN LESS THAN 2250 FLIGHT HOURS FROM THE INCORPORATION OF THIS SERVICE BULLETIN (BASIC ISSUE). FOR AIRCRAFT THAT HAD REWORKED PFS INSTALLED, THIS RETROACTIVE ACTION MUST BE ACCOMPLISHED IN LESS THAN 2250 FLIGHT HOURS						
SB 604-27-013 Airframe SB - Complied With #2986	MODIFICATION - RUDDER AND TAB - INTRODUCTION OF AN ADJUSTABLE BALANCE SPRING ASSEMBLY FOR THE RUDDER CONTROL SURFACE	12-JUL-2004 H: 2246.30 L: 857					
SB 604-27-013 R1 Airframe SB - Open #3105	MODIFICATION - RUDDER AND TAB - INTRODUCTION OF AN ADJUSTABLE BALANCE SPRING ASSEMBLY FOR THE RUDDER CONTROL SURFACE						
	Notes (AVG MAN HRS: 12)						
SB 604-27-014 Airframe SB - Complied With #3235	MODIFICATION - FLAPS - SERIALIZATION OF FLAP ACTUATOR BEAMS	21-MAY-2005 H: 2522.30 L: 983					
	Notes (AVG MAN HRS: 16) (NOTE: COMPLIANCE RECOMMENDED AT THE NEXT ACCESS TO THE FLAP ACTUATOR BEAMS OR ASSOCIATED BRACKETS. FOR FLAP ACTUATOR BEAMS, PART NO. 600-14250-27, HELD AS SPARE, COMPLIANCE IS RECOMMENDED IN LESS THAN ONE MONTH FROM THIS SERVICE BULLETIN RELEASE DATE.)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-27-015 PART B Airframe SB - Open #3566	SPECIAL CHECK - HORIZONTAL STABILIZER TRIM-ACTUATING SYSTEM - EXAMINE SCREW JACK ON HORIZONTAL STABILIZER FOR SIGNS OF OIL						
	Notes (AVG MAN HRS: 6)						
SB 604-27-015 PART A Airframe SB - Open #3706	SPECIAL CHECK - HORIZONTAL STABILIZER TRIM-ACTUATING SYSTEM - EXAMINE SCREW JACK ON HORIZONTAL STABILIZER FOR SIGNS OF OIL						
	Notes (AVG MAN HRS: 8)						
SB 604-27-015 Airframe SB - Complied With #1075	SPECIAL CHECK - HORIZONTAL STABILIZER TRIM-ACTUATING SYSTEM - EXAMINE SCREW JACK ON HORIZONTAL STABILIZER FOR SIGNS OF OIL						
	Notes (NOTE: THIS SERVICE BULLETIN APPLIES ONLY TO THOSE OPERATORS WHO HAVE PERFORMED EITHER: (A) THE 48 MONTH SCHEDULED MAINTENANCE TASK JOB INSTRUCTION CARD (JIC) TASK 27-40-00-204 PRIOR TO 29 JUNE 2000, OR (B) THE AIRCRAFT MAINTENANCE MANUAL (AMM) TASK 12-20-04-640-817 PRIOR TO 15 OCTOBER 1999.)	12-JUL-2004					
		H: 2246.30					
		L: 857					
SB 604-27-016 Airframe SB - Complied With #836	SPECIAL CHECK/REWORK - RUDDER SYSTEM - ANTI-ROTATION TAB ON RUDDER TRIM SWITCH COULD BE MISSING AND INCORRECT TORQUE APPLIED TO ATACHING NUT						
	Notes (AVG MAN HRS: 2)	18-DEC-2008					
		H: 3551.50					
		L: 1484					
SB 604-27-018 PART B Airframe SB - Open #1913	REWORK - ELEVATOR POWER CONTROL SYSTEM - POSSIBLE FOULING CONDITION BETWEEN THE HYDRAULIC PRESSURE LINES AND THE ELEVATOR POWER CONTROL UNITS (PCUS)						
	Notes (AVG MAN HRS: 20) (NOTE: RECOMMENDED BEFORE THE NEXT FLIGHT IF INSUFFICIENT GAP IS FOUND IN PART A.)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-27-018 PART C Airframe SB - Open #2880	REWORK - ELEVATOR POWER CONTROL SYSTEM - POSSIBLE FOULING CONDITION BETWEEN THE HYDRAULIC PRESSURE LINES AND THE ELEVATOR POWER CONTROL UNITS (PCUS) Notes (AVG MAN HRS: 24) (NOTE: RECOMMENDED BEFORE THE NEXT FLIGHT IF INSUFFICIENT GAP IS FOUND IN PART A AND ONE OR MORE PCUS ARE FOUND DAMAGED IN PART B)						
SB 604-27-018 PART A Airframe SB - Open #2594	SPECIAL CHECK - ELEVATOR POWER CONTROL SYSTEM - POSSIBLE FOULING CONDITION BETWEEN THE HYDRAULIC PRESSURE LINES AND THE ELEVATOR POWER CONTROL UNITS (PCUS) Notes (AVG MAN HRS: 5)						
SB 604-27-018 Airframe SB - Open #382	SPECIAL CHECK/REWORK - ELEVATOR POWER CONTROL SYSTEM - POSSIBLE FOULING CONDITION BETWEEN THE HYDRAULIC PRESSURE LINES AND THE ELEVATOR POWER CONTROL UNITS (PCUS)						
SB 604-27-020 PART D Airframe SB - N/A #541	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - PITCH FEEL SIMULATOR DISCONNECT CHECK AND REPLACEMENT OF BEARING AND LEVER ASSEMBLY Notes .NO ACTION REQUIRED					25-MAR-2010 H: 3793.70 L: 1600	
SB 604-27-020 PART B Airframe SB - Complied With #2125	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - PITCH FEEL SIMULATOR DISCONNECT CHECK AND REPLACEMENT OF BEARING AND LEVER ASSEMBLY					25-JAN-2007 H: 2895.70 L: 1155	
SB 604-27-020 PART A Airframe SB - Complied With #2367	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - PITCH FEEL SIMULATOR DISCONNECT CHECK AND REPLACEMENT OF BEARING AND LEVER ASSEMBLY					25-JAN-2007 H: 2895.70 L: 1155	



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-27-020 Airframe SB - Complied With #2359	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - PITCH FEEL SIMULATOR DISCONNECT CHECK AND REPLACEMENT OF BEARING AND LEVER ASSEMBLY	21-JUN-2005 H: 2522.30 L: 983					
	Notes .FURTHER ACTION REQUIRED						
SB 604-27-020 PART C Airframe SB - Complied With #2487	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - PITCH FEEL SIMULATOR DISCONNECT CHECK AND REPLACEMENT OF BEARING AND LEVER ASSEMBLY	25-JAN-2007 H: 2895.70 L: 1155					
SB 604-27-020 R1 PART A Airframe SB - Complied With #3110	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - PITCH FEEL SIMULATOR DISCONNECT CHECK AND REPLACEMENT OF BEARING AND LEVER ASSEMBLY	25-JAN-2007 H: 2895.70 L: 1155					
SB 604-27-020 R1 PART D Airframe SB - Open #3614	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - PITCH FEEL SIMULATOR DISCONNECT CHECK AND REPLACEMENT OF BEARING AND LEVER ASSEMBLY						
SB 604-27-020 R1 PART C Airframe SB - Open #1365	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - PITCH FEEL SIMULATOR DISCONNECT CHECK AND REPLACEMENT OF BEARING AND LEVER ASSEMBLY	25-JAN-2007 H: 2895.70 L: 1155					
SB 604-27-020 R1 PART B Airframe SB - Open #1685	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - PITCH FEEL SIMULATOR DISCONNECT CHECK AND REPLACEMENT OF BEARING AND LEVER ASSEMBLY						
SB 604-27-020 R1 Airframe SB - Open #695	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SYSTEM - PITCH FEEL SIMULATOR DISCONNECT CHECK AND REPLACEMENT OF BEARING AND LEVER ASSEMBLY						
SB 604-27-021 Airframe SB - Open #1644	SPECIAL CHECK/REWORK - ELEVATOR CONTROL SURFACE SYSTEM - POSSIBILITY OF LOOSE BEARINGS IN THE DOUBLE LEVER ASSEMBLY OF THE ELEVATOR GAIN CHANGER						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-27-022 PART B Airframe SB - Complied With #1413	SPECIAL CHECK - FLAP ACTUATING MECHANISM SYSTEM - OUTBOARD FLAP ACTUATORS WITH NON-CONFORMANT TRUNNION BLOCK ROTATION	31-MAY-2005 H: 2522.30 L: 983					
	Notes .2A-2B - NO FURTHER ACTION REQUIRED						
SB 604-27-022 Airframe SB - Open #961	SPECIAL CHECK/REWORK - FLAP ACTUATING MECHANISM SYSTEM - OUTBOARD FLAP ACTUATORS WITH NON-CONFORMANT TRUNNION BLOCK ROTATION						
	Notes (AVG MAN HRS: 30)						
SB 604-27-024 PART B Airframe SB - Open #3062	REWORK - AILERON, ELEVATOR AND RUDDER POWER CONTROL SYSTEM - REPLACEMENT OF POWER CONTROL UNIT NAS1611 O-RINGS						
	Notes (AVG MAN HRS: 49)						
SB 604-27-024 PART A Airframe SB - Open #403	SPECIAL CHECK - AILERON, ELEVATOR AND RUDDER POWER CONTROL SYSTEM - REPLACEMENT OF POWER CONTROL UNIT NAS1611 O-RINGS						
	Notes (AVG MAN HRS: 10)						
SB 604-27-024 Airframe SB - Complied With #1274	SPECIAL CHECK/REWORK - AILERON, ELEVATOR AND RUDDER POWER CONTROL SYSTEM - REPLACEMENT OF POWER CONTROL UNIT NAS1611 O-RINGS	23-MAY-2005 H: 2522.30 L: 983					
SB 604-27-025 Airframe SB - N/A #806	MODIFICATION - ELEVATOR CONTROL SYSTEM - REPLACE PITCH FEEL SIMULATORS WITH IMPROPERLY STAKED SHEAR PINS	13-FEB-2017 H: 5969.40 L: 2571					
	Notes (AVG MAN HRS: 8).BY AIRCRAFT S/N						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-27-027 Airframe SB - Superseded #1066	MODIFICATION - RUDDER POWER CONTROL SYSTEM - REPLACEMENT OF RUDDER SYSTEM STOP BOLT PART NO. 600-92689-1						
	Notes .SEE REVISION 1.						
SB 604-27-027 R1 Airframe SB - Complied With #834	MODIFICATION - RUDDER POWER CONTROL SYSTEM - REPLACEMENT OF RUDDER SYSTEM STOP BOLT PART NO. 600-92689-1	16-DEC-2008					
	Notes (AVG MAN HRS: 2)	H: 3551.80 L: 1484					
SB 604-27-028 Airframe SB - Open #1602	MODIFICATION - STALL PROTECTION SYSTEM (SPS) - INTRODUCTION OF IMPROVED AOA TRANSDUCER MOUNTING AND SEALING INSTALLATION						
SB 604-27-028 R1 Airframe SB - Superseded #1020	MODIFICATION - STALL PROTECTION SYSTEM (SPS) - INTRODUCTION OF IMPROVED AOA TRANSDUCER MOUNTING AND SEALING INSTALLATION						
	Notes .SEE REVISION 2.						
SB 604-27-028 R2 Airframe SB - Open #2989	MODIFICATION - STALL PROTECTION SYSTEM (SPS) - INTRODUCTION OF IMPROVED AOA TRANSDUCER MOUNTING AND SEALING INSTALLATION						
	Notes (AVG MAN HRS: 18)DECLINED						
SB 604-27-030 Airframe SB - Superseded #1244	SPECIAL CHECK/MODIFICATION - RUDDER TRIM SYSTEM - REPLACEMENT OF RUDDER TRIM SWITCH PART NO. 093112-1-03N						
	Notes .BY SB 604-27-030 REV 1						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-27-030 R1 Airframe SB - Open #312	SPECIAL CHECK/MODIFICATION - RUDDER TRIM SYSTEM - REPLACEMENT OF RUDDER TRIM SWITCH PART NO. 093112-1-03N Notes (AVG MAN HRS: 3)DECLINED						
SB 604-27-031 Airframe SB - Superseded #2243	MODIFICATION - STALL PROTECTION SYSTEM - INTRODUCTION OF A NEW CONFIGURATION ANGLE-OF-ATTACK SENSOR Notes .SEE REVISION 1.						
SB 604-27-031 R1 Airframe SB - Superseded #1760	MODIFICATION - STALL PROTECTION SYSTEM - INTRODUCTION OF A NEW CONFIGURATION ANGLE-OF-ATTACK SENSOR Notes .SEE REVISION 2.						
SB 604-27-031 R2 Airframe SB - Open #679	MODIFICATION - STALL PROTECTION SYSTEM - INTRODUCTION OF A NEW CONFIGURATION ANGLE-OF-ATTACK SENSOR Notes (AVG MAN HRS: 140)DECLINED						
SB 604-27-032 Airframe SB - Superseded #886	MODIFICATION - HORIZONTAL STABILIZER TRIM-ACTUATING SYSTEM - REPLACE THE HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) PART NUMBER 604-92305-3 OR -5 (8454-1 OR 8454-2) WITH PART NUMBER 604-92305-7 (8454-3) Notes .SEE REVISION 1.						
SB 604-27-032 R1 Airframe SB - Superseded #334	MODIFICATION - HORIZONTAL STABILIZER TRIM-ACTUATING SYSTEM - REPLACE THE HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) PART NUMBER 604-92305-3 OR -5 (8454-1 OR 8454-2) WITH PART NUMBER 604-92305-7 (8454-3) Notes .SEE REVISION 2.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-27-032 R2 Airframe SB - Complied With #1362	MODIFICATION - HORIZONTAL STABILIZER TRIM-ACTUATING SYSTEM - REPLACE THE HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) PART NUMBER 604-92305-3 OR -5 (8454-1 OR 8454-2) WITH PART NUMBER 604-92305-7 (8454-3)	23-MAR-2017 H: 5979.10 L: 2576					
	Notes (AVG MAN HRS: 20.5)						
SB 604-27-034 Airframe SB - Complied With #3655	MODIFICATION - HORIZONTAL STABILIZER TRIM-ACTUATING SYSTEM (HSTA) -SERIALIZATION OF THE ACTUATOR PINS AND TRUNNIONS	23-MAR-2017 H: 5979.10 L: 2576					
	Notes (AVG MAN HRS: 20) (NOTE: RECOMMENDED WITHIN 2500 FLIGHT HRS OR 48 MONTHS OR AT THE NEXT HSTA SCHEDULED MAINTENANCE, WHICHEVER COMES FIRST FROM THIS SERVICE BULLETIN RELEASE DATE (BASIC ISSUE) THE INTENT OF THIS SERVICE BULLETIN WAS MET ON THE AIRCRAFT THAT FOLLOW WITH THE SERVICE NON-INCORPORATED ENGINEERING ORDERS (SNIEO) LISTED IN THE TABLE THAT FOLLOWS: SNIEO NUMBER S05, AIRCRAFT NUMBER 5559 SNIEO NUMBER S06, AIRCRAFT NUMBER 5364 SNIEO NUMBER S07, AIRCRAFT NUMBER 5326 SNIEO NUMBER S08, AIRCRAFT NUMBER 5						
SB 604-27-034 R1 Airframe SB - N/A #803	MODIFICATION - HORIZONTAL STABILIZER TRIM-ACTUATING SYSTEM (HSTA) -SERIALIZATION OF THE ACTUATOR PINS AND TRUNNIONS	14-JUL-2022 H: 7631.90 L: 3410					
	Notes (AVG MAN HRS: 21) (UPDATE NOTE: SERVICE BULLETIN 604-27-034 REV. 1, HORIZONTAL STABILIZER TRIM-ACTUATING SYSTEM (HSTA) -SERIALIZATION OF THE ACTUATOR PINS AND TRUNNIONS, NOT APPLICABLE BY INCORPORATION OF BASIC ISSUE OF SERVICE BULLETIN BY DUNCAN AVIATION UNDER WORK ORDER Z6GC, SEE MAINTENANCE ENTRY DATED 23-MAR-2017 FOR DETAILS, NO FURTHER ACTION NECESSARY.) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 2500 FLIGHT HRS OR 48 MONTHS OR AT THE NEXT HSTA SCHEDULED MAINTENANCE, WHICHEVER COMES FIRST FROM THIS SERVICE BULLETIN RELEASE DATE (BASIC ISSUE).)SERVICE BULLETIN 604-27-034 REV. 1, HORIZONTAL STABILIZER TRIM-ACTUATING SYSTEM (HSTA) -SERIALIZATION OF THE ACTUATOR PINS AND TRUNNIONS, NOT APPLICA						
SB 604-27-035 Airframe SB - Superseded #2712	MODIFICATION - FLAP POSITION AND INDICATING SYSTEM - INSTALLATION FOR THE FLAP ON -BOARD RECORDER (FOBR)						
	Notes (AVG MAN HRS: 8).SEE REVISION 1.						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-27-035 R1 Airframe SB - Superseded #1573	MODIFICATION - FLAP POSITION AND INDICATING SYSTEM - INSTALLATION FOR THE FLAP ON -BOARD RECORDER (FOBR)						
	Notes (AVG MAN HRS: 8) (NOTE: NOTE: THE FLAP ON-BOARD RECORDER (FOBR) IS ALSO KNOWN AS THE FLAP SYSTEM ON-BOARD RECORDER (FSOBR).).SEE REVISION 2.						
SB 604-27-035 R2 Airframe SB - Open #125	MODIFICATION - FLAP POSITION AND INDICATING SYSTEM - INSTALLATION FOR THE FLAP ON -BOARD RECORDER (FOBR)						
	Notes (AVG MAN HRS: 8) (NOTE: NOTE: THE FLAP ON-BOARD RECORDER (FOBR) IS ALSO KNOWN AS THE FLAP SYSTEM ON-BOARD RECORDER (FSOBR).)DECLINED						
SB 604-27-035 R3 Airframe SB - Open #1307	MODIFICATION - FLAP POSITION AND INDICATING SYSTEM - INSTALLATION FOR THE FLAP ON -BOARD RECORDER (FOBR)						
	Notes (AVG MAN HRS: 8) (NOTE: NOTE: THE FLAP ON-BOARD RECORDER (FOBR) IS ALSO KNOWN AS THE FLAP SYSTEM ON-BOARD RECORDER (FSOBR).)						
SB 604-27-037 Part B Airframe SB - Open #374	MODIFICATION - REPLACEMENT OF PILOT RUDDER PEDAL BAR ASSY OR PILOT RUDDER PEDAL AND BAR ASSEMBLIES						
	Notes (AVG MAN HRS: 10)						
SB 604-27-037 Part A Airframe SB - Open #602	SPECIAL CHECK - DVI OR EDDY CURRENT INSPECTION OF PILOT'S RUDDER PEDAL TUBES, FOR CRACKS		L: 9000			L: 9000	L: 4998
	Notes (AVG MAN HRS: 10) (NOTE: AIRCRAFT FLIGHT CYCLES (FC) FROM ENTRY IN SERVICE: BELOW 8250 FC NOTE: IF DVI IS PERFORMED.)						
SB 604-27-037 Airframe SB - Open #2928	SPECIAL CHECK/MODIFICATION - RUDDER CONTROL SYSTEM - REPLACE THE PILOT'S RUDDER PEDAL BAR ASSEMBLY OR RUDDER PEDAL ASSEMBLY						
	Notes (AVG MAN HRS: 12)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-27-038 Airframe SB - Open #2412	MODIFICATION - HORIZONTAL STABILIZER TRIM-ACTUATING SYSTEM - REPLACEMENT OF MOTOR CONTROL UNIT (MCU) WITH LONGER FIXATION SCREWS						
	Notes (AVG MAN HRS: 8)						
SB 604-27-039 Airframe SB - Open #2340	SPECIAL CHECK/MODIFICATION - RUDDER CONTROL SYSTEM - INSPECTION OF RUDDER LOAD LIMITER						
	Notes (UPDATE NOTE: SERVICE BULLETIN 604-27-039 DECLINED AT THIS TIME. NO FURTHER ACTION NECESSARY.)DECLINED						
SB 604-27-039 Part C Airframe SB - Open #2889	SPECIAL CHECK/MODIFICATION - RUDDER CONTROL SYSTEM - INSPECTION OF RUDDER LOAD LIMITER - MODIFICATION - REPLACEMENT OF THE RUDDER PCU LOAD LIMITER(S)						
	Notes (AVG MAN HRS: 10) (UPDATE NOTE: SERVICE BULLETIN 604-27-039 DECLINED AT THIS TIME. NO FURTHER ACTION NECESSARY.)DECLINED						
SB 604-27-039 Part B Airframe SB - Open #2596	SPECIAL CHECK/MODIFICATION - RUDDER CONTROL SYSTEM - INSPECTION OF RUDDER LOAD LIMITER - SPECIAL CHECK - ONE TIME VISUAL INSPECTION OF THE RUDDER PCU LOAD LIMITERS						
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: SERVICE BULLETIN 604-27-039 DECLINED AT THIS TIME. NO FURTHER ACTION NECESSARY.) (NOTE: COMPLIANCE: WITHIN 3400 FH FROM THIS SB RELEASE (BASIC ISSUE) RECOMMENDED IN CONJUNCTION WITH TLMC 5-10-40 (27-23-00-101).)DECLINED						
SB 604-27-039 Part A Airframe SB - Open #3158	SPECIAL CHECK/MODIFICATION - RUDDER CONTROL SYSTEM - INSPECTION OF RUDDER LOAD LIMITER - SPECIAL CHECK - TEMPORARY PERIODIC TESTING OF THE RUDDER PCU LOAD LIMITERS						
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: SERVICE BULLETIN 604-27-039 DECLINED AT THIS TIME. NO FURTHER ACTION NECESSARY.) (NOTE: COMPLIANCE: WITHIN 1000 FH FROM THIS SB RELEASE (BASIC ISSUE) RECOMMENDED IN CONJUNCTION WITH TLMC 5-10-40 (27-21-00-101). REPEAT EVERY 800 FH UNTIL ONE-TIME VISUAL INSPECTION IS PERFORMED.)DECLINED						
SB 604-27-039 R1 Airframe SB - Open #2350	SPECIAL CHECK/MODIFICATION - RUDDER CONTROL SYSTEM - INSPECTION OF RUDDER LOAD LIMITER						
	Notes (AVG MAN HRS: 11) (UPDATE NOTE: SERVICE BULLETIN 604-27-039 DECLINED AT THIS TIME. NO FURTHER ACTION NECESSARY.)DECLINED						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-27-039 R1 Part B Airframe SB - Open #1885	SPECIAL CHECK/MODIFICATION - RUDDER CONTROL SYSTEM - INSPECTION OF RUDDER LOAD LIMITER - MODIFICATION - REPLACEMENT OF THE RUDDER PCU LOAD LIMITER(S)						
	Notes (AVG MAN HRS: 10) (UPDATE NOTE: SERVICE BULLETIN 604-27-039 DECLINED AT THIS TIME. NO FURTHER ACTION NECESSARY.) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 2200 FLIGHT HOURS FROM THIS SERVICE BULLETIN RELEASE DATE (BASIC ISSUE).)DECLINED						
SB 604-27-039 R1 Part A Airframe SB - Open #2912	SPECIAL CHECK/MODIFICATION - RUDDER CONTROL SYSTEM - INSPECTION OF RUDDER LOAD LIMITER - SPECIAL CHECK - ONE TIME VISUAL INSPECTION OF THE RUDDER PCU LOAD LIMITERS						
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: SERVICE BULLETIN 604-27-039 DECLINED AT THIS TIME. NO FURTHER ACTION NECESSARY.) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 2200 FLIGHT HOURS FROM THIS SERVICE BULLETIN RELEASE DATE (BASIC ISSUE).)DECLINED						
SB 604-27-040 Airframe SB - Complied With #1888	SPECIAL CHECK - FLAPS - INTRODUCTION OF INITIAL AND REPEAT OPERATIONAL TEST OF THE FLAPS TO VERIFY THE RETRACTION / EXTENSION TIME	31-MAY-2025	H: 400.00			H: 9049.70	H: 354.60
	Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (NOTE: COMPLIANCE: WITHIN 100 FH FROM THIS SERVICE BULLETIN RELEASE DATE (BASIC ISSUE). REPEAT EVERY 400 FH FROM THE INITIAL ACTION.)		H: 8649.70 L: 3986				
SB 604-27-041 Airframe SB - N/A #1240	MODIFICATION - FLAPS - CAP AND STOW THE FLAP SYSTEM ON-BOARD RECORDER (FSOBR) / FLAP ON-BOARD RECORDER (FOBR) HARNESS						
	Notes (AVG MAN HRS: 2)						
SB 604-28-001 Airframe SB - Open #2230	MODIFICATION - FUEL TANK WATER DRAINS - IMPROVED PROTECTIVE FINISH						
	Notes (AVG MAN HRS: 20)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-28-002 PART A Airframe SB - Open #3063	REWORK - AUXILIARY FUEL-TANK VENT-VALVES - REPLACE GASKET, PART NO. 80112-14 Notes (AVG MAN HRS: 10)						
SB 604-28-002 PART B Airframe SB - Open #3602	REWORK - AUXILIARY FUEL-TANK VENT-VALVES - REPLACE GASKET, PART NO. 80112-14 Notes (AVG MAN HRS: 12)						
SB 604-28-002 Airframe SB - N/A #3455	REWORK - AUXILIARY FUEL-TANK VENT-VALVES - REPLACE GASKET, PART NO. 80112-14 Notes .TO AIRCRAFT S/N					13-FEB-2017 H: 5969.40 L: 2571	
SB 604-28-003 Airframe SB - Complied With #3117	MODIFICATION - ENGINE STANDBY AND AUXILIARY POWER UNIT (APU) FUEL FEED SYSTEMS - REPLACEMENT OF FLEXIBLE FUEL HOSES Notes (AVG MAN HRS: 16) (NOTE: RECOMMENDED AT THE NEXT ACCESS IN THE RIGHT MAIN TANK (IF APPLICABLE THE CENTER AUXILIARY TANK ALSO), OR IN LESS THAN 18 MONTHS, WHICHEVER COMES FIRST, FROM THE SERVICE BULLETIN RELEASE DATE.)					11-SEP-2000 H: 674.00 L: 257	
SB 604-28-004 Airframe SB - N/A #1467	SPECIAL CHECK/REWORK - TRANSFER SYSTEM - CHECK-VALVE, PART NO. 601R62296-5 INSTALLATION Notes (AVG MAN HRS: 8).TO AIRCRAFT S/N					13-FEB-2017 H: 5969.40 L: 2571	



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-28-005 PART B Airframe SB - Complied With #1849	MODIFICATION - FUEL FEED SYSTEM - EXAMINE FOR CHAFING ON THE FUEL FEED LINES AND ADD BRACKETS AND CLAMPS	11-SEP-2000 H: 674.00 L: 257					
	Notes (AVG MAN HRS: 14)						
SB 604-28-005 PART A Airframe SB - Complied With #2735	SPECIAL CHECK - FUEL FEED SYSTEM - EXAMINE FOR CHAFING ON THE FUEL FEED LINES AND ADD BRACKETS AND CLAMPS	11-SEP-2000 H: 674.00 L: 257					
	Notes (AVG MAN HRS: 7)						
SB 604-28-005 Airframe SB - Open #509	SPECIAL CHECK/MODIFICATION - FUEL FEED SYSTEM - EXAMINE FOR CHAFING ON THE FUEL FEED LINES AND ADD BRACKETS AND CLAMPS						
SB 604-28-006 Airframe SB - Complied With #2669	MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - INTRODUCTION OF NEW FUEL QUANTITY GAUGING COMPUTER (FQGC) PART NUMBER 736847-4	25-JUN-2005 H: 2522.30 L: 983					
	Notes (AVG MAN HRS: 2).PARTS COMPLETED: 2A-2F FURTHER ACTION REQUIRED: NO						
SB 604-28-007 Airframe SB - Superseded #3351	MODIFICATION - TRANSFER SYSTEM - INCREASE FUEL TRANSFER RATE FROM TAIL FUEL-TANK TO THE AUXILIARY FUEL-TANK						
	Notes .SEE REVISION 1.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-28-007 R1 Airframe SB - Complied With #547	MODIFICATION - TRANSFER SYSTEM - INCREASE FUEL TRANSFER RATE FROM TAIL FUEL-TANK TO THE AUXILIARY FUEL-TANK Notes (AVG MAN HRS: 127) (NOTE: RETROACTIVE ACTION THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT ON WHICH THE BASIC ISSUE OF THIS SERVICE BULLETIN WAS DONE: (1) MAKE SURE TERMINAL LUG FOR WIRE, QB12A20 (AT CB1-M8 END), IS PART NO. MS25036-149 (RED). IF NOT, IT IS TO BE REPLACED. (2) MAKE SURE CONTACT (16 AWG TYPE), PART NO. M39029/1-102, IS INSTALLED IN TB206-9 AT TERMINALS F, G, AND H. ALSO MAKE SURE THAT A 22 AWG FILLER HAS BEEN ADDED INTO EACH CONTACT (16 AWG TYPE) IN ORDER TO ACHIEVE ACCEPTABLE CRIMPING WHEN 22 AWG WIRE IS USED WITH THIS 16 AWG TYPE CONTACT.)	27-JUN-2005 H: 2522.30 L: 983					
SB 604-28-008 Airframe SB - Complied With #2351	SPECIAL CHECK - TAIL TANKS - ADDITION OF OBSTRUCTION AND PRESSURE TEST OF THE MANIFOLD-TO-SADDLE TANK TRANSFER SHROUDS AND DRAINS Notes (AVG MAN HRS: 24)	12-JUL-2004 H: 2246.30 L: 857					
SB 604-28-009 Airframe SB - N/A #1423	SPECIAL CHECK - AUXILIARY POWER UNIT (APU) FUEL FEED SYSTEM - POSSIBLE OMISSION OF DRAINAGE PROVISIONS ON FUEL LINE BULKHEAD FITTINGS AT FS 559.00 AND FS 621.00 Notes (AVG MAN HRS: 16).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-28-010 Airframe SB - N/A #1967	MODIFICATION - MAIN AND CENTER FUEL TANKS - IMPROVED PROTECTIVE FINISH AROUND EACH FUEL TANK WATER DRAIN VALVE Notes (AVG MAN HRS: 37).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-28-011 PART C Airframe SB - Complied With #794	REWORK - ENGINE FUEL FEED SYSTEM - POSSIBLE CHAFING CONDITION BETWEEN THE MAIN FUEL FEED LINE/SHROUD ASSEMBLIES AND THE ADJACENT RETURN HYDRAULIC HOSES	03-AUG-2005 H: 2522.30 L: 983					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-28-011 PART B Airframe SB - Complied With #2208	SPECIAL CHECK - ENGINE FUEL FEED SYSTEM - POSSIBLE CHAFING CONDITION BETWEEN THE MAIN FUEL FEED LINE/SHROUD ASSEMBLIES AND THE ADJACENT RETURN HYDRAULIC HOSES	03-AUG-2005 H: 2522.30 L: 983					
SB 604-28-011 Airframe SB - Open #2283	SPECIAL CHECK/REWORK - ENGINE FUEL FEED SYSTEM - POSSIBLE CHAFING CONDITION BETWEEN THE MAIN ENGINE FUEL FEED LINE/SHROUD ASSEMBLIES AND THE ADJACENT RETURN HYDRAULIC HOSES						
Notes (AVG MAN HRS: 6)							
SB 604-28-012 Airframe SB - N/A #155	SPECIAL CHECK/MODIFICATION - AUXILIARY POWER UNIT (APU) FUEL FEED SYSTEM - VERIFY THE INSTALLATION OF THE APU FUEL FEED LINE SHROUD	13-FEB-2017 H: 5969.40 L: 2571					
Notes (AVG MAN HRS: 5).TO AIRCRAFT S/N							
SB 604-28-013 PART B Airframe SB - Open #2112	MODIFICATION - TAIL TANKS - TAIL TANK TRANSFER SHUTOFF-VALVE AND TAIL TANK REFUEL/DEFUEL SHUTOFF-VALVE						
Notes (AVG MAN HRS: 4)							
SB 604-28-013 PART A Airframe SB - Open #1981	SPECIAL CHECK - TAIL TANKS - TAIL TANK TRANSFER SHUTOFF-VALVE AND TAIL TANK REFUEL/DEFUEL SHUTOFF-VALVE						
Notes (AVG MAN HRS: 1)							
SB 604-28-013 Airframe SB - N/A #3366	SPECIAL CHECK/MODIFICATION - TAIL TANKS - TAIL TANK TRANSFER SHUTOFF-VALVE AND TAIL TANK REFUEL/DEFUEL SHUTOFF-VALVE	13-SEP-2005					
Notes .BY SERIAL NUMBER							



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-28-014 PART B Airframe SB - Complied With #2763	SPECIAL CHECK - VENT SYSTEM - TORQUE CHECK OF THE VENT LINE FITTING ATTACHMENT INSTALLED ON COUPLING ASSEMBLIES, PART NO. FC511-16AE, LOCATED IN THE SADDLE FUEL TANK AND TAIL FUEL TANK VENT SYSTEMS	03-JUN-2009 H: 3637.60 L: 1526					
	Notes (AVG MAN HRS: 1)						
SB 604-28-014 PART A Airframe SB - Complied With #3506	SPECIAL CHECK - VENT SYSTEM - TORQUE CHECK OF THE VENT LINE FITTING ATTACHMENT INSTALLED ON COUPLING ASSEMBLIES, PART NO. FC511-16AE, LOCATED IN THE SADDLE FUEL TANK AND TAIL FUEL TANK VENT SYSTEMS	03-JUN-2009 H: 3637.60 L: 1526					
	Notes (AVG MAN HRS: 1)						
SB 604-28-014 Airframe SB - Open #1456	SPECIAL CHECK - VENT SYSTEM - TORQUE CHECK OF THE VENT LINE FITTING ATTACHMENT INSTALLED ON COUPLING ASSEMBLIES, PART NO. FC511-16AE, LOCATED IN THE SADDLE FUEL TANK AND TAIL FUEL TANK VENT SYSTEMS						
SB 604-28-015 PART D Airframe SB - Open #1399	MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - TAIL TANK WIRING CLAMPS AND FUEL LEVEL SENSOR CONNECTORS REPLACEMENT						
SB 604-28-015 PART A Airframe SB - Open #15	MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - TAIL TANK WIRING CLAMPS AND FUEL LEVEL SENSOR CONNECTORS REPLACEMENT						
SB 604-28-015 PART C Airframe SB - Open #883	MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - TAIL TANK WIRING CLAMPS AND FUEL LEVEL SENSOR CONNECTORS REPLACEMENT						
SB 604-28-015 PART E Airframe SB - Open #3694	MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - TAIL TANK WIRING CLAMPS AND FUEL LEVEL SENSOR CONNECTORS REPLACEMENT						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-28-015 PART B Airframe SB - Open #2386	MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - TAIL TANK WIRING CLAMPS AND FUEL LEVEL SENSOR CONNECTORS REPLACEMENT						
SB 604-28-015 Airframe SB - Complied With #3057	MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - TAIL TANK WIRING CLAMPS AND FUEL LEVEL SENSOR CONNECTORS REPLACEMENT						
	Notes .SEE REVISION 1 FOR COMPLIANCE						
SB 604-28-015 R1 PART A Airframe SB - Complied With #2790	MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - TAIL TANK WIRING CLAMPS AND FUEL LEVEL SENSOR CONNECTORS REPLACEMENT	03-JUN-2009					
	Notes (AVG MAN HRS: 9)	H: 3637.60 L: 1526					
SB 604-28-015 R1 PART B Airframe SB - Complied With #1426	MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - TAIL TANK WIRING CLAMPS AND FUEL LEVEL SENSOR CONNECTORS REPLACEMENT	03-JUN-2009					
	Notes (AVG MAN HRS: 3)	H: 3637.60 L: 1526					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
--------------------	-------------	------------	-----------	-----------	---------	----------	-----------

SB 604-28-015 R1
Airframe
SB - Open
#1357

MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - TAIL TANK WIRING CLAMPS AND FUEL LEVEL SENSOR CONNECTORS REPLACEMENT

Notes

(NOTE: THE MODIFICATION OF THE FUEL LEVEL SENSOR CONNECTORS HAVE ALREADY BEEN DONE BY SRPSA ON THE AIRCRAFT IDENTIFIED IN THE TABLE THAT FOLLOWS AND ALREADY MEET THE INTENT OF THIS SERVICE BULLETIN:

TABLE 1
AIRCRAFT SERIAL NO. SRPSA

- 5342 82912
- 5355 85805
- 5363 80637
- 5445, 5542 86503
- 5619 68638
- 5620 68639
- 5621 68640
- 5622 68641
- 5623 68642
- 5624 68645
- 5625 68646
- 5627 68647
- 5631 68648
- 5632 68649
- 5633 74804
- 5637 74865
- 5638 74870
- 5640 74872
- 5641 74873
- 5642 74879
- 5643 74880
- 5645 68643
- 5646 74882
- 5647 68644

THE MODIFICATION OF THE TAIL TANK WIRING CLAMPS, HAVE ALREADY BEEN DONE BY SRPSA ON THE AIRCRAFT IDENTIFIED IN THE TAB

SB 604-28-015 R1
PART D
Airframe
SB - Complied With
#1452

MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - TAIL TANK WIRING CLAMPS AND FUEL LEVEL SENSOR CONNECTORS REPLACEMENT

03-JUN-2009
H: 3637.60
L: 1526

Notes

(AVG MAN HRS: 8)



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-28-015 R1 PART C Airframe SB - Complied With #1642	MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - TAIL TANK WIRING CLAMPS AND FUEL LEVEL SENSOR CONNECTORS REPLACEMENT	03-JUN-2009 H: 3637.60 L: 1526					
	Notes (AVG MAN HRS: 3)						
SB 604-28-015 R1 PART E Airframe SB - Complied With #2248	MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - TAIL TANK WIRING CLAMPS AND FUEL LEVEL SENSOR CONNECTORS REPLACEMENT	04-JUN-2009 H: 3637.60 L: 1526					
	Notes (AVG MAN HRS: 2)						
SB 604-28-016 Airframe SB - Superseded #2097	MODIFICATION - VENT SYSTEM ENHANCEMENT						
	Notes .SEE REVISION 1.						
SB 604-28-016 R1 Airframe SB - Open #2338	MODIFICATION - VENT SYSTEM ENHANCEMENT						
	Notes (AVG MAN HRS: 24)DECLINED						
SB 604-28-017 Airframe SB - Open #3072	MODIFICATION - FUEL QUANTITY INDICATING SYSTEM - REPLACE THE FUEL QUANTITY GAUGING COMPUTER (FQGC) PART NUMBER 736847-16 WITH PART NUMBER 736847-17						
	Notes (AVG MAN HRS: 1)DECLINED						
SB 604-28-018 Airframe SB - Superseded #3171	SPECIAL CHECK/REWORK - PRESSURE REFUEL/DEFUEL SYSTEM - REFUEL/DEFUEL DRAIN LINE IN THE RIGHT LIGHT COMPARTMENT						
	Notes .SEE REVISION 1.						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-28-018 R1 Airframe SB - Open #2802	SPECIAL CHECK/REWORK - PRESSURE REFUEL/DEFUEL SYSTEM - REFUEL/DEFUEL DRAIN LINE IN THE RIGHT LIGHT COMPARTMENT						
	Notes (AVG MAN HRS: 2)						
SB 604-28-019 Airframe SB - N/A #937	SPECIAL CHECK/MODIFICATION - MOTIVE FLOW SYSTEM - COLLECTOR TANK EJECTOR LINE INSIDE OF THE AUXILIARY CENTER FUEL TANKS	23-MAR-2017					
	Notes (AVG MAN HRS: 12) (NOTE: THE AIRCRAFT LISTED IN THE TABLE THAT FOLLOWS ALREADY MEET THE INTENT OF THIS SERVICE BULLETIN, IF THEY WERE MODIFIED IN ACCORDANCE WITH DRAWING 600-62550 AND THE RESPECTIVE SERVICE NON-INCORPORATED ENGINEERING ORDER (SNIEO): AIRCRAFT SERIAL NO. 5614 DRAWING 600-62550 SNIEO NO. S12 AIRCRAFT SERIAL NO. 5466, 5541, 5543, 5586, 5619, 5634, 5647, 5656 DRAWING 600-62550 SNIEO NO. S17 AIRCRAFT SERIAL NO. 5431 DRAWING 600-62550 SNIEO NO. S19).PREVIOUSLY COMPLIED WITH	H: 5979.10 L: 2576					
SB 604-28-020 Airframe SB - Superseded #3549	SPECIAL CHECK/REWORK - FUEL QUANTITY INDICATING SYSTEM - ELECTRICAL HARNESSSES INSTALLATION INSIDE THE MAIN AND CENTER FUEL TANKS						
	Notes .SEE REVISION 1.						
SB 604-28-020 R1 Airframe SB - Superseded #2257	SPECIAL CHECK/REWORK - FUEL QUANTITY INDICATING SYSTEM - ELECTRICAL HARNESSSES INSTALLATION INSIDE THE MAIN AND CENTER FUEL TANKS						
	Notes .SEE REVISION 2.						
SB 604-28-020 R2 Airframe SB - Open #1787	SPECIAL CHECK/REWORK - FUEL QUANTITY INDICATING SYSTEM - ELECTRICAL HARNESSSES INSTALLATION INSIDE THE MAIN AND CENTER FUEL TANKS						
	Notes (AVG MAN HRS: 7) (NOTE: NOTE: DEFUELING AND VENTING OF THE FUEL TANKS MUST BE DONE TO DO THIS SERVICE BULLETIN.)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-28-021 Part B Airframe SB - Open #2153	MODIFICATION - AUXILIARY POWER UNIT (APU) FUEL-FEED SYSTEM - POSSIBLE CHAFING OF THE APU NEGATIVE-G FUEL-FEED DRAIN LINE Notes (AVG MAN HRS: 8)						
SB 604-28-021 Part A Airframe SB - Open #2574	SPECIAL CHECK - AUXILIARY POWER UNIT (APU) FUEL-FEED SYSTEM - POSSIBLE CHAFING OF THE APU NEGATIVE-G FUEL-FEED DRAIN LINE Notes (AVG MAN HRS: 0.5)						
SB 604-28-021 Airframe SB - Complied With #1681	SPECIAL CHECK/MODIFICATION - AUXILIARY POWER UNIT (APU) FUEL-FEED SYSTEM - POSSIBLE CHAFING OF THE APU NEGATIVE-G FUEL-FEED DRAIN LINE Notes .PART A INSP. PART B NOT REQUIRED					18-JAN-2017 H: 5949.70 L: 2567	
SB 604-28-022 Airframe SB - Complied With #1290	SPECIAL CHECK - STANDBY FUEL FEED SYSTEM AND AUXILIARY POWER UNIT (APU) FUEL FEED SYSTEM - ENGINE AND APU ELECTRICAL FUEL PUMP CARTRIDGE/CANISTER FUEL LEAKAGE Notes (AVG MAN HRS: 3)					02-JUL-2021 H: 6939.60 L: 3034	
SB 604-28-022 R1 Airframe SB - Complied With #2647	SPECIAL CHECK - STANDBY FUEL FEED SYSTEM AND AUXILIARY POWER UNIT (APU) FUEL FEED SYSTEM - ENGINE AND APU ELECTRICAL FUEL PUMP CARTRIDGE/CANISTER FUEL LEAKAGE Notes (AVG MAN HRS: 5).NO LEAKS					28-MAR-2018 H: 6319.00 L: 2697	
SB 604-28-022 R2 Airframe SB - Open #1211	SPECIAL CHECK - STANDBY FUEL FEED SYSTEM AND AUXILIARY POWER UNIT (APU) FUEL FEED SYSTEM - ENGINE AND APU ELECTRICAL FUEL PUMP CARTRIDGE/CANISTER FUEL LEAKAGE Notes (AVG MAN HRS: 5)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-28-022 R3 Airframe SB - Complied With #3254	SPECIAL CHECK - STANDBY FUEL FEED SYSTEM AND AUXILIARY POWER UNIT (APU) FUEL FEED SYSTEM - ENGINE AND APU ELECTRICAL FUEL PUMP CARTRIDGE/CANISTER FUEL LEAKAGE	31-JAN-2024 H: 8254.00 L: 3749					
	Notes (AVG MAN HRS: 6) (UPDATE NOTE: C/W SERVICE BULLETIN 604-28-022 REV 3. STANDBY FUEL FEED SYSTEM AND AUXILIARY POWER UNIT (APU) FUEL FEED SYSTEM - ENGINE AND APU ELECTRICAL FUEL PUMP CARTRIDGE/CANISTER FUEL LEAKAGE. NO DEFECTS NOTED. THIS A REOCCURRING INSPECTION 12 MONTHS OR 600 HOURS WHICH EVER COMES FIRST. NEXT DUE IS 1-31-2025 HOURS: 8854.)						
SB 604-28-022 R3 Airframe SB - Complied With #3472	SPECIAL CHECK - STANDBY FUEL FEED SYSTEM AND AUXILIARY POWER UNIT (APU) FUEL FEED SYSTEM - ENGINE AND APU ELECTRICAL FUEL PUMP CARTRIDGE/CANISTER FUEL LEAKAGE	31-JAN-2024 H: 8254.00 L: 3749					
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: C/W SERVICE BULLETIN 604-28-022 REV 3. STANDBY FUEL FEED SYSTEM AND AUXILIARY POWER UNIT (APU) FUEL FEED SYSTEM - ENGINE AND APU ELECTRICAL FUEL PUMP CARTRIDGE/CANISTER FUEL LEAKAGE. NO DEFECTS NOTED. THIS A REOCCURRING INSPECTION 12 MONTHS OR 600 HOURS WHICH EVER COMES FIRST. NEXT DUE IS 1-31-2025 HOURS: 8854.)						
SB 604-28-023 Airframe SB - Open #870	SPECIAL CHECK/REWORK - VENT SYSTEM - VENT TUBE COUPLING SAMPLING						
	Notes (AVG MAN HRS: 8) (NOTE: CONTROLLED EFFECTIVITY)						
SB 604-28-023 R1 Airframe SB - Open #643	SPECIAL CHECK/REWORK - VENT SYSTEM - VENT TUBE COUPLING SAMPLING						
	Notes (AVG MAN HRS: 8) (NOTE: CONTROLLED EFFECTIVITY)						
SB 604-28-024 Airframe SB - Open #3425	MODIFICATION - FUEL SYSTEM - ENGINE AND APU FUEL BOOST PUMP SEALING IMPROVEMENT						
	Notes (AVG MAN HRS: 10) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 5 YEARS FROM THIS SERVICE BULLETIN RELEASE DATE. NOTE: THIS SERVICE BULLETIN MAY BE SUBJECT TO AN AIRWORTHINESS DIRECTIVE WHICH WILL MAKE IT NECESSARY TO IMPLEMENT THIS SERVICE BULLETIN.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-28-024 R1 Airframe SB - Complied With #2536	MODIFICATION - FUEL SYSTEM - ENGINE AND APU FUEL BOOST PUMP SEALING IMPROVEMENT	08-FEB-2023 H: 7925.20 L: 3563					
	Notes (AVG MAN HRS: 10) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 5 YEARS FROM THIS SERVICE BULLETIN RELEASE DATE (BASIC ISSUE).)						
SB 604-29-001 PART B Airframe SB - N/A #2019	REWORK - MAIN LANDING GEAR BAY - HYDRAULIC LINES ROUTING	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (AVG MAN HRS: 19) (UPDATE NOTE: AD NA TO AIRCRAFT SERIAL NUMBER).AD NA TO AIRCRAFT SERIAL NUMBER						
SB 604-29-001 PART A Airframe SB - N/A #2923	SPECIAL CHECK - MAIN LANDING GEAR BAY - HYDRAULIC LINES ROUTING	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: AD NA TO AIRCRAFT SERIAL NUMBER).AD NA TO AIRCRAFT SERIAL NUMBER						
SB 604-29-001 Airframe SB - N/A #1076	SPECIAL CHECK/REWORK - MAIN LANDING GEAR BAY - HYDRAULIC LINES ROUTING	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (UPDATE NOTE: AD NA TO AIRCRAFT SERIAL NUMBER).AD NA TO AIRCRAFT SERIAL NUMBER						
SB 604-29-002 Airframe SB - Open #1067	MODIFICATION - HYDRAULIC PRESSURE HOSE - ENGINE-DRIVEN PUMPS (EDP) - ADDITION OF LOCKWIRE						
	Notes (AVG MAN HRS: 4)						
SB 604-29-003 PART B Airframe SB - Open #2076	SPECIAL CHECK - HYDRAULIC SYSTEMS - FILTER MANIFOLDS, PART NO. 600-75117 AND 601R75118-1G						
	Notes (AVG MAN HRS: 8)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-29-003 Airframe SB - N/A #2206	SPECIAL CHECK - HYDRAULIC SYSTEMS - FILTER MANIFOLDS, PART NO. 600-75117 AND 601R75118-1G						
SB 604-29-003 PART A Airframe SB - Open #3288	SPECIAL CHECK - HYDRAULIC SYSTEMS - FILTER MANIFOLDS, PART NO. 600-75117 AND 601R75118-1G Notes (AVG MAN HRS: 8)						
SB 604-29-004 PART B Airframe SB - Open #2778	REWORK - HYDRAULIC SYSTEM NO. 3 - RETURN MANIFOLD RETURN FITTING - CHECK VALVE, PART NO. CKRX0511500B Notes (AVG MAN HRS: 5)						
SB 604-29-004 PART A Airframe SB - Open #3081	SPECIAL CHECK - HYDRAULIC SYSTEM NO. 3 - RETURN MANIFOLD RETURN FITTING - CHECK VALVE, PART NO. CKRX0511500B Notes (AVG MAN HRS: 1)						
SB 604-29-004 Airframe SB - Complied With #3708	SPECIAL CHECK/REWORK - HYDRAULIC SYSTEM NO. 3 - RETURN MANIFOLD RETURN FITTING - CHECK VALVE, PART NO. CKRX0511500B					30-NOV-1999 H: 488.00 L: 201	
SB 604-29-005 Airframe SB - Complied With #519	MODIFICATION - HYDRAULIC SYSTEM NO. 1 AND NO. 2 - REPLACEMENT OF BRACKETS SECURING HYDRAULIC LINES AT THE HYDRAULIC SYSTEMS SUPPORT STRUCTURE Notes (AVG MAN HRS: 4)					25-MAR-2001 H: 807.00 L: 307	
SB 604-29-006 Airframe SB - Open #1572	MODIFICATION - HYDRAULIC SYSTEM NO. 1 AND NO. 2 - REPLACEMENT OF PRESSURE HOSE ASSEMBLIES AT THE PYLON FIREWALL						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-29-006 PART B Airframe SB - Open #2782	MODIFICATION - HYDRAULIC SYSTEM NO. 1 AND NO. 2 - REPLACEMENT OF PRESSURE HOSE ASSEMBLIES AT THE PYLON FIREWALL						
SB 604-29-006 PART A Airframe SB - Open #2665	MODIFICATION - HYDRAULIC SYSTEM NO. 1 AND NO. 2 - REPLACEMENT OF PRESSURE HOSE ASSEMBLIES AT THE PYLON FIREWALL						
SB 604-29-006 R1 PART B Airframe SB - Open #1589	MODIFICATION - HYDRAULIC SYSTEM NO. 1 AND NO. 2 - REPLACEMENT OF PRESSURE HOSE ASSEMBLIES AT THE PYLON FIREWALL Notes (AVG MAN HRS: 4)						
SB 604-29-006 R1 Airframe SB - Open #140	MODIFICATION - HYDRAULIC SYSTEM NO. 1 AND NO. 2 - REPLACEMENT OF PRESSURE HOSE ASSEMBLIES AT THE PYLON FIREWALL Notes (NOTE: RETROACTIVE ACTION THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT ON WHICH THE BASIC ISSUE OF THIS SERVICE BULLETIN WAS DONE: (1) DO THE SPECIAL CHECK GIVEN IN PART B. (2) DO THE TESTING APPLICABLE TO PART B OF THIS SERVICE BULLETIN.)						
SB 604-29-006 R1 PART A Airframe SB - Open #176	MODIFICATION - HYDRAULIC SYSTEM NO. 1 AND NO. 2 - REPLACEMENT OF PRESSURE HOSE ASSEMBLIES AT THE PYLON FIREWALL Notes (AVG MAN HRS: 16)						
SB 604-29-007 Airframe SB - Open #2610	MODIFICATION - HYDRAULIC SYSTEM NO. 3 - ADDITION OF SPACERS FOR ACCUMULATOR PART NO. 601R75138-3 INSTALLATION Notes (AVG MAN HRS: 3).OPEN RECOMMENDED AT NEXT HYDRAULIC SYSTEM NO.3 ACCUMULATOR CHANGE-OUT. NOTE: THIS MODIFICATION ONLY APPLIES TO THE NEW HYDRAULIC SYSTEM NO.3 ACCUMULATOR, PART NO. 601R75138-3 MANUFACTURED BY YORK.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-29-008 Airframe SB - Superseded #3344	SPECIAL CHECK/REWORK - HYDRAULIC POWER AND LANDING GEAR - INSPECTION AND POSSIBLE REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 FOR PART NOS. 08-60163-001/002 AND 08-60164-001/002 Notes .SEE REVISION 1.(HYD SYS. NO.3)						
SB 604-29-008 Airframe SB - Open #3612	SPECIAL CHECK/REWORK - HYDRAULIC POWER AND LANDING GEAR - INSPECTION AND POSSIBLE REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 FOR PART NOS. 08-60163-001/002 AND 08-60164-001/002						
SB 604-29-008 Airframe SB - N/A #148	SPECIAL CHECK/REWORK - HYDRAULIC POWER AND LANDING GEAR - INSPECTION AND POSSIBLE REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 FOR PART NOS. 08-60163-001/002 AND 08-60164-001/002 Notes .SUPERSEDED BY SB 604-29-008 REV 1(BRAKE NO.2)						
SB 604-29-008 Airframe SB - N/A #70	SPECIAL CHECK/REWORK - HYDRAULIC POWER AND LANDING GEAR - INSPECTION AND POSSIBLE REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 FOR PART NOS. 08-60163-001/002 AND 08-60164-001/002 Notes .SUPERSEDED BY SB 604-29-008 REV 1(BRAKE NO.3)						
SB 604-29-008 Airframe SB - Superseded #1650	SPECIAL CHECK/REWORK - HYDRAULIC POWER AND LANDING GEAR - INSPECTION AND POSSIBLE REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 FOR PART NOS. 08-60163-001/002 AND 08-60164-001/002 Notes .SEE REVISION 1.(HYD SYS. NO.2)						
SB 604-29-008 Airframe SB - Superseded #1490	SPECIAL CHECK/REWORK - HYDRAULIC POWER AND LANDING GEAR - INSPECTION AND POSSIBLE REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 FOR PART NOS. 08-60163-001/002 AND 08-60164-001/002 Notes .SEE REVISION 1.(HYD SYS. NO.1)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-29-008 R1 Airframe SB - Superseded #1279	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002 Notes (AVG MAN HRS: 20).SEE REVISION 2.(NO.3-BRAKE)						
SB 604-29-008 R1 Airframe SB - Superseded #2086	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002 Notes (AVG MAN HRS: 20).SEE REVISION 2.						
SB 604-29-008 R1 Airframe SB - Superseded #542	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002 Notes (AVG MAN HRS: 20).SEE REVISION 2.(NO.1-HYD SYS)						
SB 604-29-008 R1 Airframe SB - Superseded #316	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002 Notes (AVG MAN HRS: 20).SEE REVISION 2.(NO.2-HYD SYS)						
SB 604-29-008 R1 Airframe SB - Superseded #2927	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002 Notes (AVG MAN HRS: 20).SEE REVISION 2.(NO.2-BRAKE)						
SB 604-29-008 R1 Airframe SB - Superseded #2652	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002 Notes (AVG MAN HRS: 20).SEE REVISION 2.(NO.3-HYD SYS)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-29-008 R2 Airframe SB - Complied With #3333	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002	22-JUL-2010 H: 3912.80 L: 1666					
	Notes (AVG MAN HRS: 20).IAW THE SB(NO.3-BRAKE)						
SB 604-29-008 R2 Airframe SB - Complied With #3623	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002	22-JUL-2010 H: 3912.80 L: 1666					
	Notes (AVG MAN HRS: 20).IAW THE SB(NO.1-HYD SYS)						
SB 604-29-008 R2 Airframe SB - Complied With #822	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002	22-JUL-2010 H: 3912.80 L: 1666					
	Notes (AVG MAN HRS: 20).IAW THE SB(NO.2-HYD SYS)						
SB 604-29-008 R2 Airframe SB - Complied With #844	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002	22-JUL-2010 H: 3912.80 L: 1666					
	Notes (AVG MAN HRS: 20).IAW THE SB NO ACTION REQUIRED NO AFFECTED P/N ACCUMULATORS INSTALLED(NO.2-BRAKE)						
SB 604-29-008 R2 Airframe SB - Complied With #761	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002	22-JUL-2010 H: 3912.80 L: 1666					
	Notes (AVG MAN HRS: 20).IAW THE SB(NO.3-HYD SYS)						
SB 604-29-008 R2 Airframe SB - Open #1669	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002						
	Notes (AVG MAN HRS: 20)						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-29-008 R3 Airframe SB - Superseded #1790	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002						
	Notes (AVG MAN HRS: 20) (NOTE: RETROACTIVE ACTION ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND REPLACED THEIR ACCUMULATORS, THIS SERVICE BULLETIN REVISION 03 REMAINS APPLICABLE. ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND HAVE ACCUMULATORS WITH MORE THAN 3650 FLIGHT CYCLES AND HAVE REPLACED THEIR ACCUMULATORS, REVISION 03 OF THIS SERVICE BULLETIN MUST BE INCORPORATED WITHIN THE NEXT 100 FLIGHT CYCLES. ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND HAVE ACCUMULATORS WITH 3650 FLIGHT CYCLES OR LESS AND H						
SB 604-29-008 R3 Airframe SB - Superseded #625	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002						
	Notes (AVG MAN HRS: 20) (NOTE: RETROACTIVE ACTION ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND REPLACED THEIR ACCUMULATORS, THIS SERVICE BULLETIN REVISION 03 REMAINS APPLICABLE. ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND HAVE ACCUMULATORS WITH MORE THAN 3650 FLIGHT CYCLES AND HAVE REPLACED THEIR ACCUMULATORS, REVISION 03 OF THIS SERVICE BULLETIN MUST BE INCORPORATED WITHIN THE NEXT 100 FLIGHT CYCLES. ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND HAVE ACCUMULATORS WITH 3650 FLIGHT CYCLES OR LESS AND H						
SB 604-29-008 R3 Airframe SB - Superseded #998	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002						
	Notes (AVG MAN HRS: 20) (NOTE: RETROACTIVE ACTION ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND REPLACED THEIR ACCUMULATORS, THIS SERVICE BULLETIN REVISION 03 REMAINS APPLICABLE. ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND HAVE ACCUMULATORS WITH MORE THAN 3650 FLIGHT CYCLES AND HAVE REPLACED THEIR ACCUMULATORS, REVISION 03 OF THIS SERVICE BULLETIN MUST BE INCORPORATED WITHIN THE NEXT 100 FLIGHT CYCLES. ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND HAVE ACCUMULATORS WITH 3650 FLIGHT CYCLES OR LESS AND H						

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-29-008 R3 Airframe SB - Superseded #3419	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002						
	Notes (AVG MAN HRS: 20) (NOTE: RETROACTIVE ACTION ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND REPLACED THEIR ACCUMULATORS, THIS SERVICE BULLETIN REVISION 03 REMAINS APPLICABLE. ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND HAVE ACCUMULATORS WITH MORE THAN 3650 FLIGHT CYCLES AND HAVE REPLACED THEIR ACCUMULATORS, REVISION 03 OF THIS SERVICE BULLETIN MUST BE INCORPORATED WITHIN THE NEXT 100 FLIGHT CYCLES. ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND HAVE ACCUMULATORS WITH 3650 FLIGHT CYCLES OR LESS AND H						
SB 604-29-008 R3 Airframe SB - Superseded #3380	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002						
	Notes (AVG MAN HRS: 20) (NOTE: RETROACTIVE ACTION ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND REPLACED THEIR ACCUMULATORS, THIS SERVICE BULLETIN REVISION 03 REMAINS APPLICABLE. ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND HAVE ACCUMULATORS WITH MORE THAN 3650 FLIGHT CYCLES AND HAVE REPLACED THEIR ACCUMULATORS, REVISION 03 OF THIS SERVICE BULLETIN MUST BE INCORPORATED WITHIN THE NEXT 100 FLIGHT CYCLES. ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND HAVE ACCUMULATORS WITH 3650 FLIGHT CYCLES OR LESS AND H						
SB 604-29-008 R3 Airframe SB - Superseded #3146	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002						
	Notes (AVG MAN HRS: 20) (NOTE: RETROACTIVE ACTION ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND REPLACED THEIR ACCUMULATORS, THIS SERVICE BULLETIN REVISION 03 REMAINS APPLICABLE. ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND HAVE ACCUMULATORS WITH MORE THAN 3650 FLIGHT CYCLES AND HAVE REPLACED THEIR ACCUMULATORS, REVISION 03 OF THIS SERVICE BULLETIN MUST BE INCORPORATED WITHIN THE NEXT 100 FLIGHT CYCLES. ? FOR AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND HAVE ACCUMULATORS WITH 3650 FLIGHT CYCLES OR LESS AND H						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-29-008 R4 Airframe SB - N/A #3083	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002	11-OCT-2023 H: 8130.00 L: 3683					
Notes (AVG MAN HRS: 20) (UPDATE NOTE: SB 604-29-008 REV 4, REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002, NOT APPLICABLE BY AFFECTED ACCUMULATORS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (NOTE: RETROACTIVE ACTION: THIS SERVICE BULLETIN REVISION 04 IS NOT APPLICABLE, FOR AIRCRAFT THAT HAVE REPLACED THEIR ACCUMULATORS AND INCORPORATED REVISION 03 OF THIS SERVICE BULLETIN.FOR AIRCRAFT THAT HAVE NOT INCORPORATED REVISION 03 OF THIS SERVICE BULLETIN BUT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND REPLACED THEIR ACCUMULATORS, THIS SERVICE BULLETIN REVISION 04 RE							
SB 604-29-008 R4 Airframe SB - N/A #2608	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002	11-OCT-2023 H: 8130.00 L: 3683	L: 3750			L: 7433	L: 3431
Notes (AVG MAN HRS: 20) (UPDATE NOTE: SB 604-29-008 REV 4, REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002, NOT APPLICABLE BY AFFECTED ACCUMULATORS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (NOTE: RETROACTIVE ACTION: THIS SERVICE BULLETIN REVISION 04 IS NOT APPLICABLE, FOR AIRCRAFT THAT HAVE REPLACED THEIR ACCUMULATORS AND INCORPORATED REVISION 03 OF THIS SERVICE BULLETIN.FOR AIRCRAFT THAT HAVE NOT INCORPORATED REVISION 03 OF THIS SERVICE BULLETIN BUT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND REPLACED THEIR ACCUMULATORS, THIS SERVICE BULLETIN REVISION 04 RE							
SB 604-29-008 R4 Airframe SB - N/A #829	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002	11-OCT-2023 H: 8130.00 L: 3683	L: 3750			L: 7433	L: 3431
Notes (AVG MAN HRS: 20) (UPDATE NOTE: SB 604-29-008 REV 4, REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002, NOT APPLICABLE BY AFFECTED ACCUMULATORS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (NOTE: RETROACTIVE ACTION: THIS SERVICE BULLETIN REVISION 04 IS NOT APPLICABLE, FOR AIRCRAFT THAT HAVE REPLACED THEIR ACCUMULATORS AND INCORPORATED REVISION 03 OF THIS SERVICE BULLETIN.FOR AIRCRAFT THAT HAVE NOT INCORPORATED REVISION 03 OF THIS SERVICE BULLETIN BUT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND REPLACED THEIR ACCUMULATORS, THIS SERVICE BULLETIN REVISION 04 RE							
SB 604-29-008 R4 Airframe SB - N/A #339	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002	11-OCT-2023 H: 8130.00 L: 3683	L: 3750			L: 7433	L: 3431
Notes (AVG MAN HRS: 20) (UPDATE NOTE: SB 604-29-008 REV 4, REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002, NOT APPLICABLE BY AFFECTED ACCUMULATORS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (NOTE: RETROACTIVE ACTION: THIS SERVICE BULLETIN REVISION 04 IS NOT APPLICABLE, FOR AIRCRAFT THAT HAVE REPLACED THEIR ACCUMULATORS AND INCORPORATED REVISION 03 OF THIS SERVICE BULLETIN.FOR AIRCRAFT THAT HAVE NOT INCORPORATED REVISION 03 OF THIS SERVICE BULLETIN BUT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND REPLACED THEIR ACCUMULATORS, THIS SERVICE BULLETIN REVISION 04 RE							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-29-008 R4 Airframe SB - N/A #2197	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002	11-OCT-2023 H: 8130.00 L: 3683	L: 3750			L: 7433	L: 3431
	<p>Notes</p> <p>(AVG MAN HRS: 20) (UPDATE NOTE: SB 604-29-008 REV 4, REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002, NOT APPLICABLE BY AFFECTED ACCUMULATORS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (NOTE: RETROACTIVE ACTION: THIS SERVICE BULLETIN REVISION 04 IS NOT APPLICABLE, FOR AIRCRAFT THAT HAVE REPLACED THEIR ACCUMULATORS AND INCORPORATED REVISION 03 OF THIS SERVICE BULLETIN.FOR AIRCRAFT THAT HAVE NOT INCORPORATED REVISION 03 OF THIS SERVICE BULLETIN BUT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND REPLACED THEIR ACCUMULATORS, THIS SERVICE BULLETIN REVISION 04 RE</p>						
SB 604-29-008 R4 Airframe SB - N/A #1268	MODIFICATION - HYDRAULIC POWER AND LANDING GEAR - REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002	11-OCT-2023 H: 8130.00 L: 3683	L: 3750			L: 7433	L: 3431
	<p>Notes</p> <p>(AVG MAN HRS: 20) (UPDATE NOTE: SB 604-29-008 REV 4, REPLACEMENT OF SYSTEM ACCUMULATORS NO. 1, NO. 2 AND NO. 3 AND BRAKE ACCUMULATORS NO. 2 AND NO. 3 OR PART NOS 08-60163-002 AND 08-60164-002, NOT APPLICABLE BY AFFECTED ACCUMULATORS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (NOTE: RETROACTIVE ACTION: THIS SERVICE BULLETIN REVISION 04 IS NOT APPLICABLE, FOR AIRCRAFT THAT HAVE REPLACED THEIR ACCUMULATORS AND INCORPORATED REVISION 03 OF THIS SERVICE BULLETIN.FOR AIRCRAFT THAT HAVE NOT INCORPORATED REVISION 03 OF THIS SERVICE BULLETIN BUT HAVE INCORPORATED THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN AND REPLACED THEIR ACCUMULATORS, THIS SERVICE BULLETIN REVISION 04 RE</p>						
SB 604-29-009 Airframe SB - Open #1021	MODIFICATION - HYDRAULIC SYSTEM NO. 1 AND NO. 2 - REPLACEMENT OF THE HYDRAULIC SYSTEM NO. 1 ACCUMULATOR						
	<p>Notes</p> <p>(AVG MAN HRS: 4)DECLINED</p>						
SB 604-29-010 Airframe SB - Open #2031	MODIFICATION - HYDRAULIC SYSTEM NO. 1 AND NO. 2 - REPLACEMENT OF THE HYDRAULIC SYSTEM NO. 2 ACCUMULATOR						
	<p>Notes</p> <p>(AVG MAN HRS: 4)DECLINED</p>						
SB 604-29-011 Airframe SB - Open #2224	MODIFICATION - HYDRAULIC SYSTEM NO. 3 - REPLACEMENT OF THE HYDRAULIC SYSTEM NO. 3 ACCUMULATOR						
	<p>Notes</p> <p>(AVG MAN HRS: 4)DECLINED</p>						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-29-012 Airframe SB - Open #1958	MODIFICATION - HYDRAULIC SYSTEM REPLENISHING AND HYDRAULIC POWER - INTRODUCTION OF HYDRAULIC SERVICING PLACARDS WITH VALUES AT DIFFERENT AMBIENT TEMPERATURES						
	Notes (AVG MAN HRS: 8)DECLINED						
SB 604-29-013 Airframe SB - Superseded #1509	MODIFICATION - HYDRAULIC SYSTEM NO. 3 - RELOCATION OF THE HYDRAULIC SYSTEM NO. 3 ACCUMULATOR						
	Notes (AVG MAN HRS: 137) (NOTE: POST THIS SB IMPACTS TLMC TASK 53-30-00-160).SEE REVISION 1.						
SB 604-29-013 R1 Airframe SB - Superseded #1363	MODIFICATION - HYDRAULIC SYSTEM NO. 3 - RELOCATION OF THE HYDRAULIC SYSTEM NO. 3 ACCUMULATOR						
	Notes (AVG MAN HRS: 137).SEE REVISION 2.						
SB 604-29-013 R2 Airframe SB - Complied With #3177	MODIFICATION - HYDRAULIC SYSTEM NO. 3 - RELOCATION OF THE HYDRAULIC SYSTEM NO. 3 ACCUMULATOR					05-JUL-2024 H: 8455.80 L: 3862	
	Notes (AVG MAN HRS: 137)						
SB 604-29-014 Airframe SB - Superseded #1115	MODIFICATION - HYDRAULIC SYSTEM NO. 1 AND NO. 2 - REPLACEMENT OF THE HYDRAULIC TUBE SUPPORT BRACKETS AND CLAMPS IN THE AFT EQUIPMENT COMPARTMENT						
	Notes (AVG MAN HRS: 6) (NOTE: NOTE: THE INTENT OF THIS SERVICE BULLETIN IS MET FOR AIRCRAFT THAT HAVE PREVIOUSLY COMPLETED THE MODIFICATION AS PER NOTE 2 OF KIT DRAWING K604-75012, VIA IS MODSUM IS604-29-0001.).SEE REVISION 1.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-29-014 R1 Airframe SB - Open #2600	MODIFICATION - HYDRAULIC SYSTEM NO. 1 AND NO. 2 - REPLACEMENT OF THE HYDRAULIC TUBE SUPPORT BRACKETS AND CLAMPS IN THE AFT EQUIPMENT COMPARTMENT						
	Notes (AVG MAN HRS: 6) (NOTE: NOTE: THE INTENT OF THIS SERVICE BULLETIN IS MET FOR AIRCRAFT THAT HAVE PREVIOUSLY COMPLETED THE MODIFICATION AS PER NOTE 2 OF KIT DRAWING K604-75012, VIA IS MODSUM IS604-29-0001.)						
SB 604-30-002 Airframe SB - Complied With #2505	SPECIAL CHECK/MODIFICATION - WING ANTI-ICE CONTROL AND INDICATING SYSTEM - INSPECTION OF STANDBY THERMAL SWITCHES FOR PRESENCE OF THERMAL COMPOUND					12-APR-2013 H: 4782.30 L: 2063	
	Notes (AVG MAN HRS: 2)						
SB 604-30-003 Airframe SB - N/A #1591	SPECIAL CHECK/MODIFICATION - WING ANTI-ICE DUCT MANIFOLD SYSTEM - ANTI-ICE PICCOLO DUCTS INSPECTION/REPLACEMENT						
	Notes .SUPERSEDED BY SB 604-30-003 REV 1						
SB 604-30-003 R1 Airframe SB - Complied With #840	SPECIAL CHECK/MODIFICATION - WING ANTI-ICE DUCT MANIFOLD SYSTEM - ANTI-ICE PICCOLO DUCTS INSPECTION/REPLACEMENT					12-APR-2013 H: 4782.30 L: 2063	
	Notes (AVG MAN HRS: 60) (NOTE: COMPLIANCE FOR AIRCRAFT THAT HAVE LESS THEN 2000 FLIGHT HOURS, THIS SERVICE BULLETIN IS RECOMMENDED BEFORE IT REACHES 4000 FLIGHT HOURS OR 96 MONTHS CALENDAR TIME, WHICHEVER COMES FIRST. FOR AIRCRAFT THAT HAVE MORE THAN 2000 FLIGHT HOURS OR 96 MONTHS CALENDAR TIME, THIS SERVICE BULLETIN IS RECOMMENDED WITHIN THE NEXT 2000 FLIGHT HOURS FROM ITS RELEASE DATE, (BASIC ISSUE).)						
SB 604-30-004 Airframe SB - Superseded #899	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), INTRODUCTION OF SUPPLEMENTAL GROUND WING ANTI-ICING						
	Notes (AVG MAN HRS: 350) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUALS ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, TR 604/41-1, DATED FEBRUARY 4, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, TR 604/45-1, DATED FEBRUARY 4, 2016. TASK 30-12-00-102 AND 30-22-00-101 REQUIREMENT TO BE REVIEWED AND CHANGED TO THE PROPER INTERVAL IF SB BEING PERFORMED.).SEE REVISION 1.						



Maintenance Items

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-30-004 R1 Airframe SB - Superseded #1008	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), INTRODUCTION OF SUPPLEMENTAL GROUND WING ANTI-ICING						
	Notes (AVG MAN HRS: 350) (NOTE: NOTE: SB 604-21-010 IS A PREREQUISITE FOR SB 604-30-004. HOWEVER, BOMBARDIER HAS NOT RELEASED SB 604-21-010 AT THIS TIME. ANTICIPATED RELEASE DATE IS SECOND QUARTER OF 2016. NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUALS ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, TR 604/41-1, DATED MARCH 18, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, TR 604/45-1, DATED MARCH 18, 2016. TASK 30-12-00-102 REQUIREMENT TO BE REVIEWED IF SB BEING COMPLIED.).SEE REVISION 2.						
SB 604-30-004 R2 Airframe SB - Superseded #1517	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), INTRODUCTION OF SUPPLEMENTAL GROUND WING ANTI-ICING						
	Notes (AVG MAN HRS: 350) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUALS ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, TR 604/41-2, DATED AUGUST 04, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, TR 604/45-3, DATED SEPTEMBER 02, 2016. TASK 30-12-00-102 AND 30-22-00-101 REQUIREMENT TO BE REVIEWED AND CHANGED TO THE PROPER INTERVAL IF SB BEING PERFORMED.).SEE REVISION 3.						
SB 604-30-004 R3 Airframe SB - Superseded #3569	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), INTRODUCTION OF SUPPLEMENTAL GROUND WING ANTI-ICING						
	Notes (AVG MAN HRS: 350) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUALS ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016. TASK 30-12-00-102 AND 30-22-00-101 REQUIREMENT TO BE REVIEWED AND CHANGED TO THE PROPER INTERVAL IF SB BEING PERFORMED.).SEE REVISION 4.						
SB 604-30-004 R4 Airframe SB - Open #3014	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), INTRODUCTION OF SUPPLEMENTAL GROUND WING ANTI-ICING						
	Notes (AVG MAN HRS: 350) (NOTE: NOTE: THIS SERVICE BULLETIN IS MANDATED BY AIRWORTHINESS DIRECTIVE (AD) TCCA, AD CF-2017-07R1 AND EASA, AD CF-2017-07R1. NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUALS ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016. TASK 30-12-00-102 AND 30-22-00-101 REQUIREMENT TO BE REVIEWED AND CHANGED TO THE PROPER INTERVAL IF SB BEING PERFORMED.)DECLINED						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-30-005 Airframe SB - Superseded #3201	MODIFICATION - ENGINE COWL DUCTING SYSTEM - INSTALLATION OF SUPPORT BRACKET AND CLAMPS ON T2 SENSOR ANTI-ICE TUBE						
	Notes (AVG MAN HRS: 11).SEE REVISION 1.						
SB 604-30-005 Part C Airframe SB - Open #1605	MODIFICATION - ENGINE COWL DUCTING SYSTEM - INSTALLATION OF SUPPORT BRACKET AND CLAMPS ON T2 SENSOR ANTI-ICE TUBE						
	Notes (AVG MAN HRS: 3)						
SB 604-30-005 Part B Airframe SB - Open #1635	MODIFICATION - ENGINE COWL DUCTING SYSTEM - INSTALLATION OF SUPPORT BRACKET AND CLAMPS ON T2 SENSOR ANTI-ICE TUBE						
	Notes (AVG MAN HRS: 5)						
SB 604-30-005 Part A Airframe SB - Open #389	MODIFICATION - ENGINE COWL DUCTING SYSTEM - INSTALLATION OF SUPPORT BRACKET AND CLAMPS ON T2 SENSOR ANTI-ICE TUBE						
	Notes (AVG MAN HRS: 3)						
SB 604-30-005 R1 Part C Airframe SB - Open #1397	MODIFICATION - ENGINE COWL DUCTING SYSTEM - INSTALLATION OF SUPPORT BRACKET AND CLAMPS ON T2 SENSOR ANTI-ICE TUBE						
	Notes (AVG MAN HRS: 3)						
SB 604-30-005 R1 Airframe SB - Open #1164	MODIFICATION - ENGINE COWL DUCTING SYSTEM - INSTALLATION OF SUPPORT BRACKET AND CLAMPS ON T2 SENSOR ANTI-ICE TUBE						
	Notes DECLINED						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-30-005 R1 Part A Airframe SB - Open #2962	MODIFICATION - ENGINE COWL DUCTING SYSTEM - INSTALLATION OF SUPPORT BRACKET AND CLAMPS ON T2 SENSOR ANTI-ICE TUBE						
	Notes (AVG MAN HRS: 3)						
SB 604-30-005 R1 Part B Airframe SB - Open #3465	MODIFICATION - ENGINE COWL DUCTING SYSTEM - INSTALLATION OF SUPPORT BRACKET AND CLAMPS ON T2 SENSOR ANTI-ICE TUBE						
	Notes (AVG MAN HRS: 5)						
SB 604-30-005 R2 Airframe SB - Open #3044	MODIFICATION - ENGINE COWL DUCTING SYSTEM - INSTALLATION OF SUPPORT BRACKET AND CLAMPS ON T2 SENSOR ANTI-ICE TUBE						
SB 604-30-005 R2 Part B Airframe SB - Open #2150	MODIFICATION - ENGINE COWL DUCTING SYSTEM - INSTALLATION OF SUPPORT BRACKET AND CLAMPS ON T2 SENSOR ANTI-ICE TUBE - MODIFICATION						
	Notes (AVG MAN HRS: 5)						
SB 604-30-005 R2 Part A Airframe SB - Open #783	MODIFICATION - ENGINE COWL DUCTING SYSTEM - INSTALLATION OF SUPPORT BRACKET AND CLAMPS ON T2 SENSOR ANTI-ICE TUBE - MODIFICATION						
	Notes (AVG MAN HRS: 3)						